



Close the restoration gap: reconnexion as an essential step

Girard, A.ⁱ, Jutras, S.ⁱ & Rochefort, L.ⁱ

Laggs of bogs ensure a hydrological protection zone [1]; in restoration projects, special attention seems essential for the return of similar ecohydrological functions. However, hydrological behaviour within peat substrate in bog fragments, essential for the return of target plants [2], are still poorly understood in areas subjected to topographical constraints.



Reprofiling and tree felling appear to improve the hydrology of peatland fragments after extraction.

Preliminary results

At similar points along the slope, the water table depth is lower relative to the surface in the untreated zones (control) than in the reprofiled zones.

At a 14 m distance from the main drainage channel (decommissioned), the water table is lower in the control compared to the reprofiled treatments.

Similar results have been observed for both types of treatments (steep-slope and gentle-slope restoration); reprofiled sections exhibit hydrological indicators that are more conducive to the regrowth of sphagnum moss.

