


Figure 6.15: Velocity Profile Error Comparison for Best Water Fits

developed streamlines without hardly contributions to the lower-left stagnant regions. The effect here is two-fold; not only is there a fast stream developed along the leftmost wall of the loop, but that streamline creates a low pressure region at the elbow that results in an internal recirculation, seen by the negative vertical velocity components seen on the lower end of the legend for the right sub-figure within Figure 6.16




Figure 6.16: Lower Left Velocity Planar Cross Section

We can see that this extends all the way through the test section, as seen on the left of