Figure 6.18 and it actually continues all the way up to the top junction where it is split by creases in the tee-junction, seen in Figure 6.17. As an observation note, the apparent oddity in the upper-right corner of Figure 6.17 is the flow being deflected by the internal Steinmetz structure of the intersecting cylindrical boreholes.




Figure 6.17: Upper Left Velocity Planar Cross Section

This reveals a consequence of the use of the PIV methodology. The experimentalists later confirmed that the internal recirculation was not an artifact of the CFD, but in-fact a real, physical behavior that managed to go unrecorded by the original experimental effort.

With the visualizations covered, the final summary of the the validations efforts success can be tabulated. Below are the results using the validation uncertainty for water 2 with kOmegaSSTLM_Gb turbulence modeling and using the validation uncertainty for water 4 with kOmegaSSTLM. Aside from those two exceptions, each case is compared against its laminar results before being classified as validated or not.