
Poor Cooling Performance in a Vehicle with Dual A/C

Oct 23, 2022

CONDITION: Poor cooling performance in a vehicle with a dual (front/rear) A/C system. The system uses a joint type expansion valve* in the rear cooling unit, with no magnetic valve. The compressor has been confirmed to be ok, and the front expansion valve was replaced recently.

CAUSE: The thermosensitive tube of the rear expansion valve has become loose and is not reading the evaporator outlet temperature accurately. This caused the expansion valve to open more than necessary, and caused more refrigerant to flow to the rear cooling unit.



CORRECTION: Access the thermosensitive tube of the rear expansion valve and secure it tightly to the appropriate groove on the low-pressure tube of the rear cooling unit. Consult the manufacturer's service information to meet proper insulation requirements.

*May also be seen in various models which have similar system configurations (e.g. 2001 – 2007 Toyota Sequoia).

Product Group	Assembly	Category
Air Conditioning	Expansion Valve	Repair Procedures
Year	**Make**	**Model**
1998-2006	Toyota	Sienna

Passenger Vehicles

Commercial Vehicles



Find My Part



Where to Buy



Find My Part



Where to Buy

Passenger Vehicles



Find My Part



Where to Buy

Commercial Vehicles



Find My Part



Where to Buy

Company

Contact Us
Why DENSO
Motorsports
DENSOconnect
News & Events
DENSO Global
Careers
Warranty

Company

Contact Us
Why DENSO
Motorsports
DENSOconnect
News & Events
DENSO Global
Careers

Other Automotive

Latinoamérica
PowerEdge

Commercial/Industrial

Automatic Data Capture
EdgeCool
MovinCool
Robotics

Commercial/Industrial

Automatic Data Capture

EdgeCool

MovinCool

Robotics

Privacy Policy

Terms of Use

Do Not Sell or Share My Personal Information

Site Map

Privacy Policy

Terms of Use

Do Not Sell or Share My Personal Information

Site Map

©2026 DENSO Products and Services Americas, Inc. All rights reserved.
First Time Fit, Endurovision, Iridium Power, Iridium Racing, Platinum TT and Iridium TT are registered trademarks of DENSO.