Test Case / Original Request

Run PTC-006 using JMeter. Execute the real performance test and collect monitoring results. Assess the security surface for the same job and exact configured target.Analyze the current job’s results and generate the final PDF with security coverage and evidence, plus links to the native JMeter report, raw results, and final PDF

REAL Execution Outcome

Execution status: COMPLETED
Runner status: completed
Outcome details: REAL JMeter execution completed. Configured thresholds passed.
Process exit code: 0
Thresholds passed: True

Executive Summary

Application: Unknown
Scenario: Product Catalog API — Load Check
Job ID: JOB-51b14130cf444b79ac34f46bfea12a8b
Overall Result: WARNING

Performance and infrastructure results are generally strong, with low error rates and consistent response times under load. However, response time outliers were observed: max response time (619ms) substantially exceeded the p95 (225ms), suggesting occasional spikes. No infrastructure problems or monitoring anomalies were detected. Security coverage is incomplete—an external surface observation was not performed, so no live API security findings can be claimed; configuration coverage is limited.

Execution Profile and Artifacts

Execution mode: REAL
Workload profile:
- tool: jmeter
- target_url: https://dummyjson.com
- endpoint: /products/1
- method: GET
- users: 45
- max_rps: 20
- duration_seconds: 60
- ramp_up_seconds: 5
- expected_status_code: 200
- p95_threshold_ms: 5000
Artifact directory: src/generated_scripts/Jmeter native reports/JOB-51b14130cf444b79ac34f46bfea12a8b
Artifact references:
- aligned_time_series: src/generated_scripts/Jmeter native reports/JOB-51b14130cf444b79ac34f46bfea12a8b/jmeter_PTC_006_plan_aligned_time_series.csv
- generated_script: src/generated_scripts/Jmeter native reports/JOB-51b14130cf444b79ac34f46bfea12a8b/jmeter_PTC_006_plan.jmx
- jmeter_log: src/generated_scripts/Jmeter native reports/JOB-51b14130cf444b79ac34f46bfea12a8b/jmeter_PTC_006_plan_jmeter.log

- measurement_metadata: src/generated_scripts/Jmeter native reports/JOB-51b14130cf444b79ac34f46bfea12a8b/jmeter_PTC_006_plan_measurement_metadata.json
- monitoring_samples: src/generated_scripts/Jmeter native reports/JOB-51b14130cf444b79ac34f46bfea12a8b/jmeter_PTC_006_plan_runtime_samples.csv
- Native JMeter HTML dashboard
- JMeter dashboard + raw JTL ZIP
- native_report_entrypoint: src/generated_scripts/Jmeter native reports/JOB-51b14130cf444b79ac34f46bfea12a8b/jmeter_PTC_006_plan_native_report.html
- normalized_metrics: src/generated_scripts/Jmeter native reports/JOB-51b14130cf444b79ac34f46bfea12a8b/jmeter_PTC_006_plan_normalized_metrics.json
- Raw JMeter results (JTL)
- runner_log: src/generated_scripts/Jmeter native reports/JOB-51b14130cf444b79ac34f46bfea12a8b/jmeter_PTC_006_plan_runner.log
- time_series: src/generated_scripts/Jmeter native reports/JOB-51b14130cf444b79ac34f46bfea12a8b/jmeter_PTC_006_plan_time_series.csv

The interactive native HTML dashboard is linked as a separate artifact and is not embedded in this PDF.

Time-Series Charts (REAL Measurements)

Charts show measured values in five-second aligned buckets. Host CPU is from the load-generator machine, not the target.



Throughput over time

JMeter client-observed HTTP traffic



Load-generator host CPU over time

psutil load-generator host



Agent Activity Summary

Agent	*Summary*
Test Execution	Load test executed on /products/1 (Unknown - Product Catalog API — Load Check). Results: 1,198 total requests, 1,198 successful, 0 failed. Avg response time: 146.6085141903172 ms; 95th percentile: 225.0 ms; Max: 619.0 ms. Throughput: 19.218964118716958 TPS; Error rate: 0.0%. Latency percentiles (ms): p50=128.0, p90=198.0, p95=225.0, p99=438.0

Agent	*Summary*
Monitoring	CPU usage: 9.85% average, 19.7% peak; memory: 78.78% average, 79.4% peak; DB connections: not collected, TPS: 19.218964118716958, Response time: 146.6085141903172 ms. Data source and scope: REAL: psutil load-generator host samples and jmeter client-observed metrics. Measurement provenance: cpu_usage=psutil (load_generator_host); cpu_peak_usage=psutil (load_generator_host); memory_usage=psutil (load_generator_host); memory_peak_usage=psutil (load_generator_host); response_time=jmeter (load_generator_observed_http_traffic); tps=jmeter (load_generator_observed_http_traffic); db_connections=not_collected (No target-specific database telemetry provider is configured.); total_requests=jmeter JTL (load_generator_observed_http_traffic); failed_requests=jmeter JTL (load_generator_observed_http_traffic); error_rate_pct=jmeter JTL (load_generator_observed_http_traffic); latency_percentiles_ms=jmeter JTL (load_generator_observed_http_traffic). No alerts triggered.
Security Validation	Status: WARNING. Live security check: not assessed. Issue: The external API surface observation did not complete, so no response-security findings are claimed. Issue: external_surface was not assessed; missing evidence: No authorized external surface observation was completed.. Issue: Scope limitation: configuration validator outcomes describe profile declarations; any live result is a separate single-request observation and does not prove control effectiveness. Issue: No matching application security profile: No versioned profile matches the trusted application, environment, target origin, endpoint, and method. Issue: Live security check was requested, but no live result was recorded. Control coverage: {'requested_count': 1, 'assessed_count': 0, 'not_assessed_count': 1} Control assessment evidence: - external_surface: not_assessed; basis=live_observation; evidence=[] Assessment limitations: - No authorized external surface observation was completed. - No versioned profile matches the trusted application, environment, target origin, endpoint, and method. - No runtime security checks were performed; results describe configuration declarations only. - The requested live security observation did not complete.
Analysis	Performance and infrastructure results are generally strong, with low error rates and consistent response times under load. However, response time outliers were observed: max response time (619ms) substantially exceeded the p95 (225ms), suggesting occasional spikes. No infrastructure problems or monitoring anomalies were detected. Security coverage is incomplete—an external surface observation was not performed, so no live API security findings can be claimed; configuration coverage is limited.
Reporting	A PDF report was generated, including all findings, recommendations, and an executive summary.

Per-API Findings (Test Execution)

- /products/1 [WARNING / medium]
avg=146.6085141903172ms p95=225.0ms max=619.0ms throughput=19.218964118716958 req/s error_rate=0.0% http_status=200
* Max response time (619.0ms) is 2.8x p95 (225.0ms) -- outlier spikes present.
history: No historical context available for this scenario and API. Analysis is based on static threshold breach only.
recommendation: The max response time shows significant spikes (2.8x higher than p95), indicating occasional outliers under load. Without historical or SLA context, address by reviewing backend logs for slow traces; if spikes repeat across runs, consider tuning backend performance or scaling.

Infrastructure Health (Monitoring)

Status: PASS (monitoring_agent reported: OK)
CPU usage: 9.85% Memory usage: 78.78% DB connections: None TPS: 19.218964118716958
Response time (monitoring): 146.6085141903172ms

Security Findings (Security Agent)

Status: WARNING Security score: N/A
Security result job ID: JOB-51b14130cf444b79ac34f46bfea12a8b.
Live security check: not assessed.
Issues:
- The external API surface observation did not complete, so no response-security findings are claimed.
- external_surface was not assessed; missing evidence: No authorized external surface observation was completed..
- Scope limitation: configuration validator outcomes describe profile declarations; any live result is a separate single-request observation and does not prove control effectiveness.
- No matching application security profile: No versioned profile matches the trusted application, environment, target origin, endpoint, and method.
- Live security check was requested, but no live result was recorded.
Control coverage: {'requested_count': 1, 'assessed_count': 0, 'not_assessed_count': 1}
Requested controls: external_surface
Not assessed controls: external_surface
Control evidence and provenance:
- external_surface: not_assessed; basis=live_observation; evidence fields=[]; references=[]
Assessment limitations:
- No authorized external surface observation was completed.
- No versioned profile matches the trusted application, environment, target origin, endpoint, and method.
- No runtime security checks were performed; results describe configuration declarations only.
- The requested live security observation did not complete.

Recommended Next Steps

- /products/1: The max response time shows significant spikes (2.8x higher than p95), indicating occasional outliers under load. Without historical or SLA context, address by reviewing backend logs for slow traces; if spikes repeat across runs, consider tuning backend performance or scaling.
- Security: address the issues/recommendations listed above before next deployment.