

**TUV Rheinland (India) Pvt. Ltd (6126126), Bengaluru**ULR No. : ULR-
TC611626100000079F

DOC No. : TUV Rheinland (India) Pvt. Ltd. 27/B, 2nd Cross Road,
Telephone : +91 9620288803 Electronic City Phase-1, Bangalore, Bengaluru,
FAX : - Bengaluru Rural, Karnataka, India - 560100
E-Mail : guruprasad.br@ind.tuv.com
BO Code : None

Test REPORT AS PER : IS 17631 (2022)**QR Code/Barcode : 100001256347****REPORT NO : 10518331/2026/SS/3_1**

DATE : 14 Mar, 2026

PART A. PARTICULARS OF SAMPLE SUBMITTED

a) Customer Name & Address : MBTC INTRAFURNISH PRIVATE LIMITED
POCKET J, 113 AND 114, SECTOR 4, DSIIDC,
NEAR FOREST AREA, BAWANA INDUSTRIAL AREA,
BAWANA, NORTH WEST DELHI, DELHI, INDIA -
110039

b) Nature of sample : SS

c) Grade/Variety/Type/Class Size etc : NAME OF THE PRODUCT: WORK CHAIRS; LEAD
MODEL: ASTRIDE OCTAVE HB OFFICE CHAIR;
CONSTRUCTION OF CHAIR: WITH RECLINING
PROVISIONS, WITH CASTORS, WITHOUT
FOOTREST; MAXIMUM USER MASS AND USAGE
HOUR PER WEEK: 110 KG AND USED FOR 40
HOUR PER WEEK

d) Declare values, if any : ASTRIDE Octave HB office chair

e) Batch No. & Date of Manufacture : 20260121/

f) Quantity : 2 chairs of lead model (Octave HB); 2meter
fabric (Seat fabric) 2meter Fabric (Back Fabric)

g) Date of Receipt : 05 Feb, 2026

h) BIS Seal : Verified by Sample Cell

i) IO's Signature : Verified by Sample Cell

j) Any other Information / Expiry Date, If any : -/NA

k) Date of Commencement of Testing : 05 Feb, 2026

l) Date of Completion of Testing : 14 Mar, 2026

m) Section Code : 26ME296E2

n) Section Report No. : 26ME296E2_1

o) Report Type : New

p) Reference Report No. :

q) Remarks :

Sathish Kumar R
OIC SAMPLE CELL
(Authorized Signatory)
Authorized on: 14 Mar, 2026 13:53 PM

This is a Computer Generated Report.

PART B. SUPPLEMENTARY INFORMATION

- | | |
|--|----------------|
| 1. Reference to sampling procedure, wherever applicable. | Not Applicable |
| 2. Supporting documents for the measurements taken and results derived like graphs, table sketches and or photographs as appropriate to test report, if any. | Yes |
| 3. Deviation from the test methods as prescribed in relevant ISS/Work instruction, if any. | No |
| 3. NABL Report required ? | Yes |

Ajaykumar M
OIC Mechanical
(Authorized Signatory)
Authorized on: 14 Mar, 2026 13:52 PM

This is a Computer Generated Report.

PART C. TEST RESULT

S.No.	Clause No Table No. Sl. No	Parameter - Method of test	Test Description	Min Limit	Max Limit	Unit	Result/ Observation
1	CI-7.5.5	Castor and Chair-Base Durability	-	-	-	-	No damage or deformation Observed No overturning of chair Observed No fractures or breakage observed No loosening of joints observed
2	CI-7.5.4	Foot-rest Durability	-	-	-	-	Test Not Applicable
3	CI-7.5.3	Swivel Test	-	-	-	-	No damage or deformation Observed No overturning of chair Observed No fractures or breakage observed No loosening of joints observed
4	CI-7.5.2	Arm Rest Durability	-	-	-	-	No damage or deformation Observed No overturning of chair Observed No fractures or breakage observed No loosening of joints observed
5	CI-7.5.1	Seat and Back Durability	-	-	-	-	No damage or deformation Observed No overturning of chair Observed No fractures or breakage observed No loosening of joints observed
6	CI-7.4.6	Foot Rest Static Load Test	-	-	-	-	Test Not Applicable
7	CI-7.4.5	Arm Rest Sideways Static Load Test	-	-	-	-	No damage or deformation Observed No fractures or breakage observed No loosening of joints observed
8	CI-7.4.4	Arm Rest Downward Static Load Test — Front	-	-	-	-	No damage or deformation Observed No fractures or breakage observed No loosening of joints observed
9	CI-7.4.3	Arm Rest Downward Static Load Test — Central	-	-	-	-	No damage or deformation Observed No fractures or breakage observed No loosening of joints observed

10	CI-7.4.2	Combined Seat and Back Static Load Test	-	-	-	-	No damage or deformation Observed No fractures or breakage observed No loosening of joints observed
11	CI-7.4.1	Seat Front Edge Static Load Test	-	-	-	-	No damage or deformation Observed No fractures or breakage observed No loosening of joints observed
12	CI-7.3.7	Rearwards Overturning for Chairs with Backrest Inclination	-	-	-	-	No damage or deformation Observed No fractures or breakage observed No loosening of joints observed
13	CI-7.3.6	Rearwards Overturning for Chairs Without Back Rest Inclination	-	-	-	-	No damage or deformation Observed No overturning of chair Observed No fractures or breakage observed No loosening of joints observed
14	CI-7.3.5	Sideways Overturning for Chairs With Arm Rests	-	-	-	-	No damage or deformation Observed No overturning of chair Observed No fractures or breakage observed No loosening of joints observed
15	CI-6.2 (b) (8)	For Natural Leather: Colour fastness to water	-	-	-	-	Test Not Applicable
16	CI-6.2 (b) (7)	For Natural Leather: Water vapour permeability	-	-	-	-	Test Not Applicable
17	CI-6.2 (b) (6)	For Natural Leather: Colour fastness to water spotting	-	-	-	-	Test Not Applicable
18	CI-6.2 (b) (5)	For Natural Leather: Colour fastness to rubbing	-	-	-	-	Test Not Applicable
19	CI-6.2 (b) (4)	For Natural Leather: Colour fastness to artificial light	-	-	-	-	Test Not Applicable
20	CI-6.2 (b) (3)	For Natural Leather: Finish adhesion	-	-	-	-	Test Not Applicable
21	CI-6.2 (b) (1)	For Natural Leather:- Tear strength	As per IS 17637	-	-	-	Test Not Applicable
22	CI-6.2 (b) (2)	For Natural Leather:- Flexing endurance	-	-	-	-	Test Not Applicable
23	CI-6.2 (a) (14)	For Fabric and Synthetic Leather:- Resistance to cold	-	-	-	-	Test Not Applicable
24	CI-6.2 (a) (13)	For Fabric and Synthetic Leather:- Bursting strength	-	12.0	-	kg/cm ²	14.1 (kg/cm ²)
25	CI-6.2 (a) (12)	For Fabric and Synthetic Leather:- Abrasion resistance	-	-	-	-	Seat Knit fabric & back Mesh fabric: No thread Breakdown occurred up to 35000 rubs

26	CI-6.2 (a) (11)	For Fabric and Synthetic Leather:- Resistance to damage by flexing	-	-	-	-	Test Not Applicable
27	CI-6.2 (a) (10)	For Fabric and Synthetic Leather:- Seam slippage	-	-	-	-	Test Not Applicable
28	CI-6.2 (a) (9)	For Fabric and Synthetic Leather:- Coating adhesion strength	-	-	-	-	Test Not Applicable
29	CI-6.2 (a) (8)	For Fabric and Synthetic Leather:- Pilling resistance	-	-	-	-	Seat Knit fabric & Back Mesh fabric: No of Rubs Pilling Fuzzing After 125 Rubs: 4-5 4-5 After 500 Rubs: 4-5 4-5 After 1000 Rubs: 4-5 4-5 After 2000 Rubs: 4-5 4-5 After 5000 Rubs: 4-5 4-5
30	CI-6.2 (a) (7)	For Fabric and Synthetic Leather:- Colour fastness to water	-	-	-	-	Seat Knit Fabric: Colour change: 4-5 - Staining on Acetate: 4-5 -Staining on Cotton: 4-5 -Staining on Nylon: 4-5 - Staining on Polyester: 4-5 -Staining on Acrylic: 4-5 -Staining on Wool: 4-5 Back Mesh fabric: Colour change: 4-5 - Staining on Acetate: 4-5 -Staining on Cotton: 4-5 -Staining on Nylon: 4-5 - Staining on Polyester: 4-5 -Staining on Acrylic: 4-5 -Staining on Wool: 4-5
31	CI-6.2 (a) (6)	For Fabric and Synthetic Leather:- Colour fastness to perspiration	-	-	-	-	Seat Knit Fabric: ACIDIC ALKALINE Colour change: 4-5 4-5 -Staining on Acetate: 4-5 4-5 - Staining on Cotton: 4-5 4-5 -Staining on Nylon: 4-5 4-5 - Staining on Polyester: 4-5 4-5 -Staining on Acrylic: 4-5 4-5 - Staining on Wool: 4-5 4-5 Back Mesh fabric: ACIDIC ALKALINE Colour change: 4-5 4-5 -Staining on Acetate: 4-5 4-5 - Staining on Cotton: 4-5 4-5 -Staining on Nylon: 4-5 4-5 - Staining on Polyester: 4-5 4-5 -Staining on Acrylic: 4-5 4-5 - Staining on Wool: 4-5 4-5
32	CI-6.2 (a) (5)	For Fabric and Synthetic Leather:- Colour fastness to rubbing	-	-	-	-	Seat Knit Fabric: Dry 4-5, Wet 4-5 Back Mesh Fabric: Dry 4-5, Wet 4-5
33	CI-6.2 (a) (4)	For Fabric and Synthetic Leather:- Colour fastness to light	-	-	-	-	Seat Knit Fabric: 4 Back Mesh fabric: 4
34	CI-6.2 (a) (3)	For Fabric and Synthetic Leather:- Tear strength	-	-	-	-	Test Not Applicable

35	CI-6.2 (a) (2)	For Fabric and Synthetic Leather:- Elongation at break	As per IS 17637	-	-	-	Test Not Applicable
36	CI-6.1 (g)	Adhesive performance	-	-	-	-	Test Not Applicable
37	CI-6.1 (f)	Resistance to marking by cold oils and fats;	-	-	-	-	Test Not Applicable
38	CI-6.1 (e)	Resistance to marking by cold liquids	As per IS 17637	-	-	-	Test Not Applicable
39	CI-6.1 (d)	Resistance to dry heat;	As per IS 17637	-	-	-	Test Not Applicable
40	CI-6.1 (c)	Resistance to wet heat;	As per IS 17637	-	-	-	Test Not Applicable
41	CI-6.1 (b)	Pencil hardness	As per IS 17637	-	-	-	Test Not Applicable
42	CI-7.3.4	Sideways Overturning for Chairs Without Arm Rests	-	-	-	-	Test Not Applicable
43	CI-7.3.3	Forwards Overturning for Chairs with Foot Rest	-	-	-	-	Test Not Applicable
44	CI-7.3.2	Forwards Overturning	-	-	-	-	No damage or deformation Observed No overturning of chair Observed No fractures or breakage observed No loosening of joints observed
45	CI-7.3.1	Front Edge Overturning	-	-	-	-	No damage or deformation Observed No overturning of chair Observed No fractures or breakage observed No loosening of joints observed
46	CI-6.2 (a) (1)	For Fabric and Synthetic Leather:- Breaking load	specified in IS 17637	-	-	-	Test Not Applicable
47	CI-6.1 (a)	Resistance to mechanical damage	As per IS 17637	-	-	-	Test Not Applicable
48	clause 5	DIMENSIONS	as per IS 3663	470.0	510.0	mm	508.0 (Seat Width: 508.0mm)
49	clause 4	DESIGN AND WORKMANSHIP	as per IS 17524	-	-	-	Design and Workmanship Design details not received, hence not evaluated. Workmanship is good, All edges are smooth and safe, hollow parts are capped, movable parts prevent injury

Ajaykumar M
OIC Mechanical
(Authorized Signatory)
Authorized on: 14 Mar, 2026 13:52 PM

This is a Computer Generated Report.

.....

PART D. REMARKS

Ajaykumar M
OIC Mechanical
(Authorized Signatory)
Authorized on: 14 Mar, 2026 13:52 PM

This is a Computer Generated Report.



Prüfbericht-Nr.: Test report no.:	IN26ZT5M 001 ULR-TC611626100000079F	Auftrags-Nr.: Order no.:	147164276 Seite 1 von 14 Page 1 of 14
Kunden-Referenz-Nr.: Client reference no.:	2721631	Auftragsdatum: Order date:	2026-02-06
Auftraggeber: Client:	MBTC INTRAFURNISH PRIVATE LIMITED POCKET J, 113 AND 114, SECTOR 4, DSIIDC, NEAR FOREST AREA, BAWANA INDUSTRIAL AREA,,BAWANA,NORTH WEST DELHI,DELHI,INDIA-110039		
Prüfgegenstand: Test item:	ASTRIDE OCTAVE HB OFFICE CHAIR		
Bezeichnung / Typ-Nr.: Identification / Type no.:	ASTRIDE OCTAVE HB OFFICE CHAIR		
Auftrags-Inhalt: Order content:	Performance and Safety test		
Prüfgrundlage: Test specification:	IS 17631:2022 Work Chairs - Specification		
Wareneingangsdatum: Date of sample receipt:	2026-02-02		
Prüfmuster-Nr.: Test sample no.:	A004205776-001		
Prüfzeitraum: Testing period:	2026-02-02 – 2026-03-14		
Ort der Prüfung: Place of testing:	27/B, 2nd Cross, Electronic City, Phase 1, Bangalore		
Prüflaboratorium: Testing laboratory:	TÜV Rheinland (India) Pvt. Ltd		
Prüfergebnis*: Test result*:	Pass		
geprüft von: tested by: Sachin Shivaraj	genehmigt von: authorized by: Ajay Kumar		
Datum: Date: 2026-03-14	Ausstellungsdatum: Issue date: 2026-03-14		
Stellung / Position:	Senior Engineer	Stellung / Position:	Lab Manager
Sonstiges / Other:	Discipline: Mechanical Group: Performance/Durability/Safety BIS Sample Code : 10518331/2026/SS/3 QR Code Number : 100001256347		
Zustand des Prüfgegenstandes bei Anlieferung: Condition of the test item at delivery:	Prüfmuster vollständig und unbeschädigt Test item complete and undamaged		
* Legende: P(ass) = entspricht o.g. Prüfgrundlage(n) F(ail) = entspricht nicht o.g. Prüfgrundlage(n) N/A = nicht anwendbar N/T = nicht getestet * Legend: P(ass) = passed a.m. test specification(s) F(ail) = failed a.m. test specification(s) N/A = not applicable N/T = not tested			
Dieser Prüfbericht bezieht sich nur auf das o.g. Prüfmuster und darf ohne Genehmigung der Prüfstelle nicht auszugsweise vervielfältigt werden. Dieser Bericht berechtigt nicht zur Verwendung eines Prüfzeichens. This test report only relates to the above mentioned test sample. Without permission of the test center this test report is not permitted to be duplicated in extracts. This test report does not entitle to carry any test mark.			

1	Alle eingesetzten Prüfmittel waren zum angegebenen Prüfzeitraum gemäß eines festgelegten Kalibrierungsprogramms unseres Prüfhauses kalibriert. Sie entsprechen den in den Prüfprogrammen hinterlegten Anforderungen. Die Rückverfolgbarkeit der eingesetzten Prüfmittel ist durch die Einhaltung der Regelungen unseres Managementsystems gegeben. Detaillierte Informationen bezüglich Prüfkonditionen, Prüfequipment und Messunsicherheiten sind im Prüflabor vorhanden und können auf Wunsch bereitgestellt werden. <i>The equipment used during the specified testing period was calibrated according to our test laboratory calibration program. The equipment fulfils the requirements included in the relevant standards. The traceability of the test equipment used is ensured by compliance with the regulations of our management system. Detailed information regarding test conditions, equipment and measurement uncertainty is available in the test laboratory and could be provided on request.</i>
2	Wie vertraglich vereinbart, wurde dieses Dokument nur digital unterzeichnet. Der TÜV Rheinland hat nicht überprüft, welche rechtlichen oder sonstigen diesbezüglichen Anforderungen für dieses Dokument gelten. Diese Überprüfung liegt in der Verantwortung des Benutzers dieses Dokuments. Auf Verlangen des Kunden kann der TÜV Rheinland die Gültigkeit der digitalen Signatur durch ein gesondertes Dokument bestätigen. Diese Anfrage ist an unseren Vertrieb zu richten. Eine Umweltgebühr für einen solchen zusätzlichen Service wird erhoben. Informationen zur Verifizierung der Authentizität unserer Dokumente erhalten Sie auf folgender Webseite: go.tuv.com/digital-signature <i>As contractually agreed, this document has been signed digitally only. TUV Rheinland has not verified and unable to verify which legal or other pertaining requirements are applicable for this document. Such verification is within the responsibility of the user of this document. Upon request by its client, TUV Rheinland can confirm the validity of the digital signature by a separate document. Such request shall be addressed to our Sales department. An environmental fee for such additional service will be charged. For information on verifying the authenticity of our documents, please visit the following website: go.tuv.com/digital-signature</i>
3	Prüfklausel mit der Note * wurden an qualifizierte Unterauftragnehmer vergeben und sind unter der jeweiligen Prüfklausel des Berichts beschrieben. Abweichungen von Prüfspezifikation(en) oder Kundenanforderungen sind in der jeweiligen Prüfklausel im Bericht aufgeführt. <i>Test clauses with remark of * are subcontracted to qualified subcontractors and described under the respective test clause in the report.</i> <i>Deviations of testing specification(s) or customer requirements are listed in specific test clause in the report.</i>
4	Die Entscheidungsregel für Konformitätserklärungen basierend auf numerischen Messergebnissen in diesem Prüfbericht basiert auf der "Null-Grenzwert-Regel" und der "Einfachen Akzeptanz" gemäß ILAC G8:2019 und IEC Guide 115:2021, es sei denn, in der auf Seite 1 dieses Berichts genannten angewandten Norm ist etwas anderes festgelegt oder vom Kunden gewünscht. Dies bedeutet, dass die Messunsicherheit nicht berücksichtigt wird und daher auch nicht im Prüfbericht angegeben wird. Zu weiteren Informationen bezüglich des Risikos durch diese Entscheidungsregel siehe ILAC G8:2019. <i>The decision rule for statements of conformity, based on numerical measurement results, in this test report is based on the "Zero Guard Band Rule" and "Simple Acceptance" in accordance with ILAC G8:2019 and IEC Guide 115:2021, unless otherwise specified in the applied standard mentioned on Page 1 of this report or requested by the customer. This means that measurement uncertainty is not taken in account and hence also not declared in the test report. For additional information to the resulting risk based of this decision rule please refer to ILAC G8:2019.</i>

Prüfbericht-Nr.: IN26ZT5M 001		Seite 3 von 14	
Test report no.: ULR-TC611626100000079F		Page 3 of 14	
Absatz Clause	Anforderungen - Prüfungen / Requirements - Tests	Messergebnisse – Bemerkungen/ Measuring results - Remarks	Ergebnis Result

1	Produktdetails <i>Product details</i>	WORK CHAIRS; LEAD MODEL: ASTRIDE OCTAVE HB OFFICE CHAIR; CONSTRUCTION OF CHAIR: WITH RECLINING PROVISIONS, WITH CASTORS, WITHOUTFOOTREST; MAXIMUM USER MASS AND USAGE HOUR PER WEEK: 110 KG AND USED FOR 40 HOUR PER WEEK	
2	Maße / Gewicht <i>Dimensions / Weight</i>	Refer page Number-06 Weight: 12.650 kg	
3	Bedienelemente <i>Operating elements</i>	-	
4	Ausstattung / Zubehör <i>Equipment / Accessories</i>	-	
5	Verwendete Materialien <i>Used materials</i>	-	
6	Sonstiges <i>Other</i>	Test sample(s), as well sample information, description, product details and intended usage was provided by customer. The laboratory is not be responsible for the information/data provided by the customer which can affect the validity of results.	
7	Prüfmusterbereitstellung: <i>Test sample obtaining</i>	☒ Sending by customer ☐ Sampling by TÜV Rheinland Group ☐ others:	

Pic:01 Front View	Pic:02 Rear View
	

Prüfbericht-Nr.: IN26ZT5M 001			
Test report no.: ULR-TC611626100000079F			
Absatz Clause	Anforderungen - Prüfungen / Requirements - Tests	Messergebnisse – Bemerkungen/ Measuring results - Remarks	Ergebnis Result

Pic:03 Side View	Pic:03 Bottom View
	

S.No	Test parameter	Clause	Page No.
Part A- Tests covered under NABL accreditation			
1	Design Workmanship	Clause 4 :IS 17631: 2022	5
2	Dimensions	Clause 5:IS 17631: 2022	6
3	Colour fastness to light	Clause 6.2 a) 4 : IS 17631: 2022	7
4	Colour fastness to rubbing	Clause 6.2 a) 5 : IS 17631: 2022	7
5	Colour fastness to perspiration	Clause 6.2 a) 6 : IS 17631: 2022	8
6	Colour fastness to water	Clause 6.2 a) 7 : IS 17631: 2022	8
7	Pilling resistance	Clause 6.2 a) 8 : IS 17631: 2022	9
8	Abrasion resistance	Clause 6.2 a)12: IS 17631: 2022	9
9	Front Edge Overturning	Clause 7.3.1:IS 17631: 2022	10
10	Forwards Overturning	Clause 7.3.2:IS 17631: 2022	10
11	Sideways Overturning for Chairs with Arm Rests	Clause 7.3.5:IS 17631: 2022	10
12	Rearwards Overturning for Chairs Without Back Rest Inclination	Clause 7.3.6:IS 17631: 2022	10
13	Rearwards Overturning for Chairs with Backrest Inclination	Clause 7.3.7:IS 17631: 2022	10
14	Seat Front Edge Static Load Test	Clause 7.4.1:IS 17631: 2022	10
15	Combined Seat and Back Static Load Test	Clause 7.4.2:IS 17631: 2022	11
16	Arm Rest Downward Static Load Test — Central	Clause 7.4.3:IS 17631: 2022	11
17	Arm Rest Downward Static Load Test — Front	Clause 7.4.4:IS 17631: 2022	11
18	Arm Rest Sideways Static Load Test	Clause 7.4.5:IS 17631: 2022	11
19	Seat and Back Durability	Clause 7.5.1:IS 17631: 2022	12
20	Arm Rest Durability	Clause 7.5.2:IS 17631: 2022	12
21	Swivel Test	Clause 7.5.3:IS 17631: 2022	12
22	Castor and Chair-Base Durability	Clause 7.5.5:IS 17631: 2022	13
23	MARKING - Verification	Clause 9:IS 17631: 2022	13
Part B - Tests not covered under NABL accreditation			
24	Bursting strength	Clause 6.2(a) 13: IS 17631:2022	14

Prüfbericht-Nr.: IN26ZT5M 001		Seite 5 von 14	
Test report no.: ULR-TC611626100000079F		Page 5 of 14	
Absatz <i>Clause</i>	Anforderungen - Prüfungen / <i>Requirements - Tests</i>	Messergebnisse – Bemerkungen/ <i>Measuring results - Remarks</i>	Ergebnis <i>Result</i>

Clause	Test Item	Parameter / Observation	Result	Conclusion
4.1	Design/Model	Shall be as declared by the manufacturer.	Model: ASTRIDE OCTAVE HB OFFICE CHAIR	Data
4.2	Workmanship	The exposed/accessible edges and protruding parts shall be free from burrs, sharp edges and shall be rounded or chamfered. The ends of accessible hollow components shall be closed or capped. Movable and adjustable parts shall be designed so that injuries and inadvertent operation are avoided. In case wooden components, the same shall be free from any stain, unless it is intended as part of design feature.	Workmanship is good	P

Prüfbericht-Nr.: IN26ZT5M 001 Test report no.: ULR-TC611626100000079F			
Absatz Clause	Anforderungen - Prüfungen / Requirements - Tests	Messergebnisse – Bemerkungen/ Measuring results - Remarks	Ergebnis Result

5	Dimensions  Technical parameter 1. With armrests 2. With locking device 3. With reclining 4. Without footrest 5. With castors 6. Load bearing material Material – Plastic, Fabric, Wooden, MS/CRCA Dimensions:- A) Seat - A - Chair with Adjustable Height Seat - Min-460 to Max-550 +/- 20MM B - Effective Seat Depth - 440mm +/- 20MM C - Seat Width - 490mm +/- 20MM B) Armrests - G - Height of Armrests Above Point Z of the Seat - Min-220 to Max-280 +/- 20MM G1 - Inside Distance Between Armrests - 460MM +/- 20MM G2 - Set Back of Armrests in Relation to the Front of the Seat- 100MM +/- 20MM G3 - Length of the Armrests- 240mm +/- 20mm G4 - Width of the Armrests - 90mm +/- 20mm C) Backrest - W - Chair with Adjustable Height Lumbar Support - Min-170 to Max-260 +/- 20MM V - Vertical height of area of essential lumbar support (having X at its center) - 130MM +/- 20MM U - Width of area of essential lumbar support - 270MM +/- 20MM Tilting: 90° to 135° ASTRIDE®	The dimensions are verified against the customer declared specifications. (Tolerance ± 20mm) i) Seat A Seat height: 1) Chair with fixed height seat: NA 2) Chair with adjustable height seat: 461mm to 565 mm B Effective seat depth: 1) 17 Chair with fixed back: 455 mm 2) 21 Chair with adjustable back: NA C Seat Width: 508 mm Slope of the seat in relation of horizontal from front to back: NA ii) Armrests (if provided) G Height of armrests above point Z of the seat: 215 mm to 284 mm G1 Inside distance between armrests: 466 mm G2 Set back of armrests in relation to the front of the seat: 90 mm G3 Length of the armrests: 245 mm G4 Width of the armrests: 92 mm iii) Backrest W Centre of the backrest above the Z: 1) Chair with fixed backrest: NA 2) Chair with adjustable backrest or adjustable lumbar support pad: 170 mm to 250 mm 3) Chair with pivoted backrest: NA V Vertical height of area of essential lumbar support (having X at its center): 130 mm Width of area of essential lumbar support: 270 mm U Horizontal curvature of lumbar support, radius: NA iv) Tilting: 90° - 135°	P
---	---	--	---

Prüfbericht-Nr.: IN26ZT5M 001			
Test report no.: ULR-TC611626100000079F			
Absatz Clause	Anforderungen - Prüfungen / Requirements - Tests	Messergebnisse – Bemerkungen/ Measuring results - Remarks	Ergebnis Result

6.1	RAW MATERIALS REQUIREMENTS	The test sample rigid surfaces shall be tested for the following tests and shall qualify the minimum performance ratings specified in IS 17637.	Not applicable for work chairs	NA
-----	-------------------------------	---	--------------------------------	----

6.2 (a)	For Fabric and Synthetic Leather			
6.2(a)(1)	Breaking load	Test Method: IS 1969 (Part 1) Performance Requirement: 350 N (Both Direction)	NA Remark: test is Not Applicable since submitted sample is Knitted.	NA
6.2(a)(2)	Elongation at break	Test Method: IS 1969 (Part 1) Performance Requirement: Knitted Length: 35% Width: 40% Test Method: IS 1969 (Part 1) Performance Requirement: Mesh Length: 50% Width: 50%	NA Remark: test is Not Applicable since submitted sample is Knitted.	NA
6.2(a)(3)	Tear strength	Test Method: IS 6489 (Part 1) -	NA Remark: test is Not Applicable since submitted sample is Knitted.	NA
6.2(a)(4)	Colour fastness to light	Test Method: IS/ISO 105-B02 Performance Requirement: 4	Seat Knit Fabric: 4 Back Mesh fabric: 4	P
6.2(a)(5)	Colour fastness to rubbing	Test Method: IS/ISO 105-X12 Performance Requirement: Dry 4, Wet 3	Seat Knit Fabric: Dry 4-5, Wet 4-5 Back Mesh Fabric: Dry 4-5, Wet 4-5	P

Prüfbericht-Nr.: IN26ZT5M 001			
Test report no.: ULR-TC611626100000079F			
Absatz Clause	Anforderungen - Prüfungen / Requirements - Tests	Messergebnisse – Bemerkungen/ Measuring results - Remarks	Ergebnis Result

6.2(a)(6)	Colour fastness to perspiration	Test Method: IS/ISO 105-E04 Performance Requirement: 3	Seat Knit Fabric			P
				ACIDIC	ALKALINE	
			Colour change	4-5	4-5	
			-Staining on Acetate	4-5	4-5	
			-Staining on Cotton	4-5	4-5	
			-Staining on Nylon	4-5	4-5	
			-Staining on Polyester	4-5	4-5	
			-Staining on Acrylic	4-5	4-5	
			-Staining on Wool	4-5	4-5	
			Back Mesh fabric			P
				ACIDIC	ALKALINE	
			Colour change	4-5	4-5	
			-Staining on Acetate	4-5	4-5	
			-Staining on Cotton	4-5	4-5	
			-Staining on Nylon	4-5	4-5	
			-Staining on Polyester	4-5	4-5	
			-Staining on Acrylic	4-5	4-5	
			-Staining on Wool	4-5	4-5	
6.2(a)(7)	Colour fastness to water	Test Method: IS/ISO 105- E01 Performance Requirement: 3	Seat Knit Fabric			P
			Colour change		4-5	
			-Staining on Acetate		4-5	
			-Staining on Cotton		4-5	
			-Staining on Nylon		4-5	
			-Staining on Polyester		4-5	
			-Staining on Acrylic		4-5	
			-Staining on Wool		4-5	
			Back Mesh fabric			
			Colour change		4-5	
			-Staining on Acetate		4-5	
			-Staining on Cotton		4-5	
			-Staining on Nylon		4-5	
			-Staining on Polyester		4-5	
			-Staining on Acrylic		4-5	
			-Staining on Wool		4-5	

Prüfbericht-Nr.: IN26ZT5M 001			
Test report no.: ULR-TC611626100000079F			
Absatz Clause	Anforderungen - Prüfungen / Requirements - Tests	Messergebnisse – Bemerkungen/ Measuring results - Remarks	Ergebnis Result

6.2(a)(8)	Pilling resistance	Test Method: IS 10971 (Part 2) Performance Requirement: 3 (for 5 000 cycle)	Seat Knit fabric & Back Mesh fabric			P
			No of Rubs	Pilling	Fuzzing	
			After 125 Rubs	4-5	4-5	
			After 500 Rubs	4-5	4-5	
			After 1000 Rubs	4-5	4-5	
			After 2000 Rubs	4-5	4-5	
			After 5000 Rubs	4-5	4-5	
6.2(a)(9)	Coating adhesion strength	Test Method: IS 7016 (Part 5) Performance Requirement:	NA Remark: test is Not Applicable since submitted sample does not have coating.			NA
6.2(a)(10)	Seam slippage	Test Method: IS/ISO 13936-2 Performance Requirement:	NA Remark: test is Not Applicable since submitted sample is Knitted.			NA
6.2(a)(11)	Resistance to damage by flexing	Test Method: IS 7016 (Part 4) Performance Requirement:	NA Remark: test is Not Applicable since submitted sample does not have coating.			NA
6.2(a)(12)	Abrasion resistance	Test Method: IS 12673 (Part 2) Performance Requirement: 35000 (Office) at 12 kPa load	Seat Knit fabric & back Mesh fabric: No thread Breakdown occurred up to at 35000 rubs			P
6.2(a)(14)	Resistance to cold.	Test Method: IS 1259 -	NA Remark: test is Not Applicable since submitted sample does not have coating.			NA
6.2(b)	For Natural Leather		Not applicable (Product does not have natural leather)			NA

Prüfbericht-Nr.: IN26ZT5M 001			
Test report no.: ULR-TC611626100000079F			
Absatz Clause	Anforderungen - Prüfungen / Requirements - Tests	Messergebnisse – Bemerkungen/ Measuring results - Remarks	Ergebnis Result

7	Safety requirements			
7.3	Stability test			
7.3.1	Front Edge Overturning	Allow the mass (M=27kg) to hang freely	No damage or deformation Observed No overturning of chair Observed No fractures or breakage observed No loosening of joints observed	P
7.3.2	Forwards Overturning	Downwards force F1= 600N Horizontal force F2= 20N	No damage or deformation Observed No overturning of chair Observed No fractures or breakage observed No loosening of joints observed	P
7.3.3	Forwards Overturning for Chairs with Footrest	Downwards force F1= 1100N Horizontal force F2= 20N	Not Applicable (Product does not have footrest)	NA
7.3.4	Sideways Overturning for Chairs Without Arm Rests	Downwards force F1= 600N Horizontal force F2= 20N	Not Applicable (Product is with Arms)	NA
7.3.5	Sideways Overturning for Chairs with Arm Rests	Downwards force F1= 250N Downwards force F2= 350N Horizontal force F3= 20N	No damage or deformation Observed No overturning of chair Observed No fractures or breakage observed No loosening of joints observed	P
7.3.6	Rearwards Overturning for Chairs Without Back Rest Inclination	Downwards force F1= 600N Horizontal force F2= 192N	No damage or deformation Observed No overturning of chair Observed No fractures or breakage observed No loosening of joints observed	P
7.3.7	Rearwards Overturning for Chairs with Backrest Inclination	Load:130kg	No damage or deformation Observed No overturning of chair Observed No fractures or breakage observed No loosening of joints observed	P
7.4	Static-load Tests			
7.4.1	Seat Front Edge Static Load Test	Seat Force= 1600N Cycle=10 Time: 10+2 sec.	No damage or deformation Observed No fractures or breakage observed No loosening of joints observed	P

Prüfbericht-Nr.: IN26ZT5M 001			
Test report no.: ULR-TC611626100000079F			
Absatz Clause	Anforderungen - Prüfungen / Requirements - Tests	Messergebnisse – Bemerkungen/ Measuring results - Remarks	Ergebnis Result

7.4.2	Combined Seat and Back Static Load Test	Seat Force=1600N Back Force=560N Cycle =10 Time: 10+2 sec.	No damage or deformation Observed No fractures or breakage observed No loosening of joints observed	P
7.4.3	Arm Rest Downward Static Load Test — Central	Force =750N on each Arms Cycle =5 Time: 10+2 sec	No damage or deformation Observed No fractures or breakage observed No loosening of joints observed	P
7.4.4	Arm Rest Downward Static Load Test — Front	Force =375N on each Arms Cycle =5 Time: 10+2 sec	No damage or deformation Observed No fractures or breakage observed No loosening of joints observed	P
7.4.5	Arm Rest Sideways Static Load Test	Force =400N Cycle =10 Time: 10+2 sec	No damage or deformation Observed No fractures or breakage observed No loosening of joints observed	P
7.4.6	Footrest Static Load Test	Force =1300N Cycle =10 Time: 10+2 sec	Not Applicable (Product does not have footrest)	NA

Prüfbericht-Nr.: IN26ZT5M 001			
Test report no.: ULR-TC611626100000079F			
Absatz Clause	Anforderungen - Prüfungen / Requirements - Tests	Messergebnisse – Bemerkungen/ Measuring results - Remarks	Ergebnis Result


7.5	Durability Tests			
7.5.1	Seat and Back Durability	Step 1: Seat Force(A): 1100N and 120,000cycle Step 2: Seat force(C): 1100N Back force(B):320N Cycle:80,000 Step 3: Seat force(J): 1100N Back force(E):320N Cycle:20,000 Step 4: Seat force(F): 1100N Back force(H):320N Cycle:20,000 Step 5: (alternating) Seat force(D): 1100N Seat force(G):1100N Cycle:20,000	No damage or deformation Observed No overturning of chair Observed No fractures or breakage observed No loosening of joints observed	P
7.5.2	Arm Rest Durability	400N on Each Arms Cycle 60,000	No damage or deformation Observed No overturning of chair Observed No fractures or breakage observed No loosening of joints observed	P
7.5.3	Swivel Test	M1= 60kg M2=35kg Cycle= 120,000	No damage or deformation Observed No overturning of chair Observed No fractures or breakage observed No loosening of joints observed	P
7.5.4	Foot-rest Durability	Force= 900N Cycle= 50,000	Not Applicable (Product does not have footrest)	NA

Prüfbericht-Nr.: IN26ZT5M 001			
Test report no.: ULR-TC611626100000079F			
Absatz Clause	Anforderungen - Prüfungen / Requirements - Tests	Messergebnisse – Bemerkungen/ Measuring results - Remarks	Ergebnis Result

7.5.5	Castor and Chair-Base Durability	Mass= 110kg Cycle= 1,00000 Stroke distance (760 ± 10) mm on smooth surface	No damage or deformation Observed No overturning of chair Observed No fractures or breakage observed No loosening of joints observed	P
9	Marking			
9.1	-	Each chair shall be indelibly and legibly marked with the following particulars: a) Manufacturer's name, brand name or his recognized trademark, if any: b) Date of manufacture. c) Design/Model Number (as declared by the manufacturer); and d) Batch/lot number.	a) Manufacturer's name: MBTC Intrafurnish Private Limited Brand Name: ASTRIDE b) Date of manufacture: 21 January 2026 c) Design/Model Number: ASTRIDE Octave HB office chair d) Batch/Lot number: NOT AVAILABLE Refer pic:05	P
9.2	-	Each work chair meant to be assembled by the customer shall have the instruction for assembly provided as a leaflet and/or available in digital document file.	Not Applicable (Assembly service will be carried out by the MBTC team)	NA
9.3	BIS Certification Marking	The product(s) conforming to the requirements of this standard may be certified as per the conformity assessment schemes under the provisions of <i>Bureau of Indian Standards Act, 2016</i> and the Rules and Regulations framed thereunder, and the product(s) may be marked with the Standard Mark.	Not Applicable (BIS certification to be obtained separately after testing)	NA

Prüfbericht-Nr.: IN26ZT5M 001 Test report no.:		Seite 14 von 14 Page 14 of 14	
Absatz Clause	Anforderungen - Prüfungen / Requirements - Tests	Messergebnisse – Bemerkungen/ Measuring results - Remarks	Ergebnis Result

6.2(a)(13)	Bursting Strength	Test Method: IS 1966 (Part 1) Performance requirement: 12 (for knitted fabric) kg/cm² 18 (for net and mesh) kg/cm²	Seat Knit fabric: 14.1 kg/cm² Back Mesh fabric: 19.9 kg/cm²	P
------------	-------------------	---	--	---



*** Key:** P = Pass F =Fail NA =Not Applicable
 NC =Not Conducted as per client request NT =Not Tested DATA =Record data only

.END OF TEST REPORT..