


Client Description:

Client: ABC
Pipeline Name: XYZ
Pipeline Section: AN9



Feature Location on Pipe:



Pipe Description:

Pipe Number: 35
Pipe Length (m): 12.51
WT (mm): 12.7
Latitude: 16.46085615
Longitude: 82.18708905

Comment:

Feature Description:

Feature:	Corrosion	Absolute Distance (m):	622.123
Feature type:	Metal Loss	Length (mm):	49
Anomaly dimension class:	AXIAL GROOVING	Width (mm):	22
Surface Location:	Internal	Max. Depth(%):	19
Remaining wall thickness (mm):	10.3	Orientation(hr:min):	09:14
ERF:	0.308	Latitude:	16.46085615
Safe pressure (kg/cm ²):	405.88	Longitude:	82.18708905

Pipe Location:

Upstream Weld
619.93(m)

	Flange	Magnet		Magnet	Magnet
Abs. Dist.:	20.54(m)	3.85(m)		11369.44(m)	11369.44(m)
Latitude:	16.46285068	16.46284066		16.48405575	16.48405288
Longitude:	82.18914831	82.18912956		82.09214678	82.09211947

U/S	↑ 599.39(m)	↑ 616.08(m)	10749.51(m) ↑	10749.51(m) ↑	D/S
-----	-------------	-------------	---------------	---------------	-----

	Bend	Bend	Bend		Bend	Bend	Bend
Abs. Dist.:	41.04(m)	15.95(m)	8.19(m)		10528.06(m)	11207.46(m)	11325.38(m)
Latitude:	16.46283531	16.46284351	16.46280669		16.4805281	16.48390449	16.48387759
Longitude:	82.18912979	82.18914302	82.18910768		82.09878414	82.09346831	82.09236139

L	↑ 578.89(m)	↑ 603.98(m)	↑ 611.74(m)	9908.13(m)	↑ 10587.53(m)	↑ 10705.45(m)	R
---	-------------	-------------	-------------	------------	---------------	---------------	---

Pipe No:	32	33	34	35	36	37
Pipe Length(m):	12.34	11.66	12.96	12.51	12.46	12.57
WT(mm):	12.7	12.7	12.7	12.7	12.7	12.7

FLOW

