

Repair evidence and remaining failures | no-delay Gazebo
Solid/dashed: repetitions; green shading: Position; not real-flight validation
A Loaded DRCDA, before mode changes
SO(3) error [deg]
Time since first Offboard entry [s]
Reference repair only
C2 integral candidate
B Loaded DRCDA, before mode changes
Position error norm [m]
Time since first Offboard entry [s]
C Mode returns: unresolved instability
SO(3) error [deg]
Time since first Offboard entry [s]
D Separate lateral-stress test
Reference speed [m/s; symlog]
Time since first Offboard entry [s]
Original projection
Continuous reference