

HVAC & MEP INSPECTION REPORT

Site: GM Workflow Test Tower

Site Information


Site Name:	GM Workflow Test Tower
Visit Date:	2026-07-19
Report Generated:	2026-07-19 16:12:59 (GST)
Total Items Inspected:	2

Inspection Items

Item 1: Chiller Unit 2

Asset Name:	Chiller Unit 2
System Type:	HVAC
Description:	Chiller with partial load test
Quantity:	1
Brand:	Carrier
Specification:	Model 30XA-400
Comments:	Minor vibration observed, recommended monitoring.
Photos Attached:	1

Attached Photos (1 total):

		
---	--	--


Item 2: AHU-05

Asset Name:	AHU-05
System Type:	HVAC
Description:	Air Handling Unit - Level 5
Quantity:	1
Brand:	Trane
Specification:	12,000 CFM



Comments:	Filters replaced, differential pressure within limits.
Photos Attached:	1

Attached Photos (1 total):



Supervisor Review

Inspection completed. Minor issues noted, safe to operate.

Supervisor Signature:	
-----------------------	--

Operations Manager Comments

Agree with supervisor assessment. Schedule follow-up in 30 days.

Operations Manager Signature:	
-------------------------------	--


Business Development Comments

No commercial impact foreseen at this stage.

Business Development Signature:	
---------------------------------	--


Procurement Comments

Spare parts quotation to be requested only if vibration worsens.

Procurement Signature:	
-------------------------------	--

General Manager Comments

Approved. Proceed as per Operations Manager plan.

General Manager Signature:	
-----------------------------------	--

Document signed on: July 19, 2026 at 16:12 (GST)