


Mining Compliance Report: Odisha_0

Site: odisha_0 | Generated: 2025-10-15 23:07

Satellite Imagery




Detected Mining Areas



Legal vs Illegal Mining

odisha_0: Compliance Check



Mining Analytics

Block	Area_m2	MeanDepth_m	Volume_m3	OutsideLease
Block-1	117400.0	4.18	314327.3	No
Block-2	214400.0	5.51	739868.8	Yes
TOTAL	331800.0	-	1054196.1	214400.0 m ² VIOLATION

3D Terrain Visualization

odisha_0: 3D Mining Terrain Visualization

