



Damage Assessment Report

2 damages assessed


VEHICLE**MAKE****Suzuki****MODEL****Alto****YEAR****2025****BODY TYPE****hatchback****TOTAL ESTIMATE****24,276** PKR

Range 14,130 – 34,422 PKR

2 estimated

DAMAGE SUMMARY

#	DAMAGE	PANEL	SEVERITY	DECISION	METHOD	COST
1	Scratch	Rear Left Door	Minor	Repair	Spot Paint	12,142 PKR
2	Scratch	Rear Left Door	Minor	Repair	Spot Paint	12,134 PKR

DAMAGE PHOTOS**Scratch**

Rear Left Door


12,142 PKR

Minor

Repair

Spot Paint

Range 7,069 – 17,215 PKR

**Scratch**

Rear Left Door

12,134 PKR

Minor

Repair

Spot Paint

Range 7,061 – 17,207 PKR