



# Structural Repair Quality Analysis Report


Natural Frequencies Comparison




Frequency Response Spectrum




Mode Shape Comparison (First 3 Modes)



Damping Ratios Comparison



Quality Score Breakdown



**0.499**

Repair Quality Score

Poor - Minimal Improvement

2026-01-13 15:34:31