

**Test Report** No.: GZHL2304009470SD Date: Apr 17, 2023 Page 1 of 10

MINISO (GUANGZHOU) CO., LTD

Sample Receiving Date

ROOM 2501, NO. 486 HEYE SQUARE, KANGWANG MIDDLE ROAD, LIWAN DISTRICT, GUANGZHOU, CHINA

: LARGE SHOPPING BAG Sample Description

Manufacturer : GUANGZHOU BAIYUN HUALI PLASTIC FACTORY

Country of Origin : CHINA

As above test item and its relevant information regarding to the submission are provided and confirmed by the applicant. SGS is not liable to either the test item or its relevant information, in terms of the accuracy, suitability, reliability or/and integrity accordingly.

\*\*\*\*\*

**Test Performing Date** : Apr 03, 2023 to Apr 17, 2023

**Test Performed** : Selected test(s) as requested by applicant

Test Result(s) : For further details, please refer to the following page(s)

: Apr 03, 2023

Signed for and on behalf of SGS-CSTC Standards Technical Services Co., Ltd. Guangzhou Branch

Arthur Mak

Authorized Signatory





Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <a href="https://www.sgs.com/en/Terms-and-Conditions">https://www.sgs.com/en/Terms-and-Conditions</a>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Cilent's instructions, if any. The Company's sole responsibility is to its Cilent and this document does not exonerate parties to a transaction form exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approved of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN\_Doccheck@gs.com

No.198, Kezhu Road, Science City, Economic & Technological Development Area, Guangzhou, Guangdong, China 510663 中国・广东・广州高新技术产业开发区科学城科珠路198号 邮编: 510663



**Test Report** No.: GZHL2304009470SD Date: Apr 17, 2023 Page 2 of 10

Test Conducted: Based on QB/T 2461-1999 Clause 5.1~5.3

Test Results: Details shown as following table

Test Item	Test Requirement / Test Method	Test Result
<b>5.1</b> Appearance	No holes or defects that affect use.	PASS
5.2 Specifications	The width and deviation, as well as the thickness and deviation, should comply with the requirements of Table 1 and Table 2.	PASS (See annex 1)
5.3 Physical and mechanical properties	It should comply with the provisions of Clause 4.3 in GB/T 4456	PASS (See annex 1)

Annex 1

SGS Ref No.: GZMR230400876501

# Summary of Results:

No.	Test Item	Test Method	Result	Conclusion
1	Width QB/T 2461-1999 Section 6.2.1 & GB/T 6673-2001		See result	Pass
2	Dart Impact	QB/T 2461-1999 Section 6.3.2 & GB/T 9639.1- 2008 Method A	Number of non ruptures: 10	Pass
3	Tensile Strength and Elongation at Break	QB/T 2461-1999 Section 6.3.1 & GB/T 13022-1991	See result	Pass
4	Thickness	QB/T 2461-1999 Section 6.2.2 & GB/T 6672-2001	See result	Pass

Note: Pass: Meet the requirements;

Fail: Does not meet the requirements;

/ : Not Apply to the judgment.



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <a href="https://www.sgs.com/en/Terms-and-Conditions">https://www.sgs.com/en/Terms-and-Conditions</a>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction form exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.


Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sqs.com"

No.198, Kezhu Road, Science City, Economic & Technological Development Area, Guangzhou, Guangdong, China 510663 中国・广东・广州高新技术产业开发区科学城科珠路198号 邮编: 510663



**Test Report** No.: GZHL2304009470SD Date: Apr 17, 2023 Page 3 of 10

# Original Sample Photo:



1.Test Item: Width

Sample Description: Plastic bag

Test Method: QB/T 2461-1999 Section 6.2.1 & GB/T 6673-2001

**Test Condition:** 

Nominal width:490mm(Provided by client)

Measured by straight steel ruler

Lab Environment Condition:  $(23\pm2)^{\circ}$ °,  $(50\pm5)^{\circ}$ RH

### Test Result:

Test Item	Test Result	Requirement in QB/T 2461- 1999 Table 1(401~500mm)	Conclusion
Width	486mm	1	1
Width Limit Deviation	-3mm -4mm	±12mm	Pass

### Note:

- 1. Since the nominal width is provided by the client, the relevant results and conclusion of this report are only made for these data, SGS is not responsible for the authenticity, integrity of these data and the validity of results and conclusion.
- 2.Limit Deviation, mm= Maximum value (minimum value) nominal value



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <a href="https://www.sgs.com/en/Terms-and-Conditions">https://www.sgs.com/en/Terms-and-Conditions</a>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Cilent's instructions, if any. The Company's sole responsibility is to its Cilent and this document does not exonerate parties to a transaction form exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approved of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN\_Doccheck@gs.com

No.198, Kezhu Road, Science City, Economic & Technological Development Area, Guangzhou, Guangdong, China 510663 中国・广东・广州高新技术产业开发区科学城科珠路198号 邮编: 510663



**Test Report** No.: GZHL2304009470SD Date: Apr 17, 2023 Page 4 of 10

# **Equipment Information:**

Equipment	Model	Equipment No.	Calibration date	Next Calibration date
Straight Steel Ruler	600mm	GZMR-PL-E017- 10	2023-01-17	2024-01-16

2.Test Item: Dart Impact

Sample Description: Plastic bag

Test Method: QB/T 2461-1999 Section 6.3.2 & GB/T 9639.1-2008 Method A

**Test Condition:** 

Nominal Thickness: 0.06mm(Provided by client)

Dart weight: 80g

Number of Specimens tested:10

Lab Environmental Condition: (23±2)℃, (50±5)%RH

## Test Result:

Test Item	Test Result	Requirement in QB/T 2461-1999 Section 5.3 & GB/T 4456-2008 Table 3 (PE-HD Film)	Conclusion
Dart Impact	Number of non ruptures: 10	Number of non ruptures ≥8	Pass

### Note:

Test specimens were cut from the sample.

The inside surface was faced to the falling dart.



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <a href="https://www.sgs.com/en/Terms-and-Conditions">https://www.sgs.com/en/Terms-and-Conditions</a>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Cilent's instructions, if any. The Company's sole responsibility is to its Cilent and this document does not exonerate parties to a transaction form exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approved of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.


Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN\_Doccheck@gs.com

No.198, Kezhu Road, Science City, Economic & Technological Development Area, Guangzhou, Guangdong, China 510663 中国・广东・广州高新技术产业开发区科学城科珠路198号 邮编: 510663



**Test Report** Date: Apr 17, 2023 Page 5 of 10 No.: GZHL2304009470SD

Test Photo:



# **Equipment Information:**

Equipment	Model	Equipment No.	Calibration date	Next Calibration date
Falling Dart Impact Tester	FDI-01	GZMR-PL-E181	2023-02-20	2024-02-19



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <a href="https://www.sgs.com/en/Terms-and-Conditions">https://www.sgs.com/en/Terms-and-Conditions</a>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction fore exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755)83071443, or email: CN.Doccheck@sgs.com")

t (86-20) 82155555

No.198, Kezhu Road, Science City, Economic & Technological Development Area, Guangzhou, Guangdong, China 510663 中国・广东・广州高新技术产业开发区科学城科珠路198号 邮编: 510663

t (86-20) 82155555 sgs.china@sgs.com



**Test Report** No.: GZHL2304009470SD Date: Apr 17, 2023 Page 6 of 10

3.Test Item: Tensile Strength and Elongation at Break

Sample Description: Plastic bag

Test Method: QB/T 2461-1999 Section 6.3.1 & GB/T 13022-1991

Test Condition:

Specimen: Type I

Specimen thickness: 0.061mm Testing speed: 500mm/min

Gauge length: 40mm

Test Result:

	Test Result		Requirement in QB/T	
 			2461-1999 Section 5.3	Conclusion
Test Item			& GB/T 4456-2008	Conclusion
			Table 3 (PE-HD Film)	
	Transverse	33.0MPa		Pass
Tensile Strength	Longthways	44.1MPa	≥25MPa	Pass
	Lengthways	(See table 1)		rass
Elongation at Break	Transverse	640%	≥230%	Pass
Liongation at break	Lengthways	730%	25070	Pass

### Table 1:

Specimen	#1	#2	#3	#4	#5	#6	#7	#8	#9	#10
Tensile Strength, MPa	30.96	32.01	23.04	56.32	35.65	66.79	53.24	56.21	45.10	41.44

Note: Test specimens were cut from the sample.



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <a href="https://www.sgs.com/en/Terms-and-Conditions">https://www.sgs.com/en/Terms-and-Conditions</a>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Cilent's instructions, if any. The Company's sole responsibility is to its Cilent and this document does not exonerate parties to a transaction form exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approved of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.


Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN\_Doccheck@gs.com

No.198, Kezhu Road, Science City, Economic & Technological Development Area, Guangzhou, Guangdong, China 510663 中国・广东・广州高新技术产业开发区科学城科珠路198号 邮编: 510663





**Test Report** Page 7 of 10 No.: GZHL2304009470SD Date: Apr 17, 2023

Test Photo:




**During Test** 





Before Test - Transverse







Before Test - Lengthways

After Test - Lengthways



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <a href="https://www.sgs.com/en/Terms-and-Conditions">https://www.sgs.com/en/Terms-and-Conditions</a>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction fore excressing all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, who they prove that approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755)8307 1443, or email: CN\_Doccheck@sgs.com").

No.198, Kezhu Road, Science City, Economic & Technological Development Area, Guangzhou, Guangdong, China 510663 中国・广东・广州高新技术产业开发区科学城科珠路198号 邮编: 510663

t (86-20) 82155555 www.sgsgroup.com.cn

t (86-20) 82155555 sgs.china@sgs.com



**Test Report** No.: GZHL2304009470SD Date: Apr 17, 2023 Page 8 of 10

## **Equipment Information:**

Equipment	Model	Equipment No.	Calibration date	Next Calibration date
Universal Testing  Machine	CMT6103	GZMR-PL-E022	2022-06-22	2023-06-21

4.Test Item: Thickness

Sample Description: Plastic bag

Test Method: QB/T 2461-1999 Section 6.2.2 & GB/T 6672-2001

Test Condition:

Nominal Thickness: 0.060mm(Provided by client)

Load: 0.8N

Lab Environment Condition:  $(23\pm2)^{\circ}$ C,  $(50\pm5)$ %RH

Test Result:

Test Item	Test Result	Requirement in QB/T 2461- 1999 Table 1(0.060mm)	Conclusion
Thickness	0.061mm	1	1
Mean Deviation	1.7%	±12%	Pass
Limit Deviation	+0.007mm -0.001mm	±0.018mm	Pass

#### Note:

- 1. Since the nominal thickness is provided by the client, the relevant results and conclusion of this report are only made for these data, SGS is not responsible for the authenticity, integrity of these data and the validity of results and conclusion.
- 2.Limit Deviation, mm= Maximum value (minimum value) nominal value
- 3.Mean Deviation, %= (Average value -nominal value)/nominal value ×100
- 4. Test specimens were cut from the sample.



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <a href="https://www.sgs.com/en/Terms-and-Conditions">https://www.sgs.com/en/Terms-and-Conditions</a>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Cilent's instructions, if any. The Company's sole responsibility is to its Cilent and this document does not exonerate parties to a transaction form exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approved of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.


Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN\_Doccheck@gs.com

No.198, Kezhu Road, Science City, Economic & Technological Development Area, Guangzhou, Guangdong, China 510663 中国・广东・广州高新技术产业开发区科学城科珠路198号 邮编: 510663



**Test Report** Page 9 of 10 No.: GZHL2304009470SD Date: Apr 17, 2023

# Test photo:



# **Equipment Information:**

Equipment	Model	Equipment No.	Calibration date	Next Calibration date
Digital Thickness	0mm~9mm/0.	GZMR-PL-E025	2022-10-27	2023-04-26
Gauge	001mm	GZIVIK-PL-EU23	2022-10-27	2023-04-20



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <a href="https://www.sgs.com/en/Terms-and-Conditions">https://www.sgs.com/en/Terms-and-Conditions</a>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction form exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755)83071443, or email: CN.Doccheck@sgs.com

No.198, Kezhu Road, Science City, Economic & Technological Development Area, Guangzhou, Guangdong, China 510663 t (86-20) 82155555 www.sgsgroup.com.cn



**Test Report** Page 10 of 10 No.: GZHL2304009470SD Date: Apr 17, 2023

# Sample Photo(s):



Sample as received

Remark: The report is the English version of Chinese test report GZHL2304009470SD\_CN. The Chinese version shall prevail in case of discrepancy between the Chinese version and English version.

Unless otherwise stated, the decision rule for conformity reporting is based on Binary Statement for Simple Acceptance Rule (w=0) stated in ILAC-G8:09/2019.

\*\*\*End of Report\*\*\*



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <a href="https://www.sgs.com/en/Terms-and-Conditions">https://www.sgs.com/en/Terms-and-Conditions</a>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Cilent's instructions, if any. The Company's sole responsibility is to its Cilent and this document does not exonerate parties to a transaction form exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approved of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN\_Doccheck@gs.com

中国・广东・广州高新技术产业开发区科学城科珠路198号 邮编: 510663

t (86-20) 82155555