

## IH 45 in Dallas District


- Completed in 1975
- 8-in CRCP Slab
- 6-in soil cement base
- 6-in lime treated subgrade with 4 % lime

## **IH0045 [DAL] Test Section**






TYPICAL SECTIONS SHEET 1 OF 5 SHEETS





**FWD** 

IH0045 (DAL), 8in/1975



## **Deflection at Punchout**









## **DCP**

Location	Layer	mm/blow	CBR	Modulus (ksi)
DCP1 (Good Section)	1	0.26	1302.15	251.14
	2	0.07	5890.06	659.81
DCP2 (Bad Section)	1	0.41	800.05	183.88
	2	2.25	117.80	53.96

