

Comprehensive Car Inspection Report



Thorough inspection with
300+ quality checks



Precise insights from
experienced technicians



Trusted by
over 600,000 customers



Hyundai Verna

SX1.5VTVT IVT | 2025 | AT | Petrol

Inspection location: Gurgaon

Report generated on: 24 Apr, 2025



10M +
Cars
Inspected

200 +
Cities
present

1M+
Cars
sold



Content of report

01

Your report at a glance

Overview of your overall car condition



02

Inspection summary


Category wise ratings and condition



03

Detailed Evaluation of each category

1. Exterior & Tyres
2. Engine & Transmission
3. Steering, Suspension & Brakes
4. Air Conditioning
5. Electricals & Interiors
6. Other Details



04

OEM installed features & specs

1. Safety
2. Fuel & Performance
3. Entertainment & Communication
4. Dimensions & Capacity
5. Engine, Transmission & Brakes
6. Comfort & Convenience



👁 At a glance



BMW 2 Series

2020 | Automatic | Petrol

Overall
rating

4.5/5

Excellent



Inspection date

24 Jan, 2025

Based on 300+ checkpoints by car experts



Odometer reading

100 kms



Chassis number

2H2XA59BWDY987665



Health report summary

Based on our evaluation, your car is free from accidents, flood damage, and meter tampering. Additionally, there's surface rust on the left A-pillar and right rear door. The engine has minor noise. There's leakage from the engine oil side cover and battery acid

- Based on our evaluation, your car is free from accidents, flood damage, and meter tampering. Additionally, there's surface rust on the left A-pillar and right rear door. The engine has minor noise.
- There's leakage from the engine oil side cover and battery acid leakage. The clutch is hard, and the leather seats are worn out.
- Based on our evaluation, your car is free from accidents, flood damage, and meter tampering. Additionally, there's surface rust on the left A-pillar and right rear door. The engine has minor noise

Inspection summary



This section provides a comprehensive evaluation of the most recent car assessment, meticulously divided into five key categories to offer an in-depth and accurate overview.

Exterior & Tyres

The exterior of the car has scratches and some parts have been repainted. The tyres have a tread depth of 3-5mm.

3.7/5
Neutral

Engine & Transmission

The engine is in good condition. There are no issues with blow-by, engine sound, or exhaust smoke. However, the engine oil is dirty.

4.5/5
Excellent

Steering, Suspension & Brakes

Your car's steering, suspension, and brakes are all in good condition. There are no issues that need immediate attention.

4.5/5
Excellent

Air Conditioning

The air conditioning in your car is working perfectly. The AC, heater, and climate control are all functional.

4.7/5
Excellent

Electricals & Interiors

Your car has all the electrical features working well, including power windows, airbags, music system, and a reverse camera. The interior is in good condition with leather seats and a sunroof.

4.4/5
Excellent

Vehicle images



Exterior & Tyres

Engine & Transmission

Electricals & Interiors

Steering, Suspension & Brakes

Air Condition

Other Details

01. Exterior & Tyres

Perfect parts: 26 | Imperfect parts: 25



Parameters	Perfect	Imperfect
Boot Floor	✓	
Pillar LHS A	✓	
Pillar LHS B	✓	
Pillar LHS C	✓	
Pillar RHS A	✓	
Pillar RHS B	✓	
Pillar RHS C	✓	
Apron LHS	✓	
Apron RHS	✓	
Apron RHS LEG	✓	
Apron LHS LEG	✓	
Firewall	✓	
Cowl Top	✓	
Upper Cross Member (Bonnet Patti)	✓	
Front Show	✓	
Lower Cross Member	✓	
Radiator Support	✓	

- Exterior & Tyres
- Engine & Transmission
- Electricals & Interiors
- Steering, Suspension & Brakes
- Air Condition
- Other Details

Parameters	Perfect	Imperfect
Head Light Support	✓	
Windshield Rear	✓	
Light LHS Taillight	✓	
Light LHS Fog Light	✓	
Light RHS Fog Light	✓	
ORVM - Manual / Electrical LHS	✓	
Tyre Spare Tyre	✓	
Grill	✓	
Is the Car Waterlogged?	✓	
Roof		!
Bonnet/Hood		!
Dicky Door / Boot Door		!
Quarter Panel LHS		!
Quarter Panel RHS		!
Fender LHS		!
Fender RHS		!
Running Border LHS		!
Running Border RHS		!
Door LHS Front		!

- Exterior & Tyres
- Engine & Transmission
- Electricals & Interiors
- Steering, Suspension & Brakes
- Air Condition
- Other Details

Parameters	Perfect	Imperfect
Door LHS Rear		
Door RHS Front		
Door RHS Rear		
Windshield Front		
Light LHS Headlight		
Light RHS Headlight		
Light RHS Taillight		
Bumper Front		
Bumper Rear		
ORVM - Manual / Electrical RHS		
Alloy Wheel		
LHS Front Tyre		
LHS Rear Tyre		
RHS Front Tyre		
LHS Rear Tyre		

Exterior & Tyres

Engine & Transmission

Electricals & Interiors

Steering, Suspension & Brakes

Air Condition

Other Details




Roof: No Dents, Scratched



Bonnet/Hood: No Dents, Scratched



Dicky Door / Boot Door: No Dents, Scratched



Quarter Panel LHS: No Dents, Repainted




Quarter Panel RHS: No Dents, Repainted



Fender LHS: No Dents, Scratched, Repainted



Fender RHS: No Dents, Repainted



Running Border LHS: No Dents, Scratched, Repainted

Exterior & Tyres

Engine & Transmission

Electricals & Interiors

Steering, Suspension & Brakes

Air Condition

Other Details



Running Border RHS: No Dents, Repainted



Door LHS Front: No Dents, Scratched, Repainted



Door LHS Rear: No Dents, Repainted, Scratched



Door RHS Front: No Dents, Repainted



Door RHS Rear: No Dents, Repainted



Windshield Front: Scratched

Exterior & Tyres

Engine & Transmission

Electricals & Interiors

Steering, Suspension & Brakes

Air Condition

Other Details



LHS Rear Tyre:  30% life remaining



RHS Front Tyre:  70% life remaining



LHS Rear Tyre:  30% life remaining



02. Engine & Transmission

Perfect parts: 11 | Imperfect parts: 01



Parameters	Perfect	Imperfect
Engine		
Engine Sound		
Exhaust Smoke		
Engine Permissible Blow by (Back Compression)		
Clutch		

- Exterior & Tyres
- Engine & Transmission
- Electricals & Interiors
- Steering, Suspension & Brakes
- Air Condition
- Other Details

Parameters	Perfect	Imperfect
Gear Shifting		
Engine Oil Level Dipstik		
Battery		
Coolant		
Sump		
Engine Oil		

03. Electricals & Interiors

Perfect parts: 14 | Imperfect parts: 00



Parameters	Perfect	Imperfect
4 Power Windows		
Airbag Feature		
Music System		
Leather Seat		
Sunroof		
Steering Mounted Audio Control		
ABS		
Rear Defogger		

Exterior & Tyres

Engine & Transmission

Electricals & Interiors

Steering, Suspension & Brakes

Air Condition

Other Details

Parameters	Perfect	Imperfect
Reverse Camera		
Electrical		
Interior		
Parking Sensor		
No. Of Airbags		
No. Of Power Windows		

Parameters	Number
No. Of Airbags	2
No. Of Power Windows	4



04. Steering, suspension & Brakes

Perfect parts: 02 | Imperfect parts: 01



Parameters	Perfect	Imperfect
Steering		
Suspension		
Brake		



Exterior & Tyres

Engine & Transmission

Electricals & Interiors

Steering, Suspension & Brakes

Air Condition

Other Details

05. Air Conditioning

Perfect parts: 03 | Imperfect parts: 0



Parameters

Perfect

Imperfect

AC Cooling



Heater



Climate Control AC



06. Other details

Available : 02 | Not available: 00



Parameters

Available

Not available

Duplicate Key



Chassis Embossing



OEM installed features & specs

Understanding the features and specifications of the **Hyundai Verna** is essential to ensure it aligns with your preferences, needs, and lifestyle, helping you find the perfect automotive match.



Power window
Front & rear



Airbags
04



Seating capacity
05

 Safety


Parameters	Metric
Front Fog Lights	Yes
ISOFIX-Child Seat Anchor Points	Yes
Anti-lock Braking System (ABS)	No
Central Locking	Keyless Entry
Rear Defogger	Yes
Airbags	04

 Fuel & Performance


Parameters	Metric
Max power (bhp)	81.80
Max torque (Nm)	114.7
Fuel tank capacity (lit)	24
Emission Standard	BSIV

 Entertainment & Communication

Instrument panel type	360 degree camera	Speaker brand
Analogue & digital	Yes	JBL




 Interior & Exterior





Dimensions & Capacity





Engine, Transmission & Brakes

Parameteres	Metric
Gear Box- No. of Gears	04
Displacement (cc)	1800
Transmission type	Manual
Cylinders	02
Break type (rear)	Drum
Break type (front)	Drum
Number of disc brakes	02

 Comfort & Convenience

Parameteres	Metric
Seat upholstery (cc)	1800
Auto climate control	Yes
Wireless charging pad	Yes
Steering wheel material	Alloy & Synthetic Leather
Smart Card/Smart Key	Yes
Top model	Yes

Parking sensors

No



Rear AC

Yes



Power windows

Front & rear



Steering adjustment

Tilt & telescope



Driver seat adjustment

Manual



Cruise control

No



Air conditoner

Yes



Push button start

Yes



Thank you for choosing us!

We truly appreciate your decision to prioritize the safety and maintenance of your vehicle. By opting for a thorough inspection, you're ensuring not only the longevity of your car but also peace of mind for you and your loved ones.

Should you have any questions about the inspection report or need further assistance, please don't hesitate to reach out. We're here to help and ensure your vehicle remains in top condition.


Thank you once again for your trust and patronage.

Other services by

- [CHALLAN](#)
- [SERVICE HISTORY](#)
- [PERSONAL LOAN](#)



Buying, selling, and financing pre-owned cars is now easier than ever!



Experience CARS24 App on mobile

[GET IT ON Google Play](#)[Download on the App Store](#)

Keep in touch

care@cars24.com