Ray Nicklin and Desma Nicklin

53B Remiger Road, Puhoi

Resource Consent Application

Appendix C: SEA Bush Quality Report

Cato Bolam
creating great places

PLANNERS
SURVEYORS
ENGINEERS
ARCHITECTS
ENVIRONMENTAL

Cato Bolam

creating great places

Ray Nicklin and Desma Nicklin
53B Remiger Road, Puhoi

Bush Quality Assessment Report

PLANNERS | SURVEYORS | ENGINEERS | ARCHITECTS | ENVIRONMENTAL

catobolam.co.nz

Document Record

Client	Ray Nicklin and Desma Nicklin
Site Address	53B Remiger Road, Puhoi
Job Number	40320
Document	Bush Quality Assessment Report
Document No	40320-RP-ENV-EC02

Issue and Status

Date of Issue	04/03/2020
Status	Final

Author	Brittany Pearce – Ecologist
Reviewer	Myles Goodwin – Principal
Approved for Issue	Myles Goodwin – Principal

Originating Office

Office	Orewa
Postal Address	PO Box 157, Orewa 0946
Phone	09 427 0072

Contents

1.0 Introduction 1

2.0 Overview of Bush on Property 1

3.0 Bush Areas CU, CP, CQ and CR 2

3.1 Physical Description 2

3.2 Vegetation 2

3.3 Photos 3

3.4 Significance Assessment 4

3.4.1 Bush Quality Assessment Scale 1 5

3.4.2 Bush Quality Assessment Scale 2 6

3.4.3 Summary 6

4.0 Bush Areas CS and CT 6

4.1 Physical Description 6

4.2 Vegetation 6

4.3 Photos 7

4.4 Significance Assessment 8

4.4.1 Bush Quality Assessment Scale 1 8

4.4.2 Bush Quality Assessment Scale 2 9

4.4.3 Summary 9

5.0 Bush Area CV 9

5.1 Physical Description 9

5.2 Vegetation 10

5.3 Photos 10

5.4 Significance Assessment 11

5.4.1 Bush Quality Assessment Scale 1 11

5.4.2 Bush Quality Assessment Scale 2 12

5.4.3 Summary 12

6.0 Conclusion and Recommendations 12

7.0 Limitations 13

Appendix A: Scheme Plan showing planting areas 1

1.0 Introduction

This report relates to three stands of native bush over 2ha in size on the property located at 53B Remiger Road and Tunnel Road, Puhoi. An additional stand smaller than 2ha is also proposed for protection under this application.

Two of the stands are identified as Significant Ecological Area (SEA) under the Auckland Unitary Plan (Operative in Part) 2016 (AUP(OP)). The other stands are considered to meet sub-factors required to qualify as SEA, and also meet the significance criteria under the still operative Auckland Council District Plan (Rodney Section) 2013 (District Plan), as described in this report.

The protection of the bush areas described in this report will result in a valuable contribution to the preservation and improvement of native habitat, steep slopes, and watercourses in the surrounding landscape, where bush is largely fragmented and exotic pastureland and forestry dominate.

2.0 Overview of Bush on Property

The expected ecosystem type of this property prior to human disturbance is a mix of kauri, podocarp, broadleaved forest and taraire, tawa, podocarp forest[1]. The majority of this forest has been cleared for grazing in the past, and the majority of the remaining areas are currently grazed. Both ecosystem types are still present on the property, but are damaged by stock grazing, weed and pest invasion, and expected logging in the past. Only one stand is currently fenced from grazing.

The outer edges of the bush stands, as well as steeper slopes across the property, are currently regenerating with native vegetation with manuka, kanuka, totara, and lancewood being the most common canopy species in these areas. Regeneration is generally denser on those slopes less accessible to stock access.

A summary of the bush areas proposed for protection is included below (See Appendix A for Scheme Plan):

Scheme Ref	Area	SEA?	Description
CU, CP, CQ, CR	35.17ha	Yes	Mature podocarp-broadleaf forest with a grazed understorey, with taraire forest on the lower slopes, covering the south facing slopes above the main stream flowing west to east across the property.
CT and CS	10.2ha	Yes	Mature podocarp-broadleaf forest with an understorey of varied quality (some regenerating).
CV	6.7ha	No	Mature podocarp-broadleaf forest with stock proof fencing and a dense regenerating understorey.

Additional stands of kauri, podocarp, broadleaved forest are present to the south of Area CU. These were initially planned to be covenanted as Areas CT and CS, but it has now been proposed to covenant

[1] Singers, N.; Osborne, B.; Lovegrove, T.; Jamieson, A.; Boow, J.; Sawyer, J.; Hill, K.; Andrews, J.; Hill, S.; Webb, C. 2017. Indigenous terrestrial and wetland ecosystems of Auckland. Published by Auckland Council.

the SEA bush to the northeast of Area CU instead. The southern bush areas were going to be very difficult to fence due to the topography which includes of steep slopes and trenches. A bush quality assessment of the SEA bush area has found it to be of a higher quality than the southern bush areas (the northern SEA bush scored 33 against the significance criteria under the ACDP (RS) while the southern bush scored 24). The proposed new covenant areas CT and CS protect an additional 2.1ha of bush compared to what was initially proposed.

The property is located in close proximity to existing private bush covenants, QEII reserves and Department of Conservation reserves. In the immediately surrounding landscape, however, plantation forest and pasture land dominate. This increases the importance of preserving bush in this location, as well as being located in the upper catchment for a significant tributary of the Puhoi River.

In terms of weed species, presence within the bush areas is relatively low due to frequent grazing. Pines (*Pinus radiata*) occur in the canopy of some areas in low quantity, with a larger group in Area CV. These should be selectively poisoned.

The general approach to implementing the ACDP(RS) Appendix 7B Bush Quality Assessment is to get sample points that are representative of the variability that is commonly present throughout a forest patch. This allows for an overall average quality assessment under the assessment guidelines. In the case of this property, a separate bush assessment was carried out in each of the areas larger than 2ha proposed for covenanting. The AUP(OP) significance criteria are also discussed where relevant.

A description of each area followed by the assessment undertaken is shown below. The areas of bush referred to are as labelled on the Scheme Plan in **Appendix A**.

3.0 Bush Areas CU, CP, CQ and CR

3.1 Physical Description

These bush areas are part of a continuous stand of bush and cover approximately 35.17ha across predominately south facing slopes with the peak of the hill being located in the northwest of the area. The main watercourse of the property runs from west to east through the southern part of the bush. To the north of the watercourse is an existing farm track that is to be fenced either side and excluded from the proposed covenant. For the most part, canopy closure is achieved across this track.

There is an existing fence around the eastern part of the bush, but stock are grazed within the bush and a track for stock movement runs from the eastern site west and south to the south-western clearing which is not proposed for covenanting. The land to the north of this clearing appears to have recently naturally regenerated from pasture due to higher inaccessibility for stock.

3.2 Vegetation

The forest in these areas is primarily mature mixed podocarp and broadleaf forest. Stands of taraire forest are more common on the lower slopes in the south, and regenerating kanuka and totara are common on the edges.

The youngest vegetation occurs in the western central area, where regeneration across steep slopes appears to have occurred in a previously cleared area relatively recently. Pasture species and

regenerating gorse persist in this part of the bush, but other than this area weed presence is generally very low, excepting for the existing tracks. For the track running through the centre of the bush, this will be contained within the covenant and left to regenerate for which control of weed species such as kikuyu and foxglove will be essential. Other weed species observed include pine and Japanese honeysuckle.

Understorey cover within the bush area is generally low, due to the stock access, with only ground cover or unpalatable species occurring. The steeper parts of the bush, such as the northeast, where stock rarely venture, have a greater understorey community. More variation is generally found in the epiphytic and climbing species which have persisted in the bush despite disturbance to the understorey, and likely the canopy, in the past.

Canopy species observed in this bush area include totara, kanuka, karaka, puriri, taraire, silver fern, nikau, titoki, kohekohe, lancewood, rewarewa, maire, kahikatea, wheki, manuka, cabbage tree, rimu, rata, mapou, hangehange, and putaputaweta.

Common understorey, epiphytic and climbing species observed include rasp fern, thin-leaved coprosma, mapou, forest sedge, thin-leaved bastard grass, manuka, brake fern, basket grass, totara, hangehange, NZ gloxinia, hook grass, twiggy coprosma, scented fern, white rata, tank lily, hanging spleenwort, kiekie, leather leaf fern, and hound's tongue fern.


3.3 Photos

The following photos show examples of the canopy vegetation of the bush.









The following photos show examples of the understorey vegetation of the bush.









An overview of the bush looking north is shown below.



3.4 Significance Assessment

The entire area, stretching onto the western neighbouring property, is identified as SEA_ T_2535, which meets the SEA factor for Threat Status and Rarity, presumably because both kauri, podocarp, broadleaved forest and taraire, tawa, podocarp forest are endangered ecosystems in the Auckland Region[2] .

[2] Singers, N.; Osborne, B.; Lovegrove, T.; Jamieson, A.; Boow, J.; Sawyer, J.; Hill, K.; Andrews, J.; Hill, S.; Webb, C. 2017. Indigenous terrestrial and wetland ecosystems of Auckland. Published by Auckland Council.

However, it is recognised that the SEA status of the bush area has no weighting in the ACDP (RS) bush quality assessment, which is still operative. This assessment is therefore outlined below.

3.4.1 Bush Quality Assessment Scale 1

The general approach to implementing the bush quality assessment is to get sample points that are representative of the variability that is commonly present throughout a forest patch. This allows for an overall average quality assessment under the assessment guidelines. Assessment at three canopy locations throughout the bush was undertaken as below.



Bush Quality Assessment Field Sheet (Appendix 7B of District Plan Rodney, 2011)

SCALE 1

RANK	**4**	**3**	**2**	**1**	**0**	**Site 1**	**Site 2**	**Site 3**
CANOPY								
1. % of natives	81-100%	61-80%	41-60%	25-40%	<25%	4	4	4
2. % of canopy closure	81-100%	61-80%	41-60%	25-40%	<25%	4	2	3
3. Number of species	>12	8-11	4-7	2-3	1	3	2	2
4. Height	>8m	6.1-8m	4.1-6m	3.1-4m	<3m	4	2	4
UNDERSTOREY								
5. % of natives	81-100%	61-80%	41-60%	25-40%	<25%	4	2	4
6. % ground cover	81-100%	61-80%	41-60%	25-40%	<25%	2	1	0
7. Number of species	>12	8-11	4-7	2-3	1	4	3	2
					SITE TOTALS:	**25**	**16**	**19**

TOTAL A (average of all sites): 20

On scale 1, a final score of 20 is achieved. Based on this score, these areas exceed the quality standard required without the need to proceed to scale 2.

3.4.2 Bush Quality Assessment Scale 2

While significance of the bush is achieved under scale 1, it is also considered that five points would be awarded for the potential of regeneration in the parts of the bush that are in the early scrubby stages of succession (west) and throughout the understorey. This regeneration would be rapidly assisted through the completion of stock proof fencing around the bush. It is also considered five points could be awarded for aesthetic value due to the bush clad slopes of the peak located in the northwest of the area, and five points would be awarded for a continuous stand over 8ha.

3.4.3 Summary

Based on scale 1 and scale 2 scores, the total score for the bush area is 35. This bush area therefore meets the acceptance criteria for significance under the ACDP(RS) as well as being identified as SEA.

An ongoing management plan for the proposed bush covenant is provided in association with this application.

4.0 Bush Areas CS and CT

4.1 Physical Description

These bush areas cover approximately 10.2ha across south and southwest facing slopes. The main watercourse runs down the western boundary of Area CT, intercepts towards to southern end of Area CT and continues along the southern boundary of Area CS. The two bush areas described in this section of the report are contiguous.

There is a fence above the northern boundary of Area CS separating it from Remiger Road, but the rest of this bush area and Area CT are not currently fenced. Most of these two areas of bush cannot be easily reached by stock, but stock can access the less steep and less dense areas of the bush, such as the southern part of Area CT. Narrow gullies and steep land within and around the edges of the bush have been colonised with regenerating native vegetation.

4.2 Vegetation

The forest in Areas CS and CT is mature mixed podocarp and broadleaf forest. Regenerating kanuka forest with totara and lancewood featuring in the canopy is more common on the outer edges. Taraire and kohekohe form the dominant canopy, with nikau and tree ferns also being abundant. Kahikatea are common closer to the edges of the bush and the watercourses.

Canopy species observed in this bush area include taraire, kohekohe, kahikatea, nikau, rimu, totara, rewarewa, manuka, kanuka, lancewood, and wheki.

Understorey cover within the bush area is varied, due to grazing that occurs in some of the more accessible areas. The steeper parts of the bush, where stock rarely venture, have a greater understorey community. More variation is generally found in the epiphytic and climbing species which have persisted in the bush despite past disturbance to the understorey and canopy. Common understorey, epiphytic and climbing species observed include twiggy coprosma, white rata, ground ferns, nikau, parataniwha, manuka and kanuka, totara, tank lily, kiekie, kawakawa, and putaputaweta.

4.3 Photos

The following photos show examples of the canopy of Areas CS and CT.









The following photos show examples of the understorey and internal areas of Bush Areas CS and CT.









4.4 Significance Assessment

Both Areas CT and CS are identified as SEA_T_2535, which meets the SEA factor for Threat Status and Rarity, presumably because both kauri, podocarp, broadleaved forest and puriri forest are endangered ecosystems in the Auckland Region[3] .

However, it is recognised that the SEA status of the bush area has no weighting in the ACDP (RS) bush quality assessment, which is still operative. This assessment is therefore outlined below.

4.4.1 Bush Quality Assessment Scale 1

The general approach to implementing the bush quality assessment is to get sample points that are representative of the variability that is commonly present throughout a forest patch. This allows for an overall average quality assessment under the assessment guidelines. Assessment at three canopy locations throughout the bush was undertaken as below.



[3] Singers, N.; Osborne, B.; Lovegrove, T.; Jamieson, A.; Boow, J.; Sawyer, J.; Hill, K.; Andrews, J.; Hill, S.; Webb, C. 2017. Indigenous terrestrial and wetland ecosystems of Auckland. Published by Auckland Council.

Bush Quality Assessment Field Sheet (Appendix 7B of District Plan Rodney, 2011)

SCALE 1

RANK	4	3	2	1	0	Site 1	Site 2	Site 3
CANOPY								
1. % of natives	81-100%	61-80%	41-60%	25-40%	<25%	4	4	4
2. % of canopy closure	81-100%	61-80%	41-60%	25-40%	<25%	3	3	4
3. Number of species	>12	8-11	4-7	2-3	1	2	2	3
4. Height	>8m	6.1-8m	4.1-6m	3.1-4m	<3m	4	4	4
UNDERSTOREY								
5. % of natives	81-100%	61-80%	41-60%	25-40%	<25%	4	4	4
6. % ground cover	81-100%	61-80%	41-60%	25-40%	<25%	2	2	3
7. Number of species	>12	8-11	4-7	2-3	1	3	2	4
					SITE TOTALS:	**22**	**21**	**27**

TOTAL A (average of all sites): 23.3

On scale 1, a final score of 23.3 is achieved. Based on this score, Areas CS and CT exceed the quality standard required without the need to proceed to scale 2.

4.4.2 Bush Quality Assessment Scale 2

While significance of the bush is achieved under scale 1, it is also considered that five points would be awarded for the potential of regeneration throughout parts of the understorey. This regeneration would be rapidly assisted through the completion of stock proof fencing around the bush. It is also considered a further 5 points would be awarded for a continuous stand over 8ha.

4.4.3 Summary

Based on scale 1 and scale 2 scores, the total score for the bush area is 33. This bush area therefore meets the acceptance criteria for significance under the ACDP(RS).

An ongoing management plan for the proposed bush covenant is provided in association with this application.

5.0 Bush Area CV

5.1 Physical Description

This bush area covers approximately 6.7ha in the east of the property across predominantly west facing slopes with a gully running south through the western part of the bush. A stream flows through this gully, entering the bush area from the southwest.

This area is entirely fenced from stock with a seven wire post and batten fence, plus an electric wire, allowing for dense regeneration of the understorey vegetation compared to the two bush stands previously described in this report.

5.2 Vegetation

The forest in Area CV is primarily mature mixed podocarp and broadleaf forest. Some larger trees occur in this area compared to those previously described, including several emergent rata and kauri trees. The central northern canopy contains a group of pines which are proposed to be poisoned.

Native canopy species observed in this bush area include taraire, nikau, rata, kahikatea, rimu, karaka, kauri, silver fern, cabbage tree, totara, mamaku, and pate.

Understorey cover is dense and includes species typical of this forest type such as nikau, mapou, mahoe, hangehange, and ground ferns and sedges.

5.3 Photos

The following photos show examples of the canopy of Area CV.



The following photos show examples of the internal areas and understorey of Area CV.









5.4 Significance Assessment

This area is not identified as SEA so becomes non-complying under the AUP(OP). However, given it contains the same threatened ecosystem type as the areas previously described, and in a better condition due to the stock proof fencing, it is considered the area has merit under SEA sub-factor 2(a)[4].

The area has also been assessed under the still applicable ACDP(RS) criteria as below.

5.4.1 Bush Quality Assessment Scale 1

The general approach to implementing the bush quality assessment is to get sample points that are representative of the variability that is commonly present throughout a forest patch. This allows for an overall average quality assessment under the assessment guidelines. Assessment at three canopy locations throughout the bush was undertaken as below.



[4] (2) **Threat Status and Rarity** (a) It is an indigenous habitat, community or ecosystem that occurs naturally in Auckland and has been assessed (using the IUCN threat classification system) to be threatened, based on evidence and expert advice (including Holdaway et al. Status assessment of NZ naturally uncommon ecosystems).

Bush Quality Assessment Field Sheet (Appendix 7B of District Plan Rodney, 2011)

SCALE 1

RANK	4	3	2	1	0	Site 1	Site 2	Site 3
CANOPY								
1. % of natives	81-100%	61-80%	41-60%	25-40%	<25%	4	4	2
2. % of canopy closure	81-100%	61-80%	41-60%	25-40%	<25%	4	4	3
3. Number of species	>12	8-11	4-7	2-3	1	2	2	2
4. Height	>8m	6.1-8m	4.1-6m	3.1-4m	<3m	4	4	4
UNDERSTOREY								
5. % of natives	81-100%	61-80%	41-60%	25-40%	<25%	4	4	4
6. % ground cover	81-100%	61-80%	41-60%	25-40%	<25%	4	3	3
7. Number of species	>12	8-11	4-7	2-3	1	4	4	3
					SITE TOTALS:	**26**	**25**	**21**

TOTAL A (average of all sites): 24

On scale 1, a final score of 24 is achieved. Based on this score, Area CV exceeds the quality standard required without the need to proceed to scale 2.

5.4.2 Bush Quality Assessment Scale 2

This bush area achieves the quality standards under Scale 1 only. It is considered no further points would be awarded under scale 2.

5.4.3 Summary

Based on scale 1 and scale 2 scores, the total score for the bush area is 24. This bush area therefore meets the acceptance criteria for significance under the ACDP(RS).

An ongoing management plan for the proposed bush covenant is provided in association with this application.

6.0 Conclusion and Recommendations

Protecting the bush areas outlined in this report will have significant benefits for terrestrial fauna and flora and provide additional security for the conservation of bush in the wider landscape. The overall proposal will result in the protection of most of the significant bush on this property meaning weed and pest management will be more effective, and the areas will provide beneficial ecological stepping stones across the entire site and connecting to surrounding SEAs and native vegetation.

Approximately 53.07ha of significant bush are present in the areas described in this report. These areas have vegetation quality exceeding the minimum requirements for acceptance based on the assessment criteria outlined in Appendix 7B of the District Plan and Schedule 3 of the Auckland Unitary Plan.

It is thus considered the bush areas proposed for covenanting meet the requirements for a bush protection subdivision under the operative plans.

This assessment is subject to the following recommendations:

I. Stock are excluded by permanent fence from all bush areas.
II. The covenant fence lines are regularly checked and maintained as stock proof.
III. Feral goats, deer, and other pest animals that may be present are controlled.
IV. Control of existing ecological weeds and pests occurs.
V. Regular monitoring for invasive weeds occurs and any infestations are dealt with.
VI. Registration of bush protection covenants on the titles to the land.

7.0 Limitations

This report has been prepared for the particular project described to us and its extent is limited to the scope of work agreed between the client and Cato Bolam Consultants Limited.

No responsibility is accepted by Cato Bolam Consultants Limited or its directors, servants, agents, staff or employees for the accuracy of information provided by third parties and/or the use of any part of this report in any other context or for any other purposes.

This report is for the use by the client only, and should not be used or relied upon by any other person or entity or for any other projects.

Ray Nicklin and Desma Nicklin

53B Remiger Road, Puhoi

Bush Quality Assessment Report

Appendix A: Scheme Plan showing planting areas

Cato Bolam
creating great places

PLANNERS
SURVEYORS
ENGINEERS
ARCHITECTS
ENVIRONMENTAL

This drawing and design remains the property of, and may not be reproduced or amended without the written permission of Cato Bolam Consultants Ltd. No liability shall be accepted for unauthorised use of this drawing and design.

N

Auckland Council
Comprised in:

RT NA137A/506Ltd	57.4262ha
RT NA105B/748	24.1140ha
RT NA31C/965	21.6507ha
RT NA757/204Ltd	37.0692ha
RT NA2100/21Ltd	160.87ha
RT NA127B/898	1.1705ha
Total Area	302.3006ha

Areas and measurements are subject to survey.

- Riparian Margin Protection
- Significant Ecological Area
- Proposed Building Area
- Watercourse
- Extent of Flood Plain

Areas (CP)-(CV) (53.07ha) are to be subject to land covenants to protect native bush .

Areas (CN)(CO)(CX)-(CZ)(Z) (0.9ha) are to be subject to land covenants to protect riparian planting.

Cato Bolam
creating great places
PLANNERS | SURVEYORS | ENGINEERS
ARCHITECTS | ENVIRONMENTAL

R.C.& D.E. Nicklin
53B Rimiger Road
Puhoi

Lots 1 - 8 being
Proposed Subdivision of
Lot 8 DP 208981, Lot 5 DP 198556
Lot 1 DP 179794, Allots 32,35,54A &
Pt Allots 30,31,36 Parish of Puhoi

FOR RESOURCE CONSENT

No.	REVISION (DESCRIPTIONS)	NAME	DATE
A	Issued for Resource Consent	MG	12/03/2020
SURVEYED			
DESIGNED			
DRAWN		LS	08/09/2017

DATE	ORIGINAL SCALE	ORIGINAL SIZE
12/03/2020	1:10,000	A3

DRAWING NO.	REVISION
40320-DR-PLN-1200	A