Lime Addition Effect on Corrosion of Reinforced Mortar

M.C.C. Oliveira, Cíntia G.F. Costa, Carlos Roberto Araujo, and V.F.C. Lins* Corrosion and Surface Engineering Laboratory, Antio Carlos Avenue 6627, Zip Code 31270901, Belo Horizonte, Brazil

vlins@deg.ufmg.br

Abstract

This study aims to investigate the effect of lime addition in cement mortar on corrosion resistance of carbon and galvanized steel reinforcements. Mixed mortars were studied containing three contents of lime (6.7, 13.3, and 26.3 wt.%). The water retention, incorporated air, and compression strength of reinforced mortars were determined. Corrosion resistance of carbon and galvanized steel in mixed mortars was evaluated. Immersion tests were performed using the reinforced mortars consisting of 12 cycles of immersion in a solution of 3.5% (wt./v) NaCl and drying in a stove at 60°C. In each cycle, the sample was partially immersed in a saline solution for two days and dried in a stove at 60°C for five days. Electrochemical impedance spectroscopy was used to monitoring reinforcement corrosion after cyclic tests. These measurements were repeated after 36 months of the cyclic immersion testing. Before cyclic testing, the corrosion potential of carbon steel and galvanized steel increased as the concentration of lime in the mortar increased. After the cyclic immersion tests in a saline solution, the polarization resistance of carbon and galvanized steel reinforcement increased as the lime content in mortar increased, demonstrating the protective effect of lime. After 36 months, the polarization resistance of steels in mixed mortars with the highest lime content was the lowest. For the carbon and galvanized steel in cement and mixed mortars, the polarization resistance increased after 36 months of the cyclic test.

Keywords: Lime, Mortar, Reinforcement corrosion, Electrochemical impedance spectroscopy.

Introduction

Studies focusing on materials used in Cultural Heritage conservation projects are increasingly relevant [1–3]. Heritage buildings have been built with mud/clay bricks and lime-based mortars since quite early historical times, as confirmed by traces of ancient constructions in Palestine and Turkey dating back to 12,000 b. C [1]. Autogenous self-healing in lime-based mortars is a well-known phenomenon related to the deposition of calcite in cracks in mortars with high lime content [1]. Aerial lime-based mortars are recommended by many experts to restore the ancient buildings due to their compatibility with ancient building materials [4]. The lime-cement mortars could reduce the

disadvantages presented by both lime-based mortars and cement-based mortars [5,6]. Garcia-Cuadrado et al. [7] studied the fracture behavior of lime-cement masonry mortars prepared with various fractions of lime and cement. One possibility that has arisen with the use of mixed mortar is related to the effect of lime addition on the corrosion resistance of the reinforcement. The reinforcement corrosion depends on the concrete-reinforcement interfacial condition which depends on the mortar used [8].

Sébaïbi et al. [9] studied the effect of various slaked limes on the microstructure of a lime-cement-sand mortar. Several papers are found about admixtures and properties of lime-based mortars [10-15]. However, on our best knowledge, literature about corrosion resistance of carbon and galvanized reinforcements in a mixed mortar is scarce.

Thus, this study aims to investigate the effect of adding lime in mortar, seeking thus greater resistance to corrosion of reinforcing carbon and galvanized steel associated with an economic feasibility. The technique of electrochemical impedance spectroscopy was used to evaluate the corrosion resistance of reinforcements after partial immersion tests in a saline environment. After three years of the immersion tests, new electrochemical tests were performed to evaluate the effect of time on the reinforcement corrosion.

Experimental

The mortars were prepared according to the composition shown in Table 1. The CPIII 40 RS cement (sulfate resistant and with addition of a blast furnace slag), which showed a compression strength of 45 MPa at 28 days, CH-I hydrated lime which consists of calcium and magnesium hydroxides, and quartz sand were utilized. The characterization of hydrated lime provided by manufacturer is shown in Table 2. The galvanized steel shows a 366 g/m2 of zinc (51µm of thickness). The carbon steel CA-50 showed yield strength of 500 MPa. The reinforcements were covered with electrical tape, and leaving a length of 5 cm uninsulated inside the prismatic specimen. The exposed area of reinforcement in mortar was 7.854 cm2. The exposed ends of the armor were sealed with tape.

The water/cement ratio was determined for the consistency of 260 \pm 5 mm, and the tests with started with a content of 16 wt.% of water of the total weight of solids, for each mixture (Table 1).

Table 1 - Composition of samples

Mortar	Trace (wt.% of	Lime concentration	Water/
			cement

	cement,	(wt.%)	ratio
High content of lime	1:2.5:6	26.3	2.67
Medium content of lime	1:1:6	13.3	1.62
Low content of lime	1:0.5:6	6.7	1.35
Without lime	1:0:6	0	1.31

Table 2 - Characterization of hydrated lime

Total non-volatile base oxides	≥ 90%
Insoluble waste	≤8%
Total not-hydrated oxides	≤10%
Moisture	≤0,5%
Retained on # 30 sieve (0.600 mm) sieve	≤0,5%
Retained on #200 sieve (0.075 mm)	≤10%
Water retention	≥75%
Incorporation of sand	≥3%
Plasticity	≥110%

The wires of a carbon or galvanized steel with a diameter of 5.00 mm were used. The identification of molds according to the mixture and the type of frame was made considering the lime content: H (high), M (medium), L (low), W (no lime) and the type of armor: G (galvanized), A (carbon steel).

2.1 Water retention

A cylindrical cast steel (100 mm in diameter and 25mm in height – internal measures) was weighed with a resolution of 0.1g (mass registration: Mm). Similarly, 12 dry filter paper discs (85 g/cm2 and 110 mm diameter) were weighed with a resolution of 0.01 g (mass registration: Mse). The mold was filled with mortar (using a spatula) into ten layers to form a small excess (subsequently crushed by the blade of the spatula). Molds with mortar were weighed with a resolution of 0.1 g (mass registration: Mma). Under the surface of the mortar two gauze screens (surgical type, with 110 mm edge), the set of 12 filter paper disks and a rigid plate (110mm diameter, 5 mm thick, one face having machining smooth) were placed. Subsequently, a weight of 2 kg (consisting of metal solid cylinder with 110 mm diameter) was placed on the rigid plate. After 2 minutes of application of the load, the weight of 2 kg and the rigid board were removed. The set of filter papers were removed and immediately weighed in the balance with a resolution of 0.01 g (mass registration Mf). The amount of water retention ratio was calculated by the following equation:

$$Ra = [1 - (M - Mse)] \times 100/AF (Mma - Mm)$$
 [1]

Where:

Ra: water retention

AF: factor water / fresh mortar: AF = Mw/M + Mw

Mw: total mass of water added to the mix in g

M: mortar mass industrialized or mass sum of the anhydrous components in the case of work mortar, g

Mse: mass of the dried disc in g

Mma: mass of the mold with mortar in g

Mm: mass of the empty mold in g

2.2 Incorporated air

For determination of entrained air content, the most common method used is based on Boyle's law for determining the air content by the ratio of pressure and volume at a given temperature (manometric method). In this method, the employee meter comprises a

measuring hood and a sealing system. Its principle of operation consists in introducing water to a certain height on the known volume sample of mortar, and applying a predetermined air pressure by means of a small pump on the water. The determination consists in reducing the air volume of the mortar sample, by observing the amount of water penetrating under the applied pressure, and this amount is calibrated in terms of the percentage of air voids in the mortar sample. Thus, the device directly provides the air volume of the sample.

2.3 Compression strength

Four cylindrical specimens (5 cm x 10 cm) by age with freshly prepared mortar having the pattern consistency index were prepared. The specimens were kept for 48 hours in the mold (in a humid chamber with a relative humidity of 95%) and then demoulded; samples were immersed in water (inside the camera) to the age of the test (except in the case of mortars with lime that after demolded were kept outdoor lab until the age test). Prior to the compression test, the specimen was capped with sulfur and its diameter was measured with calipers in two orthogonal positions in its middle third, recording the average in millimeters. After the axial rupture test, specimens were press-calculated individual resistance (each sample breaking load divided by the area of the sample section, expressed in MPa) and the average strength (average of individual resistors, expressed in MPa).

2.4 Electrochemical measurements and immersion tests

The open circuit potential was measured using the samples as received (after 12 hours immersion in water), and after 12 cycles of immersion in a saline solution and drying. The equipment used was the Omnimetra PG-29, the reference electrode was Ag/AgCl, and the counter electrode was an austenitic stainless steel plate.

Immersion tests were performed consisting of 12 cycles of immersion in a solution of 3.5 (wt./v)% of NaCl and drying in a stove at 60oC. In each cycle, the sample was partially immersed in a saline solution for two days and dried in a stove at 60oC for five days. The measurement was performed after the immersion stage.

The Electrochemical Impedance Spectroscopy (EIS) was performed immediately after the immersion tests, using a AUTOLAB 30 potentiostat, and the data acquired by the FRA for Windows v. 2.3 of Eco Chemie B. V. The frequency range used was from 100 kHz to 10 mHz, with amplitude of 20 mV. These measurements were repeated after 36 months of immersion testing to determine the effect of time on the corrosion resistance of

reinforcement. Measurements of open circuit potential and electrochemical impedance spectroscopy were repeated using the potentiostat Princeton Versastat 3. Data were acquired by using the VersaStudio software. The impedance results were treated using the ZsimpWin software.

For the characterization of corrosion products of reinforcements, X-ray diffraction was performed, using an Empyrean Philips – Panalytical diffractometer, $CuK\alpha$ radiation and graphite monochromator crystal. The analysis method relies on a comparison of the values of the interplanar spacing and intensities of the peaks in the diffractograms of the samples and a reference sample using the default PDF–2 database ICDD – International Centre for Diffraction Data. The pattern of the ICDD PDF–2 database used for the identification of crystalline phases was copper (Cu) – ICDD # 85–1326. The characterization of corrosion products was performed after 12 cycles of the immersion and drying tests.

The finished diameter of the reinforcement was measured after 12 cycles of immersion and drying, immersing the sample in the pickling solution of 3.5 g of hexamethylenetetramine dissolved in 500 mL of hydrochloric acid (density = 1.19g / cm3), and the volume made up to 1 liter. The pickling was performed for 10 minutes according to the ASTM G1-90 standard, using a hydrochloric acid solution 1:1 with 3.5 g/L hexamethylenetetramine. The reinforcements were washed with distilled water, dried and the diameter of wire was measured until constant value. The reduction of the reinforcement diameter is an auxiliary technique to evaluate the reinforcement corrosion.

Results and Discussion

A higher water/cement ratio, as observed for the sample with higher lime content, tends to generate higher porosity and benefit from the entry of aggressive agents to the reinforcement steel and cement itself [16]. Lime mortars have higher water retention capacity than the cement mortar as shown in Table 3. This result is due to a higher fineness, high specific surface, and greater adsorption capacity of its particles of lime mortar with a formation of a gel on the surface of the particles up to 100% water depending on the particle volume [4].

Table 3 - Incorporated air and water retention of mixed mortars

Mortar	Water/cement	Incorporated air	Water retention
Lime	ratio	(%)	(%)

concentration (wt.%)			
High lime content (26.3)	2.67	3.4	96.6
Medium lime content (13.3)	1.62	4.2	98.3
Low lime content	1.35	5.8	98.8
(6.7)			
Without lime	1.31	6.1	91.4
(0)			

Lime mortars showed lower values of incorporated air than the cement mortar. Carvalho Jr [17] reported values of incorporated air in the range of 4-10% for mixed (cement and lime) mortars. A higher incorporated air content can contribute with entry of aggressive gaseous agents to concrete such as oxygen and carbon dioxide. However, the analysis should be made considering the sample pore structure. Compression strength results of mortars are shown in Table 4. Compression strength is influenced primarily by the nature of the binder, nature of the aggregates, proportion binder/aggregate, water/cement ratio of the fresh mixture and the execution technique of coating.

Table 4 - Compression strength of mixed mortars

Compres	Compression strength (MPa)			
3 days	7 days	28 days		
2.28	4.94	7.86		
2.39	6.10	8.56		
2.07	4.58	7.14		
0.68	1.48	2.67		
	3 days 2.28 2.39 2.07	2.28 4.94 2.39 6.10 2.07 4.58		

The highest compressive strength obtained after 28 days of curing time are for samples without lime or with a lower lime content; the lime addition in mortar reduced the compressive strength of the samples which could lead the generation of cracks, affecting the stability and durability of structures. Cement significantly improves compressive strength of mortar [6]. However, the deleterious effect on the compressive strength was more evident in the case of adding 26.3 wt.% of lime in mortar corresponding to the highest content of lime [4].

The obtained values of corrosion potential of carbon and galvanized steel reinforcements in cement and mixed mortars were shown in Table 5 and Table 6.

Table 5 - Results of Ecorr of galvanized reinforcements in cement and mixed mortars

Samples	Ecorr (mV) _{Ag/AgCl}	Ecorr	Ecorr (mV) _{Ag/AgCl}
	(before cyclic test)	(mV) _{Ag/AgCI} (immediately after cyclic	(after 36 months)
		test)	
Without lime	-910 ± 54	-890 ± 71	-379 ± 34
Low lime content	-650 ± 32	-770 ± 69	-417 ± 25
Medium lime content	-710 ± 50	-780 ± 54	-459 ± 31
High lime content	-735 ± 58	-760 ± 61	-448 ± 36

Table 6 - Corrosion potential of carbon steel reinforcement

Samples	Ecorr (mV) _{Ag/AgCl}	Ecorr	Ecorr (mV) _{Ag/AgCl}
	(before cyclic test)	$(mV)_{Ag/AgCl}$	
		(after cyclic test)	(after 36 months)
Without lime	-484±38	-610±43	-451±31

Low lime content	-458±32	-650±52	-487±29
Medium lime content	-300±40	-620±37	-473±38
High lime content	-283±25	-560±50	-464±37

For galvanized reinforcements in concrete, the first mechanism of zinc corrosion occurs in the beginning when the system is still wet or the hardening process has not reached 95% of the solidification of the matrix [18]. This is usually in a timeframe of 48 hours. When the system is still wet and highly alkaline, the zinc is attacked by a combination of hydroxyl ions and calcium.

$$Zn + 2 OH - + Ca2 + = CaZnO2 + H2$$
 [2]

The formation of calcium zincates occurs due to the amphoteric character of zinc. The calcium zincates improve the adhesion between the zinc and the matrix. However, if the reaction occurs too fast, the hydrogen that is formed (H2) reduces significantly the strength of the composite as a spongy layer is formed around the wire, which is detrimental to the properties of reinforced mortar.

Before the cyclic test, there is an increase in corrosion potential of carbon steel and galvanized steel with the lime addition in mortar (Tables 5 and 6). This result demonstrates the beneficial effect of lime on corrosion resistance of steel. In the case of lime addition on mortar, carbon dioxide gas is necessary for curing the mortar with calcium oxide in masonry. The CO2 improves the passivation of zinc region and contributes to increase the corrosion resistance of galvanized steel. For the galvanized steel, low lime content was sufficient to increase the open circuit potential of reinforcement. For the carbon steel, the effect of lime addition on corrosion potential was significant for medium and high contents of lime in mortar.

For the galvanized steel reinforcement in mortar with low lime content, and for all samples of carbon steel reinforcement, after cyclic immersion in a saline solution, the corrosion potential reduced indicating the deleterious effect of chlorides in this medium.

After 36 months of the cyclic test, the corrosion potential of all samples became higher than the corrosion potential measured immediately after immersion tests. This result can be due to the increase of alkaline content in mortar. Lime mortars have autogenous self-healing properties due to dissolution, transport and re-precipitation of calcium compounds [1].

But after 36 months of the cyclic tests in a saline solution, the highest corrosion potentials were obtained for the reinforcement in mortar without lime for the galvanized and the carbon steel reinforcements.

The results of electrochemical impedance spectroscopy are shown in Table 7. Figures 1 and 2 show Bode diagrams for carbon and galvanized steel reinforcement after 36 months of immersion tests, respectively.

Table 7 - Polarization resistance of carbon and galvanized steels in cement and mixed mortars after cyclic tests

Carbon steel	Rp Ω.cm ²	Rp Galvanized steel Ω.cm² vclic (after		Rp Ω.cm²	Rp Ω.cm²
	(after cyclic tests)			(after cyclic tests)	(after
		months)			months)
Without lime	10	190	Without lime	30	900
Low lime content	15	174	Low lime content	25	400
Medium lime content	13	148	Medium lime content	57	320
High lime content	18	55	High lime content	68	110




Figure 1 - Bode diagram for carbon steel reinforcement after 36 months of immersion tests.




Figure 2 - Bode diagram for galvanized steel reinforcement after 36 months of immersion tests.

After cyclic tests, the carbon steel showed the highest corrosion potential (Table 6) and polarization resistance (Table 7) for the mortar with the highest lime content. The lime addition was beneficial to the corrosion resistance of reinforcements. After cyclic tests, the corrosion potential of galvanized steel was higher for the mortar with lime addition than the cement mortar as shown in Table 5, and the polarization resistance was the highest for galvanized steel in mortar with the highest lime content.

However, after 36 months, the polarization resistance of steel in mortars with the highest lime content was the lowest. In the beginning of project, the best corrosion behavior was observed for carbon and galvanized steel in mortars with high content of lime. After 36 months of molding, the highest corrosion resistance of reinforcement was obtained in mortars without lime fooling by mortars with the addition of low and medium lime concentrations.

For the carbon and galvanized steels in mortar, the polarization resistance and corrosion potential increased with time for all samples as shown in Tables 5 to 7. The alkaline content of mortars increased after 36 months of the cyclic test.

After the cyclic tests, the mortars were broken, the final diameters of reinforcements were measured and mortars were analyzed by using X-ray diffraction (XRD) to identify the phases present. The initial diameter of wire was 5 mm. The results of measurement of the final diameter of reinforcements after cyclic tests are shown in Table 8.

Table 8 - Final diameter of carbon and galvanized steel reinforcements in cement and mixed mortars

Samples	Diameter of carbon steel	Diameter of galvanized steel	
without and with lime	(mm)	(mm)	
Without lime (0%)	4.0 ± 0.2	4.5 ± 0.2	
Low content (6.7 wt.%)	4.6 ± 0.3	4.7 ± 0.3	
Medium content (13.3 wt.%)	4.5 ± 0.3	4.6 ± 0.2	
High content (26.3 wt.%)	4.3 ± 0.2	4.5 ± 0.1	

For the carbon steel reinforcements, after the cyclic immersion tests, the final diameter of reinforcement was lower for the cement mortar. This result agrees with the smaller value of the polarization resistance obtained for the carbon steel reinforcement in this condition. The other values of the final diameter of reinforcements obtained by using a gravimetric method are similar.

The phases identified by using XRD were SiO2: 4.2542, 2.4562, 2.2808, 1.8174, 1.6713, 1.5411, 1.3716, 1.1837, 1.1527 (peak values in Å); FeOOH-lepidocrocite: 2.4593, 1.9266, 1.6214; FeO(OH)-tetragonal: 2.2859, 1.3752, 1.1573; Fe2O3: 2.5327, 2.5100, 1.4520; β -FeOOH - akaganeite: 3.333, 2.6344, 2.5502, 1.9540, 2.2952; portlandite, Ca(OH)2: 4.9063, 2.6270, 1.9262, 1.6864 1.4475, 1.2091; CaCO3: 3.8537, 2.8435, 2.2840, 1.9122, 1.8749, 1.2180, 1.1864, 1.1534. The SiO2 and portlandite are usual phases present in mortars and concrete (Yan-Rong et al., 2016). The akageneite is an iron corrosion product which is formed in environments containing chlorides [19].

In galvanized reinforced mortars, ZnO: 2.4760, 1.6260, 1.3790, 1.4770 and Zn(OH)2: 2.2263, 1.374, 1.3868 were found.

Conclusions

Before the cyclic test, there is an increase in corrosion potential of carbon steel and galvanized steel with the lime addition in mortar.

After cyclic tests consisting of immersion in a saline solution and drying at 60oC, the polarization resistance of carbon and galvanized steel increased as the lime content in mortar increased, demonstrating the protective effect of lime.

The corrosion products identified in carbon steel reinforced mortars By using X-ray diffraction, after the cyclic tests, were: FeOOH-lepidocrocite, FeO(OH)-tetragonal, Fe2O3, and β-FeOOH (akageneite). In galvanized reinforced mortars, ZnO and Zn(OH)2 were found besides lepidocrocite, akageneite, FeO(OH)-tetragonal, and Fe2O3.

After 36 months of the cyclic test, the polarization resistance of steel in mortars with the highest content of lime was the lowest. The polarization resistance and corrosion potential increased after 36 months of the cyclic test for all samples.

The reinforcements showed a best corrosion behavior in cement mortar than in mixed mortars after 36 months of the cyclic test.

Acknowledgements

The authors thank the funding agencies Fundação de Amparo à Pesquisa do Estado de Minas Gerais, Conselho Nacional de Desenvolvimento Científico e Tecnológico and Coordenação de Aperfeiçoamento de Pessoal de Nível Superior.

References

- [1] 'Effect of age and level of damage on the autogenous healing of lime mortars', C. De Nardi, A. Cecchi, L. Ferrara, A. Benedetti, D. Cristofori, *Composites Part B: Engineering*, **124**, pp.144–157, 2017.
- [2] 'Natural hydraulic lime versus cement for blended lime mortars for restoration works', B.A. Silva, A.P. Ferreira Pinto, A. Gomes, *Construction and Building Materials*, **94**, pp. 346–360, 2015.
- [3] 'Trass-lime reinforced mortars in strengthening and reconstruction of historical masonry walls', J. Jasieńko, D. Logoń, W. Misztal, *Construction and Building Materials*, **102**, pp. 884-892, 2016.
- [4] 'A study of traditional blood lime mortar for restoration of ancient buildings', S. Fang, K. Zhang, H. Zhang, B. Zhang, Cement and Concrete Research, **76**, pp. 232–241, 2015.
- [5] 'Pore structure and mechanical properties of cement-lime mortars', M. Arandigoyen, J.I. Alvarez, *Cement and Concrete Research*, **37**, pp. 767–775, 2007.
- [6] 'The Influence of Cement on Properties of Lime Mortars', L. Gulbe, I. Vitina, J. Setina, *Procedia Engineering*, **172**, pp. 325–332, 2017.

- [7] 'Study and analysis by means of surface response to fracture behavior in lime-cement mortars fabricated with steelmaking slags', J. García-Cuadrado, A. Rodríguez, I.I. Cuesta, V. Calderón, S. Gutiérrez-González, *Construction and Building Materials*, **138**, 1, pp. 204–213, 2017.
- [8] 'Experimental investigation of the relation between damage at the concrete-steel interface and initiation of reinforcement corrosion in plain and fibre reinforced concrete', A. Michel, A. O. S. Solgaard, B. J. Pease, M. R. Geiker, H. Stang, J.F. Olesen, *Corrosion Science*, 77, pp. 308-321, 2013.
- [9] "The effect of various slaked limes on the microstructure of a lime-cement-sand mortar", Y. Sébaïbi, R.M. Dheilly, B. Beaudoin, M. Quéneudec, *Cement and Concrete Research*, **36**, 5, pp. 971-978, 2006.
- [10] 'Effect of water-repellent admixtures on the behaviour of aerial lime-based mortars', A. Izaguirre, J. Lanas, J.I. Álvarez, *Cement and Concrete Research*, **39**, 11, pp. 1095-1104, 2009.
- [11] 'Addition of cement to lime-based mortars: Effect on pore structure and vapor transport", M.J. Mosquera, B. Silva, B. Prieto, E. Ruiz-Herrera, *Cement and Concrete Research*, **36**, 9, pp. 1635-1642, 2006.
- [12] 'Influence of nanosilica and a polycarboxylate ether superplasticizer on the performance of lime mortars', J.M. Fernández, A. Duran, I. Navarro-Blasco, J. Lanas, R. Sirera, J.I. Alvarez, *Cement and Concrete Research*, **43**, pp. 12-24, 2013.
- [13] 'Ageing of lime mortars with admixtures: Durability and strength assessment", A. Izaguirre, J. Lanas, J.I. Álvarez, *Cement and Concrete Research*, **40**, 7, pp. 1081–1095, 2010.
- [14] 'Effect of maturation time on the fresh and hardened properties of an air lime mortar", H. Paiva, A. Velosa, R. Veiga, V.M. Ferreira, *Cement and Concrete Research*, **40**, 3, pp. 447–451, 2010.
- [15] 'The difference in behaviour between calcitic and dolomitic lime mortars set under dry conditions: The relationship between textural and physical-mechanical properties', A. Arizzi, G. Cultrone, *Cement and Concrete Research*, **42**, 6, pp. 818-826, 2012.

- [16] 'Chloride-induced corrosion on reinforcing steel: from the fundamentals to the monitoring techniques', M.F. Montemor, A.M.P. Simões, M.G.S. Ferreira, *Cement and Concrete Composites*, **25**, 4-5, pp. 491-502, 2003.
- [17] 'Avaliação da aderência dos revestimentos argamassados: uma contribuição à identificação do sistema de aderência mecânico', A. N. Carvalho Jr., PhD Thesis, Universidade Federal de Minas Gerais, Belo Horizonte, Brazil, 331p, available at: http://www.bibliotecadigital.ufmq.br/dspace/handle/1843/ISMS-6NARYH, 2005.
- [18] 'Galvanized Steel Reinforcement in Concrete', S. R. Yeomans, Elsevier, Amsterdam, 2004.
- [19] 'On the formation of β -FeOOH (akaganéite) in chloride-containing environments', C. Rémazeilles, P. Refait, *Corrosion Science*, **49**, 2, pp. 844–857, 2007.