

Visual Evidence Record

Sample Business Park

Building Diagnostic Robotics

Visual evidence record supporting the roof condition assessment.

Building Scanned

Sample Business Park

Location

123 ABC St, Brooklyn, NY

Test Date

May 13th, 2026 10:00 AM

On Site Engineers

BDR Field Team

Headline Findings

53

Roof Condition Index

Fair

Visual Condition

3 years

Remaining Roof Life

MRR Recommendation: **Major Repair Needed**

Remaining Service Life: **3 years**



Contents

1	How to Use This Document	1
1.1	Capture Maps and Photographs	1
1.2	Severity Key	1
2	Visual Anomaly Record	2
2.0.1	Section 1 Anomalies	2
2.0.2	Section 2 Anomalies	7
2.0.3	Section 3 Anomalies	20

| How to Use This Document

| 1.1 Capture Maps and Photographs

For each roof section and defect type, a capture map shows where Roofus acquired each numbered evidence image. The numbered annotated photographs for that defect type follow each map. A capture marker identifies the robot position, not an exact defect bounding-box location.

| 1.2 Severity Key

High — Highest-priority validated repair scope requiring immediate review and corrective planning.

Medium — Near-term corrective scope to include in the next approved repair cycle.

Low — Planned maintenance and lower-priority repairs coordinated with routine work and capital planning.

Condition indices, repair costs, and recommendations are in the **Roof Condition Assessment Report**.

Visual Anomaly Record

For each roof section and defect type, a capture map shows where Roofus acquired the numbered evidence photographs that follow. Each marker identifies a robot capture position, not an exact defect bounding-box location.

2.0.1 Section 1 Anomalies

Debris And Vegetation




Evidence Summary

Total Defects	4
Quantity	4 EA
Repair Priority	Medium


Estimated Repair Cost

\$660.00

Figure 2.1. Section 1 — Debris And Vegetation capture locations



(a) Capture 1 - 1 Defect



(b) Capture 2 - 1 Defect



(c) Capture 3 - 1 Defect



(d) Capture 4 - 1 Defect

Defective Seams




Evidence Summary

Total Defects	5
Quantity	15 LF
Repair Priority	Medium

Estimated Repair Cost

\$216.90

Figure 2.3. Section 1 — Defective Seams capture locations



(a) Capture 1 - 4 Defects



(b) Capture 2 - 1 Defect

Flashed Penetrations



Evidence Summary

Total Defects	4
Quantity	4 EA
Repair Priority	High


Estimated Repair Cost

\$332.44

Figure 2.5. Section 1 — Flashed Penetrations capture locations



(a) Capture 1 - 1 Defect



(b) Capture 2 - 1 Defect



(c) Capture 3 - 1 Defect



(d) Capture 4 - 1 Defect

Improper Equipment Supports



Evidence Summary

Total Defects	29
Quantity	27 EA
Repair Priority	Low

Estimated Repair Cost
\$3,240.00

Figure 2.7. Section 1 — Improper Equipment Supports capture locations



(a) Capture 1 - 1 Defect




(b) Capture 2 - 1 Defect



(c) Capture 3 - 3 Defects



(d) Capture 4 - 3 Defects




(e) Capture 5 - 1 Defect




(f) Capture 6 - 4 Defects



(a) Capture 7 - 1 Defect



(b) Capture 8 - 2 Defects




(c) Capture 9 - 2 Defects



(d) Capture 10 - 1 Defect



(e) Capture 11 - 2 Defects



(f) Capture 12 - 1 Defect




(a) Capture 13 - 2 Defects




(b) Capture 14 - 1 Defect



(c) Capture 15 - 1 Defect



(d) Capture 16 - 1 Defect



(e) Capture 17 - 2 Defects

Patching



Evidence Summary

Total Defects	5
Quantity	100 SF
Repair Priority	Low

Estimated Repair Cost
\$276.60

Figure 2.11. Section 1 — Patching capture locations



(a) Capture 1 - 1 Defect



(b) Capture 2 - 1 Defect



(c) Capture 3 - 2 Defects



(d) Capture 4 - 1 Defect

Base Flashing-Membrane Material



Evidence Summary

Total Defects	1
Quantity	5 LF
Repair Priority	Medium
Estimated Repair Cost	\$42.35

Figure 2.13. Section 1 — Base Flashing-Membrane Material capture locations



(a) Capture 1 - 1 Defect

Ridges




Evidence Summary

Total Defects	2
Quantity	15 SF
Repair Priority	Low

Estimated Repair Cost

\$247.05

Figure 2.15. Section 1 — Ridges capture locations



(a) Capture 1 - 2 Defects

2.0.2 Section 2 Anomalies

Debris And Vegetation



Evidence Summary

Total Defects	33
Quantity	31 EA
Repair Priority	Medium

Estimated Repair Cost

\$5,115.00

Figure 2.17. Section 2 — Debris And Vegetation capture locations



(a) Capture 1 - 1 Defect



(b) Capture 2 - 1 Defect



(c) Capture 3 - 1 Defect



(d) Capture 4 - 1 Defect



(e) Capture 5 - 2 Defects



(f) Capture 6 - 2 Defects




(a) Capture 7 - 1 Defect



(b) Capture 8 - 1 Defect



(c) Capture 9 - 1 Defect



(d) Capture 10 - 1 Defect



(e) Capture 11 - 1 Defect



(f) Capture 12 - 1 Defect




(a) Capture 13 - 2 Defects




(b) Capture 14 - 1 Defect




(c) Capture 15 - 2 Defects



(d) Capture 16 - 1 Defect



(e) Capture 17 - 1 Defect



(f) Capture 18 - 1 Defect



(a) Capture 19 - 1 Defect



(b) Capture 20 - 1 Defect



(c) Capture 21 - 1 Defect




(d) Capture 22 - 1 Defect



(e) Capture 23 - 1 Defect



(f) Capture 24 - 1 Defect



(a) Capture 25 - 1 Defect



(b) Capture 26 - 1 Defect



(c) Capture 27 - 1 Defect



(d) Capture 28 - 1 Defect



(e) Capture 29 - 1 Defect

Base Flashing




Evidence Summary

Total Defects	73
Quantity	250 LF + 80 SF
Repair Priority	High
Estimated Repair Cost	\$4,126.50

Figure 2.23. Section 2 — Base Flashing capture locations



(a) Capture 1 - 1 Defect



(b) Capture 2 - 1 Defect



(c) Capture 3 - 1 Defect




(d) Capture 4 - 2 Defects



(e) Capture 5 - 1 Defect



(f) Capture 6 - 2 Defects




(a) Capture 7 - 1 Defect



(b) Capture 8 - 1 Defect




(c) Capture 9 - 1 Defect




(d) Capture 10 - 1 Defect




(e) Capture 11 - 1 Defect



(f) Capture 12 - 2 Defects




(a) Capture 13 - 1 Defect




(b) Capture 14 - 1 Defect



(c) Capture 15 - 1 Defect



(d) Capture 16 - 1 Defect



(e) Capture 17 - 1 Defect




(f) Capture 18 - 2 Defects



(a) Capture 19 - 1 Defect



(b) Capture 20 - 1 Defect



(c) Capture 21 - 1 Defect



(d) Capture 22 - 1 Defect



(e) Capture 23 - 1 Defect



(f) Capture 24 - 1 Defect



(a) Capture 25 - 1 Defect



(b) Capture 26 - 2 Defects



(c) Capture 27 - 1 Defect



(d) Capture 28 - 1 Defect



(e) Capture 29 - 1 Defect




(f) Capture 30 - 2 Defects



(a) Capture 31 - 2 Defects



(b) Capture 32 - 1 Defect



(c) Capture 33 - 1 Defect



(d) Capture 34 - 1 Defect



(e) Capture 35 - 2 Defects



(f) Capture 36 - 1 Defect



(a) Capture 37 - 1 Defect



(b) Capture 38 - 1 Defect



(c) Capture 39 - 1 Defect




(d) Capture 40 - 1 Defect



(e) Capture 41 - 1 Defect




(f) Capture 42 - 1 Defect



(a) Capture 43 - 1 Defect



(b) Capture 44 - 1 Defect



(c) Capture 45 - 1 Defect



(d) Capture 46 - 1 Defect




(e) Capture 47 - 1 Defect



(f) Capture 48 - 2 Defects




(a) Capture 49 - 2 Defects




(b) Capture 50 - 2 Defects




(c) Capture 51 - 1 Defect



(d) Capture 52 - 1 Defect



(e) Capture 53 - 1 Defect



(f) Capture 54 - 1 Defect



(a) Capture 55 - 1 Defect



(b) Capture 56 - 1 Defect



(c) Capture 57 - 2 Defects



(d) Capture 58 - 1 Defect



(e) Capture 59 - 1 Defect



(f) Capture 60 - 1 Defect



(a) Capture 61 - 1 Defect

Metal Cap Flashing



Evidence Summary

Total Defects	23
Quantity	85 LF + 24 SF
Repair Priority	High

Estimated Repair Cost

\$1,322.65

Figure 2.35. Section 2 — Metal Cap Flashing capture locations



(a) Capture 1 - 1 Defect



(b) Capture 2 - 1 Defect



(c) Capture 3 - 1 Defect



(d) Capture 4 - 1 Defect



(e) Capture 5 - 1 Defect



(f) Capture 6 - 1 Defect



(a) Capture 7 - 1 Defect



(b) Capture 8 - 1 Defect



(c) Capture 9 - 1 Defect



(d) Capture 10 - 2 Defects



(e) Capture 11 - 1 Defect



(f) Capture 12 - 1 Defect



(a) Capture 13 - 1 Defect



(b) Capture 14 - 1 Defect




(c) Capture 15 - 1 Defect



(d) Capture 16 - 1 Defect



(e) Capture 17 - 1 Defect



(f) Capture 18 - 1 Defect




(a) Capture 19 - 1 Defect



(b) Capture 20 - 1 Defect



(c) Capture 21 - 1 Defect



(d) Capture 22 - 1 Defect


Patching



Evidence Summary

Total Defects	33
Quantity	775 SF
Repair Priority	Medium
Estimated Repair Cost	\$2,910.90


Figure 2.40. Section 2 — Patching capture locations



(a) Capture 1 - 1 Defect



(b) Capture 2 - 1 Defect



(c) Capture 3 - 1 Defect



(d) Capture 4 - 3 Defects



(e) Capture 5 - 1 Defect



(f) Capture 6 - 1 Defect



(a) Capture 7 - 1 Defect



(b) Capture 8 - 1 Defect



(c) Capture 9 - 1 Defect



(d) Capture 10 - 2 Defects



(e) Capture 11 - 1 Defect



(f) Capture 12 - 2 Defects



(a) Capture 13 - 2 Defects




(b) Capture 14 - 1 Defect



(c) Capture 15 - 2 Defects




(d) Capture 16 - 1 Defect



(e) Capture 17 - 2 Defects



(f) Capture 18 - 2 Defects




(a) Capture 19 - 1 Defect



(b) Capture 20 - 1 Defect



(c) Capture 21 - 1 Defect



(d) Capture 22 - 1 Defect




(e) Capture 23 - 1 Defect



(f) Capture 24 - 2 Defects

Ponding




Evidence Summary

Total Defects	3
Quantity	2 EA
Repair Priority	Low

Estimated Repair Cost
\$683.85

Figure 2.45. Section 2 — Ponding capture locations



(a) Capture 1 - 1 Defect



(b) Capture 2 - 1 Defect



(c) Capture 3 - 1 Defect

Ridges



Evidence Summary


Total Defects	12
Quantity	150 SF
Repair Priority	Low

Estimated Repair Cost
\$2,619.00

Figure 2.47. Section 2 — Ridges capture locations



(a) Capture 1 - 1 Defect



(b) Capture 2 - 3 Defects



(c) Capture 3 - 1 Defect



(d) Capture 4 - 1 Defect



(e) Capture 5 - 1 Defect



(f) Capture 6 - 1 Defect



(a) Capture 7 - 1 Defect




(b) Capture 8 - 1 Defect



(c) Capture 9 - 2 Defects

Splits



Evidence Summary

Total Defects	1
Quantity	25 SF
Repair Priority	High
Estimated Repair Cost	\$166.74

Figure 2.50. Section 2 — Splits capture locations



(a) Capture 1 - 1 Defect

Defective Seams



Evidence Summary

Total Defects	8
Quantity	35 LF
Repair Priority	Medium
Estimated Repair Cost	\$506.10

Figure 2.52. Section 2 — Defective Seams capture locations



(a) Capture 1 - 2 Defects



(b) Capture 2 - 1 Defect



(c) Capture 3 - 3 Defects




(d) Capture 4 - 1 Defect



(e) Capture 5 - 1 Defect

Surface Deterioration




Evidence Summary

Total Defects	2
Quantity	Not priced
Repair Priority	Not priced
Estimated Repair Cost	Not priced

Figure 2.54. Section 2 — Surface Deterioration capture locations



(a) Capture 1 - 1 Defect



(b) Capture 2 - 1 Defect

2.0.3 Section 3 Anomalies

Debris And Vegetation



Evidence Summary

Total Defects	2
Quantity	2 EA
Repair Priority	Medium

Estimated Repair Cost

\$330.00

Figure 2.56. Section 3 — Debris And Vegetation capture locations



(a) Capture 1 - 1 Defect



(b) Capture 2 - 1 Defect


Improper Equipment Supports



Evidence Summary

Total Defects	5
Quantity	5 EA
Repair Priority	Low
Estimated Repair Cost	\$600.00

Figure 2.58. Section 3 — Improper Equipment Supports capture locations



(a) Capture 1 - 2 Defects



(b) Capture 2 - 1 Defect



(c) Capture 3 - 1 Defect



(d) Capture 4 - 1 Defect

Patching



Evidence Summary

Total Defects	28
Quantity	650 SF
Repair Priority	Medium
Estimated Repair Cost	\$2,441.40

Figure 2.60. Section 3 — Patching capture locations



(a) Capture 1 - 1 Defect



(b) Capture 2 - 2 Defects



(c) Capture 3 - 1 Defect



(d) Capture 4 - 1 Defect



(e) Capture 5 - 2 Defects



(f) Capture 6 - 2 Defects



(a) Capture 7 - 1 Defect




(b) Capture 8 - 1 Defect



(c) Capture 9 - 1 Defect



(d) Capture 10 - 1 Defect




(e) Capture 11 - 3 Defects



(f) Capture 12 - 1 Defect



(a) Capture 13 - 1 Defect



(b) Capture 14 - 1 Defect




(c) Capture 15 - 1 Defect



(d) Capture 16 - 1 Defect



(e) Capture 17 - 2 Defects



(f) Capture 18 - 1 Defect



Defective Seams



Figure 2.65. Section 3 — Defective Seams capture locations



Base Flashing




Figure 2.67. Section 3 — Base Flashing capture locations



(a) Capture 1 - 2 Defects



(b) Capture 2 - 1 Defect



(c) Capture 3 - 3 Defects



(d) Capture 4 - 1 Defect