



WEEK 4: PRACTICAL



23.



24. Root cause is layer 1 fault on R2. Interface FastEthernet0/0 connecting to SW1 was administratively shutdown, causing loss of connectivity between the DNS Server network and PC1 network.


25.

```
Router>ena
Router#conf t
Enter configuration commands, one per line.  End with CNTL/Z.
Router(config)#interface FastEthernet0/0
Router(config-if)#no shutdown

Router(config-if)#
%LINK-5-CHANGED: Interface FastEthernet0/0, changed state to up

%LINEPROTO-5-UPDOWN: Line protocol on Interface FastEthernet0/0, changed state
to up
exit
Router(config)#end
Router#
%SYS-5-CONFIG_I: Configured from console by console
```

26.



27. the fault was at OSI Layer1, physical. Evidence that led to conclusion was red link light.

