
CLUTCH DISC INSPECTION [F66M-R]

id0510q2157500

1. Inspect the lining surface for discoloration and grease adhesion.
2. Inspect the torsion springs for weakness and the rivets for looseness.
3. Using a vernier caliper, measure the depth between the lining surface and the rivet head.

SKYACTIV-G 1.5




am5uuw00003646

SKYACTIV-D 1.5

Minimum clutch disc thickness
0.3 mm {0.01 in}

- If it is less than the minimum, replace the clutch disc.




adejjw00013429

4. Measure the clutch disc runout using a dial gauge.

Maximum clutch disc runout
0.7 mm {0.03 in}

- If it exceeds the maximum, replace the clutch disc.



am3uuw00002096