
Full Website Audit Report

Key Findings & Priorities



Client: Valvanta

Website: valvantadigital.co.za

Prepared by: Valvanta Digital Agency

Methodology

This audit uses Lighthouse in navigation mode with mobile emulation.

Lighthouse version	13.0.1
Audit date	2026-03-07T09:45:29.238967+00:00
Categories tested	performance, seo
Mode	navigation
Device emulation	mobile, desktop
URLs tested	5

Execution config

Config key	Value
only_categories	performance, seo
mobile	mobile emulation + throttling
desktop	desktop preset

Standards Alignment Statement

This report aligns findings to WCAG 2.1 Level A and AA (automated checks only), Google Core Web Vitals, and Google Search Essentials.

This audit reflects automated testing only and does not constitute full legal compliance certification.

Limitations & Scope Disclaimer

This report is based on automated Lighthouse checks and reflects a point-in-time snapshot. It does not replace manual testing, user research, or full compliance reviews.

Findings should be validated in real user conditions and with assistive technologies where applicable.

Tested URLs

All URLs included in this audit run.

#	URL
1	https://valvantadigital.co.za/
2	https://valvantadigital.co.za/about
3	https://valvantadigital.co.za/services/website-design
4	https://valvantadigital.co.za/services/ecommerce
5	https://valvantadigital.co.za/services/social-media-management

Key Findings & Priorities

Prioritisation method: Priorities are assigned by combining (1) user impact indicated by Lighthouse field metrics (especially mobile TBT, main-thread work, transfer size, and server latency), (2) breadth of impact across multiple URLs (site-average patterns and repeated per-URL drivers like large images and heavy scripts), and (3) estimated implementation effort (quick wins such as image compression and script loading strategy ranked above deeper architectural changes).

Issue	Priority	Impact	Effort	Short explanation
Reduce mobile Total Blocking Time by addressing main-thread work (Script Evaluation and long 'Other' tasks)	High	Lower input delay risk on mobile and improve perceived responsiveness; site average mobile TBT is ~294 ms with a peak at 599 ms on a service page, indicating meaningful blocking for some users.	Medium	Across the site, mobile main-thread work averages ~1853 ms, and TBT is materially higher than desktop (~294 ms vs ~5 ms). Per-URL breakdowns show large time in Script Evaluation and 'Other', so reducing JS execution, splitting bundles, and deferring non-critical work should directly reduce blocking.
Optimize images to reduce total transfer size (especially large PNGs and large JPEG hero/content images)	High	Faster load progression and more stable performance on slower networks; images are the largest contributor to bytes (site average ~1.39 MB image transfer, and the homepage is ~3.13 MB images).	Low	Site averages show images dominate transfer. The homepage includes multiple very large PNG assets (e.g., ~810 KB and ~647 KB testimonial icons) plus large JPEGs (~553 KB). Compressing, resizing, and adopting more efficient formats will reduce total bytes and improve Speed Index and general load consistency.
Reduce third-party transfer and mitigate slow third-party origins (notably instagram.com and tag/analytics endpoints)	Medium	Improves reliability and reduces variance in load time and latency; average third-party transfer is ~484 KB and the slowest origins include instagram.com in the server-latency modes.	Medium	Both site-level and per-URL server latency modes frequently include instagram.com and analytics/tag endpoints. Third-party transfer averages ~0.48 MB, and some pages show very large third-party transfer (e.g., ~1.25 MB). Deferring, limiting, or conditionally loading third-party resources can reduce dependency on slower origins.
Investigate and reduce unusually high request counts on some templates (e.g., 82 requests on /about)	Medium	Reduces overhead and improves load efficiency; high request counts can increase connection/setup costs and amplify the effect of any latency.	Medium	While site average requests are ~32, the /about page shows 82 requests on both mobile and desktop. Consolidating assets, removing redundant dependencies, and improving caching strategy should bring request counts closer to the site norm.
Improve baseline server response time for the site origin	Low	Incremental improvement to overall load; site average server latency is ~324-345 ms and the site origin is consistently a major contributor.	High	The site origin (valvantadigital.co.za) shows server response times around ~300-344 ms across multiple pages. Further improvements typically require hosting/runtime tuning, caching, or backend optimizations, which are higher effort and should follow front-end byte and main-thread reductions.