


Address	8252 Agarito Way	Community	University Place
Assigned To	Edgar Mejia	Builder	Beazer

Section	Punch Item	Created By	Due Date
Bathroom #	Need 3 additional clips on down tub, only 1 installed.	Shane Miles	Fri. Nov 22, 2019



Address	8222 Plumbago Way	Community	University Place
Assigned To	Armando Alvarez	Builder	Beazer

Section	Punch Item	Created By	Due Date
Outside	Tape/flash Around tankless water heater	Shane Miles	Fri. Nov 22, 2019



Address	8028 Cornelius Drive	Community	Commodore @ Preston
Assigned To	Ben Testing	Builder	K.Hovnanian

Section	Punch Item	Created By	Due Date
Kitchen	Only need stuff stubout at kitchen gas remove shut off loop	Robert Maner	Fri. Nov 22, 2019




No image
available

Section	Punch Item	Created By	Due Date
Outside	Patio gas option not installed at balcony ^{OBJ}	Robert Maner	Fri. Nov 22, 2019




No image
available

Section	Punch Item	Created By	Due Date
Master Bath #	Need spacers under master toilet flange	Robert Maner	Fri. Nov 22, 2019



Address	5676 Berea Street	Community	Trinity Crossing
Assigned To	Ben Testing	Builder	Lennar

Section	Punch Item	Created By	Due Date
Bathroom #	Install whole tub enclosure, ready	Robert Maner	Fri. Nov 22, 2019



Section	Punch Item	Created By	Due Date
Master Bath #	Install master tub enclosure, ready	Robert Maner	Fri. Nov 22, 2019



No image
available




Address	335 Red Hill Road	Community	Stoney Creek
Assigned To	Carlos Poncio	Builder	Lennar

Section	Punch Item	Created By	Due Date
Outside	Wrap front hose bib and tape exterior	Robert Maner	Fri. Nov 22, 2019



No image available

Section	Punch Item	Created By	Due Date
Water Heater	Sleeve pex at tankless box	Robert Maner	Fri. Nov 22, 2019



Section	Punch Item	Created By	Due Date
Outside	Properly tape and seal all exterior penetrations ^(OB)	Robert Maner	Fri. Nov 22, 2019




No image
available

Section	Punch Item	Created By	Due Date
Outside	Cap Exterior cleanouts	Robert Maner	Fri. Nov 22, 2019



No image
available

Section	Punch Item	Created By	Due Date
Outside	Tape and seal patio gas penetration ^{OBJ}	Robert Maner	Fri. Nov 22, 2019



Section	Punch Item	Created By	Due Date
Outside	WRap hose bib and tape and seal penetrations ^{OBJ}	Robert Maner	Fri. Nov 22, 2019



No image
available


Section	Punch Item	Created By	Due Date
Inside	Secure pex manifold and wall at master closet	Robert Maner	Fri. Nov 22, 2019




Section	Punch Item	Created By	Due Date
Inside	Nail guard half-inch pex in wall at master closet	Robert Maner	Fri. Nov 22, 2019



Section	Punch Item	Created By	Due Date
Master Bath #	Install deck mount at master tub	Robert Maner	Fri. Nov 22, 2019



Section	Punch Item	Created By	Due Date
Master Bath #	Install concrete under master tub [08]	Robert Maner	Fri. Nov 22, 2019



Section	Punch Item	Created By	Due Date
Master Bath #	Install tubs ^{OBJ}	Robert Maner	Fri. Nov 22, 2019



Section	Punch Item	Created By	Due Date
Master Bath #	Properly align master toilet flange rain and secure with screws ^{OBJ}	Robert Maner	Fri. Nov 22, 2019



Section	Punch Item	Created By	Due Date
Inside	Install up tub and insulate P-trap	Robert Maner	Fri. Nov 22, 2019




Section	Punch Item	Created By	Due Date
Inside	Insulate pex lines 2 foot from exterior at kitchen pantry	Robert Maner	Fri. Nov 22, 2019



Section	Punch Item	Created By	Due Date
Kitchen	Protect pex from subflooring	Robert Maner	Fri. Nov 22, 2019



Section	Punch Item	Created By	Due Date
Overall	Two full boxes of PVC fittings in pex insulation left on site	Robert Maner	Fri. Nov 22, 2019



Section	Punch Item	Created By	Due Date
Bathroom #	Down hole showerhead and valve on wrong wall, not installed on marked wall!	Robert Maner	Fri. Nov 22, 2019



Section	Punch Item	Created By	Due Date
Bathroom #	Properly align down hall toilet flange ring and secure with screws	Robert Maner	Fri. Nov 22, 2019



Section	Punch Item	Created By	Due Date
Bathroom #	Install hall tub with concrete and block underneath	Robert Maner	Fri. Nov 22, 2019



Section	Punch Item	Created By	Due Date
Bathroom #	Install spacer under up bath three toilet flange	Robert Maner	Fri. Nov 22, 2019




Section	Punch Item	Created By	Due Date
Bathroom #	Nail guard up bath three toilet supply ^{OBJ}	Robert Maner	Fri. Nov 22, 2019



No image available

Section	Punch Item	Created By	Due Date
Powder Bath #	Need to stubout for up powder toilet	Robert Maner	Fri. Nov 22, 2019



Section	Punch Item	Created By	Due Date
Powder Bath #	Nail guard powder toilet supply	Robert Maner	Fri. Nov 22, 2019

