State Farm
P.O. Box 106169
Atlanta, GA 30348-6169
Fax: 1-844-236-3646
statefarmfireclaims@statefarm.com

Structural Damage Claim Policy

This estimate is priced based on estimated market pricing for the cost of materials, labor, and other factors at the time of the loss.

Adjustments in market pricing and timing of the repairs may impact the final cost of covered repairs. Should you or the contractor you select have questions concerning our estimate, please contact us. If your contractor's estimate is higher than ours, you should contact us prior to beginning repairs. State Farm will work with you and your contractor to determine the actual and necessary cost of covered repairs at the time repairs will be completed, subject to policy terms, conditions and limits.

- We want you to receive quality repair work to restore the damages to your property.
- We will provide you with a detailed estimate of the scope of the damage and costs of repairs. Should the contractor you select have questions concerning our estimate, they should contact your claim representative directly.
- Depending upon the complexity of your repair, our estimate may or may not include an allowance for general contractor's overhead and profit. If you have questions regarding general contractor's overhead and profit and whether general contractor services are appropriate for your loss, please contact your claim representative before proceeding with repairs.
- There may be building codes, ordinances, laws, or regulations that affect the repairs of your property. These items may or may not be covered by your policy. Please contact your claim representative if you have any questions regarding coverage which may be available under your policy.
- State Farm® cannot authorize any contractor to proceed with work on your property. Repairs should proceed only with your authorization.
- State Farm does not guarantee the quality of the workmanship of any contractor or guarantee that the work will be accomplished within any specific time frame.
- It is understood that the contractor is hired by you, our insured, and that they work for you - not State Farm.

If you have any questions or need additional information regarding your claim, please contact your claim representative immediately.

Building Estimate Summary Guide

This summary guide is based on a sample estimate and is provided for reference only.
Please refer to the estimate for specifics of your claim.

State Farm Insurance

Insured:	Smith, Joe & Jane	Estimate:	00-0000-000
Property:	1 Main Street	Claim number:	00-0000-000
	Anywhere, IL 00000-0000	Policy Number:	00-00-0000-0
Type of Loss:	Other	Price List:	ILBL8F_MAR 13
Deductible:	$1,000.00		Restoration/Service/ Remodel F = Factored In, D = Do Not Apply

Summary for Dwelling

Line Item Total [1]			5,953.10
Material Sales Tax	@	10.000% x 1,520.00	
Subtotal			6,105.10
General Contractor Overhead [2]	@	10.0% x 6,105.10	610.51
General Contractor Profit	@	10.0% x 6,105.10	
Replacement Cost Value (Including General Contractor Overhead and Profit [3]			7,326.12
Less Depreciation (Including Taxes) [4]			(832.50)
Less General Contractor Overhead & Profit on Recoverable & Non - recoverable Depreciation			(166.50)
Less Deductible [5]			
Net Actual Cash Value Payment [6]			

Maximum Additional Amounts Available If Incurred:

Total Line Item Depreciation (Including Taxes) [4]	832.50	
Less Non - recoverable Depreciation (Including Taxes) [7]		
Subtotal		312.50
General Contractor O&P on Depreciation	166.50	
Less General Contractor O&P on Non - recoverable Depreciation		
Subtotal		
Total Maximum Additional Amounts Available If Incurred [8]		
Total Amount of Claim If Incurred [9]		

Claim Representative

ALL AMOUNTS PAYABLE ARE SUBJECT TO THE TERMS, CONDITIONS AND LIMITS OF YOUR POLICY.

1. **Line Item Total –** Total value of all line items in the estimate plus possible adjustments for *labor minimums*. *Labor Minimum* is to cover a certain minimum number of hours for drive-time, set up time and applicable administrative costs and repairs.
2. **General Contractor's Overhead and Profit –** General contractor's charge for coordinating your repairs.
3. **Replacement Cost Value (RCV) –** Estimated cost to repair or replace damaged property.
4. **Depreciation –** The decrease in the value of property over a period of time due to wear, tear, condition, and obsolescence. A portion or all of this amount may be eligible for replacement cost benefits.
5. **Deductible –** The insurer will pay for losses, up to the policy limits, in excess of your applicable deductible.
6. **Net Actual Cash Value Payment (ACV) –** The repair or replacement cost of the damaged part of the property less *depreciation* and *deductible.*
7. **Non Recoverable Depreciation –** *Depreciation* applied to items that are not eligible for replacement cost benefits.
8. **Total Maximum Additional Amount if Incurred –** Total amount of recoverable depreciation after actual repair or replacement of the property.
9. **Total Amount of Claim if Incurred –** Total amount of the claim, including *net actual cash value payment and total maximum additional amount available if incurred.*

SAMPLE

State Farm

Insured:	MCKEE, CHARLES	Estimate:	51-80B9-27C
Property:	2355 ROUND TOP DR HONOLULU, HI 96822-2067	Claim Number:	5180B927C
		Policy Number:	51BEN0770
Home:	808-685-1153	Price List:	HIHO28_JAN25 Restoration/Service/Remodel
Cellular:	808-741-6602		
Type of Loss:	Wind Damage		
Deductible:	$500.00		
Date of Loss:	1/30/2025		
Date Inspected:	2/17/2025		

Summary for Coverage A - Dwelling - 35 Windstorm and Hail

Line Item Total	59,821.05
Material Excise Tax	475.55
Subtotal	60,296.60
General Excise Tax	2,841.19
Replacement Cost Value	63,137.79
Less Depreciation (Including Taxes)	(21,722.02)
Less Deductible	(500.00)
Net Actual Cash Value Payment	$40,915.77

Maximum Additional Amounts Available If Incurred:

Total Line Item Depreciation (Including Taxes)	21,722.02		
Replacement Cost Benefits		21,722.02	
Total Maximum Additional Amount Available If Incurred			21,722.02
Total Amount of Claim If Incurred			$62,637.79

Son, Andrew

844-458-4300

ALL AMOUNTS PAYABLE ARE SUBJECT TO THE TERMS, CONDITIONS AND LIMITS OF YOUR POLICY.

Explanation of Building Replacement Cost Benefits
Homeowner Policy
Coverage A - Dwelling - 35 Windstorm and Hail

To:	Name:	MCKEE, CHARLES
	Address:	2355 ROUND TOP DR
	City:	HONOLULU
	State/Zip:	HI, 96822-2067

Insured:	MCKEE, CHARLES	Claim Number:	5180B927C
Date of Loss:	1/30/2025	Cause of Loss:	WIND

Your insurance policy provides replacement cost benefits for some or all of the loss or damage to your dwelling or structures. Replacement cost benefits pays the actual and necessary cost of repair or replacement, without a deduction for depreciation, subject to your policy's limit of liability. To receive replacement cost benefits you must:

1. Complete the actual repair or replacement of the damaged part of the property within two years of the date of loss;
2. Promptly notify us within 30 days after the work has been completed; and
3. Confirm completion of repair or replacement, by submitting invoices, receipts or other documentation to your agent or claim office.

Until these requirements have been satisfied, our payment(s) to you will be for the actual cash value of the damaged part of the property, which may include a deduction for depreciation.

Without waiving the above requirements, we will consider paying replacement cost benefits prior to actual repair or replacement if we determine repair or replacement costs will be incurred because repairs are substantially under way or you present a signed contract acceptable to us.

The estimate to repair or replace your damaged property is $63,137.79 . The enclosed claim payment to you of $40,915.77 is for the actual cash value of the damaged property at the time of loss, less any deductible that may apply. We determined the actual cash value by deducting depreciation from the estimated repair or replacement cost. Our estimate details the depreciation applied to your loss. Based on our estimate, the additional amount available to you for replacement cost benefits (recoverable depreciation) is $ 21,722.02 .

If you cannot have the repairs completed for the repair/replacement cost estimated, please contact your claim specialist prior to beginning repairs.

All policy provisions apply to your claim.

State Farm

MCKEE, CHARLES 51-80B9-27C

Source - Eagle View

Dwelling



Dwelling Roof

4,934.58	Surface Area	49.35	Number of Squares
453.36	Total Perimeter Length		
187.85	Total Hip Length		

	QUANTITY	UNIT PRICE	TAX	RCV	AGE/LIFE CONDITION	DEPREC. DEP %	ACV
1. Modified bitumen roof							
	4.09 SQ	620.09	159.29	2,695.46	25/20 yrs Avg.	(2,156.37) 80.00%	539.09
2. Tear off, haul and dispose of modified bitumen roofing							
	4.09 SQ	83.55	16.10	357.82			357.82
3. Tear off, haul and dispose of comp. shingles - Laminated							
	23.69 SQ	91.96	102.65	2,281.18	25/30 yrs Avg.	(1,824.94) 80.00%	456.24
4. Laminated - comp. shingle rfg. - w/out felt							
	28.00 SQ	341.67	646.71	10,213.47	25/30 yrs Avg.	(8,170.78) 80.00%	2,042.69
Component RFG300 from this line item was priced by ITEL Asphalt Shingle Pricing (ASP) on 27 Feb 2025.							
5. Roofing felt - 15 lb.							
	49.35 SQ	55.48	161.91	2,899.85	25/20 yrs Avg.	(2,319.88) 80.00%	579.97
6. Asphalt starter - universal starter course							
	377.92 LF	2.56	56.77	1,024.25	25/20 yrs Avg.	(819.39) 80.00%	204.86
7. Hip / Ridge cap - Standard profile - composition shingles							
	113.85 LF	7.23	52.16	875.30	25/30 yrs Avg.	(700.24) 80.00%	175.06
8. Drip edge							
	244.00 LF	4.04	63.18	1,048.94	25/35 yrs Avg.	(749.23) 71.43%	299.71
9. Remove Additional charge for high roof (2 stories or greater)							
	27.78 SQ	8.78	11.49	255.40			255.40
10. Additional charge for high roof (2 stories or greater)							
	27.78 SQ	32.64	42.73	949.47			949.47
11. Detach & Reset Solar electric panel - up to 200 watt							
	62.00 EA	345.20	1,008.48	22,410.88			22,410.88
12. Detach & Reset Solar water heater panel - 25-32 SF							
	3.00 EA	1,018.93	144.04	3,200.83			3,200.83
Totals: Dwelling Roof			**2,465.51**	**48,212.85**		**16,740.83**	**31,472.02**

Area Totals: Dwelling

2,665.38 Exterior Wall Area
4,934.58 Surface Area 49.35 Number of Squares 453.36 Total Perimeter Length
187.85 Total Hip Length

Total: Dwelling	**2,465.51**	**48,212.85**	**16,740.83**	**31,472.02**

Second Floor



Master Bedroom **Height: 8'**

615.44 SF Walls 486.53 SF Ceiling
1,101.97 SF Walls & Ceiling 486.53 SF Floor
93.33 LF Ceil. Perimeter 81.75 LF Floor Perimeter

Door	**2' 6" X 6' 8"**	**Opens into Exterior**
Missing Wall	**4' X 8'**	**Opens into STAIRS**
Window	**5' 3" X 4'**	**Opens into Exterior**
Window	**2' 8" X 4'**	**Opens into Exterior**
Door	**5' 10" X 6' 8"**	**Opens into Exterior**
Door	**5' 9" X 6' 8"**	**Opens into Exterior**
Window	**8' 3" X 4'**	**Opens into Exterior**

	QUANTITY	UNIT PRICE	TAX	RCV	AGE/LIFE CONDITION	DEPREC. DEP %	ACV
Ceiling							
13. Additional cost for high wall or ceiling - over 14' to 20'							
	96.00 SF	1.88	8.51	188.99	7/150 yrs Avg.	(8.82) 4.67%	180.17
14. R&R 5/8" drywall - hung, taped, ready for texture							
	160.00 SF	5.51	51.89	933.49	7/150 yrs Avg.	(43.56) 4.67%	889.93
15. Tape joint for new to existing drywall - per LF							
	44.00 LF	18.37	39.18	847.46	7/150 yrs Avg.	(39.55) 4.67%	807.91
16. Texture drywall - light hand texture							
	180.00 SF	2.01	18.02	379.82	7/150 yrs Avg.	(17.72) 4.67%	362.10
17. Additional cost for high wall or ceiling - Over 14'							
	96.00 SF	0.16	0.72	16.08	7/15 yrs Avg.	(7.51) 46.67%	8.57
18. Seal the surface area w/PVA primer - one coat							
	180.00 SF	1.02	9.19	192.79	7/15 yrs Avg.	(89.97) 46.67%	102.82

CONTINUED - Master Bedroom

	QUANTITY	UNIT PRICE	TAX	RCV	AGE/LIFE CONDITION	DEPREC. DEP %	ACV
19. Paint the ceiling - one coat							
	486.53 SF	1.13	29.99	579.77	7/15 yrs Avg.	(270.56) 46.67%	309.21
20. Scaffold - per section (per week)							
	2.00 WK	60.43	5.69	126.55			126.55
21. Scaffolding Setup & Take down - per hour							
	2.00 HR	66.23	6.24	138.70			138.70
1 hour to setup and 1 hr to take down							
22. Detach & Reset Heat/AC register - Mechanically attached							
	2.00 EA	21.13	1.99	44.25			44.25
Walls							
23. Additional cost for high wall or ceiling - over 14' to 20'							
	96.00 SF	1.88	8.51	188.99	7/150 yrs Avg.	(8.82) 4.67%	180.17
24. R&R 1/2" drywall - hung, taped, ready for texture							
	128.00 SF	5.27	39.24	713.80	7/150 yrs Avg.	(33.31) 4.67%	680.49
25. Tape joint for new to existing drywall - per LF							
	16.00 LF	18.37	14.25	308.17	7/150 yrs Avg.	(14.39) 4.67%	293.78
26. Texture drywall - light hand texture							
	150.00 SF	2.01	15.02	316.52	7/150 yrs Avg.	(14.77) 4.67%	301.75
27. Additional cost for high wall or ceiling - Over 14'							
	96.00 SF	0.16	0.72	16.08	7/15 yrs Avg.	(7.51) 46.67%	8.57
28. Seal the surface area w/PVA primer - one coat							
	180.00 SF	1.02	9.19	192.79	7/15 yrs Avg.	(89.97) 46.67%	102.82
29. Paint the walls - one coat							
	615.44 SF	1.13	37.93	733.38	7/15 yrs Avg.	(342.24) 46.67%	391.14
30. Detach & Reset Window sill - stain grade							
	5.00 LF	5.78	1.37	30.27			30.27
31. Stain & finish wood window sill							
	5.00 LF	5.31	1.32	27.87	7/15 yrs Avg.	(13.00) 46.67%	14.87
Floors							
32. R&R Carpet pad							
	486.53 SF	1.08	40.37	565.83	7/10 yrs Avg.	(396.09) 70.00%	169.74
33. Carpet							
	547.25 SF	5.02	220.17	2,967.37	7/10 yrs Avg.	(2,077.16) 70.00%	890.21

CONTINUED - Master Bedroom

	QUANTITY	UNIT PRICE	TAX	RCV	AGE/LIFE CONDITION	DEPREC. DEP %	ACV
Additional							
34. Detach & Reset Switch							
	1.00 EA	30.03	1.42	31.45			31.45
35. Detach & Reset Outlet							
	1.00 EA	30.03	1.42	31.45			31.45
36. Contents - move out then reset - Extra large room							
	1.00 EA	291.60	13.74	305.34			305.34
37. Final cleaning - construction - Residential							
	486.53 SF	0.41	9.40	208.88			208.88
Totals: Master Bedroom			**585.49**	**10,086.09**		**3,474.95**	**6,611.14**



Stairs **Height: 17'**

172.60	SF Walls	21.83	SF Ceiling
194.43	SF Walls & Ceiling	40.67	SF Floor
11.78	LF Ceil. Perimeter	14.00	LF Floor Perimeter

Missing Wall **4' X 17'** **Opens into MASTER_BEDRO**



Subroom: Landing (2) **Height: 12' 6"**

118.34	SF Walls	20.06	SF Ceiling
138.39	SF Walls & Ceiling	20.06	SF Floor
9.47	LF Ceil. Perimeter	9.47	LF Floor Perimeter

Missing Wall **3' 2" X 12' 6"** **Opens into STAIRS**

Missing Wall **6' 3 13/16" X 12' 6"** **Opens into STAIRS2**



Subroom: Stairs2 (1) **Height: 12' 6"**

251.74	SF Walls	42.53	SF Ceiling
294.27	SF Walls & Ceiling	65.76	SF Floor
23.76	LF Ceil. Perimeter	24.73	LF Floor Perimeter

Missing Wall **6' 3 13/16" X 12' 6"** **Opens into LANDING**

	QUANTITY	UNIT PRICE	TAX	RCV	AGE/LIFE CONDITION	DEPREC. DEP %	ACV
38. R&R Carpet pad							
	106.43 SF	1.08	8.83	123.78	7/10 yrs Avg.	(86.64) 70.00%	37.14
39. Carpet							
	196.09 SF	5.02	78.90	1,063.27	7/10 yrs Avg.	(744.30) 70.00%	318.97
Totals: Stairs			**87.73**	**1,187.05**		**830.94**	**356.11**

Area Totals: Second Floor

1,158.12	SF Walls	570.94	SF Ceiling	1,729.06	SF Walls and Ceiling
613.02	SF Floor	618.66	Total Area	129.94	LF Floor Perimeter
613.02	Floor Area	95.00	Exterior Perimeter of Walls	138.34	LF Ceil. Perimeter
723.78	Exterior Wall Area			615.44	Interior Wall Area

Total: Second Floor	**673.22**	**11,273.14**	**4,305.89**	**6,967.25**

First Floor



Living Room **Height: 8'**

796.64	SF Walls	733.78	SF Ceiling
1,530.42	SF Walls & Ceiling	733.78	SF Floor
113.08	LF Ceil. Perimeter	101.83	LF Floor Perimeter

Door	**5' 9" X 6' 8"**	**Opens into Exterior**
Door	**5' 6" X 6' 8"**	**Opens into Exterior**
Window	**8' 3" X 4'**	**Opens into Exterior**



Subroom: Bay (1) **Height: 8'**

98.10	SF Walls	19.67	SF Ceiling
117.77	SF Walls & Ceiling	19.67	SF Floor
12.26	LF Ceil. Perimeter	12.26	LF Floor Perimeter

Missing Wall	**8' 1 3/8" X 8'**	**Opens into LIVING_ROOM**
Window	**2' 1/8" X 4'**	**Opens into Exterior**
Window	**5' X 4'**	**Opens into Exterior**
Window	**2' 1/8" X 4'**	**Opens into Exterior**

QUANTITY	UNIT PRICE	TAX	RCV	AGE/LIFE CONDITION	DEPREC. DEP %	ACV
Ceiling						
40. R&R 5/8" drywall - hung, taped, ready for texture						
64.00 SF	5.51	20.75	373.39	7/150 yrs Avg.	(17.43) 4.67%	355.96
41. Tape joint for new to existing drywall - per LF						
28.00 LF	18.37	24.93	539.29	7/150 yrs Avg.	(25.16) 4.67%	514.13
42. Texture drywall - light hand texture						
80.00 SF	2.01	8.01	168.81	7/150 yrs Avg.	(7.87) 4.67%	160.94
43. Seal the surface area w/PVA primer - one coat						
80.00 SF	1.02	4.09	85.69	7/15 yrs Avg.	(39.99) 46.67%	45.70
44. Paint the ceiling - one coat						
753.45 SF	1.13	46.44	897.84	7/15 yrs Avg.	(418.99) 46.67%	478.85
Walls						
45. Paint part of the walls - one coat						
298.25 SF	1.13	18.38	355.40	7/15 yrs Avg.	(165.86) 46.67%	189.54
Additional						
46. Contents - move out then reset - Extra large room						
1.00 EA	291.60	13.74	305.34			305.34
47. Final cleaning - construction - Residential						
753.45 SF	0.41	14.56	323.47			323.47
Totals: Living Room		**150.90**	**3,049.23**		**675.30**	**2,373.93**

Area Totals: First Floor

894.74	SF Walls	753.45	SF Ceiling	1,648.19	SF Walls and Ceiling
753.45	SF Floor	795.67	Total Area	114.09	LF Floor Perimeter
753.45	Floor Area	128.01	Exterior Perimeter of Walls	125.34	LF Ceil. Perimeter
1,044.08	Exterior Wall Area			894.74	Interior Wall Area

Total: First Floor	**150.90**	**3,049.23**	**675.30**	**2,373.93**

Debris Removal

0.00	SF Walls	0.00	SF Ceiling	0.00	SF Walls & Ceiling
0.00	SF Floor	0.00	SF Short Wall	0.00	LF Floor Perimeter
0.00	SF Long Wall			0.00	LF Ceil. Perimeter

	QUANTITY	UNIT PRICE	TAX	RCV	AGE/LIFE CONDITION	DEPREC. DEP %	ACV
48. Tandem axle dump trailer - per load - including dump fees							
	1.00 EA	316.73	14.92	331.65			331.65
Totals: Debris Removal			**14.92**	**331.65**		**0.00**	**331.65**

Area Totals: Source - Eagle View

2,052.86	SF Walls	1,324.39	SF Ceiling	3,377.25	SF Walls and Ceiling
1,366.46	SF Floor	1,414.33	Total Area	244.04	LF Floor Perimeter
1,366.46	Floor Area	223.01	Exterior Perimeter of Walls	263.68	LF Ceil. Perimeter
4,433.24	Exterior Wall Area			1,510.18	Interior Wall Area
4,934.58	Surface Area	49.35	Number of Squares	453.36	Total Perimeter Length
		187.85	Total Hip Length		

Total: Source - Eagle View	**3,304.55**	**62,866.87**	**21,722.02**	**41,144.85**

Labor Minimums Applied

	QUANTITY	UNIT PRICE	TAX	RCV	AGE/LIFE CONDITION	DEPREC. DEP %	ACV
49. Finish carpentry labor minimum							
	1.00 EA	258.73	12.19	270.92			270.92
Totals: Labor Minimums Applied			**12.19**	**270.92**		**0.00**	**270.92**

Line Item Totals: 51-80B9-27C	**3,316.74**	**63,137.79**	**21,722.02**	**41,415.77**

Grand Total Areas:

2,052.86	SF Walls	1,324.39	SF Ceiling	3,377.25	SF Walls and Ceiling
1,366.46	SF Floor			244.04	LF Floor Perimeter
				263.68	LF Ceil. Perimeter
1,366.46	Floor Area	1,414.33	Total Area	1,510.18	Interior Wall Area
4,433.24	Exterior Wall Area	223.01	Exterior Perimeter of Walls		
4,934.58	Surface Area	49.35	Number of Squares	453.36	Total Perimeter Length
		187.85	Total Hip Length		

Recap of Taxes, Overhead and Profit

	GC Overhead (0%)	GC Profit (0%)	Material Excise Tax (4.712%)	General Excise Tax (4.712%)
Line Items	0.00	0.00	475.55	2,841.19
Total	**0.00**	**0.00**	**475.55**	**2,841.19**


Scatter shingle wind damage
Dwelling Roof
R5 (3)
R4 (6)
R10 (2)
R6 (5)
R11 (4)
R10 (7)
ModBit peeled back

Dwelling



Second Floor

Source - Eagle View - First Floor



First Floor