policy | asc | 16 cm rise, 27 cm tread, 0 mm nosing | 6 steps | seed 29, env 64

Full-flight geometry and trajectory



Progress and corridor tracking



Velocity and pauses | longest 3.62 s



Body orientation



Foot contact and slip proxy



Action changes at policy cadence | aggregate second RMS 0.054



FAIL | case completion 0.0% | falls 0, stalls 32, lateral escapes 0
Representative first-episode trace; source: isaaclab/logs/2026-10-11_01-21-27_easy100-core-checkpoints/result.json
Missing panels mean telemetry was not recorded. Contact-foot speed is a slip proxy; plots alone do not certify smoothness.