NOTE: MIL-STD-407 has been redesignated as a Test Method Standard. The cover page has been changed for Administrative reasons. There are no other changes to this Document.

MIL-STD-407
15 FEBRUARY 1957
SUPERSEDING
NAVSHIPS 250-344-7
JANUARY 1955

DEPARTMENT OF DEFENSE
TEST METHOD

VISUAL INSPECTION GUIDE FOR RUBBER MOLDED ITEMS

AMSC N/A FSC 93GP

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.

**OFFICE OF THE ASSISTANT SECRETARY OF DEFENSE,
WASHINGTON 25, D. C.**

15 FEBRUARY 1957.

Supply and Logistics
VISUAL INSPECTION GUIDE FOR RUBBER MOLDED ITE.MS
MIL-STD-407

1. This standard has been approved by the Department of Defense and is mandatory for use by the Departments of the Army, the Navy, and the Air Force, effective immediately.

2. In accordance with established procedure, the Standardization Division has designated the Ordnance Corps, the Bureau of Ships, and the Air Force, respectively, as Army–Navy-Air Force custodians of this standard.

3. Recommended corrections, additions, or deletions should be addressed to the Standardization Division, Office of the Assistant Secretary of Defense (Supply and Logistics), Washington 25, D. C.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.

FOREWORD

Government material procurement specifications have been primarily concerned with detailing composition, construction and necessary physical requirements. However, little attention has been paid to defining the limits of acceptable quality regarding manufacturing defects other than such generalizations as “the workmanship shall be first class”. In such a diverse industry as that of rubber manufacturing, individual plants vary considerably in their production and quality control techniques. Defects are likely to occur from many causes such as variation in the quality of the basic materials and variations in manufacturing processes and finishing operations. Therefore, the quality generalizations used in this document must of necessity cover a considerable range which represents the best available judgment. This document is issued as a practical yardstick which Inspectors w-ill use to appraise visually the quality of rubber molded items.

Source: https://assist.dla.mil -- Downloaded: 202610-26T07:31Z
Check the source to verify that this is the current version before use.

CONTENTS

1. SCOPE AND PURPOSE ---------- 1
1.1 SCOPE ---------- 1
1.2 PURPOSE ---------- 1
2. REFERENCED DOCUMENTS ---------- 1
2.1 STANDARDS ---------- 1
3. DEFINITIONS ---------- 1
4. DEFECT DESCRIPTIONS AND CLASSIFICATION ---------- 1

TABLES

Table I—Defects Classification

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.

LIST OF FIGURES

1. Air check—location I—major; location II—minor.
2. Air checks—location I—major; location II—major.
3. Trapped air—location I—major; location II—major,
4. Trapped air—location I—major; location II—major,
5. Trapped air—location I—major; location II—minor.
6. Trapped air—location I—major; location II—minor,
7. Blister—location I—major; location II—major.
8. Blister—1ocation I—major; location II—major.
9. Blister—1ocation I—major; location II—major.
10. Blister—1ocation I—major; location II—minor.
11. Blister—1ocation I—major; location II—minor.
12. Blister—1ocation I—major; location II—minor.
13. Bloom, heavy—location I—major; location II—minor.
14. Bloom, heavy-location I—major; location II—minor.
15. Cavity, damaged—location I—major; location II—minor.
16. Cavity, damaged-location I—major; location II—minor.
17. Cavity, damaged—location I—major; location II—minor.
18. Cavity, damaged—location I—major; location II—minor.
19. Cavity, damaged—location I—major; location II—minor.
20. Cavity, damaged—location I—major; location-minor.
21. Cavity, small mold scratch—location I—not a defect; location II—not a defect.
22. Coating, defective—location I—major; location II—major.
23. Coating, defective—location I—major; location II—major.
24. Coating, defective-location I—major; location II—major,
25. Crack—location I—major; location II—major,
26. Crack—1ocation I—major; location II—major,
27. Crack—1ocation I—major; location II—major.
28. Crack—1ocation I—major; location II—minor, .
29. Deformed—location I—major; location II—major. (Upper example is a defective. Lower example is a correct one for comparison.)
30. Deformed—location I—major; location II—minor.
31. Deformed—location I—major; location II—minor,
32. Deformed—location I—major; location II—minor.
33. Bad fill—location I—major; location II—major.
34. Bad fill—location I—major; location II—major.
35. Bad fill-location I—major; location II—major.
36. Poor fill-location I—major; location II—minor.
37. Flash, cured-in—location I—major; location II—major.
38. Flash, cured-in—location I—major; location II—minor.
39. Flow mark—location I—major; location II—minor.
40. Flow mark—location I—major: location II—minor.
41. F1ow mark—location I—major; location II—minor.
42. Flow mark—location I—major; location II—minor.
43. Foreign material—location I—major; location II—major.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.

44. Foreign material—location I—major; location II major.
45. Foreign material—location I—major; location II—minor.
46. Pin hole—location I—major; location II—minor.
47. Pin hole—location I—major; location II—minor.
48. Pin hole—location I—major; location II—minor.
49. Marking not clearly legible—minor.
50. Marking not clearly legible—minor.
51. Marking not clearly legible—minor.
52. Dirty mold—Iocation I—major; location II—minor.
53. Dirty mold—location I—major: location II—minor.
54. Dirty mold—location I—major; location II—minor.
55. Dirty mold—location I–major: location II—minor.
56. Porosity—location I—major; location II—major.
57. Porosity—location I—major; location II—major.
58. Porosity—location I—major: location II—minor.
59. Porosity—location I—major: location II—minor.
60. Off register—location I—major; location II—major.
61. Off register—location I—major; location II—major.
62. Off register—location I major; location II—minor.
63. Off register—location I major; location II—minor.
64. Off register—location I major; location II—minor.
65. Back rind—location I major; location II—major.
66. Back rind—location I major; location II—major.
67. Back rind—location I major; location II—minor.
68. Back rind—location I major; location II—minor.
69. Sprue mark—location I major; location II—major.
70. Sprue mark—location I—major; location II—not a defect.
71. Sprue mark—location I major; location II—not a defect.
72. Trim, buff—location I—major; location II—major.
73. Trim, buff—location I—major; location II—minor.
74. Trim, buff—location I—major; location II—minor.
75. Trim, buff—location I—not a defect; location 2—not a defect.
76. Trim, hand—location I—major: location II—not a defect.
77. Trim, hand—location I—major; location II—not a defect.
78. Trim, hand—location I—major; location II—not a defect.
79. Trim, hand—location I—major; location II—not a defect.
80. Trim, hand—location I—major; location II—not a defect.
81. Trim, machine—location I—major: location II—major.
82. Trim, machine—location I—major; location II—major,
83. Trim, machine—location I—major; location II—major.
84. Trim, machine—location I—major; location II—minor. (Top example is correct for comparison. Bottom example is a defective.)
85. Trim, machine—location I—major; location II—minor.
86. Trim, machine—location I—major; location II—minor.
87. Trim, machine—location I—major; location II—major. (Top example is the defective. Bottom example is a correct one for comparison.)
88. Trim, machine location I—major; location II—major.
89. Trim, machine location I—major; location. II—major.
90. Trim, machine location I—major; location II—major.
91. Trim, tumble—location I—major; location II—major.
92. Trim, tumble—location I—major; location II—not a defect.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.

93. Trim, tumble—location I—major; location II—not a defect.
94. Floating fabric—location I—major; location II—minor.
95. Bad adhesion—location I—major; location II—major.
96. Bad adhesion—location I—major; location II—major.
97. Bad adhesion—location I—major; location II—major.
98. Poor adhesion—location I—major; location II—minor.
99. Poor adhesion—location I—major; location II—minor.
100. Poor adhesion—location I—major; location II—minor.
101. Excessive flash—location I—major; location II—major.
102. Excessive flash—location I—major; location II—major.
103. Excessive flash—location I—major; location II—major.
104. Excessive flash—location I—minor; location II—not a defect,
105. Misplaced (insert)—location I—major; location II—major.
106. Misplaced (insert)—location I—major; location II—major.
107. Missing (insert)—location I—major; location II—major.
108. Missing (insert)—location I—major; location II—major.
109. Rust—location I—major; location II—major.
110. Rust—location I—major; location II—minor.
111. Bad staking—location I—major; location II—major. (Top bolt is the defective. Bottom bolt shows the correct position.)
112. Bad threads—major.
113. Bad threads—major.
114. Bad threads—major. (Top bolt has chafed threads. Bottom bolt is an acceptable example.)
115. Bad threads—major; (Threads in the top bolt are missing. Other bolts are acceptable examples.)
116. Poor threads—minor.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.

1. SCOPE AND PURPOSE

1.1 Scope. This document covers the defects for conventional rubber molded items, that is, articles which are made by curing rubber compounds in a forming mold. Cast plastisol items, "O" rings, pneumatic tires and tubes, molded rubber fuel tanks, ebonite items and items containing cellular rubber are specifically excluded.

1.2 Purpose. The primary objective of this document is to present word descriptions and photographs of possible defects in rubber molded items that may be presented for inspection. In addition it provides a training aid for inspectors.

1.2.1 In general, this document is not intended to take the place of a particular inspection procedure aid which may be provided for inspectors to verify conformance with a particular specification. The quality requirements specified in the basic specification are governing.

2. REFERENCED DOCUMENTS

2.1 Standards

MILITARY

ML-STD-105—Sampling Procedures and Tables for Inspection by Attributes.

MIL-STD-177—Rubber Products, Terms for Visible Defects of.

(Copies of specifications, standards, drawings, and publications required by contractors in connection with specific procurement functions should be obtained from the procuring agency or as directed by the contracting officer.)

3. DEFINITIONS

3.1 The categories, major and minor defects, are as defined in Standard MIL-STD-105.

3.2 Word descriptions of defects used in this standard are in accordance with Standard MIL-STD-177.

3.3 Location I defect. The condition where the imperfection occurs on a primary use part of the item surface as regards dimensional tolerances or physical stress in service.

3.4 Location II defect. The condition where the imperfection does not occur on a primary use part of the item surface as regards dimensional tolerances or physical stress in service.

3.5 Fabric, floating. The condition where a reinforcing fabric is not in the correct position.

3.6 Staking, bad. The condition where an insert is not in the correct position.

4. DEFECT DESCRIPTIONS AND CLASSIFICATION

4.1 Since the classification of certain defects depends on the service requirements of the item, it is imperative that the end use be known before inspection is started. In the majority of cases, the end uses will be apparent or can be readily determined from the procurement document. However, in case of doubt, the cognizant technical bureau or agency (on primes) or the endorsing inspection service (on subs) should be requested to supply this information.

4.2 The classification of defects for molded items is more complex than that for a single-shape, single-application item such as V-belts. Molded items are produced in a nearly infinite variety of sizes and shapes so that there is no common or typical shape for this class of item. Also, these items have several principal end uses or service requirements which are dissimilar in the amount of perfection or quality required. These include the following:

(a) *Flexing* —A primary use where the item undergoes constant or intermittent bending, twisting or deflecting during service such as a vibration isolation mounting.

(b) *Sealing* —A primary use where the item serves as an airtight or watertight closure such as a gasket or a boot.

(c) *Barring (barrier material)* —A primary use where the item serves as an impervious material to passage of a liquid or gas such as a diaphragm or pneumatic closure.,

(d) *Matching* –A primary application for dimensional tolerances where the item must be assembled with mating parts such as a stud mounting or a cable connector.

(e) Protecting-An intermediate use where the item serves as a covering material and physical stress is non-existent or occurs infrequently, such as a brake pedal.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.

(f) *Filling* —Subordinate use where the item serves merely as an interns] space filler and physical stress is non-existent or occurs infrequently.

A molded item may, and frequently does, have two or more of these service requirements in combination.

4.3 It is recognized that the rejection of an inspection lot of molded items for defects which are not commensurate with the dimensional tolerances or degree of quality required by the user can result in an appreciable increase in the cost of production. Also, in some instances the enforcement of very high standards could result in an appreciable decrease in the volume of production. Accordingly, some of the defects in this standard are classified under three categories (major, minor, or acceptable) depending on the type of service requirement Note the definitions of location I and location II defects under definition of terms

4.4 Illustrations. The illustrations of physical defects, as shown on figures 1 through 116 and listed in table I, have been selected as typical ones, it not being feasible to gather examples of all possible defects.

Table I. —*Defects Classification*

Figure No.	Defect		Major	Minor
	ALL RUBBER PARTS			
1	Air check	—location I	x	
		location II		x
2	Air checks—whole surface	—location I	x	
		location II	x	
3	Air trapped—amount shown	—location I	x	
		location II	x	
4	Air trapped—extending through body	—location I	x	
		location II	x	
5 and 6	Air trapped—amount shown	—location I	x	
		location II		x
7, 8 and 9	Blister—extending through body	—location I	x	
		location II	x	
10, 11 and 12	Blister	—location I	x	
		location II		x
13 and 14	Bloom—heavy	—location I	x	
		location II		x
Not shown	Bloom—light	—location I		x
		location II	Not a defect	
	NOTE.—Under certain conditions, for example where ozone resistance is required, bloom necessarily results, and in this case, bloom is not a defect.			
15 through 20	Cavity, damaged	—location I	x	
		location II		x
21	Cavity—small mold scratch	—location I (usually)	Not a defect	
		location II (always)	Not a defect	
22, 23 and 24	Coating, defective (missing)	—location I	x	
		location II	x	
25, 26 and 27	Crack—extending through body	—location I	x	
		location II	x	
28	Crack	—location I	x	
		location II		x
29	Deformed	—location I	x	
		location II	x	
30, 31 and 32	Deformed	—location I	x	
		location II		x

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.

Table I. —*Defects Classification*— Continued

Figure No.	Defect		Major	Minor
	ALL RUBBER PARTS—continued			
33, 34 and 35	Fill, bad	—location I	x	
		location II	x	
36	Fill, poor	—location I	x	
		location II		x
37	Flash, cured in (delamination)	—location I	x	
		location II	x	
38	Flash, cured in (no delamination)	—location I	x	
		location II		x
	Flash, excessive. See "Trim" listings and "Flash, excessive" under "Rubber-Metal parts"			
39, 40, 41 and 42	Flow mark (no internal delamination)	—location I	x	
		location II		x
	With internal delamination this is a major defect in all cases			
43 and 44	Foreign material (extending into body)	—location I	x	
		location II	x	
45	Foreign material (on surface)	—location I	x	
		location II		x
Not shown	Hole (material missing or void through body)	—location I	x	
		location II	x	
46, 47 and 48	Hole pin	—location I	x	
		location II		x
49, 50 and 51	Identification, not clearly legible			x
52, 53, 54 and 55	Mold, dirty	—location I	x	
		location II		x
56 and 57	Porosity (extending into body)	—location I	x	
		location II	x	
58 and 59	Porosity (surface only)	—location I	x	
		location II		x
60 and 61	Register, off (dimensions outside specified limits or where part would not fit in a subsequent assembly).	—location I		
		location II	x	
62, 63 and 64	Register, off (dimensions inside specified limits and defect would not affect subsequent assembly).	—location I	x	
		—location II		x
65 and 66	Rind, back (dimensional distortion or a void extending into body).	—location I	x	
		location II	x	
67 and 68	Rind, back (no dimensional distortion and no internal void).	—location I	x	
		location II		x
69	Sprue mark (excess backrind)	—location I	x	
		location II	x	
70 and 71	Sprue mark (slight projection or recess)	—location I	x	
		location II	Not a defect	
72	Trim, buff (material missing)	—location I	x	
		location II	x	
73 and 74	Trim, buff (small material missing)	—location I	x	
		location II		x
75	Trim, buff (only surface marked)	—location I generally location II always	Not a defect	
Not shown	Trim, hand (material missing or large piece of flash attached).	—location I	x	
		location II	x	
76, 77, 78, 79 and 80	Trim, hand (excess material)	—location I	x	
		location II	Not a defect	

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.

Table I. —*Defects Classification*— Continued

Figure No.	Defect		
	ALL RUBBER PARTS—continued		
81, 82 and 83	Trim, machine (material missing)	—location I	x
		location II	
84, 85 and 86	Trim, machine (small undercut)	—location I	
		location II	x
87, 88, 89	Trim, machine (excess material)	—location I	
		location II	x
Not shown	Trim, machine (small excess material)	—location I	x
	NOTE: Similar to figure 74	location II	
90	Trim, machine (tear)	—location I	
		location II	x
91	Trim, tumble (material missing)	—location I	x
		location II	x
Not shown	Trim, tumble (small material missing)	—location I	
		location II	x
Not shown	Trim, tumble (large excess material)	—location I	x
		location II	x
92 and 93	Trim, tumble (small excess material)	—location I	x
		location II	Not a defect
	FABRIC INSERTS		
Not shown	Fabric broken, delamination or missing	—location I	
		location II	x
Not shown	Fabric, floating (dimensional distortion)	—location I	x
		location II	x
94	Fabric, floating (no dimensional distortion)	—location I	x
		location II	x
	METAL INSERTS		
95, 96 and 97	Adhesion, bad	—location I	x
		location II	x
98, 99 and 100	Adhesion, poor (slight edge break)	—location I	x
		location II	x
101, 102 and 103	Flash, excessive (functional)	—location I	x
		—location II	
104	Flash, excessive (nonfunctional)	—location I	x
		location II	Not a defect
105 and 106	Misplaced	—location I	
		location II	
107 and 108	Missing	—location I	
		location II	
109	Rust (excessive)	—location I	x
		location II	x
110	Rust	—location I	x
		location II	
111	Staking, bad	—location I	x
		location II	x
112, 113, 114, 115	Threads, bad		x
116	Threads, poor		x

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.

Copies of specifications, standards, drawings, and publications required by contractors in connection. with specific procurement functions should be obtained from the procuring agency or as directed by the constructing officer.

Copies of this standard for Military use may be obtained as indicated in the foreword to the Index of Military Specifications and Standards.

Copies of this Standard may be obtained for other than official use by individuals, firms, and contractors from the Superintendent of Documents, U. S. Government Printing Office, Washington 25, D. C.

Both the title and the identifying symbol number should be stipulated when requesting copies of Military Standards.

Notice.—When Government drawings, specifications, or other data are used for any purpose other than in connection with a definitely related Government procurement operation, the United States Government thereby incurs no responsibility, nor any obligation whatsoever; and the fact that the Governmfent may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacturer use or sell any patented invention that may in any way be related thereto.

Custodians:

Army—Ordnance Corps
Navy—Bureau of Ships
Air Force

Other interest:

Army—CEQSigT
Navy—AOr[v]

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 1. *—Air check—location I—major; location II—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 2. *—Air checks—location I—major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 202610-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 3. —*Trapped air—location I—major; location II—major.*

4241820—57—2

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 4. *—Trapped air—location I—major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 5. *—Trapped air—location I—major; location II—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026l0-26T07:31Z
Check the source to verify that this is the currentversion before use.




FIGURE 6. *—Trapped air—location I—major; location II—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 7. *—Blister—location I—major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 8. *—Blister location I—major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 9. *—Blister—location I—major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 10. *—Blister—location I—major; location II—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 11. *—Blister—location I—major; location II—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 12. *—Blister—location I—major; location II—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 13. *—Bloom, heavy—location I—major; location II—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 14. *—Bloom ¡heavy—location I—major; location II—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026¹0-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 15. *—Cavity, damaged—location I—major; location II—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 16. *—Cavity damaged—location I—major; location II—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 17. *—Cavity, damaged—location I—major; location II—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 18. *—Cavity, damaged—location I—major; location II—minor*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 19. *—Cavity, damaged—location I—major; location II—minor.*

4241820—57—3

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 20. *—Cavity, damaged—location I—major; location—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 21. *—Cavity, small mold scratch—location I—not a defect (usually); location II—not a defect.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 22. *—Coating, defective—location I—major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 23. *—Coating, defective—location I—major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 24. *—Coating, defective—location I—major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 25. —*Crack—location I—major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE *26. —Crack—location I—major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 27. *—Crack—location I—major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 28. *—Crack—location I—major; location II—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 29. *—Deformed—location I—major; location II—major. Upper example is a defective. Lower example is a correct one for comparison.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 30. *—Deformed—location I—major. location II—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 31. *—Deformed—location I—major; location II—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 32. *—Deformed—location I—major; location II—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 33. *—Bad fill—location I—major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 34. *—Bad fill—location I—major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 35. *—Bad fill—location I—major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 36. *—Poor fill—location I—major; location II—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 37. *—Flash, cured-in—location I–major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 38. *—Flash, cured-in location I—major; location II—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 39. *—Flow mark—location I—major; location II—minor. With internal delamination this is a major defect in all cases.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 40. *—Flow mark—location I—major; location II—minor. With internal delamination this is a major defect in all cases.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 41. *—Flow mark—location I—major; location II—minor. With internal delamination this is a major defect in all* cases.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 42. *—Flow mark—location I—major; location II—minor. With internal delamination this is a major defect in all cases.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 43. *—Foreign material—location I—major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 44. *—Foreign material—location I—major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 45. *—Foreign material—location I—major; location II—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 46. *—Pin hole—location I—major; location II—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 47. *—Pin hole—location I—major; location II—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 48. *—Pin hole—location I—major; location II—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 49. *—Marking not clearly legible—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 50. *—Marking not clearly legible—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 51. *—Marking not clearly legible—minor.*

4241820—57—5

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 52. *—Dirty mold—location l—major; location II—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 53. *—Dirty mold—location I—major; location II—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 54. *—Dirty mold—location I—major; location II—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 55. *—Dirty mold—location I—major; location II—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 56. *—Porosity—location I—major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 57. *—Porosity—location I—major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 58. *—Porosity—location I—major; location II—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 59. *—Porosity—location I—major; location II—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 60. *—Off register—location I—major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 61. *—Off register— location I—major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 62. *—Off register—location I— major; location II—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 63. *—Off register—location I—major; location II—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 64. *—Off register—location I—major; Iocation II—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 65. *—Back rind—location I—major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 66. *—Back rind—location I—major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 67. *—Back rind—location I—major; location II—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 68. *—Back rind—location I—major; location II—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 69. *—Sprue mark—location I—major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 70. *—Sprue mark—location I—major; location II—not a defect.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 71. *—Sprue mark—location I—major; location II—not a defect.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 72. *—Trim, buff—location I—major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 73. *—Trim, buff—location I—major; location II—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 74. *—Trim, buff—location I—major; location II—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 75. *—Trim, buff—location I—not a defect (generally); location II—not a defect.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 76. *—Trim, hand—location I—major; location II—not a defect.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 77. *—Trim, hand—location I—major; location II—not a defect.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 78. *—Trim, hand—location I—major; location II—not a defect.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 79. *—Trim, hand—location I—major; location II—not a defect.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 80. *—Trim, hand—location I—major; location II—not a defect.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 81. *—Trim, machine—location I—major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 82. *—Trim, machine—location I—major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 83. *—Trim, machine—location I—major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 84. *—Trim, machine—location I—major; location II—minor. Top example is correct for comparison. Bottom example is a defective.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 85. *—Trim, machine—location I—major; location II—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 86. *—Trim, machine—location I—major; location II—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 87. *—Trim, machine—location I—major; location II—major. Top example is the defective. Bottom example is a correct one for comparison.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 88. *—Trim, machine—location I—major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 89. *—Trim, machine—location I—major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 90. *—Trim, machine—location I—major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 91. *—Trim, tumble—location I—major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 92. *—Trim, tumble—location I—major; location II—not a defect.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 93. *—Trim, tumble—location I—major; location II—not a defect.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 94. *—Floating fabric—location I—major; location II—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 95. *—Bad adhesion—location I—major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 96. *—Bad adhesion—location I—major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 97. *—Bad adhesion—location I—major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 98. *—Poor adhesion—location I—major; location II—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 99. *—Poor adhesion—location I—major; location II—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 100. *—Poor adhesion—location I—major; location II—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 101. *—Excessive flash—location I—major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 102. *—Excessive flash—location I—major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 2026l0-26T07:31Z
Check the source to verify that this is the currentversion before use.



FIGURE 103. *—Excessive flash—location I—major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 104. *—Excessive flash—location I—minor; location II—not a defect.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 105. *—Misplaced (insert) location I—major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 106. *—Misplaced (insert) location I—major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 107. *—Missing (insert)—location I—major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 108. *—Missing (insert)—location I—major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 109. *—Rust—location I—major; location II—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 110. *—Rust—location I—major; location II—minor.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 111. *—Bad staking—location I—major; location II—major. Top bolt is the defective. Bottom bolt shows the correct position.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 112. *—Bad threads—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 113. *—Bad threads—major.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.



FIGURE 114. *—Bad threads—major. Top bolt has chafed threads. Bottom bolt is an acceptable example.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 115. *—Bad threads—major. Threads in the top bolt are missing. Other bolts are acceptable examples.*

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.




FIGURE 116. *—Poor threads—minor.*

*U.S. GOVERNMENT PRINTING OFFICE: 1989 - 704-034/14134

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.

STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

(See Instructions – Reverse Side)

1. DOCUMENT NUMBER	2. DOCUMENT TITLE

3a. NAME OF SUBMITTING ORGANIZATION	4. TYPE OF ORGANIZATION *(Mark one)*
	☐ VENDOR
b. ADDRESS *(Street, City, State, ZIP Code)*	☐ USER
	☐ MANUFACTURER
	☐ OTHER *(Specify)*: _____

5. PROBLEM AREAS

a. Paragraph Number and Wording:

b. Recommended Wording:

c. Reason/Rationale for Recommendation:

6. REMARKS

7a. NAME OF SUBMITTER *(Last, First, MI)* – Optional	b. WORK TELEPHONE NUMBER *(Include Area Code)* – Optional
c. MAILING ADDRESS *(Street, City, State, ZIP Code)* – Optional	8. DATE OF SUBMISSION *(YYMMDD)*

DD FORM 82 MAR 1426

PREVIOUS EDITION IS OBSOLETE.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T07:31Z
Check the source to verify that this is the current version before use.