
MILITARY SPECIFICATION SHEET

BOOT, DUST AND WATER SEAL, BUSHING SEAL, TYPE A (FOR TOGGLE SWITCH 0.469 DIAMETER) STYLE 10 (PANEL BUSHING SEAL ONLY)

This specification is approved for use by all Departments and Agencies of the Department of Defense.

The requirements for acquiring the boot described herein shall consist of this specification and the latest issue of MIL-B-5423.



(a)

ALTERNATE CONFIGURATIONS


(a) BOTH VERSIONS ARE ACCEPTABLE AND ARE MUTUALLY INTERCHANGEABLE PROVIDED THEY MEET THE SPECIFIED REQUIREMENTS

© FIGURE 1. Bushing seal style 10.

© denotes changes.

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 202610-17T04:45Z
Check the source to verify that this is the current version before use.



DETAIL OF BUSHING SEAL ASSEMBLY

Inches	mm	Inches	mm
.015	0.38	.420	10.67
.062	1.57	.432	10.97
.072	1.83	.461	11.71
.083	2.11	.472	11.99
.105	2.67	.650	16.51
.120	3.05	.677	17.20

NOTES:
1. Dimensions are in inches.
2. Metric equivalents are given for general information only.
3. Unless otherwise specified, tolerance is ±.015 (0.38 mm) for three place decimals.
4. This seal is intended for use with toggle switches per MIL-S-3950, MIL-S-8834, and MIL-S-83731.
5. Bushing seal to be so assembled that surface marked "Top" is up, or "Bottom" is down.

FIGURE 1. Bushing seal, style 10 - Continued.

Source: https://assist.dla.mil -- Downloaded: 202610-17T04:45Z
Check the source to verify that this is the current version before use.

REQUIREMENTS:

Dimensions and configuration: See figure 1.

Silicone rubber: Grade 50.

Watertightness: The boot (bushing seal) shall be assembled to the test enclosure using a solid bushing of dimensions equivalent to a bushing of an applicable switch (including the non-turn notch). The solid bushing and bushing seal shall be assembled per figure 1. The test shall be conducted in accordance with the "Final" watertightness test of MIL-B-5423, except that the pressure shall be limited to 6 pounds-force per square inch gauge, external pressure only, and no operations are required. At the conclusion of this procedure, the test enclosure shall be examined in the bushing area for evidence of water leakage.

The following tests are not required: Restoring force, durability, sand and dust, vibration, salt spray, endurance and lubricant.

Part number: M5423/16-01.

Custodians:
Army - ER
Navy - AS
Air Force - 85

Review activities:
Army - MI
Navy - EC
Air Force - 11, 99

User activities:
Army - AT, AV, ME
Navy - CG, MC, OS

Preparing activity:
Army - ER

Agent:
DLA - ES

(Project 5930-1335)

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T04:45Z
Check the source to verify that this is the current version before use.