MIL-S-63255C (AR)
28 SEPTEMBER 1985
SUPERSEDING
MIL-S-63255B (AR)
9 October 1981

MILITARY SPECIFICATION

SAFETY AND ARMING DEVICE, GUIDED MISSILE: M143 MECHANICAL PARTS AND ASSEMBLY FOR

This specification is approved for use by the U.S. Army Armament Munitions and Chemical Command, and is available for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 Scope. This specification covers the Quality Assurance Provisions and special requirements for the fabrication of the Mechanical Assembly for the PATRIOT M143 Safety and Arming Device.

2. APPLICABLE DOCUMENTS

2.1 Government documents.

2.1.1 Specifications, standards, and handbooks. Unless otherwise specified, the following specifications, standards, and handbooks of the issue listed in that issue of the Department of Defense Index of Specifications and Standards (DoDISS) specified in the solicitation form a part of this specification to the extent specified herein.

SPECIFICATIONS

MILITARY

MIL-W-46132	- Welding, Fusion, Electron Beam, Process For
MIL-A-48078	- Ammunition, Standard Quality Assurance Provisions, General Specification For

Beneficial comments (recommendations, additions, deletions) and any pertinent data which may be of use in improving this document should be addressed to: Commander, US Army Armament Research and Development Center, Attn: AMSMC-QA, Dover, New Jersey 07801-5001 by using the self-addressed Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or by letter.

FSC: 1336

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

MIL-S-63257 - Safety and Arming Device, GM: M143 Loading, Assembling and Packing For

STANDARDS

MILITARY

MIL-STD-105 - Sampling Procedures and Tables For Inspection by Attributes

MIL-STD-1460 - Soldering of Electrical Connections and Printed Wiring Assemblies, Procedure For

(Copies of specifications, standards, handbooks, drawings, and publications required by manufacturers in connection with specific acquisition functions should be obtained from the contracting activity or as directed by the contracting officer.)

2.1.2 Other Government documents, drawings, and publications. The following other Government documents, drawings, and publications form a part of this specification to the extent specified herein.

DRAWINGS

U.S. ARMY ARMAMENT RESEARCH AND DEVELOPMENT CENTER

9311102 - Mechanical Assembly

2.1.3 Order of precedence. In the event of a conflict between the text of this specification and the references cited herein, the text of this specification shall take precedence.

3. REQUIREMENTS

3.1 Materials. Materials shall be in accordance with applicable drawings, specifications and standards.

3.2 Components and assemblies. The components and assemblies shall comply with all requirements specified on Drawing (Dwg) 9311102 and associated drawings, specifications, and standards.

3.2.1 Base Plate assembly (9311084). The electron beam welds shall withstand a pull of 300 pounds (lbs.), min. without separation or cracking.

3.2.2 "G" Weight assembly (9311082). The bushings shall withstand on axial load of 30 lbs, min. without deforming the hole or moving above flush in the "G" Weight.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

3.2.3 Gear-pinion assemblies (9311736, 9311738, 9311745). The assemblies shall withstand the static axial loads and torques specified on their respective drawings without complete separation.

3.2.4 Delay escapement (9331773). The plates shall not separate when an axial pull of 50 + 1 lbs. is applied in the direction indicated on the drawing.

3.3 Mechanical assembly (9311102). All electrical switching (Rotor and Latch Monitors) shall be simulated by external switching when testing the mechanical assembly only.

3.3.1 Continuity. The electrical resistances shall meet the requirements specified in Table I for the positions indicated:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

TABLE I. Resistance

Identification	Designation	Terminals	Resistance (Ohms) Safe & Locked	Safe & UnLocked	Safe & Locked
Rotor Monitor (Left)	S2 (Left)	E1-E2	GT 20M	GT 20M	0.3 Max
Rotor Monitor (Right	S2 (Right)	E1-E2	GT 20M	GT 20M	0.3 Max
Latch Monitor (Left)	S1 (Left)	E1-E3	1 Max	GT 20M	1 Max
Latch Monitor (Left)	S1 (Left)	E1-E2	GT 20M	1 Max	GT 20M
Latch Monitor (Right)	S1 (Right)	E1-E3	1 Max	GT 20M	1 Max
Latch Monitor (Right)	S1 (Right)	E1-E2	GT 20M	1 Max	GT 20M
Condition Monitor (Left)	S2 (Left)	E4-E3	0.3 Max	0.3 Max	GT 20M
Condition Monitor (Right)	S2 (Right)	E4-E3	0.3 Max	0.3 Max	GT 20M
Detonator Contacts (Left)	S2 (Left)	E5-E6	GT 20M	GT 20M	0.3 Max
Detonator Contacts (Right)	S2 (Right)	E5-E6	GT 20M	GT 20M	0.3 Max
Solenoid (Left)	Left	Across Leads	12.5 to 14.9	Not Required	Not Required
Solenoid (Right)	Right	Across Leads	12.5 to 14.9	Not Required	Not Required

Greater than (GT)

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

3.3.2 Insulation resistance. The insulation resistance shall be not less than 20 megohms when measured between the base plate and the locations (See figure 3) indicated in both positions listed in Table II.

TABLE II. Isolation resistance

	Position	
	Safe & Locked	Armed & Locked
a.	S1 (R) E1	S1 (R) E1
b.	S1 (R) E2	S1 (R) E2
c.	S2 (R) E1	S2 (R) E1
d.	S2 (R) E2	S2 (R) E3
e.	S2 (R) E4	S2 (R) E4
f.	S2 (R) E5	S2 (R) E5
g.	S2 (R) E6	S2 (R) E6
h.	Solenoid (R) Lead*	N/A
i.	S1 (L) E1	S1 (L) E1
j.	S1 (L) E2	S1 (L) E2
k.	S2 (L) E1	S2 (L) E1
l.	S2 (L) E2	S2 (L) E3
m.	S2 (L) E4	S2 (L) E4
n.	S2 (L) E5	S2 (L) E5
o.	S2 (L) E6	S2 (L) E6
p.	Solenoid (L) Lead*	N/A

*Only one lead wire is required.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

3.3.3 Intent-to-launch (ITL). With the Mechanical Assembly in the Safe and Locked position, the resistance measured between Latch Monitor (Right) S1 (Right) E1 to E3 and Latch Monitor (Left) S1 (Left) E1 to E3 shall be 1 ohm maximum. The application of a 25.2 - 1.0V pulse for a duration of 180 ± 10 milliseconds to both sets of solenoid leads connected in parallel shall unlock the Mechanical Assembly. This unlocking shall be indicated by a resistance of 1 ohm (max) when measured between the Latch Monitor (Right) S1 (Right) E1 to E2 and Latch Monitor (Left) S1 (Left) E1 to E2. This measurement shall be taken 215 + 15 milliseconds after the start of the applied pulse.

3.3.4 Detonator rotor arming. Arming is defined as the detonator rotors rotating from the Safe and Unlocked position (See Table I Rotor Monitor Right and Rotor Monitor Left) to the Armed position (See Table I Rotor Monitor Right and Rotor Monitor Left). The Mechanical Assembly shall be Locked in the Armed position (See Table I Latch Monitor Right and Latch Monitor Left) within 300 milliseconds of arming.

3.3.4.1 Detonator rotor arming time. With the Mechanical Assembly in the Safe and Unlocked position, each detonator rotor shall arm in not less than 3.0 seconds and not greater than 4.1 second when the +Z axis (See Figures 1 & 2) is subjected to 11.9 ± 0.2g's at a temperature of 70 ± 18°F.

3.3.5 Non-arming. With the Mechanical Assembly in the Safe and Unlocked position (See Table I), neither detonator rotor shall rotate to the Armed and Locked position (See Table I when subjected to a constant acceleration of 4.0 ± 0.5g in the +Z axis for a period of 20 seconds min (See Figure 1 & 2).

3.3.6 Return to safe. With no simulated g force applied, the Mechanical Assembly shall return to the Safe and Locked position (See Table I Safe & Locked Condition) from the Armed and Locked position (See Table I Armed & Locked Condition) when a Return to Safe Pulse of 35.0 + 1.0V having a duration of 350 ± 150 milliseconds is applied to both solenoids simultaneously (See Figure 3). The Mechanical Assembly may be rearmed and resafed or removed from the test fixture (if used) or placed base down and subjected to additional return to safe pulses or both. The frequency of application of pulses shall not exceed a rate of four (4) pulses per minute.

3.3.7 First article inspection. This specification contains technical provisions for first article inspection. Requirements for the submission of first article shall be as specified in the contact.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

3.4 Workmanship.

3.4.1 General. All parts and assemblies shall be fabricated and loaded in a thorough, workmanlike manner. They shall be free of burrs, chips, sharp edges, unblended radii, cold solder joints, surface defects, cracks, grease, dirt, corrosion products and other foreign matter. The cleaning method used shall not be injurious to any part, nor shall the parts be contaminated by the cleaning agent. Exterior surface coatings shall be continuous except for a few light scratches not exposing base material. All required markings shall be neat and sharply defined.

3.4.2 Molded parts. The molded parts shall be free of porosity, warpage in excess of drawing dimensions, checks, cracks, chipped edges, scratches and other defects which would affect their serviceability.

3.4.3 Adhesives, lubricants and sealants. Adhesives, lubricants or sealants shall not be used in the mechanical assembly if the shelf life is expired or reduced effectiveness is expected due to acceleration aging.

3.4.4 Workmanship of weldments. Weldments shall be free from slag, flux, salt baths residue, cracks, weld spatter and other foreign materials and excess porosity.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for inspection and standard quality assurance provisions. Unless otherwise specified herein or in the contract, the provisions of MIL-A-48078 shall apply and are hereby made a part of this detail specification.

4.2 Classification of inspections. The following types of inspection shall be conducted on this item:

a. First Article Inspection

b. Quality Conformance Inspection

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

4.3 First article inspection

4.3.1 Submission. The contractor shall submit a first article sample for evaluation in accordance with provisions of 4.3.2. The first article sample shall consist of the following items in sample quantities as indicated.

Drawings	Part Description	Quantity
9311020	Switch Board Asembly	6
9311021	Board, Switch	6
9311022	Block, Mounting (Outer Plate)	6
9311027	Rotor, Detonator	6
9311030	Resistor Shorting Plate Detonator Assembly	6
9311031	Shorting Plate Detonator Assembly	6
9311034	Balance Rotor Assembly	6
9311035	Gear, Escapement	6
9311036	Rotor, Balance	6
9311038	Outer Plate Assembly	6
9311039	Plate, Outer	6
9311040	Rotor Latch Assembly	6
9311041	Latch, Rotor	6
9311042	Latch Post Assembly	6
9311043	Post, Latch	6
9311044	Post Assembly	6
9311045	Post	6
9311046	Anchor, Rotor Latch Spring	6

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

9311047	"G" Weight	6
9311049	Bumper	6
9311050	Rail	6
9311051	Spring, Rotor Latch Detent	6
9311054	Spring, "G" Weight Latch Detent	6
9311055	Block, Mounting (Center Plate)	6
9311056	Housing, "G" Weight Latch	6
9311057	Latch, "G: Weight	6
9311058	Housing, Detonator	6
9311059	Top Plate Assembly	6
9311060	Plate, Top	6
9311061	Latch Actuator Solenoid Assembly	6
9311062	Actuator, Latch	6
9311063	Pin "G" Weight Latch	6
9311064	Solenoid, Rotary	6
9311065	Bearing, Rotor Latch Detent	6
9311066	Pin, Rotor Latch	6
9311068	Spring, "G" Weight Latch	6
9311069-1	Boss, Base	6
9311069-2	Boss, Base	6
9311080	Switch, Subminiature	6
9311082	"G" Weight Asembly	6
9311083	Spring, "G" Weight	6
9311084	Base Plate Assembly	6

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

9311086	Detent, Rotor Latch	6
9311087	Detonator Rotor Subassembly	6
9311088	Resistor Shorting Plate Detonator Housing Assy	6
9311089	Board, Stiffener	6
9311092	Bushing	6
9311102	Mechanical Assembly	6
9311103	Plate, Base	6
9311104	Center Plate Assembly	6
9311105	Plate, Center	6
9311349	"G" Weight Latch Housing Assembly	6
9311365	Cable, Subminiature-Switch (Master)	6
9311366	Subminiature-Switch Assembly	6
9311384	Plate, Shorting, Detonator	6
9311385	Plate, Shorting	6
9311400	Spring, Rotor Latch	6
9321559	Detent, "G" Weight Latch	6
9331736	Escapement Gear-Pinion Assembly	6
9331737	Gear, Number 2	6
9331738	No. 2 Gear-Pinion Assembly	6
9331739	Pinion, Escapement	6
9331740	Gear, Escapement	6
9331741	Gear, No. 1	6
9331742	Plate, Top	6
9331743	Plate, Bottom	6

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

9331744	Pinion, No. 1	6
9331745	No. 1 Gear-Pinion Assembly	6
9331746	Shaft, Lever	6
9331750	Pinion, Number 2	6
9331771	Lever Assembly	6
9331773	Delay Escapement	6

4.3.2 Inspections to be performed. The First Article parts submitted in accordance with paragraph 4.3.1 will be subjected by the Government to any or all the requirements of the applicable drawings and to the inspections of Table III. All inspections listed in Table III shall be classified Major unless otherwise specified.

4.3.3 Rejection. See MIL-A-48078.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

TABLE III. First article inspection

CLASSIFICATION OF DEFECTS & TESTS MIL-S-63255C (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.3.4	Safety and Arming Device, GM: M143, Mechanical Assembly, Components and Subassemblies				See 4.3.1
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Mechanical Assembly, Components and Subassemblies (Drawing list - paragraph 4.3.1) Examination for defects	6		3	4.4.2.2 - 4.4.2.73

NOTES:

AMSMC Form 1570, 1 Feb 85 Replaces DRSMC-QA (D) Form 160, 1 Aug 83, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

4.4 Quality conformance inspection.

4.4.1 Inspection lot formation. Inspection lots shall comply with the lot formation provisions of MIL-A-48078.

4.4.2 Examination. See MIL-A-48078.

a. Sampling plans. Unless otherwise specified in the Classification of Defects and Tests Tables, sampling plans for Major and Minor defects shall be in accordance with MIL-STD-105, Inspection Level II.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.1	Switch, Subminiature	1 OF 1	9311080
			NEXT HIGHER ASSEMBLY 9311366

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Operate position of lever		0.40%	3.2	Gage
102	Operating lever not free		0.40%	3.2	Manual
103	Operating force		0.40%	3.2	Gage
Minor					
201	Lever contact surface damage		0.65%	3.2	Visual
202	Adhesive missing over ends of pin in spring lever (2 places)		0.65%	3.2	Visual
203	Terminals not pre-tinned		0.65%	3.2	Visual
204	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63255C (AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.2	Switch Board Assembly		9311020
			NEXT HIGHER ASSEMBLY 9311104

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Location of long contacts		0.40%	3.2	Gage
102	Contacts in line with center hole in operating position, 6 places		0.40%	3.2	Gage
103	Free position of contacts		0.40%	3.2	Gage
104	Evidence of solder bridging prior to application of adhesive		0.40%	3.2	Visual
105	Contacts fail to return to free position after full deflection to board surface		0.40%	3.2	Manual/Gage
106	Contact force at operating position		0.40%	3.2	Gage/Test
Minor					
201	Improper copper wire		0.65%	3.2	Visual
202	Adhesive in area of contact bend or operating		0.65%	3.2	Visual
203	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.3	Board, Switch	1 OF 1	9311021
			NEXT HIGHER ASSEMBLY 9311020

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Diameter of large hole for detonator rotor shaft		0.40%	3.2	Gage
102	Diameter of mounting holes (2 places)		0.40%	3.2	Gage
103	Location of large hole		0.40%	3.2	Gage
104	Location of mounting holes		0.40%	3.2	Gage
105	Evidence of surface conductor irregularities		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63255C (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9311022
4.4.2.4	Block, Mounting (Outer Plate)				NEXT HIGHER ASSEMBLY 9311038
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Location of holes for outer plate mounting (2 places)		0.40%	3.2	Gage
102	Location of mounting hole for lead housing		0.40%	3.2	Gage
103	Pitch diameter of mounting hole for lead housing		0.40%	3.2	Gage
104	Pitch diameter of holes for outer plate mounting (2 places)		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 3		DRAWING NUMBER 9311027
4.4.2.5	Rotor, Detonator				NEXT HIGHER ASSEMBLY 9311087
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Improper color or location of paint		100%	3.2	Visual
Major					
101	Diameter of center shaft (2 placed)		0.40%	3.2	Gage
102	Height of shoulder on gear end		0.40%	3.2	Gage
103	Shoulder to shoulder distance of mid-diameter shaft		0.40%	3.2	Gage
104	Location of screw thread hole in side (2 places)		0.40%	3.2	Gage
105	Pitch diameter of screw threads in side (2 places)		0.40%	3.2	Gage
106	Location of hole for pin		0.40%	3.2	Gage
107	Diameter of hole for pin		0.40%	3.2	Gage
108	Total composition tolerance		0.40%	3.2	Gage

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 2 OF 3		DRAWING NUMBER 9311027
4.4.2.5	Rotor, Detonator				NEXT HIGHER ASSEMBLY 9311087
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Major					
109	Tooth-to-tooth composite tolerance		0.40%	3.2	Gage
110	End of gear teeth to centerline (2 places)		0.40%	3.2	Gage
111	Width of slots (2 places)		0.40%	3.2	Gage
112	Location of slots (2 places)		0.40%	3.2	Gage
113	Location of timing mark		0.40%	3.2	Gage
114	Surface finish on center shaft ends		0.40%	3.2	Gage
115	Location of holes for detonator housing mounting		0.40%	3.2	Gage
116	Pitch diameter of threads for detonator housing mounting (2 places)		0.40%	3.2	Gage
117	Location of hold for lead weight		0.40%	3.2	Gage
118	Depth of hole for lead weight		0.40%	3.2	Gage
Minor					
201	Protective finish missing or improper		0.65%	3.2	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 3 OF 3		DRAWING NUMBER 9311027
4.4.2.5	Rotor, Detonator				NEXT HIGHER ASSEMBLY 9311087
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Minor					
202	Scratches or surface blemishes in paint		0.65%	3.2	Visual
203	Chamfer missing from slots (2 places)		0.65%	3.2	Visual
204	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

AMSMC Form 1570, 1 Feb 85

Replaces DRSMC-QA (D) Form 160, 1 Aug 83, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET	OF	DRAWING NUMBER
4.4.2.6	Resistor Shorting Plate, Detonator Assembly		1	1	9311030
					NEXT HIGHER ASSEMBLY 9311088
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Solder not in accordance with MIL-STD-1460 (3 places)		0.40%	3.2	Visual
Minor					
201	Resistor leads not shorted together		0.65%	3.2	Visual
202	Improper resistor		0.65%	3.2	Visual
203	Improper resistor location		0.65%	3.2	Visual
204	Resistor leads not at top of pin		0.65%	3.2	Visual
205	Terminal pin loose after soldering		0.65%	3.2	Visual
206	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63255C (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9311031
4.4.2.7	Shorting Plate, Detonator Assembly				NEXT HIGHER ASSEMBLY 9311030/9321566
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Solder not in accordance with MIL-STD-1460 (2 places)		0.40%	3.2	Visual
102	Pin inserted from wrong direction		0.40%	3.2	Visual
103	Pin not swaged (2 places)		0.65%	3.2	Visual
Minor					
201	Solder outside marked area		0.65%	3.2	Visual
202	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9311034
4.4.2.8	Balance Rotor Assembly				NEXT HIGHER ASSEMBLY 9311102
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Escapement gear not against rotor or loose		0.40%	3.2	Visual/Manual
102	Pan head screw improperly seated		0.40%	3.2	Visual/Manual
103	Weight		0.40%	3.2	Gage
Minor					
201	Improper screws		0.65%	3.2	Visual
202	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.9	Gear, Escapement	1 OF 1	9311035
			NEXT HIGHER ASSEMBLY 9311034

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Profile of outside diameter		0.40%	3.2	Gage
102	Profile of root diameter		0.40%	3.2	Gage
103	Location of two mounting holes		0.40%	3.2	Gage
104	Diameter of mounting holes		0.40%	3.2	Gage
105	Thickness		0.65%	3.2	Gage
106	Surface finish in gear teeth		0.40%	3.2	Visual
Minor					
201	Protective finish missing, incomplete or improper		0.65%	3.2	Visual
202	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 2		DRAWING NUMBER 9311036
4.4.2.10	Rotor, Balance				NEXT HIGHER ASSEMBLY 93311034
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Diameter of large hole		0.40%	3.2	Gage
102	Diameter of center shaft (2 places)		0.40%	3.2	Gage
103	Shoulder to shoulder distance of mid-diameter		0.40%	3.2	Gage
104	Height of shoulder on gear end		0.40%	3.2	Gage
105	Location of threaded holes (2 places)		0.40%	3.2	Gage
106	Pitch diameter of screw threads (2 places)		0.40%	3.2	Gage
107	Total composite tolerance		0.40%	3.2	Gage
108	Tooth-to-tooth composite tolerance		0.40%	3.2	Gage
109	Location of timing mark		0.40%	3.2	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63255C (AR)

PARAGRAPH	TITLE		SHEET 2 OF 2		DRAWING NUMBER 9311036
4.4.2.10	Rotor, Balance				NEXT HIGHER ASSEMBLY 9311034
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Minor					
201	Surface finish in gear teeth		0.65%	3.2	Visual
202	Surface finish on center shaft ends		0.65%	3.2	Visual
203	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

AMSMC Form 1570, 1 Feb 85

Replaces DRSMC-QA (D) Form 160, 1 Aug 83, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9311038
4.4.2.11	Outer Plate Assembly				NEXT HIGHER ASSEMBLY 9311102
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Rotor latch detent does not move freely		0.40%	3.2	Manual
102	Retaining ring on rotor latch detent missing or not in groove		0.40%	3.2	Visual
103	Mounting block not against plate or loose		0.40%	3.2	Visual
104	Sub-miniature switch orientation incorrect		0.40%	3.2	Visual
105	Sub-miniature switch assembly screws loose		0.40%	3.2	Visual
106	Rotor latch assembly does not move freely		0.40%	3.2	Manual
107	Rotor latch spring not in notch (2 places)		0.40%	3.2	Visual
108	Spacer not present, if necessary, to prevent override of rotor latch by rotor latch detent		0.40%	3.2	Manual
Minor					
201	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63255C (AR)

PARAGRAPH	TITLE		SHEET 1 OF 2		DRAWING NUMBER 9311039
4.4.2.12	Plate, Outer				NEXT HIGHER ASSEMBLY 9311038
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Location of holes (No. 14, 15)	4.5.2	0.40%	3.2	Gage
102	Location of holes (No. 1 thru 13, 17, 19, 20)	4.5.2	0.40%	3.2	Gage
103	Diameter of holes for rotors (No. 12, and 13		0.40%	3.2	Gage
104	Flatness		0.40%	3.2	Gage
105	Location of slot for latch		0.40%	3.2	Gage
106	Length of slot for latch		0.40%	3.2	Gage
107	Width of slot for latch, entire length		0.40%	3.2	Gage
108	Width of radial slot, min.		0.40%	3.2	Gage
109	Pitch diameter of holes for switch mounting (No. 14 and 15)		0.40%	3.2	Gage
110	Thickness		0.40%	3.2	Gage
111	Surface finish on cutout for slide latch		0.40%	3.2	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 2 OF 2		DRAWING NUMBER 9311039
4.4.2.12	Plate, Outer				NEXT HIGHER ASSEMBLY 9311038
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Major					
112	Location of radial slot		0.40%	3.2	Visual
113	Surface finish in holes (No. 12 and 13)		0.40%	3.2	Visual
Minor					
201	Countersink on holes for mounting (No. 5, 6 and 7)		0.65%	3.2	Gage
202	Diameter of holes (No. 1, 2, 3 and 4)		0.65%	3.2	Gage
203	Diameter of holes (No. 8, 9, 10, 11 19 and 20)		0.65%	3.2	Gage
204	Diameter of hole No. 17, min.		0.65%	3.2	Gage
205	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9311040
4.4.2.13	Rotor Latch Assembly				NEXT HIGHER ASSEMBLY 9311038
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Distance from rotor latch to end of pin, max		0.40%	3.2	Visual
102	Evidence of looseness in latch pin		0.40%	3.2	Visual
Minor					
201	Protective finish missing, incomplete or improper (except holes)		0.65%	3.2	Visual
202	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Replaces DRSMC-QA (D) Form 160, 1 Aug 83, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63255C (AR)

PARAGRAPH	TITLE		SHEET 1 OF 2		DRAWING NUMBER 9311041
4.4.2.14	Latch, Rotor				NEXT HIGHER ASSEMBLY 9311040
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Width of parallel slots (2 places)		0.40%	3.2	Gage
102	Distance between bottoms of parallel slots		0.40%	3.2	Gage
103	Pin hole diameter		0.40%	3.2	Gage
104	Location of cutout for sub-miniature		0.40%	3.2	Gage
105	Location of parallel slots		0.40%	3.2	Gage
106	Location of rectangular cutout for actuator latch		0.40%	3.2	Gage
107	Chamfer missing from start of parallel slots (4 places)		0.40%	3.2	Visual
108	Width of slot for spring		0.40%	3.2	Gage
109	Thickness in rectangular cutout		0.40%	3.2	Gage
110	Location of pin hole		0.40%	3.2	Gage
111	Pitch diameter of threaded hole		0.40%	3.2	Gage
112	Surface finish in parallel slots		0.40%	3.2	Visual

REMARKS:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 2 OF 2		DRAWING NUMBER 9311041
4.4.2.14	Latch, Rotor				NEXT HIGHER ASSEMBLY 9311040
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Minor					
201	Radii in rectangular cutout missing		0.65%	3.2	Visual
202	Evidence of poor workmanship		1.0	3.4	Visual

NOTES:

AMSMC Form 1570, 1 Feb 85

Replaces DRSMC-QA (D) Form 160, 1 Aug 83, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 of 1		DRAWING NUMBER 9311042
4.4.2.15	Latch Post Assembly				NEXT HIGHER ASSEMBLY 9311038
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Height of pins for rotor latch spring anchor		0.40%	3.2	Gage
102	Height of pin for "G" weight latch housing		0.40%	3.2	Gage
103	Pin not flush or below		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 2		DRAWING NUMBER 9311043
4.4.2.16	Post, Latch				NEXT HIGHER ASSEMBLY 9311042
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Location of holes	4.5.2	0.40%	3.2	Gage
102	Distance between plate mounting surfaces		0.40%	3.2	Gage
103	Width		0.40%	3.2	Gage
104	Depth (2 places)		0.40%	3.2	Gage
105	Depth to shoulder of top plate mounting surface		0.40%	3.2	Gage
106	Perpendicularity		0.40%	3.2	Gage
107	Pitch diameter, max., outer plate mounting (2 places)		0.40%	3.2	Gage
108	Pitch diameter, max., top plate mounting		0.40%	3.2	Gage
109	Pitch diameter, max., "G" weight latch holder mounting		0.40%	3.2	Gage
110	Pitch diameter, max., side board mounting (2 places)		0.40%	3.2	Gage

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 2 OF 2		DRAWING NUMBER 9311043
4.4.2.16	Post, Latch				NEXT HIGHER ASSEMBLY 9311042
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Major					
111	Diameter of counterbore for base plate mounting		0.40%	3.2	Gage
112	Depth of counterbore for base plate mounting, min.		0.40%	3.2	Gage
Minor					
201	Angle missing on top plate mounting end		0.65%	3.2	Visual
202	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63255C (AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.17	Post Assembly	1 OF 1	9311044
			NEXT HIGHER ASSEMBLY 9311038

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Height of spring pins (2 places)		0.40%	3.2	Gage
102	Spring pin above flush		0.40%	3.2	Visual
Minor					
201	Spring pins loose		0.65%	3.2	Visual
202	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63255C (AR)

PARAGRAPH	TITLE	SHEET 1 OF 2	DRAWING NUMBER
4.4.2.18	Post		9311045
			NEXT HIGHER ASSEMBLY 9311044

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Location of holes	4.5.2	0.40%	3.2	Gage
102	Distance between plate mounting surfaces		0.40%	3.2	Gage
103	Width		0.40%	3.2	Gage
104	Depth (2 places)		0.40%	3.2	Gage
105	Depth to shoulder of top plate mounting surface		0.40%	3.2	Gage
106	Perpendicularity		0.40%	3.2	Gage
107	Pitch diameter, max., outer plate mounting (2 places)		0.40%	3.2	Gage
108	Pitch diameter, max., top plate mounting		0.40%	3.2	Gage
109	Pitch diameter, max., side board mounting (2 places)		0.40%	3.2	Gage
110	Diameter of counterbore for base plate mounting		0.40%	3.2	Gage
111	Depth of counterbore for base plate, mounting, min.		0.40%	3.2	Gage

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 2 OF 2		DRAWING NUMBER 9311045
4.4.2.18	Post				NEXT HIGHER ASSEMBLY 9311044
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Minor					
201	Angle missing on top plate mounting end		0.65%	3.2	Visual
202	Presence of finish in tapped hole on surface indicated		0.65%	3.2	Visual
203	Evidence of poor workmanship		1.0%	3.4	Visual

38

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.19	Anchor, Rotor Latch Spring	1 OF 1	9311046
			NEXT HIGHER ASSEMBLY: 9311038

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Diameter		0.40%	3.2	Gage
102	Location of slots		0.40%	3.2	Gage
103	Width of notch		0.40%	3.2	Gage
104	Depth of notch		0.40%	3.2	Gage
105	Depth of slots		0.40%	3.2	Gage
106	Width of slots		0.40%	3.2	Gage
Minor					
201	Protective finish missing, incomplete or improper		0.65%	3.2	Visual
202	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.20	"G" Weight	1 OF 2	9311047
			NEXT HIGHER ASSEMBLY 9311015

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Height		0.40%	3.2	Gage
102	Width		0.40%	3.2	Gage
103	Height of tang for detent		0.40%	3.2	Gage
104	Thickness of tang for detent		0.40%	3.2	Gage
105	Location of slot for rail		0.40%	3.2	Gage
106	Wall thickness of cutout for rotor pin		0.40%	3.2	Gage
107	Location of latch return ramp		0.40%	3.2	Gage
108	Latch return ramp angle		0.40%	3.2	Gage
109	Surface finish on latch return ramp surface		0.40%	3.2	Visual
110	Surface finish in slot for rail		0.40%	3.2	Visual
111	Width of cutout for detent		0.40%	3.2	Gage

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.20	"G" Weight	2 OF 2	9311047
			NEXT HIGHER ASSEMBLY: 9311015

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Major					
112	Height of cutout for detent		0.40%	3.2	Gage
113	Location of hole for rail		0.40%	3.2	Gage
114	Diameter of holes (2 places)		0.40%	3.2	Gage
115	Height of latch surface		0.40%	3.2	Gage
116	Weight		0.65%	3.2	Scale
Minor					
201	Protective finish missing, incomplete or improper		0.65%	3.2	Visual
202	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil - Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63255C (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9311049
4.4.2.21	Bumper				NEXT HIGHER ASSEMBLY 9311102
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Height		0.40%	3.2	Gage
102	Location of slots (2 places)		0.40%	3.2	Gage
103	Width of slots (2 places)		0.40%	3.2	Gage
104	Width, less shoulder, max.		0.40%	3.2	Gage
105	Depth of center of radius in slot		0.40%	3.2	Gage
106	Height of shoulder, max.		0.40%	3.2	Gage
107	Flatness		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63255C (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9311050
4.4.2.22	Rail				NEXT HIGHER ASSEMBLY 9311102
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Small outside diameter		0.40%	3.2	Gage
102	Length		0.40%	3.2	Gage
103	Straightness		0.40%	3.2	Gage
104	Surface finish		0.40%	3.2	Gage
105	Diameter of head		0.40%	3.2	Gage
106	Concentricity		0.40%	3.2	Gage
107	Thickness of head		0.40%	3.2	Gage
108	Width of head to flat		0.40%	3.2	Gage
Minor					
201	Protective finish missing, incomplete or improper		0.65%	3.2	Gage
202	Chamfer missing		0.65%	3.2	Visual
203	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that 4.3 is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.23	Spring, Rotor Latch Detent	1 OF 1	9311051
			NEXT HIGHER ASSEMBLY 9311038

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Outside radius		0.40%	3.2	Gage
102	Inside radius		0.40%	3.2	Gage
103	Improper configuration		0.40%	3.2	Visual
104	Width of opening for detent		0.40%	3.2	Gage
105	Length from end to center of coil		0.40%	3.2	Gage
Minor					
201	Protective finish missing		0.65%	3.2	Visual
202	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63255C (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9311054
4.4.2.24	Spring, "G" Weight Latch Detent				NEXT HIGHER ASSEMBLY 9311102
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Inside diameter, min.		0.40%	3.2	Gage
102	Loads at compressed heights		0.40%	3.2	Gage
Minor					
201	End improper or open		0.65%	3.2	Visual
202	Protective finish missing		0.65%	3.2	Visual
203	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.25	Block, Mounting (Center Plate)	1 OF 1	9311055
			NEXT HIGHER ASSEMBLY 9311104

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Location of holes for center plate plate mounting (2 places)		0.40%	3.2	Gage
102	Location of hole for lead housing		0.40%	3.2	Gage
103	Pitch diameter of threads (3 places)		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63255C (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9311056
4.4.2.26	Housing "G" Weight Latch				NEXT HIGHER ASSEMBLY 9311349
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Location of mounting holes		0.40%	3.2	Gage
102	Location of large hole		0.40%	3.2	Gage
103	Diameter of countersunk mounting hole		0.40%	3.2	Gage
104	Diameter of large hole		0.40%	3.2	Gage
105	Diameter of non-countersunk hole		0.40%	3.2	Gage
106	Location of slot for latch set pin		0.40%	3.2	Gage
107	Width of slot		0.40%	3.2	Gage
108	Surface finish in slot and large hole		0.65%	3.2	Visual
Minor					
201	Radius around edge of slot missing		0.65%	3.2	Visual
202	Countersink missing		0.65%	3.2	Visual
203	Radius of end of slot missing (2 places)		0.65%	3.2	Visual
204	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.27	Latch, "G" Weight	1 OF 1	9311057
			NEXT HIGHER ASSEMBLY: 9311349

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Outside diameter		0.40%	3.2	Gage
102	Inside diameter		0.40%	3.2	Gage
103	Location of small hole		0.40%	3.2	Gage
104	Pitch diameter		0.40%	3.2	Gage
Minor					
201	Radius missing on solid end		0.65%	3.2	Visual
202	Radius missing on hollow end		0.65%	3.2	Visual
203	Surface finish		0.65%	3.2	Visual
204	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63255C (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9311058
4.4.2.28	Housing, Detonator				NEXT HIGHER ASSEMBLY 9311028/9311088
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Diameter of hole for detonator		0.40%	3.2	Gage
102	Depth of hole for detonator		0.40%	3.2	Gage
103	Location of hole for detonator		0.40%	3.2	Gage
104	Location of mounting holes		0.40%	3.2	Gage
105	Thickness of mounting flange		0.40%	3.2	Gage
106	Location of shorting plate mounting holes		0.40%	3.2	Gage
107	Diameter of shorting plate mounting holes (2 places)		0.40%	3.2	Gage
108	Paint incorrect or improperly located		0.40%	3.2	Visual
109	White "S" missing from green field		0.40%	3.2	Visual
Minor					
201	Sharp edges at intersection of detonator hole and wire feed through hole		0.65%	3.4	Visual
202	Radius missing at detonator hole (2 places)		0.65%	3.2	Gage
203	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.29	Top Plate Assembly		6311059
			NEXT HIGHER ASSEMBLY 9311102

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Spring pin missing, loose or above flush (2 places)		0.40%	3.2	Visual/Manual
102	Solenoid orientation improper		0.40%	3.2	Visual
Minor					
201	Lock nut missing or loose (4 places)		0.65%	3.2	Visual/Manual
202	Screw not protruding through lock nut		0.65%	3.2	Visual
203	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63255C (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9311060
4.4.2.30	Plate, Top				NEXT HIGHER ASSEMBLY 9311059
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Location of holes (No. 1-12 and 17-22)	4.5.2	0.40%	3.2	Gage
102	Location of holes (No. 13-16)	4.5.2	0.40%	3.2	Gage
103	Diameter of "G" weight rail holes (No. 13-16)		0.40%	3.2	Gage
104	Diameter of holes for pins (No. 1, 2, 17, 18, 19, 20		0.40%	3.2	Gage
105	Thickness		0.40%	3.2	Gage
106	Flatness		0.40%	3.2	Gage
107	Distance to flat of "G" weight rail holes (No. 13-16)		0.40%	3.2	Gage
Minor					
201	Countersink improper (4 places)		0.65%	3.2	Visual
202	Protective finish missing, incomplete, or improper		0.65%	3.2	Visual
203	Solenoid stud hole counterbore missing (4 places)		0.65%	3.2	Visual
204	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63255C (AR)

PARAGRAPH	TITLE		SHEET OF		DRAWING NUMBER
4.4.2.31	Latch Actuator Solenoid Assembly Solenoid, Rotary		1 2		9311061/9311064
					NEXT HIGHER ASSEMBLY 9311059
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Distance to latch actuator assembly from bottom of solenoid		0.40%	3.2	Gage
102	Location of latch actuator assembly with mounting studs		0.40%	3.2	Gage
103	Spring pin missing		0.40%	3.2	Visual
104	Stakes missing (3 places)		0.40%	3.2	Visual
	SEQUENCE REQUIRED (105, 106, 107)				
105	Output torque with 2 oz. weight @-40°C		100%	3.2	Test
106	Output torque with 3 oz. weight @-40°C		100%	3.2	Test
107	Output torque with 2.4 oz. weight @ 65.6°C		100%	3.2	Test
108	Parallelism		0.40%	3.2	Gage
109	Exit position of electrical leads		0.40%	3.2	Visual
110	Diameter of rotating shaft		0.40%	3.2	Gage
111	Spring torque @ 2° rotation		0.40%	3.2	Test
112	Spring torque @ 43° rotation, max.		0.40%	3.2	Test
113	Rotation		0.40%	3.2	Gage
114	Stroke direction		0.40%	3.2	Manual
115	Resistance @ 20°C		0.40%	3.2	Test
116	Axial shaft movement, max.		0.40%	3.2	Gage

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63255C (AR)

PARAGRAPH	TITLE		SHEET	OF	DRAWING NUMBER
4.4.2.31	Latch Actuator Solenoid Assembly/ Solenoid, Rotary			2 2	9311061/9311064
					NEXT HIGHER ASSEMBLY 9311059
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Minor					
201	Latch actuator loose on shaft		0.65%	3.2	Manual
202	Height of body, max.		0.65%	3.2	Gage
203	Wire lead length incorrect		0.65%	3.2	Gage
204	Marking missing or incorrect		0.65%	3.2	Visual
205	Improper part number		0.65%	3.2	Visual
206	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil - Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.32	Actuator, Latch	1 OF 1	9311062
			NEXT HIGHER ASSEMBLY 9352739

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Diameter of hole for solenoid rotor shaft		0.40%	3.2	Gage
102	Width of narrow arm		0.40%	3.2	Gage
103	Length of narrow arm		0.40%	3.2	Gage
104	Location of hole on narrow arm		0.40%	3.2	Gage
105	Diameter of hole on narrow arm		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63255C (AR)

PARAGRAPH	TITLE		SHEET 1 of 1		DRAWING NUMBER 9311063
4.4.2.33	Pin, "G" Weight Latch				NEXT HIGHER ASSEMBLY 9311042
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Large outside diameter		0.40%	3.2	Gage
102	Pitch diameter		0.40%	3.2	Gage
103	Length		0.40%	3.2	Gage
Minor					
201	Slot missing		0.65%	3.2	Visual
202	Protective finish missing, incomplete or improper		0.65%	3.2	Visual
203	Undercut missing		0.65%	3.2	Visual
204	Evidence of poor workmanship		1.0	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.34	Actuator, Latch Assembly	1 OF 1	9352739
			NEXT HIGHER ASSEMBLY 9311061

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Pin not flush		0.40%	3.2	Visual
102	Pin extending on wrong side		0.40%	3.2	Visual
103	Pin extended proper distance		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.2	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63255C (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9311065
4.4.2.35	Bearing, Rotor Latch Detent				NEXT HIGHER ASSEMBLY 9310038
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Pitch diameter		0.40%	3.2	Gage
102	Outside diameter of bearing surface		0.40%	3.2	Gage
103	Distance from retainer ring groove to shoulder		0.40%	3.2	Gage
104	Width of retainer ring groove		0.40%	3.2	Gage
105	Diameter of hole for spring pin		0.40%	3.2	Gage
106	Width of slot across shoulder		0.40%	3.2	Gage
107	Depth of slot across shoulder		0.40%	3.2	Gage
108	Surface finish on bearing surface		0.40%	3.2	Visual
109	Shoulder thickness		0.40%	3.2	Gage
110	Location of hole for spring pin		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil - Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.36	Pin, Rotor Latch	1 OF 1	9311066
			NEXT HIGHER ASSEMBLY 9311040

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Large diameter		0.40%	3.2	Gage
102	Small diameter		0.40%	3.2	Gage
103	Surface finish on large diameter and radius		0.40%	3.2	Gage
104	Length of large diameter		0.40%	3.2	Gage
105	Location of outside diameter		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9311068
4.4.2.37	Spring, "G" Weight Latch				NEXT HIGHER ASSEMBLY 9311349
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Outside diameter		0.40%	3.2	Gage
102	Load at compressed height		0.40%	3.2	Gage
Minor					
201	Ends improper or open		0.65%	3.2	Visual
202	Protective finish missing		0.65%	3.2	Visual
203	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER 6311069
4.4.2.38	Boss, Base		NEXT HIGHER ASSEMBLY 9311084

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Pitch diameter		0.40%	3.2	Gage
102	Length, max.		0.40%	3.2	Gage
103	Runout		0.40%	3.2	Gage
104	Large diameter		0.40%	3.2	Gage
105	Small diameter		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63255C (AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.39	"G" Weight Assembly	1 OF 1	9311082
			NEXT HIGHER ASSEMBLY 9311102

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Diameter of holes (2 places, after axial load test)		0.40%	3.2	Gage
102	Bushings not flush or below (2 places, after axial load test		0.40%	3.2	Gage
103	Location of holes		0.40%	3.2	Gage
104	Bushing axial load		0.40%	3.2.3	Test
Minor					
201	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63255C (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9311083
4.4.2.40	Spring, "G" Weight				NEXT HIGHER ASSEMBLY 9311102
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Outside diameter, min.		0.40%	3.2	Gage
102	Load at compressed height		0.40%	3.2	Gage
103	Free length	1/	0.40%	3.2	Gage
104	Load at .900 in.	1/	0.40%	3.2	Gage
105	Load at .210 in.	1/	0.40%	3.2	Gage
Minor					
201	End open		0.65%	3.2	Visual
202	Protective finish		0.65%	3.2	Visual
203	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:
1/ After compressing 10 times to a height of .210 in..

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63255C (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9311084/MIL-W-46132
4.4.2.41	Base Plate Assembly				NEXT HIGHER ASSEMBLY 9311102
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Height of boss	1/	0.40%	3.2	Gage
102	Weld strength (pull test)		2/	3.2.1	4.5.4/Test
103	Perpendicularity		0.40%	3.2	Gage
104	Flatness		0.40%	3.2	Gage
Minor					
201	Boss or weld protruding into groove for cover		0.65%	3.2	Visual
202	Evidence of weld material in threads		0.65%	3.2	Visual
203	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:
1/ 3 specimens at beginning and end of each shift per machine.
2/ Accept machine output on 0 defects and reject on 1 defect.

Source: https://assist.dla.mil -- Downloaded: 2026-02-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.42	Detent, Rotor Latch	1 OF 1	9311086
			NEXT HIGHER ASSEMBLY 9311038

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Diameter of hole		0.40%	3.2	Gage
102	Length from hole to narrow end		0.40%	3.2	Gage
103	Location of notch for latch		0.40%	3.2	Gage
Minor					
201	Thickness		0.65%	3.2	Gage
202	Surface finish in hole and as indicated		0.65%	3.2	Visual
203	Protective finish missing		0.65%	3.2	Visual
204	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63255C (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9311087
4.4.2.43	Detonator Rotor Subassembly				NEXT HIGHER ASSEMBLY 9311102
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Weight		0.40%	3.2	Scale
102	Height of straight pin, max.		0.40%	3.2	Gage
103	Shorting plate not against rotor		0.40%	3.2	Visual
Minor					
201	Incorrect screw		0.65%	3.2	Visual
202	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET	OF	DRAWING NUMBER
4.4.2.44	Resistor Shorting Plate Detonator Housing Assembly		1	1	9311088
					NEXT HIGHER ASSEMBLY 9311102
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Pins not flush or below		0.40%	3.2	Visual
102	Resistor leads against detonator housing		0.40%	3.2	Visual
103	Shorting plate not against detonator housing		0.40%	3.2	Visual
Minor					
201	Excessive adhesive		0.65%	3.2	Visual
202	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil - Downloaded: 2026-02-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63255C (AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.45	Board, Stiffener	1 OF 1	9311089
			NEXT HIGHER ASSEMBLY 9311102

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Location of mounting holes (No. 1, 2, 3, 4)	4.5.2	0.40%	3.2	Gage
102	Location of holes (No. 5 thru 20)	4.5.2	0.40%	3.2	Gage
103	Location of cutout in side, 2 places		0.40%	3.2	Gage
104	Diameter of mounting holes (No. 1, 2, 3, 4)		0.40%	3.2	Gage
Minor					
201	Edge chamfer missing		0.65%	3.2	Visual
202	Radius missing on edge (4 places)		0.65%	3.2	Visual
203	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.46	Bushing	1 OF 1	9311092
			NEXT HIGHER ASSEMBLY: 9311090

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Large outside diameter		0.40%	3.2	Gage
102	Length, max.		0.40%	3.2	Gage
103	Diameter of hole		0.40%	3.2	Gage
104	Location of hole		0.40%	3.2	Gage
105	Finish in hole		0.40%	3.2	Visual
Minor					
201	Chamfer missing (2 places)		0.65%	3.2	Visual
202	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-02-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63255C (AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.47	Mechanical Assembly (Prior to Outer Plate Assembly)	1 OF 1	9311102
			NEXT HIGHER ASSEMBLY 9311101

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Timing marks not aligned properly		0.40%	3.2	Visual
102	Detonator rotor and balance rotor gear teeth do not engage when rotated		0.40%	3.2	Visual/Manual
103	Balance rotor and escapement gear teeth do not engage when rotated		0.40%	3.2	Visual/Manual
104	Top plate to center plate screws missing or not fully seated		0.40%	3.2	Visual
105	Center plate to top plate locating pins above flush		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.48	Mechanical Assembly (Prior to "G" Weight Assembly)	1 OF 1	9311102
			NEXT HIGHER ASSEMBLY 9311101

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Solenoid actuator not engaged in rotor latch (2 places)		0.40%	3.2	Visual
102	Rotor latch assembly and rotor latch detent do not move freely upon manual operation of solenoid actuator (2 places)		0.40%	3.2	Visual/Manual
103	Outer plate to top plate locating pins above flush (4 places)		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-02-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63255C (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9311102
4.4.2.49	Mechanical Assembly				NEXT HIGHER ASSEMBLY 9311101
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	"G" weight springs missing (2 places)		0.40%	3.2	Visual
102	"G" weight latch detent springs missing (2 places)		0.40%	3.2	Visual
Minor					
201	Evidence of scratched or damaged rails		0.65%	3.2	Visual
202	Base plate screws missing or not fully seated (6 places)		0.65%	3.2	Visual
203	Flex cable damaged or broken		0.65%	3.2	Visual
204	Board stiffener screws missing (4 places)		0.65%	3.2	Visual
205	Board stiffener washers missing (3 places)		0.65%	3.2	Visual
206	Board stiffener insulated washer missing (1 place)		0.65%	3.2	Visual
207	Serial number missing		0.65%	3.2	Visual
208	Bumper oriented incorrectly		0.65%	3.2	Visual
209	Board stiffener not flush with top plate		0.65%	3.2	Visual
210	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	OF	DRAWING NUMBER
4.4.2.50	Mechanical Assembly (Electrical/ Mechanical Operation)	1	1	9311102
				NEXT HIGHER ASSEMBLY 9311101

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Continuity (Safe and Locked)		100%	3.3.1	Test
102	Insulation resistance (Safe and Locked)		100%	3.3.2	Test
103	Intent-to-launch (ITL)		100%	3.3.3	Test
104	Continuity (Safe and Unlocked)		100%	3.3.1	Test
105	Detonator rotor arming		100%	3.3.4	4.5.5/Test
106	Continuity (Armed and Locked)		100%	3.3.1	Test
107	Insulation resistance (Armed and Locked)		100%	3.3.2	Test
108	Return to safe		100%	3.3.6	Test
109	Non-arming		100%	3.3.5	4.5.6/Test

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-02-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET 1 OF 2	DRAWING NUMBER 9311103
4.4.2.51	Plate, Base		NEXT HIGHER ASSEMBLY 9311084

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Location of mounting holes (No.1, 2, 3, 4)	4.5.2	0.40%	3.2	Gage
102	Location of holes (No. 9 through 20)	4.5.2	0.40%	3.2	Gage
103	Diameter of four warhead mounting holes (No.1, 2, 3, 4)		0.40%	3.2	Gage
104	Location of warhead orientation notch		0.40%	3.2	Gage
105	Distance between slots for cover (2 places)		0.40%	3.2	Gage
106	Depth of lead output holes (No. 13, 14)		0.40%	3.2	Gage
107	Depth of holes (No. 9, 10, 11, 12, 15, 16)		0.40%	3.2	Gage
108	Depth of holes (No. 17, 18, 19, 20)		0.40	3.2	Gage
109	Flatness		0.40%	3.2	Gage
110	Depth of slot for cover		0.40%	3.2	Gage
111	Outside dimension (2 places)		0.40%	3.2	Gage
112	Location of holes (No. 5, 6, 7, 8)		0.40%	3.2	Gage

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63255C (AR)

PARAGRAPH	TITLE	SHEET 2 OF 2	DRAWING NUMBER 9311103
4.4.2.51	Plate, Base		NEXT HIGHER ASSEMBLY 9311084

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Minor					
201	Radius missing, outside corners		0.65%	3.2	Visual
202	Width of slot for cover		0.65%	3.2	Gage
203	Countersink missing, improper side or breaking through (No. 5, 6, 7, 8)		0.65%	3.2	Visual
204	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assistdla.mil -- Downloaded: 2026-01-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63255C (AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.52	Center Plate Assembly	1 OF 1	9311104
			NEXT HIGHER ASSEMBLY 9311102

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Delay escapement loose or not against center plate		0.40%	3.2	Visual/Manual
102	Mounting screws for switch board loose or not against board		0.40%	3.2	Visual/Manual
103	Mounting block loose		0.40%	3.2	Manual
104	Escapement locating pin above flush (2 places)		0.40%	3.2	Visual
Minor					
201	Evidence of adhesive in bearing surface		0.40%	3.2	Visual
202	Evidence of distortion or damage to electrical contacts		0.65%	3.2	Visual
203	Evidence of excess adhesive		0.65%	3.2	Visual
204	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026/10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE			SHEET 1 OF 2	DRAWING NUMBER 9311105
4.4.2.53	Plate, Center				NEXT HIGHER ASSEMBLY 9311104
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Location of holes (No. 1 through 4)	4.5.2	0.40%	3.2	Gage
102	Location of holes (No. 5 through 12, 23 and 24)	4.5.2	0.40%	3.2	Gage
103	Location of holes (No. 13 through 22)	4.5.2	0.40%	3.2	Gage
104	Diameter of holes for rotors (No. 9, 10, 11, and 12)		0.40%	3.2	Gage
105	Flatness		0.40%	3.2	Gage
106	Perpendicularity		0.40%	3.2	Gage
107	Pitch diameter of threads for top plate mounting (No. 3 and 4)		0.40%	3.2	Gage
108	Pitch diameter of threads for switch board mounting (No. 13, 14, 15 and 16)		0.40%	3.2	Gage
109	Thickness		0.40%	3.2	Gage
110	Height		0.40%	3.2	Gage
111	Parallelism		0.40%	3.2	Gage
112	Diameter of escapement locating pin holes (No. 23 and 24)		0.40%	3.2	Gage

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63255C (AR)

PARAGRAPH	TITLE		SHEET 2 OF 2		DRAWING NUMBER 9311105
4.4.2.53	Plate, Center				NEXT HIGHER ASSEMBLY 9311104
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Minor					
201	Mounting block hole countersink on improper side or missing (No. 17, 18, 19 and 20)		0.65%	3.2	Visual
202	Protective finish improper, incomplete or missing		0.65%	3.2	Visual
203	Depth of hole for standoff mounting, max. (2 places)		0.65%	3.2	Visual
204	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.54	"G" Weight Latch Housing Assembly	1 OF 1	9311349
			NEXT HIGHER ASSEMBLY 9311102

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Latch does not move freely		0.40%	3.2	Visual
102	"G" weight latch pin loose		0.40%	3.2	Visual
103	Spring missing		0.40%	3.2	Visual
Minor					
201	Excessive lubricant		0.65%	3.2	Visual
202	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Replaces DRSMC-QA (D) Form 160, 1 Aug 83, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET	DRAWING NUMBER
4.4.2.55	Cable, Subminiature Switch		1 OF 1	9311365
				NEXT HIGHER ASSEMBLY 9311366

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Plating on pads missing (both ends)		0.40%	3.2	Visual
102	Breaks in circuitry		0.40%	3.2	Visual
103	Delamination		0.40%	3.2	Visual
104	Tears or nicks in outside edge		0.40%	3.2	Visual
105	Cover layer length		0.40%	3.2	Gage
106	Location of holes		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9311366
4.4.2.56	Sub-Miniature Switch Assembly				NEXT HIGHER ASSEMBLY 9311038
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Soldered in accordance with MIL-STD-1460 except that no solder flux was used		0.40%	3.2	Visual
102	Incorrect switch orientation on cable		0.40%	3.2	Visual
103	Cable delamination after soldering		0.40%	3.2	Visual
Minor					
201	Cable cocked on switch		0.65%	3.2	Visual
202	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63255C (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9311384
4.4.2.57	Plate, Shorting, Detonator				NEXT HIGHER ASSEMBLY 9311031
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Location of mouting holes		0.40%	3.2	Gage
102	Diameter of mounting holes		0.40%	3.2	Gage
103	Diameter of holes for terminal pins		0.40%	3.2	Gage
104	Thickness		0.40%	3.2	Gage
105	Contacts not flush or above		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil - Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63255C (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9311385
4.4.2.58	Plate, Shorting				NEXT HIGHER ASSEMBLY 9311087
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Location of mounting holes		0.40%	3.2	Gage
102	Diameter of countersunk holes (2 places)		0.40%	3.2	Gage
103	Thickness		0.40%	3.2	Gage
104	Contacts not flush or above		0.40%	3.2	Visual
Minor					
201	Improper countersink		0.65%	3.2	Gage
202	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63255C (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9311400
4.4.2.59	Spring, Rotor Latch				NEXT HIGHER ASSEMBLY 9311038
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major	None defined				
Minor					
201	Inside diameter of loop		0.65%	3.2	Gage
202	Length, short leg		0.65%	3.2	Gage
203	Length, long leg		0.65%	2.1	Gage
204	Angle between legs		0.65%	3.2	Gage
205	Diameter of wire		0.65%	3.2	Gage
206	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9321559
4.4.2.60	Detent, "G" Weight Latch				NEXT HIGHER ASSEMBLY 9311102
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Diameter of hole		0.40%	3.2	Gage
102	Location of hole		0.40%	3.2	Gage
103	Width of corner cutout		0.40%	3.2	Gage
104	Depth of corner cutout		0.40%	3.2	Gage
105	Width of center cutout		0.40%	3.2	Gage
106	Height of center cutout		0.40%	3.2	Gage
107	Thickness of tang for "G" weight		0.40%	3.2	Gage
108	Width		0.40%	3.2	Gage
109	Width of extension with smaller outside radius		0.40%	3.2	Gage
Minor					
201	Angle missing		0.65%	3.2	Visual
202	Full outside radii missing from extensions (2 places)		0.65%	3.2	Visual
203	Depth of counterbore		0.65%	3.2	Gage
204	Diameter of counterbore		0.65%	3.2	Gage
205	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-02-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9331736
4.4.2.61	Escapement Gear-Pinion Assembly				NEXT HIGHER ASSEMBLY 9331773
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Gap between gear and pinion		0.40%	3.2	Gage
102	Static axial load		0.40%	3.2.3	Test
103	Perpendicularity		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil - Downloaded: 2026-02-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9331737
4.4.2.62	Gear, Number 2				NEXT HIGHER ASSEMBLY 9331773
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Gear profile	1/	0.40%	3.2	Gage
102	Plating improper		0.40%	3.2	Test
Minor					
201	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:
1/ Sample size per MIL-STD-105, level S-1.

Source: https://assist.dla.mil - Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9331738
4.4.2.63	No. 2 Gear-Pinion Assembly				NEXT HIGHER ASSEMBLY 9331773
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Gap between gear and pinion	1/	0.40%	3.2	Gage
102	Static axial load		0.40%	3.2.3	Test
103	Perpendicularity		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

1/ Sample size per MIL-STD-105, level S-1.

Source: https://assist.dla.mil - Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63255C (AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.64	Pinion, Escapement		9331739
			NEXT HIGHER ASSEMBLY 9331773

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Pinion profile		0.40%	3.2	Gage
102	Plating improper	1/	0.40%	3.2	Test
Minor					
201	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:
1/ Sample size per MIL-STD-105, level S-1.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63255C (AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.65	Gear, Escapement	1 OF 1	9331740
			NEXT HIGHER ASSEMBLY 9331773

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Concentricity		0.40%	3.2	Gage
102	Gear profile		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63255C (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9331741
4.4.2.66	Gear, No. 1				NEXT HIGHER ASSEMBLY 9331773
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Gear profile	1/	0.40%	3.2	Gage
102	Plating improper		0.40%	3.2	Test
Minor					
201	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES: 1/ Sample size per MIL-STD-105, level S-1.

AMSMC Form 1570, 1 Feb 85 Replaces DRSMC-QA (D) Form 160, 1 Aug 83, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63255C (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9331743
4.4.2.67	Plate, Bottom				NEXT HIGHER ASSEMBLY 9331773
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Location of locating pin hole		0.40%	3.2	Gage
102	Pitch diameter		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63255C (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9331744
4.4.2.68	Pinion, No. 1				NEXT HIGHER ASSEMBLY 9331773
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Pinion profile	1/	0.40%	3.2	Gage
102	Plating improper		0.40%	3.2	Test
Minor					
201	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:
1/ Sample size per MIL-STD-105, level S-1.

AMSMC Form 1570, 1 Feb 85

Replaces DRSMC-QA (D) Form 160, 1 Aug 83, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63255C (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9331745
4.4.2.69	No. 1 Gear-Pinion Assembly				NEXT HIGHER ASSEMBLY 9331773
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Static axial load	1/	0.40%	3.2.3	Test
102	Perpendicularity		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:
1/ Sample size per MIL-STD-105, level S-1.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.70	Shaft, Lever	1 of 1	9331746
			NEXT HIGHER ASSEMBLY 9331773

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Surface finish improper	1/	0.40%	3.2	Gage
102	Plating		0.40%	3.2	Test
Minor					
201	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES:
1/ Sample size per MIL-STD-105, level S-1.

Replaces DRSMC-QA (D) Form 160, 1 Aug 83, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63255C (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9331750
4.4.2.71	Pinion, Number 2				NEXT HIGHER ASSEMBLY 9331773
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Pinion profile	1/	0.40%	3.2	Gage
102	Plating improper		0.40%	3.2	Test
Minor					
201	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES: 1/ Sample sie per MIL-STD-105, level S-1.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63255C (AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.72	Lever Assembly	1 OF 1	9331771
			NEXT HIGHER ASSEMBLY 9331773

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Staking missing	1/	0.40%	3.2.2	Test
102	Lever pallet load	1/	0.40%	3.2	Test
Minor					
201	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES: 1/ Sample size per MIL-STD-105, level S-4.

Source: https://assist.dla.mil - Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-63255C (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9331773
4.4.2.73	Delay Escapement				NEXT HIGHER ASSEMBLY 9311104
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Axial pull of assembly	1/	0.40%	3.2.3	Test
102	Component misalignment		0.40%	3.2	Gage
103	Stake missing or above flush		0.40%	3.2	Visual
104	Escapement run-in after lubrication		100%	3.2	Visual
Minor					
201	Evidence of poor workmanship		1.0%	3.4	Visual

NOTES: 1/ Sample size per MIL-STD-105, level S-1.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

4.4.3 Testing. Testing is described in the First Article and Quality Conformance Inspection Tables.

4.4.4 Inspection equipment. The inspection equipment required to perform the examinations and tests prescribed herein is described in the "Paragraph Reference/Inspection Method" column in the tables starting with paragraph 4.4.2.1. The contractor shall submit for approval inspection equipment designs in accordance with the terms of the contract. See section 6 of MIL-A-48078 and 6.3 herein.

4.5 Methods of inspection

4.5.1 Molded components. At the start of production from a new mold or after adjustment or repair to a mold, consecutively produced units from each mold shall be dimensionally examined until four (4) consecutive units meet all applicable drawing requirements. After adjustment or repair, those dimensions affected by the adjustment or repair shall be examined. As a control of each cavity during production, three (3) parts from each cavity shall be inspected for all applicable drawing requirements after continuous production of each 5,000 parts or at the end of each week, whichever occurs first. Of the three (3) samples, one (1) sample shall be the last part produced. If any defective parts are found, that portion of production since the last control check shall be inspected for each separate type of defect.

4.5.2 Numerical control parts. In place of normal sampling associated with classification of defects, consecutively produced parts shall be dimensionally examined until four (4) consecutive parts meet all applicable drawing requirements when either a tape is prepared or changed. During production, one piece part from each four (4) hours production shall be inspected for the location of the first and last hole drilled of each size. If the sample piece part fails, all other items in that production lot shall be screened for each type of defect.

4.5.3 Stamped parts. In place of the normal sampling associated with the Classification of Defects, a sample of at least ten (10) parts shall be dimensionaly inspected to qualify the tool used in the stamping process for use in production. In addition, a random sample of five (5) parts shall be selected from the last portion of each hour's production for dimensional inspection as a control of the tool during production.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

4.5.4 Electron beam welds. A test specimen for this weldmer shall be manufactured of the identical materials, dimensions, and fit dimensions as the Base Plate Assembly except that the locatic and number of bosses on the base plate may vary. Three specimens (bosses) shall be welded at the beginning and end of each shift c each welding machine. An acceptable weld shall meet the requirements of drawing 9311084 and shall not exhibit evidence of cracking. Any specimen failing to meet these requirements shall be classed defective, and the production of that shift be rejecte and removed from the lot.

4.5.5 Procedure for detonator rotor arming test.

4.5.5.1 Initial conditions. The following conditions shall exist and be verified prior to start of test.

a. Mechanical Assembly Safe and Unlocked

b. S2 (L) E3 to E4 Closed

c. S2 (R) E3 to E4 Closed

d. S1 (L) E1 ro E2 Closed

e. S1 (R) E1 to E2 Closed

4.5.5.2 Dynamic conditions. The test equipment shall retair the Mechanical Assembly in a position such that its +Z axis initially is subjected to 0 + 0.2g's while the X or Y axis is being subjected to an acceleration level of 11.9 $\pm$ 0.2g's ("Out-of-Line" See figure 2a). When the test acceleration level has been attained, the test equipment shall smoothly transition the +Z axis of the Mechanical Assembly 90 $\pm$ 2°, within a period of time not greater than 100msec, to the condition where the Mechanical Assembly +Z axis is now experiencing the test acceleration level ("In-Line" See figure 2b). The Mechanical Assembly Device shall be positioned such that the axis of rotatic of the test equipment is through the center of gravity (CG). Record the times as specified in 3.3.4.1.

4.5.6 Procedure for non-arming test.

4.5.6.1 Initial conditions. The following conditions shall exist and be verified prior to start of test.

a. Mechanical Assembly Safe & Unlocked

b. S2 (L) E3 to E4 Closed

Source: https://assist.dla.mil -- Downloaded: 202610-26T04:26Z
Check the source to verify that this is the currentversion before use.

c. S2 (R) E3 to E4 Closed

d. S1 (L) E1 to E2 Closed

e. S1 (R) E1 to E2 Closed

4.5.6.2 Dynamic conditions. The test equipment shall preposition the +Z axis of the Mechanical Assembly (see figure 1) in the g field (see figure 2b) and subject the +Z axis to a constant 4.0 + 0.5g acceleration. The Mechanical Assembly shall not arm as specified in 3.3.5. At the completion of this test the test equipment shall increase the acceleration on the +Z axis to a level that will allow both detonators to Arm and Lock. The test equipment shall not exceed a g level of 12.1g's.

5. PACKAGING - Not applicable

6. NOTES.

6.1 Intended use. This specification is intended to be used in conjunction with MIL-S-63257, Safety and Arming Device, GM: M143 Loading, Assembling and Packing For. In the event of conflict, MIL-S-63257 shall take precedence.

6.2 Ordering data. See MIL-A-48078.

6.3 Submission of designs for approval. See 6.2.3 of MIL-A-48078. Submit equipment designs, as required, to Commander, US Army Armament, Research and Development Center, ATTN: AMSMC-QAR-I (D), Dover, New Jersey 07801-5001.

6.4 Drawings. Drawings listed in Section 2 of this specification under the heading US Army Armament Research and Development Center (ARDC) may also include drawings prepared by and identified as Edgewood Arsenal, Frankford Arsenal, Rock Island Arsenal, Picatinny Arsenal or ARRADCOM drawings. Technical data originally prepared by these activities is new under the cognizance of ARDC.

6.5 Changes from previous issue. Asterisks are not used in this revision to identify changes with respect to the previous issue due to the extensiveness of the changes.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.




Figure 1

Mechanical assembly orientation

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.




Figure 2 a & b

Patriot S&A orientation on centrifuge arm

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.




Figure 3

Top view (mechanical assembly)

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project: 1336-A499)

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

;TRUCTIONS: In a continuing effort to make our standardization documents better, the DoD provides this form for use in mitting comments and suggestions for improvements. All users of military standardization documents are invited to provide gestions. This form may be detached, folded along the lines indicated, taped along the loose edge *(DO NOT STAPLE)*, and led. In block 5, be as specific as possible about particular problem areas such as wording which required interpretation, was rigid, restrictive, loose, ambiguous, or was incompatible, and give proposed wording changes which would alleviate the blems. Enter in block 6 any remarks not related to a specific paragraph of the document. If block 7 is filled out, an nowledgement will be mailed to you within 30 days to let you know that your comments were received and are being sidered.

TE: This form may not be used to request copies of documents, nor to request waivers, deviations, or clarification of cification requirements on current contracts. Comments submitted on this form do not constitute or imply authorization waive any portion of the referenced document(s) or to amend contractual requirements.

(Fold along this line)

(Fold along this line)

ARTMENT OF THE ARMY

NO POSTAGE NECESSARY IF MAILED IN THE UNITED STATES

ICIAL BUSINESS
ALTY FOR PRIVATE USE $300

BUSINESS REPLY MAIL
FIRST CLASS PERMIT NO. 12062 WASHINGTON D C.
POSTAGE WILL BE PAID BY THE DEPARTMENT OF THE ARMY

Commander
US Army Armament Research &
Development Center
ATTN: AMSMC-QA
Dover, NJ 07801-5001

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

(See Instructions – Reverse Side)

1. DOCUMENT NUMBER	2. DOCUMENT TITLE
MIL-S-63255C (AR)	

3a. NAME OF SUBMITTING ORGANIZATION	4. TYPE OF ORGANIZATION *(Mark on*
	☐ VENDOR
b. ADDRESS *(Street, City, State, ZIP Code)*	☐ USER
	☐ MANUFACTURER
	☐ OTHER *(Specify)*:

5. PROBLEM AREAS

a. Paragraph Number and Wording:

b. Recommended Wording:

c. Reason/Rationale for Recommendation:

6. REMARKS

7a. NAME OF SUBMITTER *(Last, First, MI)* – Optional	b. WORK TELEPHONE NUMBER *(Incl Code)* – Optional
c. MAILING ADDRESS *(Street, City, State, ZIP Code)* – Optional	8. DATE OF SUBMISSION *(YYMMDD)*

(TO DETACH THIS FORM, CUT ALONG THIS LINE.)

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.