


The Fix: `max-width: 100%` vs `width: 100%`

Controlling image scaling in Responsive Web Design


Scenario 1: Container < Native Image

Both properties behave exactly the same: they scale the image down proportionally.



Scenario 2: Container > Native Image (The Danger Zone)

Native Image Size: 300px. Container Size: 800px.



Why it fails:

`width: 100%` is an absolute command. It forces the 300px image to stretch across 800px, causing severe interpolation.

Why it succeeds:

`max-width: 100%` acts as a safety limit. It says: "Grow to fit the container, **BUT** do not exceed your native file size."