



South-facing · unobstructed




sDA 59.0% mean DA 56.1% · ASE 19.8%
5 × 6 m room · window 2.21 × 1.70 m · sill 0.80 m
Warsaw · case A-00076

North-facing · unobstructed




sDA 37.5% mean DA 33.9% · ASE 0.0%
5 × 6 m room · window 2.21 × 1.70 m · sill 0.80 m
Warsaw · case A-01156

South-facing · street H/W = 1.0



sDA 15.4% mean DA 16.1% · ASE 10.8%
5 × 6 m room · window 2.21 × 1.70 m · sill 0.80 m
Warsaw · case A-00346

North-facing · street H/W = 1.0



sDA 12.9% mean DA 12.0% · ASE 0.0%
5 × 6 m room · window 2.21 × 1.70 m · sill 0.80 m
Warsaw · case A-01426

