CIRCUIT INSPECTION

DIB0D-01

Power source circuit


CIRCUIT DESCRIPTION

When the ignition switch is turned to the ACC position, battery positive voltage is applied to the terminal ACC of the ECU.

Also, if the ignition switch is turned to the ON position, battery positive voltage is applied to the terminals ACC and IG of the ECU.

When the battery positive voltage is applied to the terminal IG of the ECU while the theft deterrent system is activated, the warning stops.

Furthermore, power supplied from the terminals ACC and IG of the ECU is used as power for the door courtesy switch, position switch, etc.



INSPECTION PROCEDURE

1[]

Check ECU-B2 and SECURITY fuse.

CHECK:

Check@ontinuity@f@ECU-B2@and@SECURITY@use.

OK:

Continuity

NG

Replace faulty fuse.

OK

2[]

Check[voltage[between[terminals]]+B1,]-B2[and[E[of[theft[deterrent[ECU[connector.

PREPARATION:

(a) Turn the ignition switch OFF.

(b) Disconnect the theft deterrent ECU connector.

CHECK:

Measure[]he[]voltage[]between[]erminals[]-B1,[]-B2[]and[]E.

OK:

Voltage: 10 - 14V

ок□

Proceed_to_next_circuit_inspection_shown_on problem_symptoms_table_see_page_DI-838).

NG

3[]

Check wire harness and connector between the ft deterrent ECU and body ground See page N-38).

NG□

Repair or replace wire harness or connector.

OK

Proceed lo next circuit inspection shown on problem symptoms table (See page DI-838).