DIAQW-01


DTC	13	Front Evaporator Temperature Sensor circuit	
-----	----	---	--

## **CIRCUIT DESCRIPTION**

This sensor detects the temperature inside the cooling unit and sends the appropriate signals to the A/C amplifier.

DTC No.	Detection Item	Trouble Area
13	Open or short in front evaporator temperature sensor circuit	Front evaporator temp. sensor Harness or connector between front evaporator temp. sensor and A/C amplifier A/C amplifier


## **WIRING DIAGRAM**



# **INSPECTION PROCEDURE**

1[]

### Check[voltage[between[terminals[FRTE]and[FRSG[of]A/C[amplifier.



#### PREPARATION:

Remove A/C amplifier with connectors still connected.

#### **CHECK:**

- (a) ☐ Turn ignition switch flo ON.
- (b) Measure voltage between erminals FRTE and FRSG of A/C amplifier connector at each memberature.

#### OK:

Voltage[] at[0°C[(32°F)]][2.0 -[2.4[V at 15°C[(59°F)]] 1.4 - 1.8[V

HINT:

As the temperature increases, the voltage decreases.


NG[]

Go[to[step[2.

OK

Proceed to next circuit inspection shown on problem symptoms table see page 1-1238). However, if DTC 13 is displayed, check and replace A/C amplifier.

# 2 Check front evaporator temperature sensor.



#### PREPARATION:

Remove front evaporator temperature sensor.

### **CHECK:**

Measure resistance between terminals 1 and 2 of evaporator temperature sensor connector at each temperature.

### OK:

Resistance:

at 0°C (32°F) : 4.5 – 5.2 k $\Omega$  at 15°C (59°F) : 2.0 – 2.7 k $\Omega$ 

HINT:

As the temperature increases, the resistance decreases.

NG

Replace front evaporator temperature sensor.

ок

3 Check[harness[and[connector[between[front[evaporator]]emperature[sensor[and A/C]amplifier[See[page]]N-38).

NG

Repair or replace harness or connector.

OK

Check and replace A/C amplifier.