

RS0DF-01





INSPECTION

1. VEHICLES [NOT [INVOLVED [IN [COLLISION

Doadiagnosticsystemcheck.

(See page DI-447)

2. VEHICLES INVOLVED IN COLLISION

- (a) Doadiagnosticsystemcheck. (SeepageDI-447)
- (b) If the front fender of the car or its periphery is damaged, do a visual check for damage to the front airbag sensor, which includes the following items even if the airbag was not deployed:
 - Bracket deformation
 - Paint peeling off the bracket
 - Cracks, dents or chips in the case
 - Cracks, dents, chipping and scratches in the connector
 - Peeling off of the label or damage to the serial number