

Pre-Press Audit Report

Image-Magic Pre-Press Inspection & Safe Zone Guidelines Report


Layout #1: 01_KS(K)_Bezlam_450_2-face.tif





Parameter	Your File	Target Norm	Status
Resolution, DPI	300 DPI	300	PASS
Color Space	CMYK	CMYK	PASS
Color Profile (ICC)	CMYK (Color Management)	FOGRA39 / ISO Coated	FAIL (Color Profile: ICC not found)
Dimensions, mm	94.0 × 54.0	94.0 × 54.0	PASS
File Size, Mb	5.4	2000	PASS
Image Format TIFF	16 Bits	8 Bits 16 Bits	PASS

STATUS: ACTION REQUIRED - Layout requires pre-press review.


Layout #2: 02_Flyer_RGB_72dpi.jpg



Parameter	Your File	Target Norm	Status
 Color calibration bar, DPI	72 DPI	300	FAIL ( 300 DPI)
 Color calibration bar	sRGB	CMYK	FAIL ( sRGB,  CMYK)
 Color calibration bar (ICC)		FOGRA39 / ISO Coated	FAIL ( : ICC 
 Color calibration bar, 	90.0 × 50.1	90.0 × 50.1	PASS
 Color calibration bar, Mb	0.0	 2000	PASS
 Color calibration bar	JPEG	TIFF / PDF ()	PASS

STATUS: ACTION REQUIRED - Layout requires pre-press review.

Layout #3: 03_Sticker_CMYK_300dpi.png



Parameter	Your File	Target Norm	Status
 , DPI	300 DPI	300	PASS
	sRGB	CMYK	FAIL ( sRGB,  CMYK)
 (ICC)		FOGRA39 / ISO Coated	FAIL ( : ICC 
 , 	100.0 × 100.0	100.0 × 100.0	PASS
 , Mb	0.0	 2000	PASS
	PNG	TIFF / PDF ()	PASS

STATUS: ACTION REQUIRED - Layout requires pre-press review.