ENTERPRISE SECURITY LAB

Odoo Backup & Recovery

Restored Odoo and quotation S00001 in a separate Compose project.

Germain Daakpo Amouzou

github.com/Daakpo


Project repository: publication pending

Scope and outcomes

Area	Status	What the evidence establishes
Odoo deployment	Verified	Odoo runs and PostgreSQL is healthy.
Manual backup	Verified	7.5 MB bundle. Four checksums pass.
Manual restore	Verified	Separate instance serves S00001.
Veeam SMB access	Verified	Dedicated account uploads a test file.
Veeam recovery	Open	Final success session and recovered hashes needed.
Bare metal / RTO	Open	Recovery media and measured timing unverified.

Business data synthetic. Passwords and cookies redacted.

Lab architecture and recovery boundaries



Business data synthetic. Passwords and cookies redacted.


Ubuntu lab environment

4 GB guest RAM

Windows host with VirtualBox.

Ubuntu 22.04, amd64.

A 24 GB root filesystem constrains backup workspace.



E022 VM memory increased to 4 GB


A 24 GB guest root must hold the OS, containers and temporary backup workspace.

Container deployment

Database healthy

Odoo 18 and PostgreSQL 16 use separate named volumes.

Odoo publishes on Ubuntu loopback port 8069.



E032 Healthy PostgreSQL and running Odoo

The original stack publishes Odoo only on Ubuntu loopback. PostgreSQL has no host port.


Business record baseline

Quotation S00001

Northstart Demo Ltd

IT Support Package

1 service at $250
Final tax: 0%



E043 Saved quotation S00001

Baseline: S00001, draft quotation, $250 total, with a PDF and recovery-test.txt attachment.


Manual recovery bundle

Four integrity checks pass

Custom database dump.

Odoo data and filestore.

Configuration and project archive.



E062 Original service restarted and four checksums passed

Four SHA-256 checks pass. Database, filestore and configuration form one recovery unit.


Business data synthetic. Passwords and cookies redacted.

Database restoration

S00001 restored

A separate Compose project uses new data volumes.

The restored database query returns draft state and total 250.00.



E065 Restored database query confirms S00001


The restored SQL record returns S00001, draft state and total 250.00.

Restored application

Odoo serves the recovered record

Ubuntu reaches the recovery container at port 8069.

The original application remains separate.



E070 Restored Odoo quotation list at container IP


Separate project, volumes and network preserve the original application during recovery.

Windows SMB destination

Ubuntu upload succeeds

A dedicated Windows account writes to VeeamBackups.

Share and NTFS permissions control access.



E085 SMB upload test succeeds

GM-PC\veeambackup authenticates through a private password prompt. No password appears in E085.


Veeam Agent and DKMS rebuild

Kernel modules rebuilt

Agent 13.1.2.11.

Current kernel headers restored.

Both module files present.



E102 Veeam modules rebuilt successfully


Both veeamblksnap.ko and bdevfilter.ko rebuilt against kernel 6.8.0-85-generic. modinfo confirms version 13.1.2.11.

Recovery media storage failure

ISO creation runs out of space

Recovery-media creation stops with a space error.

Bootable recovery media remains unverified.



E094 Recovery ISO creation fails for lack of space


Cause: a ~4.8 GB workspace exhausted free space on the 24 GB root filesystem.
Remedy: provision workspace capacity before retrying, then store finished recovery media externally.

Full-machine backup attempt

Progress remains at 8%

1.9 GB processed.
373.3 MB transferred.

The stopped session ends in Failed.



E113 Backup remains at 8 percent


Root cause: snapshot storage growth exhausted root headroom. Root usage reached 99%. Forced stop restored ~2.7 GB free. Provision snapshot capacity before retrying.

7.5 MB static recovery bundle

7.5 MB static recovery bundle

All four staged-file hashes pass.

Intended Veeam mode: file level, snapshot disabled.



E117 Local recovery bundle four checksums pass

Static copy of the manual recovery point, not a new export of live data.

Lessons learned

Application checks	Database import, SQL and Odoo UI establish usability. Hashes establish byte integrity against the manifest.
Workspace capacity	ISO preparation and snapshots compete with the OS and containers for the guest root filesystem.
Mount topology	Same-filesystem bind mounts can defeat a cleanup command that relies on filesystem boundaries.
Failure domains	Windows-host storage supports guest recovery. Independent storage is needed for host-loss protection.

Findings and risks

Finding	Risk	Engineering response
24 GB guest root	ISO and snapshot space exhaustion	Provision workspace and snapshot capacity.
Backups on the host	Host loss affects source and copies	Add independent storage and an offsite copy.
Recovery ISO incomplete	Machine recovery remains untested	Create compatible amd64 media and boot-test it.
Veeam closeout open	Restore-point usability unverified	Capture Success and recovered-bundle hashes.
No measured RTO/RPO	Recovery objectives remain unknown	Time a repeatable end-to-end recovery test.

What I would do next

01 Close Veeam evidence

Successful file backup and recovery to a separate folder.
Exit check: all four recovered-file hashes pass.

02 Expand recovery capacity

Allocate workspace and create amd64 recovery media.
Exit check: media boots and the next test has headroom.

03 Separate backup storage

Add a copy outside the Windows host failure domain.
Exit check: restore from that independent copy.

04 Measure repeatability

Time recovery and record the exact backup timestamp.
Exit check: measured RTO/RPO with a repeatable runbook.

Skills demonstrated

Linux operations	Disk diagnosis, mount inspection and DKMS repair
Container infrastructure	Compose services, health checks and separate volumes
Data recovery	PostgreSQL logical restore and Odoo filestore recovery
Backup integration	Veeam Agent setup and Windows SMB access controls
Engineering judgment	Integrity checks, failure analysis and honest evidence scope

Business data synthetic. Passwords and cookies redacted.

Project materials and contact

Manual application recovery verified

Odoo 18, PostgreSQL 16, Ubuntu and Veeam Agent

GitHub portfolio: github.com/Daakpo

Planned repository: Enterprise-Security-Lab-Odoo-Recovery
Publication remains pending.

Report: docs/Enterprise_Security_Lab_Report.docx
README, technical guides and all 118 screenshots accompany this deck.

LinkedIn: linkedin.com/in/gdamouzou

Business data synthetic. Passwords and cookies redacted.