Dale Automation

Edge Drive Spiral Cooler

Inspection Details

Report #: Dale Automation 2798

Location:

Inspection Date: 21-Oct-2026 05:08 PM

Inspector Name: Kyle Kingma

Asset Details

Asset Category : Edge Drive Bread Cooler

Asset Name : Blue Ribbon Mthatha

Asset # : DSS 383-9

Meter Reading: 6000 Hours

Model/Year: 2023

1. Baffles

SN	Inspection Item	Note	Good	Repair	Replace	NA
1	Up drum sliding baffles	Up drum sliding baffles in place	✓	○	○	○
2	Up drum internal hook on baffles	Hook in baffles in place	✓	○	○	○
3	Down drum sliding baffles	All baffles in place	✓	○	○	○
4	Down Drum internal hook on baffles	Baffles are there , 2 are off	✓	○	○	○

1. Up drum sliding baffles





2. Up drum internal hook on baffles





3. Down drum sliding baffles



4. Down Drum internal hook on baffles




2. Internal Frame stabilizing tie rods

SN	Inspection Item	Note	Good	Repair	Replace	NA
5	Up Drum	Internal frame in good condition	✓	○	○	○
6	Down Drum	Drum is stable	✓	○	○	○

5. Up Drum








6. Down Drum




3. Infeed Transfer Conveyor

SN	Inspection Item	Note	Good	Repair	Replace	NA
7	Belt	Belt is in good condition	✓	○	○	○
8	Drive and sprokets	Drive sprockets still in good condition	✓	○	○	○
9	Bearings	Bearings are dry. Bearings need to be greased	○	✕	○	○

7. Belt





8. Drive and sprokets



9. Bearings



4. Belt

SN	Inspection Item	Note	Good	Repair	Replace	NA
10	Belt condition	Belt is in very good condition, could not see any borken links	✓	○	○	○
11	Edge drive links	No edge links damaged	✓	○	○	○
12	Belt rods	Steel rods installed	✓	○	○	○
13	Belt engaging		○	○	○	−
14	Belt tabs and flights		○	○	○	−
15	Bearings	Bearings need to be greased at discharge and infeed	○	✕	○	○
16	Infeed and discharge		○	○	○	−
17	Belt guides		○	○	○	−

10. Belt condition





11. Edge drive links



12. Belt rods



15. Bearings




5. Belt Oiler

SN	Inspection Item	Note	Good	Repair	Replace	NA
18	Oil level	Oil level is correct	✓	○	○	○
19	Pump & piston	Pump and piston working	✓	○	○	○
20	Pipe work	All festo piping in good condition	✓	○	○	○
21	Splitter Block	Splitter block not blocked or leaking	✓	○	○	○
22	Oiler blocks	Oiler blocks are blocked. Need to take them out and clean them	○	✕	○	○
23	Manual test	Oiler running in manual	✓	○	○	○


18. Oil level



19. Pump & piston




20. Pipe work





21. Splitter Block



22. Oiler blocks





23. Manual test



6. Coils


SN	Inspection Item	Note	Good	Repair	Replace	NA
24	Coil fins	Coil fins are in good condition	✓	○	○	○
25	Coil flashings		○	○	○	−
26	Piping and lagging	Piping and lagging in good condition	✓	○	○	○
27	Filters and frames	Filters are very clean and in good condition	✓	○	○	○
28	Drip trays	Drip trays are not blocked and allows water to flow	✓	○	○	○
29	floor drains	Floor drains are blocked	○	✕	○	○

24. Coil fins






26. Piping and lagging




27. Filters and frames




28. Drip trays






29. floor drains




7. Safeties

SN	Inspection Item	Note	Good	Repair	Replace	NA
30	E-stop	E stops working	✓	○	○	○
31	Tier lift sensors	Tier lift sensors working	✓	○	○	○
32	Product height	Product height trip sensors working	✓	○	○	○
33	Temperature probes	Temperature propes working	✓	○	○	○
34	Discharge sensor	Discharge sensors working	✓	○	○	○
35	Cross over sensor		○	○	○	−


30. E-stop



31. Tier lift sensors



32. Product height



33. Temperature probes



34. Discharge sensor



8. CIP

SN	Inspection Item	Note	Good	Repair	Replace	NA
36	Main panel		○	○	○	⊖
37	Leaks		○	○	○	⊖
38	Spray Nozzles		○	○	○	⊖

9. Fans

SN	Inspection Item	Note	Good	Repair	Replace	NA
39	Fan guards	All fans are fitted with fan guards	✓	○	○	○
40	Impellors	All impellers in good condition, no chip marks	✓	○	○	○
41	Motors	Motors in good condition and not making noise	✓	○	○	○
42	Fan direction		○	○	○	⊖

43	Fan Isolators	All fans are fitted with isolators	✓ ○ ○ ○

SN	Inspection Item	Note	Readings
44	Fan blade pitch		blade pitch is correct


39. Fan guards







40. Impellors







41. Motors



43. Fan Isolators



44. Fan blade pitch




a. Wear strips

SN	Inspection Item	Note	Good	Repair	Replace	NA
45	Rail wear strips	Wearstrip is worn. The oil doesn't carry from one rail to another due to the design	○	○	✕	○

45. Rail wear strips







b. Frame

SN	Inspection Item	Note	Good	Repair	Replace	NA
46	Legs	All legs are secure	✓	○	○	○
47	Arms (Rail Support brackets)	Arms are straight and not bent	✓	○	○	○
48	Rails	Rails are in excellent condition	✓	○	○	○
49	Top and bottom cross overs		○	○	○	−


46. Legs






47. Arms (Rail Support brackets)





48. Rails



c. Up Drum Main Drive Gearbox

SN	Inspection Item	Note	Good	Repair	Replace	NA
50	Leaks	No leaks found on gearbox, also no noise found on gearbox	✓	○	○	○
51	Oil level		○	○	○	−
52	Oil samples		○	○	○	−
53	Motor	Motor is in good condition, no noise coming from motor	✓	○	○	○
54	Base Frame	Base frame is secure	✓	○	○	○

50. Leaks








53. Motor





54. Base Frame



d. Down Drum Main Drive Gearbox

SN	Inspection Item	Note	Good	Repair	Replace	NA
55	Leaks	No leaks found in gearbox	✓	○	○	○
56	Oil level		○	○	○	−
57	Oil samples		○	○	○	−
58	Motor	No noise coming from motor	✓	○	○	○
59	Base Frame	Base frame is secure	✓	○	○	○

55. Leaks





58. Motor



59. Base Frame



e. Up Drum Drive Tower

SN	Inspection Item	Note	Good	Repair	Replace	NA
60	Sprockets	Sprockets in very good condition. No play found	✓	○	○	○
61	Bearings	Bearings in very good condition and being greased	✓	○	○	○
62	Chain couplings	Chain couplings in good condition	✓	○	○	○
63	Drive shafts	Drive shaft is aligned	✓	○	○	○
64	Spur gears	Spur gears in good condition. Engaging correctly	✓	○	○	○
65	Encoder	Encoder is secure and not loose	✓	○	○	○
66	Lockable tower doors	Locks are broken out	○	○	✗	○

60. Sprockets






61. Bearings





62. Chain couplings






63. Drive shafts



64. Spur gears








65. Encoder






66. Lockable tower doors




f. Down Drum Drive Tower

SN	Inspection Item	Note	Good	Repair	Replace	NA
67	Sprockets	No wear in sprockets and no play	✓	○	○	○
68	Bearings	Bearings are greased and in good condition	✓	○	○	○
69	Chain coupling	Chain couplings in good condition and showing no signs of wear	✓	○	○	○
70	Drive shafts	Drive shaft in good condition	✓	○	○	○
71	Spur gears	Spur gears are in good condition and no wear	✓	○	○	○
72	Encoders	Encoder is secure	✓	○	○	○
73	Lockable tower doors	Locks are broken and held on with cable ties	○	○	✗	○

67. Sprockets



68. Bearings



69. Chain coupling



70. Drive shafts



71. Spur gears







72. Encoders



73. Lockable tower doors





g. Enclosure

SN	Inspection Item	Note	Good	Repair	Replace	NA
74	Walls	Enclosure walls in good condition	✓	○	○	○
75	Flashings	All flashings are secure and not loose .	✓	○	○	○
76	Internal doors	All internal doors working correctly	✓	○	○	○
77	Infeed and Discharge openings	Openings not obstructed	✓	○	○	○

74. Walls





75. Flashings




76. Internal doors



77. Infeed and Discharge openings





h. Electrical Panel

SN	Inspection Item	Note	Good	Repair	Replace	NA
78	Doors and Panel case	Doors and case in good condition	✓	○	○	○
79	HMI	HMI in good condition and working	✓	○	○	○
80	Temperature indications	Temp display working	✓	○	○	○
81	Up drum drive settings		○	○	○	−
82	Down Drum settings		○	○	○	−
83	EWON		○	○	○	−
84	UPS		○	○	○	−
85	Aircon & panel fans	All aircons working	✓	○	○	○
86	E-stop		○	○	○	−
87	Field connections		○	○	○	−
88	Passwords		○	○	○	−

78. Doors and Panel case









79. HMI







80. Temperature indications



85. Aircon & panel fans






j. Lights

SN	Inspection Item	Note	Good	Repair	Replace	NA
89	Lights	All lights working in enclosure	✓	○	○	○

89. Lights








k. System performance


SN	Inspection Item	Note	Good	Repair	Replace	NA
90	Retension time	Retention time is set to 55min	✓	○	○	○

SN	Inspection Item	Note	Readings
91	Air - ON temps		air in temp is good
92	Air - OFF Temp		air off temp is good


90. Retension time



91. Air - ON temps



92. Air - OFF Temp



Additional Note

Overall Condition: Good Condition

Asset Safe to Use: **Yes**

Maintenance Required: Yes

Asset Status Maintenance Required

Maintenance Priority: Low

Custom Business Fields

Client Name : phelo

Contact details : 0114620044



Dale Technician Signature



Client Signature