Dale Automation

Blue Ribbon Aeroton Prover Factory Inspection

Inspection Details

Report #: Dale Automation 2747
Location: South Africa
Inspection Date: 15-Aug-2026 10:16 AM
Inspector Name: Victor

Asset Details

Asset Category : Prover
Asset Name : Blue Ribbon Aeroton
Asset # : DSS 397-4
Meter Reading: 0 Hours
Model/Year: 2024


A) Drawing Number

SN	Inspection Item	Note	Readings
1	Drawing Number		DSS-397-4

B) Material

SN	Inspection Item	Note	Good	Repair	Replace	NA
2	Material Type	-Rust deposit found on top two rails for chain -missing bolts on discharge conveyor -noisy motor on main drive gearbox -Broken light bracket inside prover -Chain oiler brush not touching the chain	◯	✕	◯	◯

2. Material Type









C) Welder/Fabricator

SN	Inspection Item	Note	Readings
3	Welder Name		n/a

Additional Note
Replace some missing bolts on covers

Overall Condition: A little wear

Asset Safe to Use: Yes

Maintenance Required: Yes

Asset Status Maintenance Required

Maintenance Priority: Low

Custom Business Fields

Client Name : blue ribbon aeroton

Contact details : 0818166485

Dale Technician Signature

Client Signature