Dale Automation

Belt replacement Pre-inspection

Inspection Details

Report #: Dale Automation 2750
Location: South Africa
Inspection Date: 20-Aug-2026 11:19 AM
Inspector Name: Raynard Kruger

Asset Details


Asset Category : Bakery
Asset Name : Snackworks Dryer Spiral
Asset # : DSS 331-9
Meter Reading: 0 Hours
Model/Year: Dale

Belt


SN	Inspection Item	Note	Good	Repair	Replace	NA
1	Belt width		○	○	○	⊖
2	Belt type		○	○	○	⊖
3	Belt condition	Belt is 8 years old Belt has been turned once and due to distortion and damage as per the photos in this report Dale Automation strongly suggests replacing the belt as there is no guarantee how long the belt will operate before failing.	○	○	⊗	○

3. Belt condition









Additional Note
Belt is 8 years old Belt has been turned once and due to distortion and damage as per the photos in this report Dale Automation strongly suggests replacing the belt as there is no guarantee how long the belt will operate before failing.

Overall Condition:	Major Repair required
Asset Safe to Use:	**Yes**
Maintenance Required:	Yes
Asset Status	Maintenance Required
Maintenance Priority:	High

Custom Business Fields

Client Name : Snackworks Isando

Contact details : 0114620044

Dale Technician Signature

Client Signature