Dale Automation

Oven General Inspection

Inspection Details

Report #: Dale Automation 2743
Location: South Africa
Inspection Date: 12-Aug-2026 09:38 AM
Inspector Name: Raynard Kruger

Asset Details

Asset Category : 8000 Oven
Asset Name : Sunbake Benoni
Asset # : DSS 269-2
Meter Reading: 0 Hours
Model/Year: Dale Bakermation

---

1. Chain & Drive

SN	Inspection Item	Note	Good	Repair	Replace	NA
1	Chain condition		○	○	○	⊖
2	Sprockets & Shaft		○	○	○	⊖
3	Chain Rail		○	○	○	⊖
4	Slats		○	○	○	⊖
5	Drive Terminal		○	○	○	⊖
6	Idle Terminal		○	○	○	⊖
7	General		○	○	○	⊖

2. Loader

SN	Inspection Item	Note	Good	Repair	Replace	NA
8	Pusher drive		○	○	○	⊖
9	Cross conveyor		○	○	○	⊖
10	Pusher arm		○	○	○	⊖
11	Deadplate		○	○	○	⊖
12	General		○	○	○	⊖

3. Unloader


SN	Inspection Item	Note	Good	Repair	Replace	NA
13	Accelerator belt		○	○	○	⊖
14	Accelerator Sprockets		○	○	○	⊖
15	Accelerator Drive		○	○	○	⊖
16	Cross conveyor		○	○	○	⊖
17	General		○	○	○	⊖

4. Bake Chamber

SN	Inspection Item	Note	Good	Repair	Replace	NA
18	Pressure Chambers		○	○	○	⊖
19	Inspection Doors		○	○	○	⊖
20	Burners		○	○	○	⊖
21	Flame tubes	The flame tubes refractory is busy breaking apart from the flame tubes replace the flame tubes Flame tubes length is 2.4 meter.	○	○	✕	○
22	Circulation Fans		○	○	○	⊖

21. Flame tubes









5. Software

SN	Inspection Item	Note	Good	Repair	Replace	NA

23	Programme Updates		○	○	○	⊖

Additional Note
Equipment is in operation, but tube integrity is compromised and not running in an efficient manner. Replace flame tubes

Overall Condition:	Major Repair required
Asset Safe to Use:	**Yes**
Maintenance Required:	Yes
Asset Status	Maintenance Required
Maintenance Priority:	High

Custom Business Fields

Client Name : Sunbake Benoni

Contact details : 0114620044



_____ _____

Dale Technician Signature **Client Signature**