



		Test and Chemical Report					
Code: FM-15-30		Version Version				2384	
GENERAL DATA							
Customer	FORD	FO Chrome	1010234	Chrome date	23-01-25	Rack	0
Reference	SL18543156AA-C1	FO Injection	2411025	Download time		Type	Validation
Denomination	EXPEDITION RR EXPE APPLIQUE			Request Documentation		N/A	
Aspect	OK	Traceability	OK	Valuation	Accepted	Approved	
Previous information Validation parts Satin Chrome SM322				Final valuation The pieces are in accordance with the specifications required by the client, so the conformity is "Accepted"			
Quick adhesion test							
Responsible				N/A			
Result				N/A			
Tests							
Test 1 WSS-M1P83-E2 - 3.5.1 Grind Saw Test							
Responsible	Start date	Start time	Finish Date	Finish time	Actual valuation date		
Karla	24-01-25	12:00	24-01-25	13:00	24-01-25		
Equipment	State		Valuation				
Saw	Finalized		OK				
Characteristic							
No evidence of peeling, flaking or lifting of the electroplate from the substrate or between the plating layers.							
Result							
The pieces do not show detachment after testing							
Observations							
Evidence							
							
Test 2 WSS-M1P83-E2 3.6.1 Stone Chip (23 °C & -20°C)							
Responsible	Start date	Start time	Finish Date	Finish time	Actual valuation date		
Karla	27-01-25	11:00	27-01-25	16:00	27-01-25		
Equipment	State		Valuation				
Gravelometer	Finalized		OK				
Characteristic							
Rating 5B min							
Result							
Rating 5B							
Observations							
According to the specification required by the client, the average chip size is between 1-3 mm and the quantity is 25-49, the maximum chip size is 1.80 mm, so the result is acceptable.							
Evidence							
							

Test 3	WSS-M1P83-E2 3.6.2 High Performance Stone Chip				
Responsible	Start date	Start time	Finish Date	Finish time	Actual valuation date
Karla	27-01-25	11:00	30-01-25	12:00	30-01-25
Equipment	State			Valuation	
Gravelometer	Finalized			OK	

Characteristic
Rating 6 min
Result
Rating 6
Observations
According to the specification required by the client, the result is acceptable
Evidence



Test 4	WSS-M1P83-E2 3.8 Corrosion - Thermal Cycle				
Responsible	Start date	Start time	Finish Date	Finish time	Actual valuation date
Karla	27-01-25	16:00	31-01-25	7:00	31-01-25
Equipment	State			Valuation	
CASS - OVEN - FREEZER	Finalized			OK	

Characteristic
The part shall show no degradation of part appearance. no evidence of plating failure, warpage, sink marks, deformation, cracks, blistering, or delamination.
Result
The pieces do not present any alteration or corrosion after testing.
Observations
Evidence





THICKNESS TEST REPORT

FORMAT ID	FM-15-01-03
FORMAT CREATION DATE:	ene-24
FORMAT REVIEW DATE:	ene-24

No. PROCESS/OPERATION	PROCESS DESCRIPTION	WORKSHOP
1450	CHROME PLATED	ALUDEC AUTOMOCION

REPORT NO.	8
------------	---

DATE	23/01/2025
ISSUED BY:	EDGAR RAMIREZ
APPROVED BY:	ANAKAREN D.

REFERENCE	SL1BS43156AA-C1
DENOMINATION	EXPEDITION RR "EXPE" APPLIQUE
OF	1010234
PRODUCTION DATE	23/01/2025

CUSTOMER	FORD
CUSTOMER NORME	WSS-M1P83-E2



Thickness measurement

Piece 1

EXPE Rack position FA3 HCD			
measurement point	Cr thickness ($\geq 0.18 \mu\text{m}$)	TOTAL Nickel Thickness ($\geq 21 \mu\text{m}$)	Cu thickness ($\geq 18 \mu\text{m}$)
1	0.42	31.8	37.7
2	0.42	28.2	30.1

Piece 2

EXPE Rack position FB31 LCD			
measurement point	Cr thickness ($\geq 0.18 \mu\text{m}$)	TOTAL Nickel Thickness ($\geq 21 \mu\text{m}$)	Cu thickness ($\geq 18 \mu\text{m}$)
1	0.45	31.7	43.6
2	0.35	33.1	32.5

Piece 3

EXPE Rack position FB34 LCD			
measurement point	Cr thickness ($\geq 0.18 \mu\text{m}$)	TOTAL Nickel Thickness ($\geq 21 \mu\text{m}$)	Cu thickness ($\geq 18 \mu\text{m}$)
1	0.42	32.9	43.4
2	0.33	28.1	37.8

HCD: High Current Density
LCD: Low Current Density

Observations
Without any alteration



S.T.E.P. TEST REPORT

FORMAT ID	FM-15-01-03
FORMAT CREATION DATE:	ene-24
FORMAT REVIEW DATE:	ene-24

No. PROCESS/OPERATION	PROCESS DESCRIPTION	WORKSHOP
1450	CHROME PLATED	ALUDEC AUTOMOCION

REPORT NO.	8
------------	---

DATE	23/01/2025
ISSUED BY:	EDGAR RAMIREZ
APROVED BY:	ANAKAREN D.

REFERENCE	SL1BS43156AA-C1
DENOMINATION	EXPEDITION RR "EXPE" APPLIQUE
OF	1010234
PRODUCTION DATE	23/01/2025



CUSTOMER	FORD
CUSTOMER NORME	WSS-M1P83-E2



Measurement point.

STEP TEST					
PIECE 2 (EXPE Rack position FB31) LCD					
	Multithickness measurement (Thickness graph)		Potential Measurement (Potential graph)		
measurement point	Nickel SB Thickness ($\geq 15 \mu\text{m}$)	Br Nickel Thickness ($\geq 6 \mu\text{m}$)	MPS Nickel Thickness (N/S)	$\Delta P(\text{NIMPS-NIB})$ (20-90 mV)	$\Delta P(\text{NIB-NISB})$ ($\geq 100 \text{ mV}$)
1	21.22	7.49	2.35	34	182


STEP TEST PIECE 3					
PIECE 3 (EXPE Rack position FB34) LCD					
	Multithickness measurement (Thickness graph)		Potential Measurement (Potential graph)		
measurement point	Nickel SB Thickness ($\geq 15 \mu\text{m}$)	Br Nickel Thickness ($\geq 6 \mu\text{m}$)	MPS Nickel Thickness (N/S)	$\Delta P(\text{NIMPS-NIB})$ (20-90 mV)	$\Delta P(\text{NIB-NISB})$ ($\geq 100 \text{ mV}$)
2	18.49	6.48	2.29	30	148



PIECE 2 PORE COUNT
(EXPE Rack position FB31) LCD:
15,600 Pores

Table 2: Minimum Discontinuity Quantities

Type	Minimum Discontinuity
Micropores	10,000 pores/cm ²



PIECE 3 PORE COUNT
(EXPE Rack position FB34) LCD:
22,400 Pores



S.T.E.P. TEST REPORT

FORMAT ID	FM-15-01-03
FORMAT CREATION DATE:	ene-24
FORMAT REVIEW DATE:	ene-24

No. PROCESS/OPERATION	PROCESS DESCRIPTION	WORKSHOP
1450	CHROME PLATED	ALUDEC AUTOMOCION

REPORT NO.	8
------------	---

DATE	23/01/2025
ISSUED BY:	EDGAR RAMIREZ
APPROVED BY:	ANAKAREN D.


REFERENCE	SL1BS43156AA-C1
DENOMINATION	EXPEDITION RR "EXPE" APPLIQUE
OF	1010234
PRODUCTION DATE	23/01/2025

CUSTOMER	FORD
CUSTOMER NORME	WSS-M1P83-E2



Measurement point.

STEP TEST					
PIECE 1 (EXPE Rack position FA3) HCD					
	Multithickness measurement graph		(Thickness)	Potential Measurement (Potential graph)	
measurement point	Nickel SB Thickness ($\geq 15 \mu\text{m}$)	Br Nickel Thickness ($\geq 6 \mu\text{m}$)	MPS Nickel Thickness (N/S)	$\Delta P(\text{NIMPS-NIB})$ (20-90 mV)	$\Delta P(\text{NIB-NISB})$ ($\geq 100 \text{ mV}$)
2	18.84	6.47	2.27	41	190



PIECE 1 PORE COUNT
(EXPE Rack position FA3) HCD:
19,200




Table 2: Minimum Discontinuity Quantities

Type	Minimum Discontinuity
Micropores	10,000 pores/cm ²