
Figure 14 — N-1 Contingency Impact and Recovery (8-Bus)
Immediate Impact
After Recovery
Relative Performance (base_of / observed_of)
0.0
0.1
0.2
0.3
0.4
0.5
L0
L1
L2
L3
L4
L5
L6
L7
L8
L9
L10
L11
L12
L13
L14
Line Outage