Quarterly Field Report

1. Summary

The survey team visited **fourteen sites** between March and May. Water levels were *lower than expected* at most of them.

Findings

- Wells near the river held steady.
- Upland wells dropped by 1.2 m on average.
- Two pumps need new seals.

1. Order seals
2. Re-test upland wells in July

Site	Depth (m)	Status
North 3	12.4	OK
Ridge 7	18.9	Low



Appendix

Measurements were taken at 09:00 local time with a calibrated sounder. Measurements were taken at 09:00 local time with a calibrated sounder. Measurements were taken at 09:00 local time with a calibrated sounder. Measurements were taken at 09:00 local time with a calibrated sounder. Measurements were taken at 09:00 local time with a calibrated sounder. Measurements were taken at 09:00 local time with a calibrated sounder. Measurements were taken at 09:00 local time with a calibrated sounder. Measurements were taken at 09:00 local time with a calibrated sounder. Measurements were taken at 09:00 local time with a calibrated sounder. Measurements were taken at 09:00 local time with a calibrated sounder. Measurements were taken at 09:00 local time with a calibrated sounder. Measurements were taken at 09:00 local time with a calibrated sounder.