
Quarry fidelity correction / review

BREEZE 2027 / PRIVATE QUARRY FIDELITY REVIEW



Private candidate ready for comparison, not approved for production. Material scope now matches the documented35.557m study extent. Historical geological fidelity is only partially recovered.

The historic native 0.9 hero is preserved exactly. New relief uses disjoint Coastal Cliff04 crops at uniform 1.03/1.06 scale; only two of four authoring crops contribute measured front-surface detail. The approved 3x material sampling and global lights are unchanged.

Brown-grey coverage is closer to original C9, but smooth boundary strips, triangular/faceted joins and folded coastal forms remain. The neutral view exposes these weaknesses. Historical C6.2 host/mask pixels are lost. This is not a pixel-identical restoration.


Strict new-region geometry gates pass. All seven known legacy component hits remain; the current first-hit survey returns six. Laptop/phone performance is unverified; browser software measurements are diagnostic only.

Stop for user review of BOTH material fidelity and geological fidelity. Stage 3A remains on hold.


Public visitor position 1

BREEZE 2027 / PRIVATE QUARRY FIDELITY REVIEW


ORIGINAL / p2 panel D



RECOVERED / preserved rejected recovery



CORRECTED / new private candidate




Reference-aligned original C9 D; current recovered/corrected exactly matched

2 / Visual approval pending; Stage 3A on hold


Public visitor position 2

BREEZE 2027 / PRIVATE QUARRY FIDELITY REVIEW


ORIGINAL / p3 panel D



RECOVERED / preserved rejected recovery



CORRECTED / new private candidate



Reference-aligned original C9 D; current recovered/corrected exactly matched

3 / Visual approval pending; Stage 3A on hold


Public visitor position 3

BREEZE 2027 / PRIVATE QUARRY FIDELITY REVIEW


ORIGINAL / p4 panel D



RECOVERED / preserved rejected recovery



CORRECTED / new private candidate




Reference-aligned original C9 D; current recovered/corrected exactly matched

4 / Visual approval pending; Stage 3A on hold


Medium-distance material inspection

BREEZE 2027 / PRIVATE QUARRY FIDELITY REVIEW


ORIGINAL / p5 panel D



RECOVERED / preserved rejected recovery



CORRECTED / new private candidate




Reference-aligned original C9 D; current recovered/corrected exactly matched

5 / Visual approval pending; Stage 3A on hold


Close scanned mineral and physical detail

BREEZE 2027 / PRIVATE QUARRY FIDELITY REVIEW


ORIGINAL / p6 panel D



RECOVERED / preserved rejected recovery



CORRECTED / new private candidate




Reference-aligned original C9 D; current recovered/corrected exactly matched


Adjacent left material surface

BREEZE 2027 / PRIVATE QUARRY FIDELITY REVIEW


ORIGINAL / p8 panel D



RECOVERED / preserved rejected recovery



CORRECTED / new private candidate




Reference-aligned original C9 D; current recovered/corrected exactly matched

7 / Visual approval pending; Stage 3A on hold


Adjacent right material surface

BREEZE 2027 / PRIVATE QUARRY FIDELITY REVIEW


ORIGINAL / p9 panel D



RECOVERED / preserved rejected recovery



CORRECTED / new private candidate




Reference-aligned original C9 D; current recovered/corrected exactly matched


Upper rim

BREEZE 2027 / PRIVATE QUARRY FIDELITY REVIEW


ORIGINAL / p10 panel D



RECOVERED / preserved rejected recovery



CORRECTED / new private candidate




Reference-aligned original C9 D; current recovered/corrected exactly matched


Rock-to-ground contact

BREEZE 2027 / PRIVATE QUARRY FIDELITY REVIEW


ORIGINAL / p11 panel D



RECOVERED / preserved rejected recovery



CORRECTED / new private candidate




Reference-aligned original C9 D; current recovered/corrected exactly matched

Hub and scaffold

BREEZE 2027 / PRIVATE QUARRY FIDELITY REVIEW

ORIGINAL / p12 panel D



RECOVERED / preserved rejected recovery



CORRECTED / new private candidate



Reference-aligned original C9 D; current recovered/corrected exactly matched

11 / Visual approval pending; Stage 3A on hold


Historical tunnel-exit orientation

BREEZE 2027 / PRIVATE QUARRY FIDELITY REVIEW


ORIGINAL / p14 panel D



RECOVERED / preserved rejected recovery



CORRECTED / new private candidate




Reference-aligned original C9 D; current recovered/corrected exactly matched


Behind-left-stalls inspection

BREEZE 2027 / PRIVATE QUARRY FIDELITY REVIEW


ORIGINAL / p15 panel D



RECOVERED / preserved rejected recovery



CORRECTED / new private candidate



Reference-aligned original C9 D; current recovered/corrected exactly matched

13 / Visual approval pending; Stage 3A on hold


Public visitor position 1

BREEZE 2027 / PRIVATE QUARRY FIDELITY REVIEW


ORIGINAL / p17 panel D



RECOVERED / preserved rejected recovery



CORRECTED / new private candidate




Reference-aligned original C9 D; current recovered/corrected exactly matched

14 / Visual approval pending; Stage 3A on hold

Aerial map

BREEZE 2027 / PRIVATE QUARRY FIDELITY REVIEW


ORIGINAL / p19 panel D



RECOVERED / preserved rejected recovery



CORRECTED / new private candidate




Reference-aligned original C9 D; current recovered/corrected exactly matched

15 / Visual approval pending; Stage 3A on hold

Aerial map

BREEZE 2027 / PRIVATE QUARRY FIDELITY REVIEW

ORIGINAL / p20 panel D



RECOVERED / preserved rejected recovery



CORRECTED / new private candidate




Reference-aligned original C9 D; current recovered/corrected exactly matched

16 / Visual approval pending; Stage 3A on hold


Along-wall physical depth

BREEZE 2027 / PRIVATE QUARRY FIDELITY REVIEW


ORIGINAL / p21 panel D



RECOVERED / preserved rejected recovery



CORRECTED / new private candidate




Reference-aligned original C9 D; current recovered/corrected exactly matched

17 / Visual approval pending; Stage 3A on hold


C8 material / Public visitor position 1

BREEZE 2027 / PRIVATE QUARRY FIDELITY REVIEW


ORIGINAL / p6 panel approved3x



RECOVERED / preserved rejected recovery



CORRECTED / new private candidate



Approved original C8 3x; material-only correction on different C5.1 host, not lost C6.2

18 / Visual approval pending; Stage 3A on hold

C8 material / Historical C8 close pose

BREEZE 2027 / PRIVATE QUARRY FIDELITY REVIEW

ORIGINAL / p7 panel approved3x



RECOVERED / preserved rejected recovery



CORRECTED / new private candidate




Approved original C8 3x; material-only correction on different C5.1 host, not lost C6.2


C8 material / Historical tunnel-exit orientation

BREEZE 2027 / PRIVATE QUARRY FIDELITY REVIEW


ORIGINAL / p8 panel approved3x



RECOVERED / preserved rejected recovery



CORRECTED / new private candidate




Approved original C8 3x; material-only correction on different C5.1 host, not lost C6.2

20 / Visual approval pending; Stage 3A on hold


C8 material / Behind-left-stalls inspection

BREEZE 2027 / PRIVATE QUARRY FIDELITY REVIEW


ORIGINAL / p9 panel approved3x



RECOVERED / preserved rejected recovery



CORRECTED / new private candidate




Approved original C8 3x; material-only correction on different C5.1 host, not lost C6.2

21 / Visual approval pending; Stage 3A on hold


C8 material / Public visitor position 1

BREEZE 2027 / PRIVATE QUARRY FIDELITY REVIEW


ORIGINAL / p11 panel approved3x



RECOVERED / preserved rejected recovery



CORRECTED / new private candidate




Approved original C8 3x; material-only correction on different C5.1 host, not lost C6.2


22 / Visual approval pending; Stage 3A on hold

Broad middle and upper wall

RECOVERED



CORRECTED




Valid public view of the original35.557m study extent; framing retained across all modes.


Neutral geometry only

BREEZE 2027 / PRIVATE QUARRY FIDELITY REVIEW

RECOVERED



CORRECTED




Temporary neutral diagnostic with all fine textures/normals and vertex colours disabled; actual runtime geometry.


Neutral material inspection

BREEZE 2027 / PRIVATE QUARRY FIDELITY REVIEW

RECOVERED



CORRECTED



Temporary browser-only neutral lights; same maps, exposure, fog and geometry.

Limitations and approval gate

The genuine original C5.1 assets survive unchanged. C6/C6.1/C6.2 do not have recovered standalone runtimes; their historical panels are compared to the nearest host and identified as non-equivalent.

C7 remains rejected. C8.1 remains an optional historical study. Neither has been silently adopted.

Three public visitor views are included without removing stalls. Positions2/3 remain substantially occluded. Non-public close/along-wall cameras are labelled and do not establish visitor acceptance on their own.

Some source-derived folds and faceted boundary transitions remain unlike the photographic quarry. Dusk still hides fine relief. No exposure or fill-light change was used to manufacture improvement.

Middle/far LODs remain too expensive for quarry-wide replication (40,940/35,296 triangles). A combined multi-context mobile startup timed out; unchanged isolated assertions passed. The full report preserves that failure and all remaining limits.

Use the new checkpoint folder and restoration index for backup. Prior Phase 1/2/3 checkpoints remain immutable. No commit, push, merge, deployment or public-default change.