Stage3A.1 pilot decision

The actual scanned faces provide greater depth, but their join into the old passage makes visible ribbons, long returns and a separate rough patch. Neutral geometry is not visually convincing. This pilot does not pass.

Strict survey: 22 / 21 / 20 inverted first hits across LOD0/1/2. Walking envelope and exact shared borders pass. glTF validates, but that does not make the geometry suitable for adoption.

Quarry C9, public C5.1 and quarry 3x sampling are preserved. Tunnel-only features use 2x enlargement by halving owned sampler repeats once; no additional PBR images. No new fixtures or global lighting.

The 6?15m passage pilot is the only new geological region. Full 42m extension and entrance refinement were stopped at the mandatory pilot gate. Missing exact artwork has not been invented.

Stage3A baseline | dusk-1x | approach | desktop



Camera [-1.9250000000000003, 1.72, -7] FOV 58 / DPR 1 / tier 0
Approved dusk lighting. Geometry is NOT accepted.

Stage3A baseline | dusk-1x | normal-walking | desktop



Camera [-2.6750000000000003, 1.72, -9] FOV 58 / DPR 1 / tier 0
Approved dusk lighting. Geometry is NOT accepted.

Stage3A baseline | dusk-1x | side-fracture | desktop



Camera [-3.7199999999999998, 1.72, -11.2] FOV 58 / DPR 1 / tier 0
Approved dusk lighting. Geometry is NOT accepted.

Stage3A baseline | dusk-1x | along-wall | desktop



Camera [-4.0375, 1.72, -8.5] FOV 58 / DPR 1 / tier 0
Approved dusk lighting. Geometry is NOT accepted.

Stage3A baseline | dusk-1x | parallax-a | desktop



Camera [-3.245, 1.72, -10.2] FOV 58 / DPR 1 / tier 0
Approved dusk lighting. Geometry is NOT accepted.

Stage3A baseline | dusk-1x | parallax-b | desktop



Camera [-4.195, 1.72, -12.2] FOV 58 / DPR 1 / tier 0
Approved dusk lighting. Geometry is NOT accepted.

Stage3A baseline | dusk-1x | vault | desktop

Camera [-3.7199999999999998, 1.72, -11.2] FOV 58 / DPR 1 / tier 0
Approved dusk lighting. Geometry is NOT accepted.

Stage3A baseline | neutral | approach | desktop



Camera [-1.9250000000000003, 1.72, -7] FOV 58 / DPR 1 / tier 0
Protected entry-route inspection. Neutral has NO PBR maps.

Stage3A baseline | neutral | normal-walking | desktop



Camera [-2.6750000000000003, 1.72, -9] FOV 58 / DPR 1 / tier 0
Protected entry-route inspection. Neutral has NO PBR maps.

Stage3A baseline | neutral | side-fracture | desktop

Camera [-3.7199999999999998, 1.72, -11.2] FOV 58 / DPR 1 / tier 0
Protected entry-route inspection. Neutral has NO PBR maps.

Stage3A baseline | neutral | along-wall | desktop



Camera [-4.0375, 1.72, -8.5] FOV 58 / DPR 1 / tier 0
Protected entry-route inspection. Neutral has NO PBR maps.

Stage3A baseline | neutral | parallax-a | desktop



Camera [-3.245, 1.72, -10.2] FOV 58 / DPR 1 / tier 0
Protected entry-route inspection. Neutral has NO PBR maps.

Stage3A baseline | neutral | parallax-b | desktop

Camera [-4.195, 1.72, -12.2] FOV 58 / DPR 1 / tier 0
Protected entry-route inspection. Neutral has NO PBR maps.

Stage3A baseline | neutral | vault | desktop



Camera [-3.7199999999999998, 1.72, -11.2] FOV 58 / DPR 1 / tier 0
Protected entry-route inspection. Neutral has NO PBR maps.

Stage3A baseline | dusk-1x | normal-walking | mobile



Camera [-2.6750000000000003, 1.72, -9] FOV 79.43425835096338 / DPR 1 / tier 0
Approved dusk lighting. Geometry is NOT accepted.

Stage3A baseline | dusk-1x | side-fracture | mobile

Camera [-3.7199999999999998, 1.72, -11.2] FOV 79.43425835096338 / DPR 1 / tier 0
Approved dusk lighting. Geometry is NOT accepted.

Stage3A baseline | dusk-1x | vault | mobile



Camera [-3.7199999999999998, 1.72, -11.2] FOV 79.43425835096338 / DPR 1 / tier 0
Approved dusk lighting. Geometry is NOT accepted.

Stage3A baseline | neutral | normal-walking | mobile



Camera [-2.6750000000000003, 1.72, -9] FOV 79.43425835096338 / DPR 1 / tier 0
Protected entry-route inspection. Neutral has NO PBR maps.

Stage3A baseline | neutral | side-fracture | mobile



Camera [-3.7199999999999998, 1.72, -11.2] FOV 79.43425835096338 / DPR 1 / tier 0
Protected entry-route inspection. Neutral has NO PBR maps.

Stage3A baseline | neutral | vault | mobile

Camera [-3.7199999999999998, 1.72, -11.2] FOV 79.43425835096338 / DPR 1 / tier 0
Protected entry-route inspection. Neutral has NO PBR maps.

Stage3A.1 diagnostic pilot | dusk-1x | approach | desktop



Camera [-1.9250000000000003, 1.72, -7] FOV 58 / DPR 1 / tier 0
Approved dusk lighting. Geometry is NOT accepted.

Stage3A.1 diagnostic pilot | dusk-1x | normal-walking | desktop



Camera [-2.6750000000000003, 1.72, -9] FOV 58 / DPR 1 / tier 0
Approved dusk lighting. Geometry is NOT accepted.

Stage3A.1 diagnostic pilot | dusk-1x | side-fracture | desktop



Camera [-3.7199999999999998, 1.72, -11.2] FOV 58 / DPR 1 / tier 0
Approved dusk lighting. Geometry is NOT accepted.

Stage3A.1 diagnostic pilot | dusk-1x | along-wall | desktop



Camera [-4.0375, 1.72, -8.5] FOV 58 / DPR 1 / tier 0
Approved dusk lighting. Geometry is NOT accepted.

Stage3A.1 diagnostic pilot | dusk-1x | parallax-a | desktop



Camera [-3.245, 1.72, -10.2] FOV 58 / DPR 1 / tier 0
Approved dusk lighting. Geometry is NOT accepted.

Stage3A.1 diagnostic pilot | dusk-1x | parallax-b | desktop

Camera [-4.195, 1.72, -12.2] FOV 58 / DPR 1 / tier 0
Approved dusk lighting. Geometry is NOT accepted.

Stage3A.1 diagnostic pilot | dusk-1x | vault | desktop



Camera [-3.7199999999999998, 1.72, -11.2] FOV 58 / DPR 1 / tier 0
Approved dusk lighting. Geometry is NOT accepted.

Stage3A.1 diagnostic pilot | dusk-2x | approach | desktop



Camera [-1.9250000000000003, 1.72, -7] FOV 58 / DPR 1 / tier 0
Approved dusk lighting. Geometry is NOT accepted.

Stage3A.1 diagnostic pilot | dusk-2x | normal-walking | desktop

Camera [-2.6750000000000003, 1.72, -9] FOV 58 / DPR 1 / tier 0
Approved dusk lighting. Geometry is NOT accepted.

Stage3A.1 diagnostic pilot | dusk-2x | side-fracture | desktop

Camera [-3.7199999999999998, 1.72, -11.2] FOV 58 / DPR 1 / tier 0
Approved dusk lighting. Geometry is NOT accepted.

Stage3A.1 diagnostic pilot | dusk-2x | along-wall | desktop



Camera [-4.0375, 1.72, -8.5] FOV 58 / DPR 1 / tier 0
Approved dusk lighting. Geometry is NOT accepted.

Stage3A.1 diagnostic pilot | dusk-2x | parallax-a | desktop



Camera [-3.245, 1.72, -10.2] FOV 58 / DPR 1 / tier 0
Approved dusk lighting. Geometry is NOT accepted.

Stage3A.1 diagnostic pilot | dusk-2x | parallax-b | desktop

Camera [-4.195, 1.72, -12.2] FOV 58 / DPR 1 / tier 0
Approved dusk lighting. Geometry is NOT accepted.

Stage3A.1 diagnostic pilot | dusk-2x | vault | desktop

Camera [-3.7199999999999998, 1.72, -11.2] FOV 58 / DPR 1 / tier 0
Approved dusk lighting. Geometry is NOT accepted.

Stage3A.1 diagnostic pilot | neutral | approach | desktop



Camera [-1.9250000000000003, 1.72, -7] FOV 58 / DPR 1 / tier 0
Protected entry-route inspection. Neutral has NO PBR maps.

Stage3A.1 diagnostic pilot | neutral | normal-walking | desktop



Camera [-2.6750000000000003, 1.72, -9] FOV 58 / DPR 1 / tier 0
Protected entry-route inspection. Neutral has NO PBR maps.

Stage3A.1 diagnostic pilot | neutral | side-fracture | desktop

Camera [-3.7199999999999998, 1.72, -11.2] FOV 58 / DPR 1 / tier 0
Protected entry-route inspection. Neutral has NO PBR maps.

Stage3A.1 diagnostic pilot | neutral | along-wall | desktop



Camera [-4.0375, 1.72, -8.5] FOV 58 / DPR 1 / tier 0
Protected entry-route inspection. Neutral has NO PBR maps.

Stage3A.1 diagnostic pilot | neutral | parallax-a | desktop

Camera [-3.245, 1.72, -10.2] FOV 58 / DPR 1 / tier 0
Protected entry-route inspection. Neutral has NO PBR maps.

Stage3A.1 diagnostic pilot | neutral | parallax-b | desktop



Camera [-4.195, 1.72, -12.2] FOV 58 / DPR 1 / tier 0
Protected entry-route inspection. Neutral has NO PBR maps.

Stage3A.1 diagnostic pilot | neutral | vault | desktop

Camera [-3.7199999999999998, 1.72, -11.2] FOV 58 / DPR 1 / tier 0
Protected entry-route inspection. Neutral has NO PBR maps.

Stage3A.1 diagnostic pilot | dusk-1x | normal-walking | mobile



Camera [-2.6750000000000003, 1.72, -9] FOV 79.43425835096338 / DPR 1 / tier 0
Approved dusk lighting. Geometry is NOT accepted.

Stage3A.1 diagnostic pilot | dusk-1x | side-fracture | mobile



Camera [-3.7199999999999998, 1.72, -11.2] FOV 79.43425835096338 / DPR 1 / tier 0
Approved dusk lighting. Geometry is NOT accepted.

Stage3A.1 diagnostic pilot | dusk-1x | vault | mobile

Camera [-3.7199999999999998, 1.72, -11.2] FOV 79.43425835096338 / DPR 1 / tier 0
Approved dusk lighting. Geometry is NOT accepted.

Stage3A.1 diagnostic pilot | dusk-2x | normal-walking | mobile

Camera [-2.6750000000000003, 1.72, -9] FOV 79.43425835096338 / DPR 1 / tier 0
Approved dusk lighting. Geometry is NOT accepted.

Stage3A.1 diagnostic pilot | dusk-2x | side-fracture | mobile

Camera [-3.7199999999999998, 1.72, -11.2] FOV 79.43425835096338 / DPR 1 / tier 0
Approved dusk lighting. Geometry is NOT accepted.

Stage3A.1 diagnostic pilot | dusk-2x | vault | mobile

Camera [-3.7199999999999998, 1.72, -11.2] FOV 79.43425835096338 / DPR 1 / tier 0
Approved dusk lighting. Geometry is NOT accepted.

Stage3A.1 diagnostic pilot | neutral | normal-walking | mobile



Camera [-2.6750000000000003, 1.72, -9] FOV 79.43425835096338 / DPR 1 / tier 0
Protected entry-route inspection. Neutral has NO PBR maps.

Stage3A.1 diagnostic pilot | neutral | side-fracture | mobile

Camera [-3.7199999999999998, 1.72, -11.2] FOV 79.43425835096338 / DPR 1 / tier 0
Protected entry-route inspection. Neutral has NO PBR maps.

Stage3A.1 diagnostic pilot | neutral | vault | mobile

Camera [-3.7199999999999998, 1.72, -11.2] FOV 79.43425835096338 / DPR 1 / tier 0
Protected entry-route inspection. Neutral has NO PBR maps.

Reading this evidence

All 50 screenshots use the actual browser renderer. Original PNGs are provided separately. Camera, lighting, FOV, tier and DPR matches are verified in matched-pose-verification.json.

Entry-route cameras inspect the protected tunnel choreography. Along-wall offsets are diagnostic; they are not ordinary public hub walking positions.

The previous Stage3A entrance remains unchanged. It has not received the proposed broader art treatment because the new passage failed its gate.

No physical laptop or mobile GPU certification is claimed. See the technical report and raw logs, including failed attempts and startup failures.