Stage3A.1 ? pilot review


The actual scanned faces provide greater depth, but their join into the old passage makes visible ribbons, long returns and a separate rough patch. Neutral geometry is not visually convincing. This pilot does not pass.

Strict survey: 22 / 21 / 20 inverted first hits across LOD0/1/2. Walking envelope and exact shared borders pass. glTF validates, but that does not make the geometry suitable for adoption.

Quarry C9, public C5.1 and quarry 3x sampling are preserved. Tunnel-only features use 2x enlargement by halving owned sampler repeats once; no additional PBR images. No new fixtures or global lighting.


The 6?15m passage pilot is the only new geological region. Full 42m extension and entrance refinement were stopped at the mandatory pilot gate. Missing exact artwork has not been invented.

Stage3A baseline | neutral | normal-walking | desktop



Camera [-2.6750000000000003, 1.72, -9] FOV 58 / DPR 1 / tier 0
Protected entry-route inspection. Neutral has NO PBR maps.

Stage3A.1 diagnostic pilot | neutral | normal-walking | desktop



Camera [-2.6750000000000003, 1.72, -9] FOV 58 / DPR 1 / tier 0
Protected entry-route inspection. Neutral has NO PBR maps.

Stage3A baseline | neutral | side-fracture | desktop




Camera [-3.7199999999999998, 1.72, -11.2] FOV 58 / DPR 1 / tier 0
Protected entry-route inspection. Neutral has NO PBR maps.

Stage3A.1 diagnostic pilot | neutral | side-fracture | desktop




Camera [-3.7199999999999998, 1.72, -11.2] FOV 58 / DPR 1 / tier 0
Protected entry-route inspection. Neutral has NO PBR maps.

Stage3A baseline | neutral | along-wall | desktop




Camera [-4.0375, 1.72, -8.5] FOV 58 / DPR 1 / tier 0
Protected entry-route inspection. Neutral has NO PBR maps.

Stage3A.1 diagnostic pilot | neutral | along-wall | desktop




Camera [-4.0375, 1.72, -8.5] FOV 58 / DPR 1 / tier 0
Protected entry-route inspection. Neutral has NO PBR maps.

Stage3A baseline | dusk-1x | approach | desktop



Camera [-1.9250000000000003, 1.72, -7] FOV 58 / DPR 1 / tier 0
Approved dusk lighting. Geometry is NOT accepted.

Stage3A.1 diagnostic pilot | dusk-1x | approach | desktop



Camera [-1.9250000000000003, 1.72, -7] FOV 58 / DPR 1 / tier 0
Approved dusk lighting. Geometry is NOT accepted.

Stage3A baseline | dusk-1x | side-fracture | desktop



Camera [-3.7199999999999998, 1.72, -11.2] FOV 58 / DPR 1 / tier 0
Approved dusk lighting. Geometry is NOT accepted.

Stage3A.1 diagnostic pilot | dusk-1x | side-fracture | desktop




Camera [-3.7199999999999998, 1.72, -11.2] FOV 58 / DPR 1 / tier 0
Approved dusk lighting. Geometry is NOT accepted.

Stage3A baseline | dusk-1x | normal-walking | mobile




Camera [-2.6750000000000003, 1.72, -9] FOV 79.43425835096338 / DPR 1 / tier 0
Approved dusk lighting. Geometry is NOT accepted.

Stage3A.1 diagnostic pilot | dusk-1x | normal-walking | mobile



Camera [-2.6750000000000003, 1.72, -9] FOV 79.43425835096338 / DPR 1 / tier 0
Approved dusk lighting. Geometry is NOT accepted.

Stage3A.1 diagnostic pilot | dusk-2x | approach | desktop



Camera [-1.9250000000000003, 1.72, -7] FOV 58 / DPR 1 / tier 0
Approved dusk lighting. Geometry is NOT accepted.

Stage3A.1 diagnostic pilot | dusk-2x | normal-walking | desktop



Camera [-2.6750000000000003, 1.72, -9] FOV 58 / DPR 1 / tier 0
Approved dusk lighting. Geometry is NOT accepted.

Stage3A.1 diagnostic pilot | dusk-2x | side-fracture | desktop




Camera [-3.7199999999999998, 1.72, -11.2] FOV 58 / DPR 1 / tier 0
Approved dusk lighting. Geometry is NOT accepted.

Stage3A.1 diagnostic pilot | dusk-2x | along-wall | desktop



Camera [-4.0375, 1.72, -8.5] FOV 58 / DPR 1 / tier 0
Approved dusk lighting. Geometry is NOT accepted.

Stage3A.1 diagnostic pilot | dusk-2x | normal-walking | mobile



Camera [-2.6750000000000003, 1.72, -9] FOV 79.43425835096338 / DPR 1 / tier 0
Approved dusk lighting. Geometry is NOT accepted.

Stage3A.1 diagnostic pilot | dusk-2x | side-fracture | mobile




Camera [-3.7199999999999998, 1.72, -11.2] FOV 79.43425835096338 / DPR 1 / tier 0
Approved dusk lighting. Geometry is NOT accepted.

Stage3A.1 diagnostic pilot | neutral | parallax-a | desktop



Camera [-3.245, 1.72, -10.2] FOV 58 / DPR 1 / tier 0
Protected entry-route inspection. Neutral has NO PBR maps.

Stage3A.1 diagnostic pilot | neutral | parallax-b | desktop



Camera [-4.195, 1.72, -12.2] FOV 58 / DPR 1 / tier 0
Protected entry-route inspection. Neutral has NO PBR maps.

Stage3A.1 diagnostic pilot | neutral | vault | desktop



Camera [-3.7199999999999998, 1.72, -11.2] FOV 58 / DPR 1 / tier 0
Protected entry-route inspection. Neutral has NO PBR maps.

Recommendation

Keep the existing Stage3A and selected C9 as preserved comparisons. Do not promote this pilot or expand the scan graft along the tunnel.

The new source crop is uniformly scaled 1.0x. It retains true native triangles and undercuts; it is not a stretched scan or an envelope-displacement surface. Its joining method nevertheless fails.

Next work should address a compatible continuous tunnel-side interface, using actual visible topology and local retopology. Repeating or adding noise to this failed join would not repair it.

This is a visual-review stop. Public rendering, stage, navigation and lighting are unchanged. Full-resolution PNGs, gallery and all technical failures are available in the same review folder.