DETERMINING OPEN CIRCUIT LOCATION (HS-CAN) [SKYACTIV-D 2.2 (R.H.D.)]

id100206000400

Caution

- Perform the following malfunction diagnosis only when it is diagnosed with a open circuit by CONTROLLER AREA NETWORK (CAN) MALFUNCTION DIAGNOSIS FLOW [SKYACTIV-D 2.2 (R.H.D.)].
- If the malfunctioning part is detected in the communication line, before disconnecting the related connector for inspection, press the connector in the connection direction to verify that there is no looseness or disconnection.
- When disconnecting the connector, verify that there is no damage, deformation, or corrosion of the connector terminals.
- 1. Verify the CAN system-related module DTCs and the failed module on the M-MDS screen.
- 2. Apply the communication error DTC and the failed module to DTC output pattern and malfunctioning location, and select the possible cause for the diagnostic result and the reference for the inspection item.

Nota

- The open circuit location can be determined by the DTC indicated in the DTC output pattern and malfunctioning location chart. DTCs not listed in the chart are not used for the determination of the open circuit location.
- 3. Inspect the possible cause and inspection item of the applicable malfunctioning part.
- 4. After repairs, return to CONTROLLER AREA NETWORK (CAN) MALFUNCTION DIAGNOSIS FLOW [SKYACTIV-D 2.2 (R.H.D.)], and verify that the repairs have been completed.

DTC output pattern and malfunctioning location

Cross (x): Communication error-related DTC and failed module

M-MDS display																		
DTC output module	DTC	DTC output pattern and malfunctioning location																
PCM (PCM)	U0101:00				×													
	U0120:00															×		
	U0121:00		×															
	U0131:00																×	
	U0140:00					×												
	U0151:00														×			
	U0155:00																	×
	U0235:00											×						
	U0100:00	×																
	U0101:00				×													
ABS	U0114:00									×								
(DSC HU/ CM)	U0131:00															×*7	×*6	
	U0154:00														×			
	U0155:00																	×
	U0235:00											×						
	U0100:00	×		×														
TCM*1	U0121:00		×	×														
(TCM)	U0141:00					×												
,	U0155:00																	×
	U0100:00	×		×														
F_BCM	U0101:00				×													
(Front body control	U0121:00		×	×														
	U0151:00														×			
module	U0155:00																	×
(FBCM))	U0214:00															×		
	U0515:00										×							
. = 0 * 2	U0100:00	×		×			×*1											
AFS ^{*2} (AFS control module)	U0131:00																×	
	U0140:00					×	×*1											
	U0155:00																	×

M-MDS	display																		
DTC output module	DTC					DT	C out	put p	atterr	n and	malf	unctio	oning	loca	tion				
4X4 ^{*3}	U0100:00	×		×			×		×										$\overline{}$
	U0101:00			<u> </u>	×		×		×										\vdash
(4WD control module)	U0121:00		×	×			×		×										
	U0100:00	×		×			×		×		×				_				\vdash
SCBS*4 (Laser sensor)	U0121:00		×	×			×		×		×								\vdash
	U0131:00		<u> </u>	<u> </u>			<u> </u>		<u> </u>									×	\vdash
	U0155:00																		×
	U0100:00	×		×			×		×		×								
FSC*5	U0121:00		×	×			×		×		×								\vdash
(Forward	U0131:00		''	- ''														×	\vdash
sensing	U0140:00					×	×		×		×								\vdash
camera)	U0155:00								1										×
(differa)	U0214:00																×		\vdash
RCM	00211100																		\vdash
(SAS control module)	U0155:00																		×
	U0100:00	×		×			×		×		×			×		×			
	U0101:00				×		×		×		×			×		×			
	U0121:00		×	×			×		×		×			×		×			
SSU	U0121:87		×	×			×		×		×			×		×			
(Start stop	U0131:00																	×	
unit)	U0140:00					×	×		×		×			×		×			
	U0146:00																		×
	U0151:00														×	×			
	U0155:00																		×
EPS	U0100:00	×		×			×		×		×			×		×			
(EPS control module)	U0121:00		×	×			×		×		×			×		×			
	U0155:00																		×
	U0100:00	×		×			×		×		×			×		×			
	U0101:00				×		×		×		×			×		×			
	U0114:00									×	×			×		×			
	U0121:00		×	×			×		×		×			×		×			
IC	U0131:00																	×	
(Instrument	U0140:00					×	×		×		×			×		×			
cluster)	U0151:00														×	×			
	U0182:00						x*8	×	×		×			×		×			
	U0214:00																×		
	U0235:00											×		×		×			
	U023A:00												×	×		×			
M-MDS disp	lay module								[Fail] displ	ay pa	ttern							
PCM		×		×			×		×		×			×		×			
ABS			×	×			×		×		×			×		×			
TCM*1					×		×		×		×			×		×			
F_BCM						×	×		×		×			×		×			
AFS ^{*2}							x*8	×	×		×			×		×			
4X4 ^{*3}										×	×			×		×			
SCBS*4												×		×		×			
FSC*5													×	×		×			
RCM															×	×			\Box
SSU																	×		
EPS																		×	
IC																			×
Possible cause and					_	_	_	_	l	١.		1,				_	_	_	
inspection item		Α	В	С	D	E	F	G	Н		J	K	L	M	N	0	Р	Q	R
					•														


*1 : ATX vehicles *2 : With AFS system *3 : 4WD vehicles

- *4: With smart city brake support
 *5: With hi-beam control (HBC) system
 *6: Without smart city brake support or steering angle sensor
 *7: With smart city brake support or steering angle sensor
- *8: MTX vehicles

Α


- Connector terminal disconnection, poor contact, damage, deformation, corrosion
 Open circuit in wiring harness between PCM and connector C-32
 Connector C-32 malfunction

- PCM malfunction



- Connector C-32
- Wiring harness between PCM terminal 2AK and connector C-32
- Wiring harness between PCM terminal 2AL and connector C-32
 PCM

- Connector terminal disconnection, poor contact, damage, deformation, corrosion
- Open circuit in wiring harness between DSC HU/CM and connector C-32
 Connector C-32 malfunction
- DSC HU/CM malfunction



DSC HU/CM connector


- · Connector C-32
- Wiring harness between DSC HU/CM terminal AF and connector C-32
- Wiring harness between DSC HU/CM terminal AC and connector C-32
- DSC HU/CM

С

ATX vehicles

- Connector terminal disconnection, poor contact, damage, deformation, corrosion
- Open circuit in wiring harness between connector C-32 and front body control module (FBCM)
- Connector C-32 malfunction
- CAN circuit in front body control module (FBCM) malfunction

System wiring diagram



Inspection item


- Connector C-32
- Wiring harness between connector C-32 and front body control module (FBCM) terminal 2P
- Wiring harness between connector C-32 and front body control module (FBCM) terminal 2N
- Front body control module (FBCM)
 - Between front body control module (FBCM) terminal 2P and front body control module (FBCM) terminal 2K

— Between front body control module (FBCM) terminal 2N and front body control module (FBCM) terminal 2I

MTX vehicles

- Connector terminal disconnection, poor contact, damage, deformation, corrosion
- Open circuit in wiring harness between connector C-32 and connector C-01
- Open circuit in wiring harness between connector C-01 and connector C-01
- Open circuit in wiring harness between connector C-01 and front body control module (FBCM)
- Connector C-32
- Connector C-01
- CAN circuit in front body control module (FBCM) malfunction

System wiring diagram



Inspection item


- Front body control module (FBCM) connectorConnector C-32

ac5wzw00004534

- Connector C-01
- · Wiring harness between connector C-32 and connector C-01
- Wiring harness between connector C-01 and connector C-01
- · Wiring harness between connector C-01 and front body control module (FBCM) terminal 2P
- Wiring harness between connector C-01 and front body control module (FBCM) terminal 2N
- Front body control module (FBCM)
 - Between front body control module (FBCM) terminal 2P and front body control module (FBCM) terminal 2K
 - Between front body control module (FBCM) terminal 2N and front body control module (FBCM) terminal 2I

D

- Connector terminal disconnection, poor contact, damage, deformation, corrosion
- Open circuit in wiring harness between TCM and connector C-01
- Open circuit in wiring harness between connector C-01 and front body control module (FBCM)
- Connector C-01 malfunction
- TCM malfunction
- CAN circuit in front body control module (FBCM) malfunction




- TCM connector
- Connector C-01
- · Front body control module (FBCM) connector

- · Wiring harness between TCM terminal E and connector C-01
- Wiring harness between TCM terminal F and connector C-01
- Wiring harness between connector C-01 and front body control module (FBCM) terminal 2R
- Wiring harness between connector C-01 and front body control module (FBCM) terminal 2L
- Front body control module (FBCM)
 - Between front body control module (FBCM) terminal 2R and front body control module (FBCM) terminal 2K
 Between front body control module (FBCM) terminal 2L and front body control module (FBCM) terminal 2I

Ε

- Connector terminal disconnection, poor contact, damage, deformation, corrosion
- Front body control module (FBCM) malfunction




• Front body control module (FBCM)

ATX vehicles

- Connector terminal disconnection, poor contact, damage, deformation, corrosion
 Open circuit in wiring harness between front body control module (FBCM) and branch A
 CAN circuit in front body control module (FBCM) malfunction

System wiring diagram



Inspection item


- Front body control module (FBCM) connector
- · Wiring harness between front body control module (FBCM) terminal 2K and branch A
- Wiring harness between front body control module (FBCM) terminal 2I and branch A
- Front body control module (FBCM)

- Between front body control module (FBCM) terminal 2P and front body control module (FBCM) terminal 2K
- Between front body control module (FBCM) terminal 2N and front body control module (FBCM) terminal 2I

MTX vehicles

- Connector terminal disconnection, poor contact, damage, deformation, corrosion
 Open circuit in wiring harness between front body control module (FBCM) and connector C-04
- Open circuit in wiring harness between connector C-04 and connectors C-49, C-50
- Connector C-04 malfunction
- Connectors C-49, C-50 malfunction
- CAN circuit in front body control module (FBCM) malfunction

System wiring diagram



Inspection item

- Front body control module (FBCM) connector
- Connector C-04
- Connectors C-49, C-50


- Wiring harness between front body control module (FBCM) terminal 2K and connector C-04
- Wiring harness between front body control module (FBCM) terminal 2I and connector C-04
- Wiring harness between connector C-04 and connectors C-49, C-50
- Front body control module (FBCM)
 - Between front body control module (FBCM) terminal 2P and front body control module (FBCM) terminal 2K
 - Between front body control module (FBCM) terminal 2N and front body control module (FBCM) terminal 2I

G

ATX vehicles

- Connector terminal disconnection, poor contact, damage, deformation, corrosion
- · Open circuit in wiring harness between AFS control module and branch A
- AFS control module malfunction

System wiring diagram



Inspection item

- AFS control module connector
- Wiring harness between AFS control module terminal A and branch A
- Wiring harness between AFS control module terminal B and branch A
- AFS control module


ac5wzw00004539

MTX vehicles

Possible cause

- Connector terminal disconnection, poor contact, damage, deformation, corrosion
- Open circuit in wiring harness between AFS control module and front body control module (FBCM)
- CAN circuit in front body control module (FBCM) malfunction
- AFS control module malfunction
- · CAN circuit in front body control module (FBCM) malfunction

System wiring diagram




- Front body control module (FBCM) connector
- AFS control module connector
- · Wiring harness between AFS control module terminal A and front body control module (FBCM) terminal 2R
- Wiring harness between AFS control module terminal B and front body control module (FBCM) terminal 2L
- · AFS control module
- Front body control module (FBCM)
 - Between front body control module (FBCM) terminal 2R and front body control module (FBCM) terminal 2K
 - Between front body control module (FBCM) terminal 2L and front body control module (FBCM) terminal 2L

Н

4WD vehicles (ATX)

- Connector terminal disconnection, poor contact, damage, deformation, corrosion
- Open circuit in wiring harness between branch A and connector C-04
- Open circuit in wiring harness between connector C-04 and connectors C-49, C-50
- Connector C-04 malfunction
- Connectors C-49, C-50 malfunction

System wiring diagram



Inspection item

- Connector C-04
- Connectors C-49, C-50
- Wiring harness between branch A and connector C-04 Wiring harness between connector C-04 and connectors C-49, C-50


ac5wzw00004541

2WD vehicles (ATX)

Possible cause


- Connector terminal disconnection, poor contact, damage, deformation, corrosion
- Open circuit in wiring harness between branch A and connector C-04
- Open circuit in wiring harness between connector C-04 and connector C-10
- Open circuit in wiring harness between connector C-10 and connector C-11
- Open circuit in wiring harness between connector C-11 and branch B
- Connector C-04 malfunction
- Connector C-10 malfunction
- Connector C-11 malfunction

System wiring diagram



- Connector C-04
- Connector C-10
- Connector C-11
- Wiring harness between branch A and connector C-04
- Wiring harness between connector C-04 and connector C-10
- Wiring harness between connector C-10 and connector C-11
- Wiring harness between connector C-11 and branch B

- Connector terminal disconnection, poor contact, damage, deformation, corrosion
- Open circuit in wiring harness between 4WD control module and connectors C-49, C-50
- Connectors C-49, C-50 malfunction
 4WD control module malfunction




4WD control module connector

- Connectors C-49, C-50
- Wiring harness between 4WD control module terminal G and connector C-49
- Wiring harness between 4WD control module terminal H and connector C-50
- 4WD control module

With smart city brake support or hi-beam control (HBC) system Possible cause

- Connector terminal disconnection, poor contact, damage, deformation, corrosion
- Open circuit in wiring harness between connectors C-49, C-50 and connector C-10
- Open circuit in wiring harness between connector C-10 and connector C-11
- Open circuit in wiring harness between connector C-11 and branch B
 Connectors C-49, C-50 malfunction
- Connector C-10 malfunction
 Connector C-11 malfunction

System wiring diagram



Inspection item

- Connectors C-49, C-50
- Connector C-10
- Connector C-11


ac5wzw00004544

- Wiring harness between connectors C-49, C-50 and connector C-10
- Wiring harness between connector C-10 and connector C-11
- Wiring harness between connector C-11 and branch B

Without smart city brake support or hi-beam control (HBC) system Possible cause

- Connector terminal disconnection, poor contact, damage, deformation, corrosion
- Open circuit in wiring harness between connectors C-49, C-50 and connector C-10
- Open circuit in wiring harness between connector C-10 and connector C-11
- Open circuit in wiring harness between connector C-11 and connector C-11
- Open circuit in wiring harness between connector C-11 and connectors C-51, C-52
- Connectors C-49, C-50 malfunction
- Connector C-10 malfunction
- Connector C-11 malfunction
- Connectors C-51, C-52 malfunction

System wiring diagram



Inspection item


Connectors C-49, C-50

- Connector C-10
- Connector C-11
- Connectors C-51, C-52
- Wiring harness between connectors C-49, C-50 and connector C-10

ac5wzw00004545

- Wiring harness between connector C-10 and connector C-11
- Wiring harness between connector C-11 and connector C-11
- Wiring harness between connector C-11 and connectors C-51, C-52

- Connector terminal disconnection, poor contact, damage, deformation, corrosion
- Open circuit in wiring harness between laser sensor and connector C-42
 Open circuit in wiring harness between connector C-42 and branch B
- Connector C-42 malfunction
- · Laser sensor malfunction




laser sensor connector

- Connector C-42
- Wiring harness between laser sensor terminal D and connector C-42
- Wiring harness between laser sensor terminal C and connector C-42
- Wiring harness between connector C-42 and branch B
- Laser sensor

L

- Connector terminal disconnection, poor contact, damage, deformation, corrosion
- Open circuit in wiring harness between forward sensing camera and connector C-42
- Open circuit in wiring harness between connector C-42 and branch B
- Connector C-42 malfunction
- Forward sensing camera malfunction




Forward sensing camera connector

- Connector C-42
- Wiring harness between forward sensing camera terminal E and connector C-42
- Wiring harness between forward sensing camera terminal C and connector C-42
- Wiring harness between connector C-42 and branch B
- Forward sensing camera


M

- Connector terminal disconnection, poor contact, damage, deformation, corrosion
- Open circuit in wiring harness between branch B and connector C-11
- Open circuit in wiring harness between connector C-11 and connector C-51, C-52
- Connector C-11 malfunction
- Connectors C-51, C-52 malfunction



- Connectors C-51, C-52
- Wiring harness between branch B and connector C-11
- Wiring harness between connector C-11 and connectors C-51, C-52

- Connector terminal disconnection, poor contact, damage, deformation, corrosion
 Open circuit in wiring harness between SAS control module and connectors C-51, C-52
 Connectors C-51, C-52 malfunction
 SAS control module malfunction




Warning

- Handling the component parts of the SRS air bag system improperly can accidentally operate (deploy) the air bag module, which may seriously injure you. Read the service warnings and cautions before handling the air bag system components of the SRS air bag system. (See AIR BAG SYSTEM SERVICE WARNINGS.)
 (See AIR BAG SYSTEM SERVICE CAUTIONS.)
- SAS control module connector
- Connectors C-51, C-52
- Wiring harness between SAS control module terminal 3K and connector C-51
- Wiring harness between SAS control module terminal 3L and connector C-52
- SAS control module

o


- Connector terminal disconnection, poor contact, damage, deformation, corrosion
- Open circuit in wiring harness between connectors C-51, C-52 and connector C-34
- Connectors C-51, C-52 malfunction
- Connector C-34 malfunction



• Connectors C-51, C-52

- Connector C-34
- Wiring harness between connectors C-51, C-52 and connector C-34


- Connector terminal disconnection, poor contact, damage, deformation, corrosion
 Open circuit in wiring harness between start stop unit and connector C-34
- Connector C-34 malfunction
- · Start stop unit malfunction



· Start stop unit connector

- · Connector C-34
- Wiring harness between start stop unit terminal 2M and connector C-34
- Wiring harness between start stop unit terminal 2O and connector C-34
- Start stop unit


- Connector terminal disconnection, poor contact, damage, deformation, corrosion
- Open circuit in wiring harness between EPS control module and connector C-34
 Connector C-34 malfunction
- EPS control module malfunction



• EPS control module connector

- · Connector C-34
- Wiring harness between EPS control module terminal 2A and connector C-34
 Wiring harness between EPS control module terminal 2D and connector C-34
- EPS control module

- Connector terminal disconnection, poor contact, damage, deformation, corrosion
- Open circuit in wiring harness between instrument cluster and connector C-34
 Connector C-34 malfunction
- Instrument cluster malfunction



Instrument cluster connector

- Connector C-34
- Wiring harness between instrument cluster terminal B and connector C-34
 Wiring harness between instrument cluster terminal D and connector C-34
 Instrument cluster