Holfelder GmbH
Feringastr. 12 a/b
85774 Unterföhring
Germany

Date: 10.11.2026
Delivery note: 2026-344819 (05.11.2026)
Your order confirmation: 2026-232475
Our purchase order: P00053

Quality report – MFJ 4.0 Unisex grey

Incoming goods inspection and photo documentation

Dear Holfelder team,

thank you for the delivery of the MFJ 4.0 jackets (grey, item SP1007176 – "Herren"). We have counted the complete delivery and carried out our incoming goods inspection. Below you will find the quantities received and the jackets that are not acceptable for sale.

Received (jackets)	Inspected	Not acceptable for sale	Accepted into stock
499	**35**	**2**	**497**
delivery note = counted	7.0 % of the delivery	both size S	

1. Quantities received and inspected

	S	M	L	XL	XXL	3XL	4XL	Total
Delivery note	40	100	134	125	50	30	20	**499**
Counted	40	100	134	125	50	30	20	**499**
Inspected	5	7	8	6	4	3	2	**35**
Not acceptable for sale	**2**	**0**	**0**	**0**	**0**	**0**	**0**	**2**

Counted quantities match the delivery note on every size – no difference. Also received: 704 zipper puller sets, not part of this jacket inspection.

2. Not acceptable for sale – 2 jackets


These jackets are stored separately and have not been taken into stock.

Colour	Size	Qty	Defect
Grey	S	1	Seams on the left sleeve not cleanly stitched.
Grey	S	1	Pocket flap corner: small hole, stitching at the corner not cleanly finished.
Total		**2**	

Our request: please review the 2 jackets listed above and let us know how you would like to proceed – repair, replacement or credit note. The jackets are ready for collection or return shipment at our warehouse.

2a. Photos – not acceptable for sale

Left: the defect. Right: the tag on the jacket.





Grey S (1) – Issue: seams on the left sleeve not cleanly stitched. Reason: visible seam defect, the seam is not secure – not acceptable for sale.



Grey S (2) – Issue: small hole at the corner of the pocket flap, stitching not cleanly finished. Reason: visible damage on the outer fabric – not acceptable for sale.