Holfelder GmbH
Feringastr. 12 a/b
85774 Unterföhring
Germany

Date: 05.11.2026
Delivery note: 2026-344396 (28.10.2026)
Your order confirmation: 2026-232475
Our purchase order: P00053

# Quality report – MFJ 4.0 Women

Incoming goods inspection and photo documentation

Dear Holfelder team,

thank you for the delivery of the MFJ 4.0 women's jackets. We have counted the complete delivery and carried out our incoming goods inspection. Below you will find the quantities received, the jackets that are not acceptable for sale, and further workmanship issues we would like you to look at for future production.

| Received (women's jackets) | Inspected | Not acceptable for sale | Accepted into stock |
|---|---|---|---|
| **1,000** | **112** | **8** | **992** |
| grey 499 · black 501 | 11.2 % (56 grey · 56 black) | grey 3 · black 5 | grey 496 · black 496 |

## 1. Quantities received

| | XS | S | M | L | XL | 2XL | 3XL | 4XL | Total |
|---|---|---|---|---|---|---|---|---|---|
| Grey – delivery note | 25 | 95 | 150 | 125 | 65 | 30 | 4 | 5 | **499** |
| Grey – counted | 25 | 95 | 150 | 125 | 65 | 30 | 4 | 5 | **499** |
| Black – delivery note | 14 | 85 | 196 | 99 | 77 | 24 | 3 | 3 | **501** |
| Black – counted | 14 | 85 | 196 | 99 | 77 | 24 | 3 | 3 | **501** |
| **Total women's jackets** | | | | | | | | | **1,000** |

Counted quantities match the delivery note on every size – no difference. Also received: zippers (21 men / 68 women), not part of this jacket inspection. Not yet delivered: 500 MFJ 4.0 Unisex grey (order confirmation 2026-232475).


## 2. Not acceptable for sale – 8 jackets

These jackets are stored separately and have not been taken into stock.

| Colour | Size | Qty | Defect |
|---|---|---|---|
| Grey | M | 1 | Uneven stitching / patch finishing in the photographed area. |
| Grey | XL | 2 | Hole in the right inner pocket; uneven stitching / patch finishing, visible missed stitches or unsecured edges. |
| Black | XS | 1 | Excess fabric at the seam, improperly stitched. |
| Black | M | 1 | IQ patch missing on one shoulder side. |
| Black | L | 1 | Lower pockets have no lining pocket bags. |
| Black | 3XL | 1 | Inner pocket damaged. |
| Black | 4XL | 1 | Small pocket and inner pocket damaged. |
| **Total** | | **8** | |

Our request: please review the 8 jackets listed above and let us know how you would like to proceed – repair, replacement or credit note. The jackets are ready for collection or return shipment at our warehouse.

## 2a. Photos – not acceptable for sale (grey)





Grey | IQ patch: visible uneven stitching / edge.





Grey | Lower patch edge: uneven attachment.



Grey | Patch corner: loose edge and irregular stitching.




Grey | Patch corner: stitching end not cleanly finished (detail).




Grey XL | Tag: hole in the right inner pocket.

## 2b. Photos – not acceptable for sale (black)

Left: the defect. Right: the tag on the jacket.






Black 3XL – Issue: inner pocket damaged. Reason: functional defect, the pocket cannot be used – not acceptable for sale.







Black 4XL – Issue: small pocket and inner pocket damaged. Reason: functional defect on two pockets – not acceptable for sale.







Black M – Issue: IQ patch missing on one shoulder. Reason: product incomplete, branding element missing – not acceptable for sale.






Black XS – Issue: excess fabric at the seam, improperly stitched. Reason: visible seam defect, seam not cleanly finished – not acceptable for sale.


Tag only – the defect is inside the pocket.




Black L – Issue: the lower pockets have no lining pocket bags. Reason: pockets cannot be used, product incomplete – not acceptable for sale.

## 3. Issues that will not keep us from putting them into sale – but please watch workmanship next time

The following findings were also documented during the inspection. These jackets have been accepted and are going into sale. We kindly ask you to pay attention to these points in future production.



1 | Sleeve seam: uneven stitching.



2 | Seam with loose thread end.



3 | Seam edge: frayed / uneven stitching.



4 | Cuff edge: irregular finishing.



5 | Seam: irregular / skipped stitches.



6 | Seam: irregular / skipped stitches (detail).



7 | Loose thread ends removed during inspection.



8 | Seam at the end of the chest zipper frayed.