

SM_A810S_REV0.5

2016.08.18

sheet01: GSM/WCDMA/LTE/CDMARF

sheet02: TRANSCEIVER(SHNNON933) / CP(SHANNON333) / CP PMIC

sheet03: BT/WIFI/GPS/TDMB/NFC


sheet04: AP (EXYNOS7420 - ISTOR)


sheet05: AP (EXYNOS7420 - ISTOR)


sheet06: PMIC/IF PMIC/BATTERY CON


sheet07: AUDIO/ IF SUB CON


sheet08: SIM / SD / BTP / SENSOR / OCTA / CAM / UPPER SUB



























AON1605(TR7001): IT'S Wrong Polar ity possibility. Check the Pin1

	Model:							
	Revision:							
	Manufacture Count :							
	Charge							
	Contact	t :						
	Date:							
	Routing	1 .						
	Resin:							
	Kesiii .							
	+ ×							
	0							
	Φ							
	Φ							
+	9							
	 S							
	8							
	+							
	×							
	0							
	Φ							
	⊕ ⊛							
	8							
	B							
	+							
	×							
	0							
	Θ							
	0							
\vdash	0			\vdash				
	<u>@</u>		-	\vdash				
	8							
	+							
	×							
	Θ							
	0							

VX_Setup(2016-01-20)_HHP

O O O O O O O O O O O O O O O O O O O	 	 	_
O O O O O O O O O O			
O O O O O O O O O O		0	
		Φ	
		0	
D N N N N N N N N N			
No			
+			
O O O O O O O O O O O O O O O O O O O			
O O O O O O O O O O O O O O O O O O O			
0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		×	
0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0			
0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0			
0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0			
0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		_	
O			
O			
D B B B B B B B B B	 		
8 8 1			
8 8 1			
+ + × × × × × × × × × × × × × × × × × ×			
O O O O O O O O O O O O O O O O O O O			
O O O O O O O O O O O O O O O O O O O			
0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		X	
0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0			
0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0			
0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0			
0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		0	
Part Part			
O			
8			
B			
+ + × × × × × × × × × × × × × × × × × ×		B	
+ + × × × × × × × × × × × × × × × × × ×		Ħ	
X			
0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0			
0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0			
0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0			
0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0			
0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		_	
0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	-		-
0 0 1 1 1 1 1 1 1 1			-
0 0 0 0 0 0 0 0 0 0			
0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0			
0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0			
8			
+ X			
8 B	 -		
0 0 0 0 0 0 0 0 0 0 8 8	-		-
• • • • • • • • • • • • • • • • • • •		×	
• • • • • • • • • • • • • • • • • • •			
• • • • • • • • • • • • • • • • • • •			
• • • • • • • • • • • • • • • • • • •			
• • • • • • • • • • • • • • • • • • •		Θ	
Ф Ф П			
⊕ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □			
□ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □			-
B ⊞			
■			
		Ħ	
		+	



AON1605(TR7001): IT'S Wrong Polar ity possibility. Check the Pin1

Model : Revision :

Manufacture Count:

Charge:
Contact:
Date:
Routing:
Resin: