ABOUT CAVITATION EROSION RESISTANCE OF THE AUSTENITIC STAINLESS STEEL HEAT TREATED

Ioan Pădurean¹, Marin Trușculescu¹, Arpad Fay², Dorian Nedelcu³, Elvira Pădurean⁴

- 1 "Politehnica" University of Timişoara padurean58@yahoo.com
- 2 University of Miskolc arpad.fay@axelero.hu
- 3 "Eftimie Murgu" University Reşiţa <u>d.nedelcu@uem.ro</u>
- 4 "TudorTănăsescu" High School elvirapadurean@yahoo.com

ABSTRACT

Paper presents the experimental results obtained by testing to cavitation erosion the Austenitic stainless steel GX5CrNi19-10 in conformity with SR EN 10283 [20] after solution treatment. The test facility used is of magnetostrictive type with nickel tube. The tests have been carried out in Timisoara Hydraulic Machinery Laboratory. The results have been compared with those of the steel 40Cr10 with good but not excellent cavitation erosions and with the steels used for hydraulic turbines T07CuMoMnNiCr165-Nb and T09CuMoMnNiCr185-Ti. For comparisons have been used the characteristic cavitation erosion curves [1], [2] and it resulted that GX5CrNi19-10 has excellent cavitation erosion qualities.

KEYWORDS

Cavitation; erosion; heat treatment, vibratory device; erosion rate; cavitation erosion time.

1. INTRODUCTION

Among the negative effects of cavitation, one of greatest importance is the erosion of the solid boundaries guiding the flow [1]. Working out hydraulic machinery with total exclusion of cavitation is not possible for economic reasons. Commonly, the running of hydraulic machinery take place with "industrial allowed cavitation" for which the power characteristics are not at all affected but cavitation erosion is present, in the limits of prescribed material losses of [1], [2]. The cavitation erosion process is a very complex one and implies two different sides, interacting mutually: the first one is the physical process of the implosion of cavitation bubbles and the other one is the way in which those implosions affect the material [1], [3]. In spite of numerous researches carried out until now, the complexity of the interaction between the implosions and the crystalline structure of the material is not completely cleared up. Anyhow, for the contemporary technique there are not materials that can resist to an intense cavitation action. Instead, for industrial allowed cavitation, the appropriate selection of materials can lead to increased intervals between consecutive repair works and that is highly recommendable from the economic point of view.

In the present work it will be analyzed the cavitation erosion resistance of the Austenitic stainless steel GX5CrNi19-10 subjected to solution heat treatment. The analysis and comparisons will be made using the characteristic values and curves obtained in a vibratory test facility with nickel tube [2].

2. TESTED MATERIAL2.1 Mechanical and chemical properties

The tested material is the Austenitic stainless steel GXCrNi19-10. Besides cavitation erosion tests, there have been made also tests to obtain the chemical composition, the mechanical properties at environmental temperature and metallographic analyses. For tests, 15 mm diameter probes were taken out from the material. The results are presented in table no. 1. From these tests it results that the specimens are manufactured from the steel GX5CrNi19-10. In agreement with the standard SR EN10283/99, at first, the specimens were subjected to water quenching and afterwards the mechanical characteristics presented in Table 1 were determined.

Table no. 1

		Steel GX5CrNi19-10. Chemical composition. Mechanical characteristics.												
Steel	Status	Chemical composition [%]						Mechanical characteristics at 20°C						
mark	Status	С	Si	Mn	Р	C	Cr	Ni	Mo	$Rp_{0,2}$	Rm	A5%	KV	НВ
		Ù	31	IVIII	Г	2	CI	111		MPa	MPa	min	J	пь
GX5CrNi 19-10 1.4308	CS 1050 ⁰ C 30 min H ₂ O	0,048	0,43	1,49	0,028	0,026	19,1	10,1	0,3	175	440	35	60	230

2.2. Metallographic examination

There have been performed macro and micro structural analyses on the specimens, before and after the cavitation erosion tests. The metallographic preparation was carried out according to "General Metallographic Standard" (Stas 4203-74) [21]; "Taking over and Preparation of Metalographic Specimens" and sr en 5000-97 [22] with regard to "Metallographic Structures and Constituents of Ferrous Products". In order to determine the micrographic magnitude of the ferritic, austenitic or Martensitic grain the standard "Metallographic Determinations" sr iso 643-93 [23] was respected, using the reactive presented in Table no. 2.

Table no. 2

Symbol	Name	Composition	Surface Preparing	Precaution
В8	Solution of Chlorine hydride and Nitric Acid	39 ml water 59 ml chl. hydr. 9 ml nitric acid Availability: without limits	Diamond paste 3µm or finely Attack Temperature: Ambient temperature Time of attack: From seconds to minutes	Precaution in using acids

The microstructure of the steel GX5CrNi19-10 obtained with an optic microscope provided with a digital camera is presented in Figure no. 1.



Figure no. 1 Steel GX5CrNi19-10 Steel GX5CrNi19-10; HT: 1050°C/30 min/ water; Mo 500x

It can be clearly seen that the investigated steel has:

- austenitic structure with macles in some grains
- the granulation is G = 8 in agreement with the ASTM standard.

2.3 Researches upon the cavitation erosion of the specimens manufactured from GX5CrNi19-10

In conformity with the ASTM standard [19] the tests were carried out on three probes, in distilled water at the temperature $T = 20\pm1$ °C.

- pressure at the liquid surface: p = pat;
- power: P = 500 W;
- specimen diameter: d=14 mm;
- specimen immersion: h = 3mm.

The total duration of the cavitation attack of 165 minutes was divided in 12 periods, as follows: one of 5 minutes, one of 10 minutes and 10 of 15 minutes. At the beginning and at the end of each period the specimens have been washed successively in current water, distilled water, alcohol, acetone, after that desiccated in a hot air current and finally weighed in an analytical balance with six characteristic figures.

3. EXPERIMENTAL RESULTS

The measured and computed data are presented in "Testing Bulletin" and subsequently the following cavitation erosion characteristic curves have been obtained:

- Variation in time of the cavitation eroded mass ma(t), Fig. 3;
- Variation in time of the cavitation erosion velocity v(t), Fig. 2.

The cavitation attack was realized at Timisoara Hydraulic Machinery Laboratory in a vibratory magnetostrictive test facility with nickel tube. The facility is characterized by the following parameters:

- vibration amplitude: $A = 94 \mu m$;
- frequency: $f = 7000 \pm 3$ Hz.

Observation: The value m_a in the "Test Bulletin" is obtained averaging the mass losses of the three tested specimens.

Testing Bulletin


Magnetostictive facility with nickel tube Material: stainless steel GX5CrNi19-10


Test liquid: distilled water Control amplitude: 47 μm Mean frequency: 7000 \pm 3% Hz

Temperature of the working liquid: 20±1°C


Tabel no. 3

Time	Eroded Mass	Erosion
<min></min>	$m_a x 10^3 < g >$	Velocity
		$Vx10^5 < g/min >$
0	0	0
5	1,8	0,4
15	2,89	0,54
30	6,55	1,92
45	8,73	2,94
60	10,61	3,97
75	12,11	5,3
90	12,88	6,6
105	13,16	7,9
120	13,5	9,3
135	13,5	10,6
150	13,5	11,9
165	13,5	13,2







The macroscopic structure of the steel GX5CrNi19-10 for different cavitation test duration is presented in Figure no. 4.











75 min MO 10X

105 min MO 10X

165 min MO 10X

165 min MO 10X

165 min MO 20X

Figure no. 4 The macroscopic structure of the steel GX5CrNi19-10 for different cavitation test duration

4. ANALISYS OF EXPERIMENTAL RESULTS

From Table no. 3 and Figure no. 3 it results that the total lost mass is very restrained $m_a = 18.26$ mg.

The characteristic curve cavitation erosion velocity function of time (Figure no. 2) presents a stabilization value vs = const. at a very low level.

The velocity in time curve presents a maximum erosion velocity equal with the stationary one $v_{max} = v_s$ and differs from the curves v(t) analyzed in [2], [3], [10], [12] for which in the first 30 minutes it presents a maximum value of the velocity $v = v_{max}$ and after that the curve shows an attenuation, till the stabilization value $v = v_s$ is attained.

In Table no. 4 there are made comparisons between the eroded masses after 165 minutes of cavitation attack and the steady state erosion velocities for many steels used in the manufacturing of hydraulic machinery [2], [3], [6], [10].

The cavitation erosion of the specimens takes place slowly, gradually and without important craters.

Table no. 3

Steady state erosion velocity and eroded mass					
Steel mark	$v_s x 10^5$	$m_a x 10^3$			
Steel mark	<g min=""></g>	<g></g>			
GX5CrNi19-10	12.50	18.26			
40Cr10	35.00	45.00			
GX5CrNiMo13-6-1	22.00	32.00			
T07	13.60	14.50			
T09	15.00	15.00			

Where T07 <=> T07 CuMoMnNiCr 165-Nb

T09 <=> T09 CuMoMnNiCr 185-Ti

5. CONCLUSIONS

The austenitic steel GX5CrNi19-10 before heat treatment has an austenitic structure with carbides precipitated at grain boundaries.

After the recommended heat treatment, the grain boundaries carbides were dissolved and the homogeneity of austenite is improved.

The cavitation erosion resistance of the steel GX5CrNi19-10 became better in comparison with other steels used commonly in manufacturing the hydraulic turbines runners.

The tests carried out with the stainless steel GX5CrNi19-10 certify a good behavior at cavitation erosion and it is useful to undertake studies for employing it in hydraulic machinery manufacturing.

ACKNOWLEDGEMENTS

We wish to express particular thanks to professor Ph. eng. Marin Trusculescu, fellow of Romanian Technical Sciences Academy and to professor Ph. eng. Arpad Fay from Miskolc, University Hungary, for guidance and useful councils during the elaboration of this work.

REFERENCES

- [1] Anton, I., Cavitația, Vol. I, II, Editura Academia R.S.R., București 1984, 1985.
- [2] Bordeasu I., Distrugeri cavitaționale, Editura MacroSOFT Timișoara 1998
- [3] Bordeașu, I., Eroziunea cavitațională asupra materialelor utilizate în construcția mașinilor hidraulice și elicelor navale. Efecte de scară, Teză de doctorat, Timișoara, 1997.
- [4] Bordeașu I., Pădurean I., Durabilitatea cavitațională a unor oțeluri aliate, Analele Facultății de Inginerie, Hunedoara, 1995.
- [5] Bordeașu I., Pădurean I., Rezistența la cavitație a oțelului 20Cr130, Lucrările Științifice ale Universității Petroșani, Vol. III, 1998.
- [6] Georgevici I., Contribuții privind dezvoltarea unor oțeluri inoxidabile cu transformare martensitică directă, Teză de doctorat, 2003
- [7] Kuzman A. F., Potentcz I., Rezistenţa la eroziune cavitaţională a unor oţeluri indigene, Buletinul Ştiinţific şi Tehnic al Institutului Politehnic "Traian Vuia" Timişoara, Tom 23(37), Fascicula 1 1978.
- [8] Kuzman A.F., Potentz I, Trusculescu M., Mitelea I., Rezistența la eroziune cavitațională a unor oțeluri indigene, Influența tratamentului termic, Buletinul Științific si Tehnic a Institutului Politehnic, " Traian Vuia" Timisoara, Tom 22 (36), Fascicula 1 1977.
- [9] Pădurean I., Bordeașu I., Rezistența la distrugere cavitațională a unor oțeluri durificate, Analele Universității Oradea, Vol. I, Fascicola Energetică 1999.
- [10] Pădurean I., Bordeașu I., Rezistența la eroziune cavitațională a oțelului 40Cr130. Lucrările Științifice ale Universității Petroșani, Vol. III, 1998.
- [11] Pădurean I., Bordeașu I., Rezistența la distrugere cavitațională a unor oțeluri durificate, Analele Universității Oradea, Vol. I, Fascicola de energetică, 1999.
- [12] Pădurean I., Bordeașu I., Rezistența la eroziune cavitațională a oțelului 40Cr130, Lucrările științifice ale Universității Petroșani, Vol. III, 1998.
- [13] Popoviciu M., Bordeaşu I., A quantitative method of estimating the cavitation behaviour of materials tested in a magnetostrictive facility, Buletin Ştiinţific Universitatea Politehnica "Timişoara", Vol 41 (55), 1996.
- [14] Popoviciu M., Kuzman A. F., -Contributions to the study of cavitation erosion on Kaplan turbine runners, Conference "Hydroforum", Gdansk, 1985..
- [15] Trușculescu M., Studiul metalelor, Editura Didactică și Pedagogică, București,1977
- [16] Truşculescu, M, Ieremia, A.,-Oţeluri inoxidabile şi refractare, Editura Facla, Timişoara, 1981.
- [17] Trușculescu M., Demian M.,- Materialotehnica, Vol.I, Metalurgie structurală. Editura Politehnica, Timișoara-2003.
- [18] Trușculescu M., Cucuruz R., Raduță A., Studiul metalelor, Analize și încercări, Litografia Universității Tehnice, Timișoara, 1992.
- [19] ***Standard method of vibratory cavitation erosion test ASTM, Standard G 32 85.
- [20] *** SR EN 10283/1999 Oțeluri turnate rezistente la coroziune
- [21] *** STAS 4203-74, Luarea și pregătirea probelor metalografice.
- [22] *** SR 5000-97, Structuri si constituenti metalografici ale probelor feroase.
- [23] *** SR ISO 643-93, Determinarea micrografică a mărimii grăuntelui feritic, austenitic sau martensitic.
- [24] *** CR 12361/1999, Reactivi pentru oţelurile inoxidabile.