

memorandum

Date: July 28, 2025

To:

cc:

From: Lauren Hull, PE, RSP₁

Re: Dixie Highway from Grange Hall Road to I-75

Background

The Road Commission for Oakland County (RCOC) received funding from the Safe Streets and Roads for All (SS4A) Grant Program for the development of a Comprehensive Safety Action Plan. As part of this effort, the segment of Dixie Highway from Davisburg Road to Grange Hall Road was studied for potential improvements. One of these improvements included a lane reconfiguration of Dixie Highway from a four-lane cross-section to a three-lane cross-section with wide shoulders. After review of that segment, it was determined that this improvement should be studied for Dixie Highway from Grange Hall Road north to I-75.

This segment of Dixie Highway is located in Groveland and Holly Townships. Dixie Highway provides connectivity to I-75 at the north end of this segment for this rural, growing community. Dixie Highway transitions from a balanced undivided highway to a divided highway near I-75. The posted speed limit is 55 mph. Significant traffic volumes are generated from events along this segment. This area hosts several events that bring traffic from other parts of the metro-Detroit region. These events include the Renaissance Festival, the Oakland County Fair, the DNR off-road vehicle park, and several regional parks. This report will focus on Dixie Highway up until the northbound and southbound lanes split near I-75.

Traffic Information

Traffic counts were not collected along this extended segment of Dixie Highway. In order to complete, an operational analysis, more data would be required. Two areas in particular have more complex operations to consider: the tie into the divided road section near I-75 and the frontage to the Renaissance Festival. Due to these constraints, this study will rely on existing road geometry to establish a footprint that includes the addition of a two-way center left-turn lane and an appropriate place to terminate the two-way center left-turn lane near I-75.

Safety Analysis

A safety analysis was performed to explore the recent crash history along the segment of Dixie Highway from Grange Hall Road to I-75. The primary focus of this analysis was to summarize and identify crash patterns. These patterns help identify safety concerns, which may be reduced by the proposed intersection improvements included in this study. Particular attention was given to head-on and angle crashes, which tend to result in more serious injuries and greater property damage.

Crash data for the analysis was downloaded from the Traffic Improvement Association's (TIA) Traffic Crash Analysis Tool (TCAT). Detailed traffic crash reports (UD-10s) for the most severe, including any crashes with pedestrian or bicyclist involvement were also downloaded and reviewed in detail. The crash data encompassed



a period of three full years spanning January 1, 2021, through December 31, 2023. Historical Crash Data can be found in the Appendix.

A summary of the segment crash data is shown in Table 1.

Table 1: Segment Crash Summary

Crash Year	Crash Type						TOTAL	Crash Severity				
	Sideswipe	Head-on	Angle	Rear End	Single Vehicle	Other		K (Fatal)	A (Incapacitating)	B (Non-Incapacitating)	C (Possible)	O (Property Damage Only)
2021	4	1	5	5	6	2	23	0	1	3	6	13
2022	3	2	3	5	17	0	30	0	0	1	3	26
2023	3	2	4	14	19	4	46	1	0	5	5	35
Total	10	5	12	24	42	6	99	1	1	9	14	74
Percent of Total	10.1%	5.1%	12.1%	24.2%	42.4%	6.1%	100.0%	1.0%	1.0%	9.1%	14.1%	74.8%

Along Dixie Highway from Grange Hall Road to I-75, there were 99 total crashes during the study period. The majority (42.4%) of these crashes were single vehicle crashes. Of the single vehicle crashes, the majority (69%) occurred when vehicles struck animals in the roadway. Of the rear end crashes, the majority (70.8%) occurred between northbound vehicles. Being unable to stop in time was the leading cause of these crashes. Of the angle crashes, the majority (66.7%) involved eastbound vehicles. Of the sideswipe crashes, all, but one, were sideswipe-same crashes. These were split evenly between northbound and southbound vehicles. Improper lane use and failing to yield were the leading causes of these crashes.

Additionally, there was one fatality and one A-level injury crash during the study period. The fatality resulted from a head on crash. A southbound vehicle was traveling too fast around a curve, ran off the roadway to the right, lost control while re-entering the roadway, crossed the centerline, and struck a northbound vehicle. The driver was not wearing a seat belt at the time of the crash and was ejected from the vehicle. The A-level injury resulted from a single vehicle crash. A northbound motorcyclist struck a deer in the roadway.

Operational Analysis

For this analysis, it was determined that there would be one lane in each direction and a two-way center left-turn lane along Dixie Highway from Grange Hall Road to I-75. At the intersection of Grange Hall Road, there would be a dedicated northbound through lane and a short right turn lane with approximately 50 feet of storage. Similarly, there would be a dedicated southbound through lane and a right turn lane with approximately 400 feet of storage. Additionally, the two-way center left-turn lane opens up to provide northbound and southbound turn lanes at the intersection.

Concept renderings and cost estimates can be found in the Appendix.



Findings and Recommendations

Based on the expected operational and safety analysis of the segment of Dixie Highway from Grange Hall Road to I-75, it is recommended to convert the existing lane configuration to a three-lane cross-section with one lane in each direction and a two-way center left-turn lane. This improvement is expected to have acceptable operations due to the low volumes along the rest of the Dixie Highway corridor. Additionally, there is expected to be an increase in safety. A two-way center left-turn lane gives drivers an area to safely stop to wait to complete their turn safely. Under existing conditions, left-turning vehicles had to stop in a through lane. This led to a pattern of rear end and sideswipe-same crashes.



APPENDIX



Transportation Improvement Association

Crash Detail for 1/1/2021 - 12/31/2023

Criteria: WHERE A.AGENCY_ID = 14 AND cast(A.DATE_VAL as date) BETWEEN '01/01/2021' AND '12/31/2023' AND A.LATITUDE IS NOT NULL AND A.LONGITUDE IS NOT NULL AND geom

#1	Location: SB DIXIE (8.329) 100 feet Nof TRIPP RD							Crash ID: 2212735						
Date:	01/23/2021		Day:	Sat	Hour:	4pm	Weather:	clear	Roadway:	dry	Light:	day		
Injy K:	0		Injy A:	0	Injy B:	1	Injy C:	0	Injy 0:	3	How:	head-on/lt		
CVT:	Groveland Twp			Area:		straight		HBD:	N	Drugs:	N	Complaint #:	2164521	
Unit#	Veh Dir	Action Prior	Event 1		Event 2		Event 3		Event 4		Haz Action		Veh Type	Damage
1	N	left turn	veh in transpt		none		none		none		imprp turn		car	multiple
2	S	go straight	veh in transpt		none		none		none		none		car	multiple

UD10: [2212735](#)

#2	Location: SB DIXIE (9.62) 422 feet Nof E HOLDRIDGE RD							Crash ID:	2195818				
Date:	01/25/2021		Day:	Mon	Hour:	4pm	Weather:	clear	Roadway:	dry	Light:	day	
Injy K:	0		Injy A:	0	Injy B:	0	Injy C:	0	Injy 0:	2	How:	ss-same	
CVT:	Groveland Twp			Area:	straight		HBD:	N	Drugs:	N	Complaint #:	2174621	
Unit#	Veh Dir	Action Prior	Event 1		Event 2		Event 3		Event 4		Haz Action	Veh Type	Damage
1	S	go straight	veh in transpt		none		none		none		carels driving	car	none
2	S	go straight	veh in transpt		none		none		none		none	pickup	lftrear

UD10: [2195818](#)

#3	Location: DIXIE (8.545) 16 feet Nof BIG SKY DR							Crash ID: 2203556						
Date:	02/07/2021		Day:	Sun	Hour:	9am	Weather:	clear	Roadway:	snow	Light:	day		
Injy K:	0		Injy A:	0	Injy B:	0	Injy C:	0	Injy 0:	2	How:	rr-end/rt		
CVT:	Groveland Twp			Area:	inter driveway			HBD:	N	Drugs:	N	Complaint #:	21116121	
Unit#	Veh Dir	Action Prior	Event 1		Event 2		Event 3		Event 4		Haz Action		Veh Type	Damage
1	S	right turn	veh in transpt		none		none		none		imprp turn		car	rtfront
2	S	go straight	veh in transpt		none		none		none		none		car	lftfront

UD10: [2203556](#)

#4	Location: DIXIE (11.173) 48 feet Sof MCCLELLAND RD							Crash ID: 2266639					
Date:	04/10/2021	Day:	Sat	Hour:	5pm	Weather:	cloudy	Roadway:	dry	Light:	day		
Injy K:	0	Injy A:	0	Injy B:	0	Injy C:	1	Injy 0:	2	How:	angle		
CVT:	Holly Twp		Area:		straight		HBD:	N	Drugs:	N	Complaint #:	21302921	
Unit#	Veh Dir	Action Prior	Event 1		Event 2		Event 3		Event 4		Haz Action	Veh Type	Damage
1	W	u-turn	veh in transpt		none		none		none		imprp turn	pickup	ctrfront
2	N	go straight	veh in transpt		none		none		none		none	car	rtside

UD10: [2266639](#)

#5 Location: SB DIXIE (8.689) 364 feet Nof HOLDRIDGE RD Crash ID: 2261848
Date: 04/22/2021 Day: Thu Hour: 11p Weather: clear Roadway: dry Light: dark/unltd
Injy K: 0 Injy A: 0 Injy B: 0 Injy C: 0 Injy 0: 1 How: single
CVT: Groveland Twp Area: straight HBD: N Drugs: N Complaint #: 21341421
Unit# Veh Dir Action Prior Event 1 Event 2 Event 3 Event 4 Haz Action Veh Type Damage
1 S go straight animal none none none none unable to stop car lftfront
UD10: [2261848](#)

#6 Location: DIXIE (10.806) 121 feet Nof BELFORD RD Crash ID: 2297611
Date: 06/21/2021 Day: Mon Hour: 10p Weather: clear Roadway: dry Light: dark/unltd
Injy K: 0 Injy A: 0 Injy B: 0 Injy C: 0 Injy 0: 1 How: single
CVT: Holly Twp Area: straight HBD: N Drugs: N Complaint #: 21539621
Unit# Veh Dir Action Prior Event 1 Event 2 Event 3 Event 4 Haz Action Veh Type Damage
1 N go straight animal none none none none none car rtfrent
UD10: [2297611](#)

#7 Location: NB DIXIE (11.191) 48 feet NWof E MCCLELLAND RD Crash ID: 2332284
Date: 07/30/2021 Day: Fri Hour: 8pm Weather: clear Roadway: dry Light: dawn
Injy K: 0 Injy A: 1 Injy B: 1 Injy C: 0 Injy 0: 0 How: single
CVT: Holly Twp Area: straight HBD: N Drugs: N Complaint #: 21680521
Unit# Veh Dir Action Prior Event 1 Event 2 Event 3 Event 4 Haz Action Veh Type Damage
1 N go straight animal none none none none none motorcycle multiple
UD10: [2332284](#)

#8 Location: TRIPP (0.004) 21 feet Eof DIXIE HWY Crash ID: 2337627
Date: 08/02/2021 Day: Mon Hour: 1pm Weather: clear Roadway: dry Light: day
Injy K: 0 Injy A: 0 Injy B: 0 Injy C: 0 Injy 0: 2 How: back
CVT: Groveland Twp Area: fwy other HBD: N Drugs: N Complaint #: 21686921
Unit# Veh Dir Action Prior Event 1 Event 2 Event 3 Event 4 Haz Action Veh Type Damage
1 W backing veh in transpt none none none none imprp backing pickup none
2 W stop on road veh in transpt none none none none none car ctrfront
UD10: [2337627](#)

#9 Location: NB DIXIE (9.078) 465 feet Sof PERRYVILLE RD Crash ID: 2350588
Date: 08/19/2021 Day: Thu Hour: 1pm Weather: clear Roadway: dry Light: day
Injy K: 0 Injy A: 0 Injy B: 0 Injy C: 0 Injy 0: 2 How: single
CVT: Groveland Twp Area: straight HBD: N Drugs: N Complaint #: 21752521
Unit# Veh Dir Action Prior Event 1 Event 2 Event 3 Event 4 Haz Action Veh Type Damage
1 N avoid veh-angle ran off road/r none none none none none car multiple
UD10: [2350588](#)

#10 Location: DIXIE (8.328) 95 feet Sof PERRYVILLE RD **Crash ID:** 2357333
Date: 08/28/2021 **Day:** Sat **Hour:** 3pm **Weather:** clear **Roadway:** dry **Light:** day
Injy K: 0 **Injy A:** 0 **Injy B:** 1 **Injy C:** 0 **Injy 0:** 3 **How:** rr-end
CVT: Groveland Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 21786421

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	N	stop on road	veh in transpt	none	none	none	failed to yield	car	ctrfront
2	N	go straight	veh in transpt	none	none	none	none	car	ctrrear

UD10: [2357333](#)

#11 Location: S DIXIE (10.595) 280 feet SEof GROVELAND RD **Crash ID:** 2361908
Date: 09/03/2021 **Day:** Fri **Hour:** 2pm **Weather:** clear **Roadway:** dry **Light:** day
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 2 **How:** rr-end
CVT: Holly Twp **Area:** fwy other **HBD:** N **Drugs:** N **Complaint #:** 21803821

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	S	go straight	veh in transpt	none	none	none	unable to stop	car	ctrfront
2	S	left turn	veh in transpt	none	none	none	none	car	ctrrear

UD10: [2361908](#)

#12 Location: NB DIXIE (8.315) 26 feet Nof TRIPP RD **Crash ID:** 2359131
Date: 09/04/2021 **Day:** Sat **Hour:** 10a **Weather:** clear **Roadway:** dry **Light:** day
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 2 **Injy 0:** 1 **How:** angle
CVT: Groveland Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 21806921

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	E	left turn	veh in transpt	none	none	none	failed to yield	car	multiple
2	N	go straight	veh in transpt	none	none	none	none	car	ctrfront

UD10: [2359131](#)

#13 Location: DIXIE (8.49) 275 feet Sof GROVELAND RD **Crash ID:** 2361920
Date: 09/11/2021 **Day:** Sat **Hour:** 3pm **Weather:** clear **Roadway:** dry **Light:** day
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 2 **How:** other
CVT: Groveland Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 21831821

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	N	left turn	veh in transpt	none	none	none	imprp turn	car	rtfront
2	S	go straight	veh in transpt	none	none	none	none	car	lftside

UD10: [2361920](#)

#14 Location: DIXIE (11.22) 100 feet Nof MCCCELLAND RD **Crash ID:** 2366020

Date: 09/11/2021 **Day:** Sat **Hour:** 12p **Weather:** clear **Roadway:** dry **Light:** day

Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 1 **Injy 0:** 5 **How:** ss-same

CVT: Holly Twp **Area:** curved **HBD:** N **Drugs:** N **Complaint #:** 21831521

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	N	go straight	loss of control	none	none	none	imprp lane use	car	lftfront
2	N	go straight	veh in transpt	none	none	none	imprp lane use	car	rtfront

UD10: [2366020](#)

#15 Location: NB DIXIE (9.686) 74 feet Sof LAHRING RD **Crash ID:** 2361894

Date: 09/12/2021 **Day:** Sun **Hour:** 9am **Weather:** cloudy **Roadway:** dry **Light:** day

Injy K: 0 **Injy A:** 0 **Injy B:** 1 **Injy C:** 1 **Injy 0:** 3 **How:** other

CVT: Groveland Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 21833321

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	N	u-turn	veh in transpt	none	none	none	carels driving	pickup	lftfront
2	N	go straight	veh in transpt	none	none	none	none	pickup	rtfront

UD10: [2361894](#)

#16 Location: DIXIE HWY (10.784) 5 feet Wof BELFORD ROAD **Crash ID:** 2377376

Date: 09/18/2021 **Day:** Sat **Hour:** 12p **Weather:** clear **Roadway:** dry **Light:** day

Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 1 **Injy 0:** 2 **How:** angle

CVT: Holly Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 21857221

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	E	left turn	veh in transpt	none	none	none	failed to yield	car	rtfront
2	S	go straight	veh in transpt	none	none	none	none	pickup	rtrear

UD10: [2377376](#)

#17 Location: PERRYVILLE (0.009) 50 feet Nof DIXIE WHY **Crash ID:** 2401202

Date: 09/26/2021 **Day:** Sun **Hour:** 11a **Weather:** clear **Roadway:** dry **Light:** day

Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 0 **How:** rr-end

CVT: Groveland Twp **Area:** inter other **HBD:** N **Drugs:** N **Complaint #:** 210199544

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	S	go straight	veh in transpt	none	none	none	unable to stop	car	rtfront
2	S	stop on road	veh in transpt	none	none	none	none	car	lftrear

UD10: [2401202](#)

#18	Location: DIXIE HWY (9.984) 1500 feet Nof LAHRING RD							Crash ID: 2401208						
Date:	09/26/2021		Day:	Sun	Hour:	4pm	Weather:	clear	Roadway:	dry	Light:	day		
Injy K:	0		Injy A:	0	Injy B:	0	Injy C:	0	Injy 0:	4	How:	rr-end		
CVT:	Holly Twp			Area:	straight			HBD:	N	Drugs:	N	Complaint #:	210199728	
Unit#	Veh Dir	Action Prior	Event 1		Event 2		Event 3		Event 4		Haz Action		Veh Type	Damage
1	N	go straight	veh in transpt		none		none		none		unable to stop		car	rtfront
2	N	slow/stop on rd	veh in transpt		none		none		none		none		car	lftrear

UD10: [2401208](#)

#19	Location: DIXIE HWY (9.356) 150 feet Nof PERRYVILLE							Crash ID: 2404510						
Date:	10/02/2021		Day:	Sat	Hour:	2pm	Weather:	clear	Roadway:	dry	Light:	day		
Injy K:	0		Injy A:	0	Injy B:	0	Injy C:	0	Injy 0:	4	How:	ss-same		
CVT:	Groveland Twp			Area:			inter driveway		HBD:	N	Drugs:	N	Complaint #:	210204563
Unit#	Veh Dir	Action Prior	Event 1		Event 2		Event 3		Event 4		Haz Action		Veh Type	Damage
1	NE	left turn	veh in transpt		none		none		none		failed to yield		car	rtfront
2	N	go straight	veh in transpt		none		none		none		none		car	lftfront

UD10: [2404510](#)

#20	Location: DIXIE (9.442) 600 feet NWof PERRYVILLE RD							Crash ID: 2406413						
Date:	10/02/2021		Day:	Sat	Hour:	3pm	Weather:	clear	Roadway:	dry	Light:	day		
Injy K:	0		Injy A:	0	Injy B:	0	Injy C:	0	Injy 0:	3	How:	ss-same		
CVT:	Groveland Twp			Area:		straight		HBD:	N	Drugs:	N	Complaint #:	210204615	
Unit#	Veh Dir	Action Prior	Event 1		Event 2		Event 3		Event 4		Haz Action		Veh Type	Damage
1	N	u-turn	veh in transpt		none		none		none		failed to yield		car	lftside
2	N	go straight	veh in transpt		none		none		none		none		car	rtfront

UD10: [2406413](#)

#21	Location: SB DIXIE (8.309) 5 feet Sof E TRIPP RD							Crash ID: 2384727						
Date:	10/02/2021		Day:	Sat	Hour:	1pm	Weather:	clear	Roadway:	dry	Light:	day		
Injy K:	0		Injy A:	0	Injy B:	0	Injy C:	1	Injy 0:	2	How:	angle		
CVT:	Groveland Twp			Area:			inter other		HBD:	N	Drugs:	N	Complaint #:	21907921
Unit#	Veh Dir	Action Prior	Event 1		Event 2		Event 3		Event 4		Haz Action		Veh Type	Damage
1	E	left turn	veh in transpt		none		none		none		failed to yield		pickup	rtside
2	N	go straight	veh in transpt		none		none		none		none		car	ctrfront

UD10: [2384727](#)

#22 Location: EB DIXIE (10.667) 100 feet NW of GROVELAND **Crash ID:** 2391801
Date: 10/02/2021 **Day:** Sat **Hour:** 3pm **Weather:** clear **Roadway:** dry **Light:** day
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 2 **How:** angle
CVT: Holly Twp **Area:** inter driveway **HBD:** N **Drugs:** N **Complaint #:** 21908421

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	E	left turn	veh in transpt	none	none	none	failed to yield	car	ctrfront
2	S	go straight	veh in transpt	none	none	none	none	pickup	rtfront

UD10: [2391801](#)

#23 Location: NB DIXIE (9.709) 50 feet NW of E LAHRING RD **Crash ID:** 2400443
Date: 10/16/2021 **Day:** Sat **Hour:** 7pm **Weather:** clear **Roadway:** dry **Light:** dark/unltd
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 1 **How:** single
CVT: Groveland Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 21964421

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	N	go straight	animal	none	none	none	none	car	ctrfront

UD10: [2400443](#)

#24 Location: N DIXIE (10.993) 517 feet Sof MCCLELLAND RD **Crash ID:** 2394542
Date: 10/18/2021 **Day:** Mon **Hour:** 7pm **Weather:** clear **Roadway:** dry **Light:** dark/unltd
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 1 **How:** single
CVT: Holly Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 21973521

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	N	go straight	animal	none	none	none	none	car	lftfront

UD10: [2394542](#)

#25 Location: NB DIXIE HWY (10.779) 20 feet Sof BELFORD RD **Crash ID:** 2414103
Date: 11/01/2021 **Day:** Mon **Hour:** 7am **Weather:** cloudy **Roadway:** dry **Light:** dawn
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 1 **Injy 0:** 3 **How:** rr-end
CVT: Holly Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 211025821

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	N	go straight	veh in transpt	none	none	none	carels driving	car	ctrfront
2	N	slow/stop on rd	veh in transpt	none	none	none	none	pickup	ctrrear

UD10: [2414103](#)

#26 Location: DIXIE HWY (11.173) 48 feet N of MCCLELLAND RD **Crash ID:** 2473249
Date: 01/02/2022 **Day:** Sun **Hour:** 2am **Weather:** snow **Roadway:** snow **Light:** dark/ltd
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 1 **How:** single
CVT: Holly Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 214422

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	N	go straight	animal	none	none	none	none	car	ctrfront

UD10: [2473249](#)

#27 Location: DIXIE (10.982) 576 feet Sof MCCCELLAND RD **Crash ID:** 2493641
Date: 01/19/2022 **Day:** Wed **Hour:** 7am **Weather:** cloudy **Roadway:** dry **Light:** dark/unltd
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 2 **How:** ss-same
CVT: Holly Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 2152722

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	N	go straight	veh in transpt	none	none	none	none	car	rtrear
2	N	go straight	veh in transpt	none	none	none	failed to yield	car	lftfront

UD10: [2493641](#)

#28 Location: NB DIXIE (8.312) 11 feet Nof E TRIPP RD **Crash ID:** 2503218
Date: 02/05/2022 **Day:** Sat **Hour:** 6pm **Weather:** clear **Roadway:** ice **Light:** dark/unltd
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 3 **How:** rr-end/lt
CVT: Groveland Twp **Area:** inter other **HBD:** N **Drugs:** N **Complaint #:** 21124022

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	S	stop on road	veh in transpt	none	none	none	unable to stop	car	roof
2	S	go straight	veh in transpt	none	none	none	none	car	ctrrear

UD10: [2503218](#)

#29 Location: NB DIXIE HWY (8.41) 528 feet Nof TRIPP RD **Crash ID:** 2520480
Date: 02/25/2022 **Day:** Fri **Hour:** 4pm **Weather:** clear **Roadway:** dry **Light:** day
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 1 **How:** single
CVT: Groveland Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 21200222

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	N	avoid veh-angle	ran off road/r	none	none	none	none	car	rtside

UD10: [2520480](#)

#30 Location: NB DIXIE (10.144) 2344 feet Sof GROVELAND **Crash ID:** 2525379
Date: 02/26/2022 **Day:** Sat **Hour:** 8pm **Weather:** clear **Roadway:** dry **Light:** dark/unltd
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 1 **How:** single
CVT: Holly Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 21202722

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	N	go straight	animal	none	none	none	none	car	rtfront

UD10: [2525379](#)

#31 Location: DIXIE (9.229) 523 feet SEof PERRYVILLE RD **Crash ID:** 2534959
Date: 03/14/2022 **Day:** Mon **Hour:** 10a **Weather:** cloudy **Roadway:** dry **Light:** day
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 1 **How:** single
CVT: Groveland Twp **Area:** other **HBD:** N **Drugs:** N **Complaint #:** 21249322

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	S	go straight	loss of control	none	none	none	carels driving	car	ctrfront

UD10: [2534959](#)

#32 Location: TRIPP (0.004) 21 feet Eof DIXIE HWY **Crash ID:** 2553107

Date: 04/08/2022 **Day:** Fri **Hour:** 5pm **Weather:** cloudy **Roadway:** wet **Light:** day

Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 0 **How:** rr-end

CVT: Groveland Twp **Area:** inter other **HBD:** N **Drugs:** N **Complaint #:** 21328122

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	W	stop on road	veh in transpt	none	none	none	failed to yield	car	rtfront
2	W	go straight	veh in transpt	none	none	none	none	car	rtrear

UD10: 2553107

#33 Location: TRIPP (0.003) 16 feet Eof DIXIE HWY **Crash ID:** 2558495

Date: 04/14/2022 **Day:** Mon **Hour:** 7pm **Weather:** clear **Roadway:** dry **Light:** day

Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 1 **How:** single

CVT: Groveland Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 21348122

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	W	go straight	fence	none	none	none	unable to stop	car	ctrfront

UD10: 2558495

#34 Location: DIXIE (10.661) 69 feet Nof GROVELAND RD **Crash ID:** 2563950

Date: 04/26/2022 **Day:** Tue **Hour:** 11p **Weather:** clear **Roadway:** dry **Light:** dark/unltd

Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 1 **How:** single

CVT: Holly Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 21393922

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	N	go straight	animal	none	none	none	none	car	lftfront

UD10: 2563950

#35 Location: N DIXIE HWY (10.778) 26 feet Sof BELFORD RD **Crash ID:** 2573463

Date: 05/05/2022 **Day:** Thu **Hour:** 7am **Weather:** clear **Roadway:** dry **Light:** day

Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 1 **How:** single

CVT: Holly Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 21419422

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	N	go straight	animal	none	none	none	none	car	ctrfront

UD10: 2573463

#36 Location: SB DIXIE HWY (11.099) 42 feet Sof I-75 FWY **Crash ID:** 2596107

Date: 06/03/2022 **Day:** Fri **Hour:** 2pm **Weather:** clear **Roadway:** dry **Light:** day

Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 2 **How:** single

CVT: Holly Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 21522122

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	S	go straight	animal	none	none	none	none	other	lftside

UD10: 2596107

#37 Location: DIXIE (7.151) 417 feet NWof GRANGE HALL RD **Crash ID:** 2606542
Date: 06/12/2022 **Day:** Sun **Hour:** 10p **Weather:** clear **Roadway:** dry **Light:** dark/unltd
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 2 **How:** single
CVT: Groveland Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 21553922
Unit# Veh Dir Action Prior Event 1 Event 2 Event 3 Event 4 Haz Action Veh Type Damage
 1 S go straight animal none none none none car lftfront
UD10: [2606542](#)

#38 Location: S DIXIE (8.547) 26 feet Nof BIG SKY DR **Crash ID:** 2623890
Date: 07/05/2022 **Day:** Tue **Hour:** 7am **Weather:** clear **Roadway:** dry **Light:** day
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 1 **How:** single
CVT: Groveland Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 21629722
Unit# Veh Dir Action Prior Event 1 Event 2 Event 3 Event 4 Haz Action Veh Type Damage
 1 S go straight animal none none none none car rtfrent
UD10: [2623890](#)

#39 Location: BELFORD (4.897) 24 feet Wof DIXIE HWY **Crash ID:** 2634222
Date: 07/20/2022 **Day:** Wed **Hour:** 4pm **Weather:** clear **Roadway:** mud **Light:** day
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 2 **How:** rr-end
CVT: Holly Twp **Area:** w/i intersection **HBD:** N **Drugs:** N **Complaint #:** 21679522
Unit# Veh Dir Action Prior Event 1 Event 2 Event 3 Event 4 Haz Action Veh Type Damage
 1 E go straight veh in transpt none none none unable to stop car rtside
 2 E slow stop on rd veh in transpt none none none none pickup lftrear
UD10: [2634222](#)

#40 Location: DIXIE (8.31) 0 feet Xof TRIPP RD **Crash ID:** 2658676
Date: 08/27/2022 **Day:** Sat **Hour:** 10a **Weather:** clear **Roadway:** dry **Light:** day
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 2 **How:** angle
CVT: Groveland Twp **Area:** w/i intersection **HBD:** N **Drugs:** N **Complaint #:** 21813422
Unit# Veh Dir Action Prior Event 1 Event 2 Event 3 Event 4 Haz Action Veh Type Damage
 1 W right turn veh in transpt none none none failed to yield car lftside
 2 N go straight veh in transpt none none none none car ctrfront
UD10: [2658676](#)

#41 Location: DIXIE (9.338) 53 feet NWof PERRYVILLE RD **Crash ID:** 2662316
Date: 09/02/2022 **Day:** Fri **Hour:** 5pm **Weather:** clear **Roadway:** dry **Light:** day
Injy K: 0 **Injy A:** 0 **Injy B:** 1 **Injy C:** 1 **Injy 0:** 0 **How:** rr-end
CVT: Groveland Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 21834622
Unit# Veh Dir Action Prior Event 1 Event 2 Event 3 Event 4 Haz Action Veh Type Damage
 1 N go straight veh in transpt none none none unable to stop motorcycle lftfront
 2 N stop on road veh in transpt none none none none car rtrear
UD10: [2662316](#)

#42 Location: NB DIXIE (8.302) 42 feet Eof TRIPP RD **Crash ID:** 2672452

Date: 09/07/2022 **Day:** Wed **Hour:** 3pm **Weather:** clear **Roadway:** dry **Light:** day

Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 1 **How:** single

CVT: Groveland Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 21851922

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	N	go straight	loss of control	none	none	none	speeding	car	multiple

UD10: [2672452](#)

#43 Location: DIXIE (9.078) 465 feet Sof PERRYVILLE RD **Crash ID:** 2671631

Date: 09/09/2022 **Day:** Fri **Hour:** 2pm **Weather:** clear **Roadway:** dry **Light:** day

Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 2 **How:** angle

CVT: Groveland Twp **Area:** inter driveway **HBD:** N **Drugs:** N **Complaint #:** 21857922

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	E	enter rdwy	veh in transpt	none	none	none	failed to yield	car	lftfront
2	S	go straight	veh in transpt	none	none	none	none	truck/bus	rtside

UD10: [2671631](#)

#44 Location: DIXIE (10.398) 1320 feet Sof GROVELAND ROAD **Crash ID:** 2674349

Date: 09/16/2022 **Day:** Fri **Hour:** 2pm **Weather:** clear **Roadway:** dry **Light:** day

Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 1 **How:** single

CVT: Holly Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 35619322

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	N	go straight	other non-fixed obj	none	none	none	none	pickup	multiple

UD10: [2674349](#)

#45 Location: NB DIXIE (7.925) 776 feet NWof W SHEILDS RD **Crash ID:** 2673091

Date: 09/17/2022 **Day:** Sat **Hour:** 10a **Weather:** clear **Roadway:** dry **Light:** day

Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 1 **Injy 0:** 1 **How:** rr-end

CVT: Groveland Twp **Area:** curved **HBD:** N **Drugs:** N **Complaint #:** 21886122

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	N	go straight	veh in transpt	none	none	none	unable to stop	motorcycle	multiple
2	N	slow/stop on rd	veh in transpt	none	none	none	none	car	lftrear

UD10: [2673091](#)

#46 Location: N DIXIE (8.985) 26 feet Sof GROVELAND RD **Crash ID:** 2673094
Date: 09/17/2022 **Day:** Sat **Hour:** 12p **Weather:** clear **Roadway:** dry **Light:** day
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 4 **How:** rr-end
CVT: Groveland Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 21886522

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	N	slow/stop on rd	veh in transpt	none	none	none	unable to stop	car	ctrfront
2	N	slow/stop on rd	veh in transpt	none	none	none	none	car	ctrrear
3	N	slow/stop on rd	veh in transpt	none	none	none	none	car	ctrrear

UD10: [2673094](#)

#47 Location: S DIXIE (10.778) 26 feet Sof BELFORD RD **Crash ID:** 2673095
Date: 09/17/2022 **Day:** Sat **Hour:** 1pm **Weather:** clear **Roadway:** dry **Light:** day
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 2 **How:** angle
CVT: Holly Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 21886722

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	W	left turn	veh in transpt	none	none	none	failed to yield	car	ctrfront
2	S	go straight	veh in transpt	none	none	none	none	car	lftside

UD10: [2673095](#)

#48 Location: SB DIXIE (9.87) 897 feet NWof LAHRING RD **Crash ID:** 2692835
Date: 09/17/2022 **Day:** Sat **Hour:** 2pm **Weather:** clear **Roadway:** dry **Light:** day
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 2 **How:** ss-same
CVT: Groveland Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 21886922

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	S	stop on road	veh in transpt	none	none	none	imprp lane use	pickup	rtside
2	S	go straight	veh in transpt	none	none	none	none	pickup	lftside

UD10: [2692835](#)

#49 Location: DIXIE HWY (9.5) 1056 feet Sof LAHRING RD **Crash ID:** 2697428
Date: 09/18/2022 **Day:** Sun **Hour:** 1pm **Weather:** clear **Roadway:** dry **Light:** day
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 10 **How:** ss-same
CVT: Groveland Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 220209948

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	S	change lanes	veh in transpt	none	none	none	imprp lane use	pickup	rtfront
2	S	go straight	veh in transpt	none	none	none	none	car	lftrear
3	S	go straight	veh in transpt	none	none	none	none	pickup	lftside

UD10: [2697428](#)

#50 Location: SB DIXIE (9.317) 58 feet SE of PERRYVILLE RD **Crash ID:** 2686305
Date: 09/28/2022 **Day:** Wed **Hour:** 10a **Weather:** cloudy **Roadway:** dry **Light:** day
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 1 **How:** single
CVT: Groveland Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 21920822

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	S	go straight	animal	none	none	none	none	car	ctrfront

UD10: [2686305](#)

#51 Location: DIXIE (8.305) 25 feet S of TRIPP RD **Crash ID:** 2697870
Date: 10/01/2022 **Day:** Sat **Hour:** 12p **Weather:** clear **Roadway:** dry **Light:** day
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 3 **Injy 0:** 0 **How:** head-on/lt
CVT: Groveland Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 21930122

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	S	left turn	veh in transpt	none	none	none	failed to yield	car	rtside
2	N	go straight	veh in transpt	none	none	none	none	car	ctrfront

UD10: [2697870](#)

#52 Location: DIXIE (10.83) 248 feet N of BELFORD RD **Crash ID:** 2702052
Date: 10/01/2022 **Day:** Sat **Hour:** 8pm **Weather:** clear **Roadway:** dry **Light:** dark/unltd
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 2 **How:** rr-end
CVT: Holly Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 21931822

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	N	slow/stop on rd	veh in transpt	none	none	none	unable to stop	car	lftfront
2	N	slow/stop on rd	veh in transpt	none	none	none	none	car	ctrrear

UD10: [2702052](#)

#53 Location: DIXIE (10.691) 229 feet NW of GROVELAND **Crash ID:** 2712762
Date: 10/30/2022 **Day:** Sun **Hour:** 8pm **Weather:** clear **Roadway:** dry **Light:** dark/unltd
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 1 **How:** single
CVT: Holly Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 211036922

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	S	go straight	animal	none	none	none	none	car	ctrfront

UD10: [2712762](#)

#54 Location: NB DIXIE (8.317) 36 feet N of TRIPP RD **Crash ID:** 2715049
Date: 10/31/2022 **Day:** Mon **Hour:** 9pm **Weather:** rain **Roadway:** wet **Light:** dark/lt
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 2 **Injy 0:** 0 **How:** head-on/lt
CVT: Groveland Twp **Area:** w/i intersection **HBD:** N **Drugs:** N **Complaint #:** 211041022

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	S	left turn	veh in transpt	none	none	none	failed to yield	car	ctrfront
2	N	go straight	veh in transpt	none	none	none	none	car	ctrfront

UD10: [2715049](#)

#55 Location: SB DIXIE HWY (8.74) 1320 feet Sof GROVELAND RD **Crash ID:** 2730465
Date: 11/04/2022 **Day:** Fri **Hour:** 8pm **Weather:** clear **Roadway:** dry **Light:** dark/unltd
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 1 **How:** single
CVT: Groveland Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 211055022
Unit# Veh Dir Action Prior Event 1 Event 2 Event 3 Event 4 Haz Action Veh Type Damage
 1 NW go straight animal none none none none car ctrfront
UD10: [2730465](#)

#56 Location: DIXIE (9.45) 1320 feet Sof LAHRING RD **Crash ID:** 2724927
Date: 11/08/2022 **Day:** Tue **Hour:** 10p **Weather:** clear **Roadway:** dry **Light:** dark/unltd
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 1 **How:** single
CVT: Groveland Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 211069122
Unit# Veh Dir Action Prior Event 1 Event 2 Event 3 Event 4 Haz Action Veh Type Damage
 1 S go straight animal none none none none car lftfront
UD10: [2724927](#)

#57 Location: DIXIE (7.589) 997 feet SEof SHEILDS RD **Crash ID:** 2733069
Date: 11/12/2022 **Day:** Sat **Hour:** 4pm **Weather:** clear **Roadway:** dry **Light:** day
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 1 **How:** single
CVT: Groveland Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 211081922
Unit# Veh Dir Action Prior Event 1 Event 2 Event 3 Event 4 Haz Action Veh Type Damage
 1 N go straight animal none none none none car lftfront
UD10: [2733069](#)

#58 Location: DIXIE (9.309) 99 feet SEof PERRYVILLE RD **Crash ID:** 2762586
Date: 12/11/2022 **Day:** Sun **Hour:** 10p **Weather:** clear **Roadway:** dry **Light:** dark/unltd
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 1 **How:** single
CVT: Groveland Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 211185922
Unit# Veh Dir Action Prior Event 1 Event 2 Event 3 Event 4 Haz Action Veh Type Damage
 1 N go straight animal none none none none car rtfront
UD10: [2762586](#)

#59 Location: TRIPP (0.002) 11 feet Eof DIXIE HWY **Crash ID:** 2787498
Date: 01/04/2023 **Day:** Wed **Hour:** 4pm **Weather:** cloudy **Roadway:** dry **Light:** dusk
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 2 **How:** rr-end
CVT: Groveland Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 2111022
Unit# Veh Dir Action Prior Event 1 Event 2 Event 3 Event 4 Haz Action Veh Type Damage
 1 W go straight veh in transpt none none none none car ctrfront
 2 W stop on road veh in transpt none none none none car ctrrear
UD10: [2787498](#)



#60 **Location:** DIXIE (9.002) 63 feet Nof GROVELAND **Crash ID:** 2793057
Date: 01/06/2023 **Day:** Fri **Hour:** 8am **Weather:** cloudy **Roadway:** wet **Light:** day
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 2 **Injy 0:** 0 **How:** angle
CVT: Groveland Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 2117923

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	E	left turn	veh in transpt	none	none	none	failed to yield	car	lftside
2	N	go straight	veh in transpt	none	none	none	none	car	ctrfront

UD10: [2793057](#)

#61 **Location:** DIXIE (9.011) 111 feet NWof GROVELAND **Crash ID:** 2802235
Date: 01/25/2023 **Day:** Wed **Hour:** 6pm **Weather:** sleet/hail **Roadway:** ice **Light:** dark/unltd
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 1 **How:** single
CVT: Groveland Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 2190023

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	S	change lanes	loss of control	none	none	none	speeding	car	lftfront

UD10: [2802235](#)

#62 **Location:** SB DIXIE (8.025) 1304 feet NWof S SHEILDS RD **Crash ID:** 2817254
Date: 02/07/2023 **Day:** Tue **Hour:** 7am **Weather:** cloudy **Roadway:** ice **Light:** dark/unltd
Injy K: 0 **Injy A:** 0 **Injy B:** 2 **Injy C:** 0 **Injy 0:** 0 **How:** head-on
CVT: Groveland Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 21137223

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	S	go straight	veh in transpt	none	none	none	none	car	multiple
2	N	go straight	loss of control	none	none	none	carels driving	pickup	multiple

UD10: [2817254](#)

#63 **Location:** SB DIXIE (11.033) 306 feet Nof BELFORD RD **Crash ID:** 2860442
Date: 04/10/2023 **Day:** Mon **Hour:** 4am **Weather:** clear **Roadway:** dry **Light:** dark/unltd
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 1 **How:** single
CVT: Holly Twp **Area:** fwy other **HBD:** N **Drugs:** N **Complaint #:** 21352223

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	S	go straight	animal	none	none	none	none	car	ctrfront

UD10: [2860442](#)

#64 **Location:** SB DIXIE (10.932) 787 feet Sof MCCLELLAND RD **Crash ID:** 2861150
Date: 04/11/2023 **Day:** Tue **Hour:** 8pm **Weather:** cloudy **Roadway:** dry **Light:** dark/ltd
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 1 **How:** single
CVT: Holly Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 21359723

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	S	go straight	animal	none	none	none	none	car	multiple

UD10: [2861150](#)

#65 **Location:** NB DIXIE (10.932) 787 feet Sof MCCLELLAND RD **Crash ID:** 2861153

Date: 04/11/2023 **Day:** Tue **Hour:** 8pm **Weather:** cloudy **Roadway:** dry **Light:** dark/ltd

Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 1 **How:** single

CVT: Holly Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 21359323

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	N	go straight	animal	none	none	none	none	car	multiple

UD10: [2861153](#)

#66 **Location:** NB N DIXIE HWY (9.653) 248 feet Sof LAHRING RD **Crash ID:** 2869266

Date: 04/23/2023 **Day:** Sun **Hour:** 1am **Weather:** clear **Roadway:** dry **Light:** dark/unltd

Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 1 **How:** single

CVT: Groveland Twp **Area:** straight **HBD:** Y **Drugs:** N **Complaint #:** 21399123

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	N	go straight	loss of control	none	none	none	speeding	car	multiple

UD10: [2869266](#)

#67 **Location:** DIXIE (7.393) 1695 feet NWof GRANGE HALL RD **Crash ID:** 2879828

Date: 05/07/2023 **Day:** Sun **Hour:** 4pm **Weather:** clear **Roadway:** dry **Light:** day

Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 1 **How:** single

CVT: Groveland Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 21448023

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	E	go straight	other fixed obj	none	none	none	imprp lane use	motorhome	rtside

UD10: [2879828](#)

#68 **Location:** DIXIE (10.516) 697 feet SEof GROVELAND **Crash ID:** 2888917

Date: 05/17/2023 **Day:** Wed **Hour:** 7pm **Weather:** clear **Roadway:** dry **Light:** day

Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 1 **How:** single

CVT: Holly Twp **Area:** fwy other **HBD:** N **Drugs:** N **Complaint #:** 21487423

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	N	go straight	animal	none	none	none	none	car	ctrfront

UD10: [2888917](#)

#69 **Location:** NB DIXIE (9.719) 100 feet Nof LAHRING RD **Crash ID:** 2888907

Date: 05/18/2023 **Day:** Thu **Hour:** 9pm **Weather:** clear **Roadway:** dry **Light:** dusk

Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 1 **How:** single

CVT: Groveland Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 21491423

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	N	go straight	animal	none	none	none	none	car	ctrfront

UD10: [2888907](#)

#70 Location: BIG SKY (0.012) 63 feet Wof DIXIE HWY Crash ID: 2894263
Date: 05/24/2023 Day: Wed Hour: 2pm Weather: clear Roadway: dry Light: day
Injy K: 0 Injy A: 0 Injy B: 0 Injy C: 0 Injy 0: 1 How: other
CVT: Groveland Twp Area: inter other HBD: N Drugs: N Complaint #: 21511423
Unit# Veh Dir Action Prior Event 1 Event 2 Event 3 Event 4 Haz Action Veh Type Damage
1 W go straight veh in transpt none none none speeding truck/bus rtside
UD10: [2894263](#)

#71 Location: SB DIXIE (10.45) 1045 feet Nof LAHRING RD Crash ID: 2900745
Date: 06/02/2023 Day: Fri Hour: 12a Weather: clear Roadway: dry Light: dark/unltd
Injy K: 0 Injy A: 0 Injy B: 0 Injy C: 0 Injy 0: 1 How: single
CVT: Holly Twp Area: straight HBD: N Drugs: N Complaint #: 21545823
Unit# Veh Dir Action Prior Event 1 Event 2 Event 3 Event 4 Haz Action Veh Type Damage
1 S go straight animal none none none none pickup rtfnt
UD10: [2900745](#)

#72 Location: DIXIE (9.327) 5 feet SEof PERRYVILLE RD Crash ID: 2907749
Date: 06/08/2023 Day: Thu Hour: 3pm Weather: clear Roadway: dry Light: day
Injy K: 0 Injy A: 0 Injy B: 1 Injy C: 0 Injy 0: 1 How: angle
CVT: Groveland Twp Area: w/i intersection HBD: N Drugs: N Complaint #: 21569623
Unit# Veh Dir Action Prior Event 1 Event 2 Event 3 Event 4 Haz Action Veh Type Damage
1 E left turn veh in transpt none none none failed to yield truck/bus rtrear
2 N go straight veh in transpt none none none none car ctrfront
UD10: [2907749](#)

#73 Location: DIXIE (10.923) 739 feet NWof BELFORD RD Crash ID: 2910129
Date: 06/13/2023 Day: Tue Hour: 9am Weather: cloudy Roadway: dry Light: day
Injy K: 0 Injy A: 0 Injy B: 0 Injy C: 0 Injy 0: 2 How: ss-opp
CVT: Holly Twp Area: straight HBD: N Drugs: N Complaint #: 21586123
Unit# Veh Dir Action Prior Event 1 Event 2 Event 3 Event 4 Haz Action Veh Type Damage
1 N go straight cross ctrline none none none imprp lane use car ctrfront
2 S go straight veh in transpt none none none none car multiple
UD10: [2910129](#)

#74 Location: DIXIE (7.532) 1299 feet SEof SHEILDS RD Crash ID: 2931778
Date: 07/07/2023 Day: Fri Hour: 8pm Weather: clear Roadway: dry Light: day
Injy K: 1 Injy A: 1 Injy B: 0 Injy C: 1 Injy 0: 1 How: head-on
CVT: Groveland Twp Area: curved HBD: Y Drugs: Y Complaint #: 21667623
Unit# Veh Dir Action Prior Event 1 Event 2 Event 3 Event 4 Haz Action Veh Type Damage
1 S none ran off road/r none none none speeding car rtfnt
2 N go straight veh in transpt none none none none car ltfnt
UD10: [2931778](#)

#75 **Location:** SB DIXIE (7.657) 639 feet SEof SHEILDS RD **Crash ID:** 2951726
Date: 08/05/2023 **Day:** Sat **Hour:** 3am **Weather:** clear **Roadway:** dry **Light:** dark/lt'd
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 1 **Injy 0:** 1 **How:** single
CVT: Groveland Twp **Area:** inter driveway **HBD:** N **Drugs:** N **Complaint #:** 21756523
Unit# **Veh Dir** **Action Prior** **Event 1** **Event 2** **Event 3** **Event 4** **Haz Action** **Veh Type** **Damage**
1 S avoid animal loss of control none none none carels driving car ctrfront
UD10: [2951726](#)

#76 **Location:** SB DIXIE (8.511) 164 feet Sof BIG SKY DR **Crash ID:** 2955345
Date: 08/05/2023 **Day:** Sat **Hour:** 6am **Weather:** clear **Roadway:** dry **Light:** dawn
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 1 **How:** single
CVT: Groveland Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 21757023
Unit# **Veh Dir** **Action Prior** **Event 1** **Event 2** **Event 3** **Event 4** **Haz Action** **Veh Type** **Damage**
1 S go straight animal none none none none car ctrfront
UD10: [2955345](#)

#77 **Location:** SB DIXIE (9.186) 750 feet SEof PERRYVILLE RD **Crash ID:** 2955347
Date: 08/05/2023 **Day:** Sat **Hour:** 10a **Weather:** clear **Roadway:** dry **Light:** day
Injy K: 0 **Injy A:** 0 **Injy B:** 1 **Injy C:** 0 **Injy 0:** 0 **How:** single
CVT: Groveland Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 21757523
Unit# **Veh Dir** **Action Prior** **Event 1** **Event 2** **Event 3** **Event 4** **Haz Action** **Veh Type** **Damage**
1 S go straight loss of control none none none speeding car multiple
UD10: [2955347](#)

#78 **Location:** NB DIXIE (8.615) 26 feet Sof E HOLDRIDGE RD **Crash ID:** 2963334
Date: 08/20/2023 **Day:** Sun **Hour:** 4pm **Weather:** cloudy **Roadway:** dry **Light:** day
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 8 **How:** rr-end
CVT: Groveland Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 21807223
Unit# **Veh Dir** **Action Prior** **Event 1** **Event 2** **Event 3** **Event 4** **Haz Action** **Veh Type** **Damage**
1 N go straight veh in transpt none none none unable to stop car ctrfront
2 N stop on road veh in transpt none none none none car ctrrear
UD10: [2963334](#)

~~**#79** **Location:** WB TRIPP (0.001) 5 feet Wof DIXIE HWY **Crash ID:** 2961540
Date: 08/21/2023 **Day:** Mon **Hour:** 6pm **Weather:** clear **Roadway:** dry **Light:** day
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 2 **How:** rr-end
CVT: Groveland Twp **Area:** inter other **HBD:** N **Drugs:** N **Complaint #:** 21811023
Unit# **Veh Dir** **Action Prior** **Event 1** **Event 2** **Event 3** **Event 4** **Haz Action** **Veh Type** **Damage**
1 W right turn veh in transpt none none none imprp lane use car ctrfront
2 W stop on road veh in transpt none none none none car ctrrear
UD10: [2961540](#)~~

#80 Location: NB DIXIE (10.212) 2302 feet Sof GROVELAND RD **Crash ID:** 2966178
Date: 08/24/2023 **Day:** Thu **Hour:** 10p **Weather:** rain **Roadway:** wet **Light:** dark/unltd
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 1 **Injy 0:** 1 **How:** single
CVT: Holly Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 21822423

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	N	go straight	loss of control	none	none	none	speeding	pickup	ctrfront

UD10: [2966178](#)

#81 Location: DIXIE (9.586) 602 feet Sof LAHRING RD **Crash ID:** 2981230
Date: 08/26/2023 **Day:** Sat **Hour:** 7pm **Weather:** clear **Roadway:** dry **Light:** day
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 7 **How:** angle
CVT: Groveland Twp **Area:** inter driveway **HBD:** N **Drugs:** N **Complaint #:** 230213789

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	E	change lanes	veh in transpt	none	none	none	imprp lane use	car	lftfront
2	N	go straight	veh in transpt	none	none	none	none	pickup	lftside

UD10: [2981230](#)

#82 Location: NB DIXIE (8.7) 5280 feet Sof LAHRING RD **Crash ID:** 3035024
Date: 09/05/2023 **Day:** Tue **Hour:** 4pm **Weather:** clear **Roadway:** dry **Light:** day
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 1 **How:** other
CVT: Groveland Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 21861523

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1		go straight	other non-fixed obj	none	none	none	carels driving	uncoded	none
2	N	go straight	other noncoll	none	none	none	none	car	lftside

UD10: [3035024](#)

#83 Location: DIXIE (9.319) 48 feet Sof PERRYVILLE **Crash ID:** 2988477
Date: 09/10/2023 **Day:** Sun **Hour:** 5pm **Weather:** clear **Roadway:** dry **Light:** day
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 5 **How:** back
CVT: Groveland Twp **Area:** w/i intersection **HBD:** N **Drugs:** N **Complaint #:** 230227371

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	SW	left turn	veh in transpt	none	none	none	failed to yield	car	rtrear
2	N	backing	veh in transpt	none	none	none	none	car	rtrear

UD10: [2988477](#)

#84 Location: DIXIE (8.246) 338 feet Sof TRIPP RD **Crash ID:** 2980245

Date: 09/14/2023 **Day:** Thu **Hour:** 12p **Weather:** clear **Roadway:** dry **Light:** day

Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 1 **Injy 0:** 1 **How:** rr-end

CVT: Groveland Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 21891823

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	N	go straight	veh in transpt	none	none	none	unable to stop	truck/bus	rtfront
2	N	slow/stop on rd	veh in transpt	none	none	none	none	car	lftrear

UD10: [2980245](#)

#85 Location: SB DIXIE (10.095) 2086 feet NWof W LAHRING RD **Crash ID:** 2991199

Date: 09/17/2023 **Day:** Sun **Hour:** 2pm **Weather:** rain **Roadway:** wet **Light:** day

Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 1 **How:** single

CVT: Holly Twp **Area:** fwy other **HBD:** N **Drugs:** N **Complaint #:** 21901923

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	S	go straight	loss of control	none	none	none	speeding	car	ctrfront

UD10: [2991199](#)

#86 Location: DIXIE (10.454) 1024 feet SEof GROVELAND **Crash ID:** 2987011

Date: 09/23/2023 **Day:** Sat **Hour:** 8pm **Weather:** clear **Roadway:** dry **Light:** dark/unltd

Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 1 **Injy 0:** 2 **How:** rr-end

CVT: Holly Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 21921823

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	N	change lanes	veh in transpt	none	none	none	unable to stop	pickup	lftfront
2	N	stop on road	veh in transpt	none	none	none	none	car	ctrfront
3	S	go straight	veh in transpt	none	none	none	none	car	lftside

UD10: [2987011](#)

#87 Location: DIXIE (8.859) 691 feet Sof GROVELAND **Crash ID:** 2998220

Date: 09/23/2023 **Day:** Sat **Hour:** 8pm **Weather:** fog **Roadway:** dry **Light:** dark/unltd

Injy K: 0 **Injy A:** 0 **Injy B:** 1 **Injy C:** 1 **Injy 0:** 2 **How:** rr-end

CVT: Groveland Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 21921923

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	S	go straight	veh in transpt	none	none	none	unable to stop	car	ctrfront
2	S	enter parking	veh parked	none	none	none	none	car	ctrrear

UD10: [2998220](#)

#88 **Location:** DIXIE (8.49) 275 feet Sof GROVELAND **Crash ID:** 2994285

Date: 09/24/2023 **Day:** Sun **Hour:** 2pm **Weather:** clear **Roadway:** dry **Light:** day

Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 3 **How:** rr-end

CVT: Groveland Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 21923423

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	N	go straight	veh in transpt	none	none	none	unable to stop	car	ctrfront
2	N	stop on road	veh in transpt	none	none	none	none	pickup	ctrrear

UD10: [2994285](#)

#89 **Location:** DIXIE (9.33) 9 feet NWof PERRYVILLE RD **Crash ID:** 3011316

Date: 09/30/2023 **Day:** Sat **Hour:** 4pm **Weather:** clear **Roadway:** dry **Light:** day

Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 2 **How:** angle

CVT: Groveland Twp **Area:** inter other **HBD:** N **Drugs:** N **Complaint #:** 230245965

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	E	left turn	veh in transpt	none	none	none	disrgd traffic cntrl	car	lftside
2	S	backing	veh in transpt	none	none	none	none	car	lftrear

UD10: [3011316](#)

#90 **Location:** DIXIE HWY (9.691) 50 feet Sof LAHRING RD **Crash ID:** 3010200

Date: 10/01/2023 **Day:** Sun **Hour:** 5pm **Weather:** clear **Roadway:** dry **Light:** day

Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 3 **How:** rr-end

CVT: Groveland Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 230246806

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	S	slow/stop on rd	veh in transpt	none	none	none	unable to stop	car	ctrfront
2	S	slow/stop on rd	veh in transpt	none	none	none	none	pickup	ctrrear

UD10: [3010200](#)

#91 **Location:** DIXIE (9.329) 4 feet NWof PERRYVILLE RD **Crash ID:** 3024030

Date: 10/01/2023 **Day:** Sun **Hour:** 3pm **Weather:** clear **Roadway:** dry **Light:** day

Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 2 **How:** ss-same

CVT: Groveland Twp **Area:** w/i intersection **HBD:** N **Drugs:** N **Complaint #:** 230246736

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	NE	avoid veh-ft/bk	veh in transpt	none	none	none	unable to stop	car	lftfront
2	N	stop on road	veh in transpt	none	none	none	none	car	rtrear

UD10: [3024030](#)

#92 **Location:** DIXIE (10.634) 73 feet SE of GROVELAND **Crash ID:** 2998243

Date: 10/03/2023 **Day:** Tue **Hour:** 3pm **Weather:** clear **Roadway:** dry **Light:** day

Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 1 **How:** single

CVT: Holly Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 21954423

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	N	go straight	animal	none	none	none	none	pickup	ltfront

UD10: [2998243](#)

#93 **Location:** NB DIXIE (8.992) 10 feet NW of W GROVELAND **Crash ID:** 3001785

Date: 10/05/2023 **Day:** Thu **Hour:** 7am **Weather:** clear **Roadway:** dry **Light:** dark/lt

Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 2 **How:** rr-end

CVT: Groveland Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 21960323

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	N	slow/stop on rd	veh in transpt	none	none	none	unable to stop	truck/bus	ctrfront
2	N	slow/stop on rd	veh in transpt	none	none	none	none	truck/bus	ctrrear

UD10: [3001785](#)

#94 **Location:** DIXIE (8.329) 100 feet NW of TRIPP RD **Crash ID:** 3018212

Date: 10/21/2023 **Day:** Sat **Hour:** 5pm **Weather:** clear **Roadway:** dry **Light:** day

Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 2 **How:** rr-end

CVT: Groveland Twp **Area:** inter other **HBD:** N **Drugs:** N **Complaint #:** 211017623

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	S	go straight	veh in transpt	none	none	none	unable to stop	car	ctrfront
2	S	left turn	veh parked	none	none	none	none	car	ctrrear

UD10: [3018212](#)

#95 **Location:** DIXIE (8.938) 274 feet S of GROVELAND **Crash ID:** 3018216

Date: 10/21/2023 **Day:** Sat **Hour:** 3pm **Weather:** cloudy **Roadway:** dry **Light:** day

Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 2 **How:** rr-end

CVT: Groveland Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 211017323

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	N	go straight	veh in transpt	none	none	none	unable to stop	car	ctrfront
2	N	slow/stop on rd	veh in transpt	none	none	none	none	car	ctrrear

UD10: [3018216](#)



#96 **Location:** DIXIE (8.464) 411 feet Sof BIG SKY DR **Crash ID:** 3018234
Date: 10/21/2023 **Day:** Sat **Hour:** 1pm **Weather:** clear **Roadway:** dry **Light:** day
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 2 **How:** rr-end
CVT: Groveland Twp **Area:** inter driveway **HBD:** N **Drugs:** N **Complaint #:** 211016623

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	N	go straight	veh in transpt	none	none	none	unable to stop	car	lftfront
2	N	left turn	veh parked	none	none	none	none	car	rtrear

UD10: [3018234](#)

#97 **Location:** DIXIE (8.645) 132 feet Nof HOLDRIDGE RD **Crash ID:** 3092498
Date: 10/21/2023 **Day:** Sat **Hour:** 8pm **Weather:** clear **Roadway:** dry **Light:** dark/unltd
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 2 **How:** other
CVT: Groveland Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 211018623

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	N	right turn	veh in transpt	none	none	none	failed to yield	car	ctrfront
2	N	go straight	veh in transpt	none	none	none	none	car	ctrfront

UD10: [3092498](#)

#98 **Location:** NB DIXIE (9.228) 528 feet Sof PERRYVILLE RD **Crash ID:** 3018190
Date: 10/22/2023 **Day:** Sun **Hour:** 2pm **Weather:** clear **Roadway:** dry **Light:** day
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 3 **How:** rr-end
CVT: Groveland Twp **Area:** fwy other **HBD:** N **Drugs:** N **Complaint #:** 211021223

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	N	slow/stop on rd	veh in transpt	none	none	none	unable to stop	car	ctrfront
2	N	slow/stop on rd	veh in transpt	none	none	none	none	car	ctrfront
3	N	slow/stop on rd	veh in transpt	none	none	none	none	pickup	ctrrear

UD10: [3018190](#)

#99 **Location:** SB DIXIE (8.329) 100 feet Nof TRIPP RD **Crash ID:** 3018192
Date: 10/26/2023 **Day:** Thu **Hour:** 7am **Weather:** rain **Roadway:** wet **Light:** dark/ltd
Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 1 **How:** rr-end
CVT: Groveland Twp **Area:** fwy other **HBD:** N **Drugs:** N **Complaint #:** 211033823

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	S	go straight	veh in transpt	none	none	none	unable to stop	pickup	none
2	S	slow/stop on rd	veh in transpt	none	none	none	none	car	rtrear

UD10: [3018192](#)

#100 Location: DIXIE (8.757) 723 feet Nof HOLDRIDGE RD **Crash ID:** 3018222

Date: 10/26/2023 **Day:** Thu **Hour:** 2pm **Weather:** cloudy **Roadway:** dry **Light:** day

Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 1 **How:** single

CVT: Groveland Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 211035523

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	S	go straight	other non-fixed obj	none	none	none	none	car	ctrfront

UD10: [3018222](#)

#101 Location: DIXIE (7.666) 591 feet SEof SHEILDS RD **Crash ID:** 3034030

Date: 11/05/2023 **Day:** Sun **Hour:** 1pm **Weather:** clear **Roadway:** dry **Light:** day

Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 2 **How:** rr-end

CVT: Groveland Twp **Area:** straight **HBD:** N **Drugs:** N **Complaint #:** 211069123

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	N	go straight	veh in transpt	none	none	none	unable to stop	car	ctrfront
2	N	slow/stop on rd	veh in transpt	none	none	none	none	car	rtrear

UD10: [3034030](#)

#102 Location: SB DIXIE (9.719) 100 feet NWof LAHRING RD **Crash ID:** 3034999

Date: 11/07/2023 **Day:** Tue **Hour:** 6am **Weather:** clear **Roadway:** dry **Light:** dark/ltd

Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 1 **How:** single

CVT: Groveland Twp **Area:** fwy other **HBD:** N **Drugs:** N **Complaint #:** 211075023

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	S	go straight	animal	none	none	none	none	car	ctrfront

UD10: [3034999](#)

#103 Location: DIXIE (9.31) 95 feet SEof PERRYVILLE RD **Crash ID:** 3034022

Date: 11/09/2023 **Day:** Thu **Hour:** 7am **Weather:** rain **Roadway:** wet **Light:** dawn

Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 1 **How:** single

CVT: Groveland Twp **Area:** fwy other **HBD:** N **Drugs:** N **Complaint #:** 211083723

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	N	slow/stop on rd	animal	none	none	none	none	car	lftfront

UD10: [3034022](#)

#104 Location: NB DIXIE (8.21) 528 feet Sof TRIPP **Crash ID:** 3050930

Date: 11/10/2023 **Day:** Fri **Hour:** 6pm **Weather:** clear **Roadway:** dry **Light:** dark/ltd

Injy K: 0 **Injy A:** 0 **Injy B:** 0 **Injy C:** 0 **Injy 0:** 1 **How:** single

CVT: Groveland Twp **Area:** fwy other **HBD:** N **Drugs:** N **Complaint #:** 211089823

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	N	go straight	animal	none	none	none	none	car	ctrfront

UD10: [3050930](#)



#105 Location: DIXIE (8.269) 216 feet Sof TRIPP RD

Crash ID: 3044420

Date: 11/11/2023

Day: Sat

Hour: 2pm

Weather: clear

Roadway: dry

Light: day

Injy K: 0

Injy A: 0

Injy B: 0

Injy C: 0

Injy 0: 2

How: ss-same

CVT: Groveland Twp

Area: straight

HBD: N

Drugs: N

Complaint #: 211091523

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	S	change lanes	veh in transpt	none	none	none	imprp lane use	car	rtside
2	S	go straight	veh in transpt	none	none	none	none	car	lftside

UD10: [3044420](#)

#106 Location: DIXIE (7.583) 1029 feet SEof SHEILDS RD

Crash ID: 3087102

Date: 12/18/2023

Day: Mon

Hour: 7pm

Weather: snow

Roadway: snow

Light: dark/unltd

Injy K: 0

Injy A: 0

Injy B: 1

Injy C: 0

Injy 0: 1

How: other

CVT: Groveland Twp

Area: straight

HBD: N

Drugs: Y

Complaint #: 211209123

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	E	go straight	loss of control	none	none	none	speeding	car	rtside
2	W	go straight	veh in transpt	none	none	none	none	pickup	ctrfront

UD10: [3087102](#)

#107 Location: WB DIXIE (8.308) 10 feet Eof N TRIPP RD

Crash ID: 3080669

Date: 12/21/2023

Day: Thu

Hour: 12p

Weather: cloudy

Roadway: dry

Light: day

Injy K: 0

Injy A: 0

Injy B: 0

Injy C: 0

Injy 0: 3

How: rr-end

CVT: Groveland Twp

Area: inter other

HBD: N

Drugs: N

Complaint #: 211217323

Unit#	Veh Dir	Action Prior	Event 1	Event 2	Event 3	Event 4	Haz Action	Veh Type	Damage
1	W	stop on road	veh in transpt	none	none	none	unable to stop	car	lftfront
2	W	go straight	veh in transpt	none	none	none	none	pickup	rtrear

UD10: [3080669](#)

Crash Type

Count	Type
0	uncoded
43	single
2	head-on
3	head-on/lt
12	angle
27	rr-end
1	rr-end/lt
1	rr-end/rt
9	ss-same
1	ss-opp
2	back
6	other
0	unknown
Totals	107

Lighting Conditions

Count	Type
0	uncoded
68	day
4	dawn
2	dusk
9	dark/ltd
24	dark/unltd
0	other
0	unknown
Totals	107

Weather Conditions

Count	Type
0	uncoded
81	clear
17	cloudy
1	fog
5	rain
2	snow
0	wind
1	sleet/hail
0	blowing snow
0	blowing sand
0	smoke
0	unknown
Totals	107

Road Condition

Count	Type
0	uncoded
93	dry
7	wet
3	ice
3	snow
1	mud
0	slush
0	debris
0	water
0	sand
0	oily
0	other
0	unknown
Totals	107

Crashes by Month

Count	Type
7	January
5	February
1	March
9	April
5	May
6	June
4	July
11	August
26	September
21	October
9	November
3	December
Totals	107

Hazardous Action

Count	Type
98	none
9	speeding
0	spd too slow
18	failed to yield
1	disrgd traffic cntrl
0	wrong way
0	left of center
0	imprp passing
9	imprp lane use
4	imprp turn
0	imprp/no signal
1	imprp backing
27	unable to stop
0	other
0	unknown
0	reckls driving
7	carels driving
Totals	174

Unit Type

Count	Type
0	Bicyclist
0	Engineer
174	Vehicle
0	Pedestrian
Totals	174

Crashes by Year

Count	Type
25	2021
33	2022
49	2023
Totals	107

Crash Severity

	Fatal	A	B	C	No Injy	Total
Persons	1	2	11	23	0	37
Crashes	1	1	9	14	82	107

Alcohol in Crashes

	Fatal	A	B	C	PDO	Total
Drinking	1	0	0	0	1	2
Not Drinking	0	1	9	14	81	105
Totals	1	1	9	14	82	107

Crashes per Hour by Day

	Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday	Total
12a-1a	0	0	0	0	0	1	0	1
1a-2a	1	0	0	0	0	0	0	1
2a-3a	1	0	0	0	0	0	0	1
3a-4a	0	0	0	0	0	0	1	1
4a-5a	0	1	0	0	0	0	0	1
5a-6a	0	0	0	0	0	0	0	0
6a-7a	0	0	1	0	0	0	1	2
7a-8a	0	1	2	1	4	0	0	8
8a-9a	0	0	0	0	0	1	0	1
9a-10a	2	0	1	0	0	0	0	3
10a-11a	0	1	0	1	0	0	4	6
11a-12p	1	0	0	0	0	0	0	1
12p-1p	0	0	0	0	2	0	4	6
1p-2p	2	1	0	0	1	0	3	7
2p-3p	3	0	0	1	1	4	3	12
3p-4p	1	0	1	1	1	0	5	9
4p-5p	3	1	1	2	0	1	3	11
5p-6p	2	0	0	0	0	2	2	6
6p-7p	0	1	0	1	0	1	1	4
7p-8p	0	2	0	1	1	0	2	6
8p-9p	1	0	2	0	0	3	5	11
9p-10p	0	1	0	0	1	0	0	2
10p-11p	2	1	1	0	1	0	0	5
11p-12a	0	0	1	0	1	0	0	2
Totals	19	10	10	8	13	13	34	107

DRAWING PATH: P:\0165_0200\17023000_PCCC_Site_StreetDrawings\City\230061_BSE\INES_DixieHwy.dwg August 4, 2025 9:30 AM



- - - -

█

EXISTING ROW
PROPERTY LINE
PROP HIGHWAY EASEMENT
PROP ROADWAY

DIXIE HWY & GRANGE HALL RD

ALTERNATIVE 1



OHM

ARCHITECTS ENGINEERS PLANNERS

OHM-ADVISORS.COM

PRELIMINARY - NOT
FOR CONSTRUCTION

PROJECT NUMBER		PM	##	##	ISSUED FOR: #####		DATE
017023006					REVISION		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		
					###		

COPYRIGHT 2025 OHM. ALL DRAWINGS AND WRITTEN MATERIALS APPEARING HEREIN CONSTITUTE THE ORIGINAL AND UNPUBLISHED WORK OF OHM AND THE SAME MAY NOT BE DUPLICATED, DISTRIBUTED, OR DISCLOSED WITHOUT PRIOR WRITTEN CONSENT OF OHM.



DIXIE HWY & GRANGE HALL RD

ALTERNATIVE 1

PRELIMINARY - NOT
FOR CONSTRUCTION


ISSUED FOR: #####
REVISION: #####
DESCRIPTION: #####

DATE: #####
DATE: #####
DATE: #####

PROJECT NUMBER: 0170230380
PM: #
#

Dixie Hwy and Grange Hall Rd
Alternative 1

DRAWING PATH: P:\016_02001\702000_POC\06_Site_Street\Drawings\City\K2P2006_06\016_02001_702000_POC_06_Site_Street.dwg July 31, 2025 2:55 PM



DIXIE HWY & MCCLELLAND RD

ALTERNATIVE 1



PRELIMINARY - NOT
FOR CONSTRUCTION

ISSUED FOR: #####	DATE
#####	#####
REVISION	DESCRIPTION
###	#####
###	#####
###	#####
###	#####

PROJECT NUMBER	PM	##
0170230060	##	##
Dixie Hwy and Holly Rd		
Alternative 1 - Page 2		

CONTINUED FROM THE PREVIOUS
INTERSECTION (GRANGE HALL)

COPYRIGHT 2025 OHM. ALL DRAWINGS AND WRITTEN MATERIALS APPEARING HEREIN CONSTITUTE THE ORIGINAL AND UNPUBLISHED WORK OF OHM AND THE SAME MAY NOT BE DUPLICATED, DISTRIBUTED, OR DISCLOSED WITHOUT PRIOR WRITTEN CONSENT OF OHM

Dixie Hwy: Option 1 (HMA Overlay)

Item	Qty	Unit	Unit Price	Amount
Mobilization	1	LSUM	\$ 269,000.00	\$ 269,000.00
Excavation	1450	Cyd	\$ 25.00	\$ 36,250.00
Embankment	710	Cyd	\$ 25.00	\$ 17,750.00
Agg Base, 10 inch (Road)	2440	Syd	\$ 25.00	\$ 61,000.00
HMA (6.5 inch, Widening)	800	Ton	\$ 140.00	\$ 112,000.00
HMA (2.5 inch)	16360	Ton	\$ 140.00	\$ 2,290,400.00
Permanent Marking and Signing	1	LSUM	\$ 50,000.00	\$ 50,000.00
MOT	1	LSUM	\$ 100,000.00	\$ 100,000.00
Restoration	2200	Syd	\$ 10.00	\$ 22,000.00
subtotal				\$ 2,958,400.00
Contingency			25%	\$ 739,600.00
TOTAL CONSTRUCTION COST				\$ 3,698,000.00